



1200 E. 151st Street
Olathe, KS 66062
913-397-8200

AVIATION SERVICE DOCUMENT NOTIFICATION

TO: Garmin GTN 6XX/7XX Xi Owner and Operators
DATE: February 24, 2021
SUBJECT: GTN Xi COM/NAV Radios

COMPLIANCE

Recommended: Compliance with this service bulletin is recommended at the next scheduled maintenance opportunity.

PURPOSE

Pilots flying or taxiing along a 180-degree true track may see the GTN Xi COM/NAV radios Red X.



NOTE

The GTN Xi COM/NAV radios still function as intended.



PRODUCTS AFFECTED

GTN 6XX/7XX Xi products with main software version 20.11 that are interfaced to a Garmin GTX 33/330(ES) using the RS-232 GTX Mode S format are affected.

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.