



1200 E. 151<sup>st</sup> Street  
Olathe, KS 66062  
913-397-8200

## AVIATION SERVICE DOCUMENT NOTIFICATION

**TO:** Garmin G500/G600 TXi Owner and Operators  
**DATE:** February 1, 2022  
**SUBJECT:** G500/G600 TXi GDU Software Version 3.30  
**CERTIFICATION AUTHORIZATION:** STC SA02571SE MDL Revision 16

---

### **COMPLIANCE**

Optional: This STC Service Bulletin may be incorporated at the owner's discretion and is not warranty reimbursable.

### **PURPOSE**

This STC Service Bulletin provides notification of an update to the AML STC SA02571SE Master Drawing List (MDL) Revision 16.

MDL revision 16 includes approval for G500/G600 TXi GDU™ Software Version 3.30.

G500/G600 TXi GDU Software Version 3.30 provides the following:

- Smart Glide™ capability when interfaced to a GTN™ Xi
- Fixes the manifold pressure marking issue described in Garmin Service Advisory 22019

### **PRODUCTS AFFECTED**

G500/G600 TXi PFD/MFD/EIS display systems installed using Approved Model List (AML) Supplemental Type Certificate (STC) SA02571SE are affected.

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.