


Information Notice

SUBJECT: GENERAL

OBSOLESCENCE INFORMATION NOTICE

ATA: 45



AIRCRAFT CONCERNED	Version(s)	
	Civil	Military
AS365	N3	
EC155	B, B1	
EC225	LP	
EC725		AP
AS332	L2	

To help you with your operational needs, Airbus Helicopters has launched an update of its Obsolescence Management approach. As obsolescence can have a direct impact on spares and repair supply, we will inform all customers about specific obsolescence issues.

Airbus Helicopters has been informed by its suppliers that the following equipment has become obsolete.

Affected equipment:

**VIBRATION PROCESSING UNIT (VPU)
P/N 704A49430069
MP/N 241-271-006-013**

Solutions:

- No spare support and no Last Buy Order (LBO) possibility for P/N 704A49430069
- Due to the obsolescence of multiple components of P/N 704A49430069, repairs are no longer possible. However, test capabilities for re-validation are maintained.
In case of a faulty VPU (P/N 704A49430069), it will be replaced by the gVPU (generic Vibration Processing Unit) (P/N 704A49439047).
- VPU P/N 704A49430069 has been replaced by the gVPU P/N 704A49439047 (MP/N 241-271-021-111). There is no Service Bulletin available for all H/C variants, but the Tasks or Work Cards in the maintenance manuals (MMA/AMM/MET) will be updated accordingly. If you need additional information, feel free to contact Airbus Helicopters.

No. 3727-I-00

If you have any questions or need further information, feel free to contact our generic obsolescence e-mail address: contact.customer-obsolescence-support.ah@airbus.com, your Airbus Helicopters Customer Support Manager (CSM) or Logistic Key Account Manager.

Disclaimer:

The information provided in this Obsolescence Information Notice does not supersede any type certifications or airworthiness instructions.