

MANDATORY BULLETINS

S/N

41358

DATE (2)	AC TOTAL TIME (3)	DIRECTIVE NUMBER (4)	ISSUED BY (5)	ISSUE DATE (6)	PART COMPLIED WITH (7)	ORGANIZATION (8)	SIGNATURE (9)
12/06/2013	00.00	BT-139-256 REV. A ✓	AGUSTA	SEP 05, 12	N/A BY ACFT S/N	AGUSTA	(A15 007) R. ENDERS
12/06/2013	00.00	BT-139-257 ✓	AGUSTA	JAN 20, 12	N/A BY P/N	AGUSTA	(A15 007) R. ENDERS
12/06/2013	00.00	BT-139-263 ✓	AGUSTA	JAN 20, 12	N/A BY ACFT S/N	AGUSTA	(A15 007) R. ENDERS
12/06/2013	00.00	BT-139-265 REV. A ✓	AGUSTA	JUL 12, 12	N/A BY P/N	AGUSTA	(A15 007) R. ENDERS
12/06/2013	00.00	BT-139-269 ✓	AGUSTA	SEP 30, 11	C/W	AGUSTA	(A15 007) R. ENDERS
12/06/2013	00.00	BT-139-270 ✓	AGUSTA	NOV 25, 11	N/A BY P/N	AGUSTA	(A15 007) R. ENDERS
12/06/2013	00.00	BT-139-273 ✓	AGUSTA	JAN 09, 12	N/A BY ACFT S/N	AGUSTA	(A15 007) R. ENDERS
12/06/2013	00.00	BT-139-275 ✓	AGUSTA	DEC 01, 11	N/A BY ACFT S/N	AGUSTA	(A15 007) R. ENDERS
12/06/2013	00.00	BT-139-276 ✓	AGUSTA	DEC 02, 11	N/A BY ACFT S/N	AGUSTA	(A15 007) R. ENDERS
12/06/2013	00.00	BT-139-278 ✓	AGUSTA	DEC 14, 11	N/A BY ACFT S/N	AGUSTA	(A15 007) R. ENDERS
12/06/2013	00.00	BT-139-285 REV. A ✓	AGUSTA	JUL 11, 12	N/A BY P/N	AGUSTA	(A15 007) R. ENDERS
12/06/2013	00.00	BT-139-286 REV. A ✓	AGUSTA	JUL 11, 12	PART I: C/W PART II: DUE AT 25 HOURS PART III: DUE AT 3 YEARS OR 10,000 LANDINGS	AGUSTA	(A15 007) R. ENDERS
12/06/2013	00.00	BT-139-288 ✓	AGUSTA	AUG 03, 12	DUE AT 3,000 HOURS	AGUSTA	(A15 007) R. ENDERS
12/06/2013	00.00	BT-139-292 ✓	AGUSTA	NOV 09, 12	N/A BY ACFT S/N	AGUSTA	(A15 007) R. ENDERS



TECHNICAL BULLETINS (AIRFRAME) COMPLIANCE SUMMARY (MANDATORY)

Aircraft Type: AW139

Serial No. : 41358

Aircraft Regn. No.: 9M-YTL

Engine Type: PT6C-67C

Engine # 1 Serial No. : PCE-KB1443

Engine # 2 Serial No.: PCE-KB1457

No.	BT Reference	Issue Date	Description	Complied at Hrs/Date	Compliance (Yes/No)	Remarks
105	139-265 Mandatory	25/Aug/2011	<p>Part I: All AB139/AW139 helicopter equipped with tail rotor blades P/N 3G6410A00131 or P/N 4G6410A00131</p> <p>Part II: All AB139/AW139 helicopters equipped with tail rotor blades P/N 3G6410A00131 or P/N 4G6410A00131, having logged more than 600 flying hours or more than 1500 landings whichever occurs first.</p> <p>Precautionary Inspection And Quarantine Of Tail Rotor Blades</p>	N/A	NO N/A to blade P/N	Superseded BT 139-251
106	139-233 Mandatory	28/Sep/2011	<p>Part I: AB139/AW139 helicopters from S/N 31005 to S/N 31157 (except S/N 31007, S/N 31094), from S/N 31201 to S/N 31357 (except S/N 31293, S/N 31301, S/N 31303, S/N 31313 and S/N 31329), from S/N 41001 to S/N 41023 and from S/N 41201 to S/N 41258, from S/N 41260 to S/N 41264, S/N 41266, S/N 41267 and S/N 41269.</p> <p>Part II: AB139/AW139 helicopters from S/N 31005 to S/N 31157 (except S/N 31007, S/N 31094), from S/N 31201 to S/N 31355 (except S/N 31293, S/N 31301, S/N 31303, S/N 31313 and S/N 31329), from S/N 41001 to S/N 41023 and from S/N 41201 to S/N 41261, S/N 41263 and S/N 412767.</p> <p>Hydraulic System Hose Inspection and Replacement in the Upper Deck Area.</p>	N/A	NO	Superseded. Rev.A
107	139-269 Mandatory	30/Sep/2011	All AB139/AW139 helicopters S/N 31005 and subsequent (except the S/N 31007, 31094, 31291, 31301, 31303, 31313 and 31329) that have not accomplished a Flight Control Hydraulic System ground functional check procedure or a main Hydraulic System operational check within the last fifty (50) flight hours prior to the receipt of this Bollettino. Operational Check of NR.1 and NR. 2 Hydraulic System	N/A	YES Refer Agusta BT Status List AQ15-09 pg 13.	N/A



TECHNICAL BULLETINS (AIRFRAME) COMPLIANCE SUMMARY (OPTIONAL)

Section: 6

Aircraft Type: AW139

Serial No. : 41358

Aircraft Regn. No.: 9M-YTL

Engine Type: PT6C-67C

Engine # 1 Serial No. : PCE-KB1443

Engine # 2 Serial No.: PCE-KB1457

No.	BT Reference	Effective Date	Description	Complied at Hrs/Date	Compliance (YES/NO)	Remarks
368	139-513 Optional	29-Jun-18	ATA 30 – Installation Of Windshield Washing System.	N/A	NO. At Customer's Option.	N/A
369	139-489 Optional	24-Jul-18	Ata 46 - Installation Of Kit Central Display Sirio Panel.	N/A	NO. At Customer's Option.	N/A
370	139-492 Optional	25-Jul-18	Ata 29 – Installation Of Hydraulic Pulsation Dampener.	N/A	NO. At Customer's Option.	N/A
371	139-523 Optional	8-Aug-18	ATA 25 – HELICOPTERS SOUNDPROOFING REPLACEMENT	N/A	No Not affected by S/N	N/A
372	139-517 Optional	24-Aug-18	ATA 25 - Installation Of Kit Sacksafoam.	N/A	No Not affected by S/N	N/A
373	139-266 Rev.A Optional	24-Aug-18	ATA 25 - Installation Of Kit Bambi Bucket Provision	N/A	No Not affected by S/N	N/A
374	139-509 Optional	13-Sep-18	ATA 71 – Installation of eaps removable parts	N/A	No Not affected by S/N	N/A
375	139-358 Rev.A Optional	10-Oct-18	ATA 71 - EXHAUST DUCTS AND REAR FIREWALL RETROMOD	N/A	NO. At Customer's Option	N/A
376	139-495 Optional	17-Oct-18	ATA 31 - FDR AND RIPS VARIANT ULB REPLACEMENT	N/A	NO. At Customer's Option	N/A

Prepared by: <u>Alyaa Afifah binti Alzailani</u> 	Checked By: <u>Amir Faisal b. Abdul Aziz</u> 	Concurred by: <u>Wan Nazriazmi b. Mohamad Idris</u>
---	---	--

29/ NOV 2018

29 NOV 2019

29 NOV 2018

*N/A : NOT APPLICABLE *W/S : WORKSHEET