

BERJAYA AIR SDN. BHD.

DOCUMENT TITLE	AIRCRAFT MAINTENANCE PROGRAMME	AIRCRAFT TYPE	AIRBUS HELICOPTERS AS 365 N3		
AMP REF.	BERJAYA/CAMO/AMP/AS365N3	ISSUE	1	REVISION	0
		DATE	1 AUGUST 2024		

No.	Reference No.	Item	Task	Manual Reference	Remarks
500 FLYING HOURS AIRFRAME MANDATORY INSPECTION					
2.	ALS 04-20-00	9° frame (stretcher support)	53/10/00/602/000/085 Check to be carried out from 5300 FH on aircraft : - that left the works before January 31, 2001 and on which edge distance on at least one hole is less than 5 mm, - PRE REPAIR 365A094159. Repair 365A094159 complies with the instructions given in § 2B2 of ASB 53.00.43.	MET 53.10.00.614	

ATA 62 – MAIN ROTOR

3.	ALS 04-20-00	Spherical thrust bearing - Attach beam pin	62/20/00/000/000/215 Check the tightening torque of the spherical thrust bearing/sleeve attachment bolts.	MET 62.20.02.604	-
4.	ALS 04-20-00	Swashplate - Bearing	62/30/00/000/000/110 Greasing with removal.	MET 12.00.00.316	-

1.1.16.B.7. 1500 FLYING HOURS AIRFRAME MANDATORY INSPECTION

No.	Reference No.	Item	Task	Manual Reference	Remarks
ATA 62 – MAIN ROTOR					
1.	ALS 04-20-00	Rotor mast	62/30/00/000/000/055 Check the nut MP/N 360A31-1020-20.	MET 62.30.07.601	-