



WORK ORDER



To: GALAXY AEROSPACE (M) SDN. BHD.

Address:	Lot 11-14, MRO Centre, Malaysia International Aerospace Centre, SAAS Airport, Subang Malaysia	Work Order Number:	2021-6395
Attention:	Mr. Syafrul Yamani Engineering Manager syafrul@galaxyaerospace.my	Work Pack Reference:	9M-PMB-6395
		Date Issued:	06/04/2021
		A/C Registration / SN:	9M-PMB/31726
		Sheet:	1 of 1

Description:

Item	Description/Task/Inspection	Reference	Man Hours
1	SB 139-444 PART III, IV & XIII TO BE COMPLY DUE TO CRACK FOUND ON REAR LH & RH EJECTOR ASSY	SB 139-444 REV. C DATED 28 JUNE 2018, PSE/ TQ/2021/22860	_____ (PLEASE ADVISE)

Remark/Notes:

1. State this Work Order reference on your Work Package. Should there is any additional job/defect (unless specified in the work package) the maintenance organization must notify GAM Continuing Airworthiness Manager prior to proceed with rectification.
2. Work must be carried out in accordance with approved data and perform by qualified personnel/ approved LAE from the maintenance organization.
3. Parts used must be written in Parts Report Form and accompanied by ARC, Serviceable Label or equivalent document.
4. Test report, parameter reading or any supporting data must be attached with the worksheet if applicable.
5. The maintenance organization shall be responsible for any damages made on the aircraft/ components during maintenance.
6. Softcopy of completed Work Package shall be submitted or as mutual agreed and GAM Continuing Airworthiness Manager must be informed once the aircraft is Release to Service.
7. Completed Work Package (original) must be submitted to GAM Continuing Airworthiness Manager office within 3 days of date of completion.

I hereby declare that an approved and up to date maintenance data has been referred for the issuance of this work order.

Thank you.
Best Regards,

Zaty Nadhira Mohamed Zuhari
 Continuing Airworthiness Management Manager
 Email: zaty@galaxyaerospace.my



CLIENT/OWNER: ROYAL MALAYSIA POLICE AIRCRAFT TYPE: AW139 REGISTRATION: 9M-PMB BASE/FACILITY: WMSA DATE IN: OUT:		SERIAL NO.	HOURS	LDG/CYCLE		WORKSHEET NO: 6395-001
	AIRCRAFT	31726				WORK/INSP/DESC: ATA 78 - EXHAUST DUCTS
	#1 ENGINE:	PCE-KB1830		N/A	N/A	WORKPACK REF: 9M-PMB-6395
	#2 ENGINE:	PCE-KB1832		N/A	N/A	LBE REF NO.: NOT APPLICABLE
				NG / N1	NF / N2	SHEET: 1 OF 1

Reason for raising: SB 139-444 PART III, IV & XIII TO BE COMPLY DUE TO CRACK FOUND ON REAR LH & RH EJECTOR ASSY (REFER ATTACHED TECHNIQAL QUERY) IN ACCORDANCE WITH SB 139-444 REV, C	Raised by and date: Ahmad Khalis Halimi 06/04/2021	Other requirements/information: NIL
--	--	--

Item	Description	Technician	* Eng. CRS	Date
1	SB 139-444 PART III, IV & XIII TO BE COMPLY DUE TO CRACK FOUND ON REAR LH & RH EJECTOR ASSY (REFER ATTACHED TECHNIQAL QUERY) REFERENCES: SB 139-444 REV. C DATED 28 JUNE 2018, PSE/TQ/2021/22860 REMARKS:			

*The work recorded above has been carried out in accordance with the requirements of the Malaysian Civil Aviation Regulation for the time being in force and in that respect the aircraft / equipment is considered fit for release to service.

*The work recorded above has been carried out in accordance with the requirements of the _____ for the time being in force and in that respect the aircraft / equipment is considered fit for release to service.

TICK ✓ WHERE APPLICABLE

PARTS LABELED & RETURNED	D.D. RAISED	DUPLICATE INSP.	GROUND RUN	FLIGHT TEST	TORQUE CHK.	ADDITIONAL WORKSHEET	MONITORED DEFECT	PLANNING FORECAST	DIARY UPDATE	STATUS UPDATE	D.D. STATUS	AIRCRAFT LOG BOOK	ENGINE LOG BOOK	PROPELLER LOG BOOK	LOG CARD	OEM/COMP LOG CARD	MOD.RECORD BOOK
--------------------------	-------------	-----------------	------------	-------------	-------------	----------------------	------------------	-------------------	--------------	---------------	-------------	-------------------	-----------------	--------------------	----------	-------------------	-----------------

