

WORK ORDER



To: GALAXY AEROSPACE (M) SDN. BHD.

<p>Address: Lot 11-14, MRO Centre, Malaysia International Aerospace Centre, SAAS Airport, Subang Malaysia</p> <p>Attention: Mr. Syafrul Yamani Engineering Manager syafrul@galaxyaerospace.my</p>	<p>Work Order Number: 2021-9061</p> <p>Work Pack Reference: 9M-BOB-9061</p> <p>Date Issued: 04/03/2022</p> <p>A/C Registration / SN: 9M-BOB/11212</p> <p>Sheet: 1 of 1</p>
--	---

Description:

Item	Description/Task/Inspection	Reference	Man Hours
1	ASB 109EP-177 NEW ISSUE PART I REV A ATA 62 - INSPECTION OF MAIN ROTOR SCISSOR CHAIN	ASB 109EP-177 NEW ISSUE PART I REV A	_____ (PLEASE ADVISE)
	<i>Due at 3706:20 FH // 10/04/2022</i>		

Remark/Notes:

1. State this Work Order reference on your Work Package. Should there is any additional job/defect (unless specified in the work package) the maintenance organization must notify GAM Continuing Airworthiness Manager prior to proceed with rectification.
2. Work must be carried out in accordance with approved data and perform by qualified personnel/ approved LAE from the maintenance organization.
3. Parts used must be written in Parts Report Form and accompanied by ARC, Serviceable Label or equivalent document.
4. Test report, parameter reading or any supporting data must be attached with the worksheet if applicable.
5. The maintenance organization shall be responsible for any damages made on the aircraft/ components during maintenance.
6. Softcopy of completed Work Package shall be submitted or as mutual agreed and GAM Continuing Airworthiness Manager must be informed once the aircraft is Release to Service.
7. Completed Work Package (original) must be submitted to GAM Continuing Airworthiness Manager office within 3 days of date of completion.

I hereby declare that an approved and up to date maintenance data has been referred for the issuance of this work order.

Thank you.
 Best Regards,

Zaty Nadhira Mohamed Zuhari
 Continuing Airworthiness Management Manager
 Email: zaty@galaxyaerospace.my



CLIENT/OWNER: JABATAN BOMBA DAN PENYELAMAT MALAYSIA	AIRCRAFT	SERIAL NO. 11212	HOURS	LDG/CYCLE	WORKPACK NO: 9M-BOB-9061
AIRCRAFT TYPE: A109E	#1 ENGINE: PCE-BC0308				WORK/INSP/DESC: ASB 109EP-177 REV A
REGISTRATION: 9M-BOB	#2 ENGINE: PCE-BC0358				AERONET JOB NO.: 2022-9061
BASE/FACILITY:				NG / N1	NF / N2
DATE IN: OUT:					AJL REF NO.:
					SHEET: 1 OF 1

Reason for raising: ASB 109EP-177 REV A PART I, ATA 62 - INSPECTION OF MAIN ROTOR SCISSOR CHAIN TO BE CARRIED OUT IN ACCORDANCE WITH JBPM/CAMO/AMP/A109E ISSUE 2 REV 0 DATE 06 MAY 2021 A109E IETP - 32ND ISSUE: 2021-09-15 UPDATED: 2021-12-10 OR LATEST APPROVED REVISION	Raised by and date: CAMO; Muhammad Ihsan Masri 04/03/2022	Other requirements/information: NIL
--	---	--

List of scheduled inspection and all work carried out under this workpack including individual reference. Master Signature Schedule

NO.	INSPECTION / WORK	WORKSHEET REF	NAME	TECH/INITIAL	SIGNATURE	APP/STAMP
1	ASB 109EP-177 REV A PART I ATA 62 - INSPECTION OF MAIN ROTOR SCISSOR CHAIN	9061-001				

PART 145 - AMO RELEASE STATEMENT THIS IS TO CERTIFY THAT ALL WORK LISTED ABOVE HAS BEEN INSPECTED AND ACCOMPLISHED IN ACCORDANCE WITH CONTRACTED AMO EXPOSITION AND PROCEDURE LATEST REVISION, AND OEM PUBLICATION/ REVISION:.....	NAME	FIRM	SIGN & APPROVAL	DATE
PART M - CAMO ACCEPTANCE STATEMENT THIS IS TO CERTIFY THAT THE ABOVE MENTIONED WORK PACKAGE HAS BEEN REVIEWED, CHECKED FOR COMPLETION AND UPDATED IN THE MAINTENANCE SOFTWARE. ALL RELEVANT AIRCRAFT/ENGINE/ MODIFICATION LOGBOOK HAS BEEN UPDATED.	NAME	FIRM	SIGN & APPROVAL	DATE



CLIENT/OWNER: JABATAN BOMBA DAN PENYELAMAT MALAYSIA AIRCRAFT TYPE: A109E REGISTRATION: 9M-BOB BASE/FACILITY: DATE IN: REFER WORKPACK OUT: REFER WORKPACK	SERIAL NO.	HOURS	LDG/CYCLE		WORKSHEET NO: 9061-001
	AIRCRAFT	11212	REFER WORKPACK		WORK/INSP/DESC: ASB 109EP-177 REV A
	#1 ENGINE:	PCE-BC0308	REFER WORKPACK		WORKPACK REF: 9M-BOB-9061
	#2 ENGINE:	PCE-BC0358	REFER WORKPACK		AJL REF NO.: REFER WORKPACK
			NG / N1	NF / N2	SHEET: 1 OF 1

Reason for raising: ASB 109EP-177 REV A PART I, ATA 62 - INSPECTION OF MAIN ROTOR SCISSOR CHAIN TO BE CARRIED OUT IN ACCORDANCE WITH JBPM/CAMO/AMP/A109E ISSUE 2 REV 0 DATE 06 MAY 2021 A109E IETP - 32ND ISSUE: 2021-09-15 UPDATED: 2021-12-10 OR LATEST APPROVED REVISION	Raised by and date: CAMO; Muhammad Ihsan Masri 04/03/2022	Other requirements/information: NIL
---	---	--

Item	Description	Technician	* Eng. CRS	Date
1	INSPECTION OF MAIN ROTOR SCISSOR CHAIN TO BE CARRIED OUT IN ACCORDANCE WITH ASB 109EP-177 NEW ISSUE PART I COMPLIANCE INSTRUCTIONS REFERENCE: ASB 109EP-177 REV A PART I REMARKS:			
1.1	THE DUPLICATE INSPECTION FOR NO1 DRIVE SHAFT INSTALLATION (CORRECT INSTALLATION, PROPER INSTALLATION AND SECURITY OF ATTACHMENT) CARRIED OUT IN ACCORDANCE WITH THE CAD 8601 PARA 5.12 (3) 1st Inspector Sign: _____ Approval/Stamp: _____ DATE: _____ 2nd Inspector Sign: _____ Approval/Stamp: _____ DATE: _____			

*The work recorded above has been carried out in accordance with the requirements of the Malaysian Civil Aviation Regulation for the time being in force and in that respect the aircraft / equipment is considered fit for release to service.

*The work recorded above has been carried out in accordance with the requirements of the _____ for the time being in force and in that respect the aircraft / equipment is considered fit for release to service.

TICK ✓ WHERE APPLICABLE

PARTS LABELED & RETURNED	D.D. RAISED	DUPLICATE INSP.	GROUND RUN	FLIGHT TEST	TORQUE CHK.	ADDITIONAL WORKSHEET	MONITORED DEFECT	PLANNING FORECAST	DIARY UPDATE	STATUS UPDATE	D.D. STATUS	AIRCRAFT LOG BOOK	ENGINE LOG BOOK	PROPELLER LOG BOOK	LOG CARD	OEM/COMP LOG CARD	MOD. RECORD BOOK
--------------------------	-------------	-----------------	------------	-------------	-------------	----------------------	------------------	-------------------	--------------	---------------	-------------	-------------------	-----------------	--------------------	----------	-------------------	------------------

Please send to the following address: LEONARDO S.p.A. CUSTOMER SUPPORT & SERVICES - ITALY PRODUCT SUPPORT ENGINEERING & LICENSES DEPT. Via Giovanni Agusta, 520 21017 Cascina Costa di Samarate (VA) - ITALY Tel.: +39 0331 225036 Fax: +39 0331 225988		SERVICE BULLETIN COMPLIANCE FORM		Date:	
		Number:			
		Revision:			
Customer Name and Address:			Telephone:		
			Fax:		
			B.T. Compliance Date:		
Helicopter Model	S/N	Total Number	Total Hours	T.S.O.	
Remarks:					
Information: We request your cooperation in filling this form, in order to keep out statistical data relevant to aircraft configuration up-to-date. The form should be filled in all its parts and sent to the above address or you can communicate the application also via Technical Bulletin Application Communication Section placed in Leonardo AW Customer Portal - MyCommunications Area. We thank you beforehand for the information given.					

