


DELIVERY NOTE WP

DELIVER TO :

GALAXY AEROSPACE (M) SDN. BHD.
CAMO DEPARTMENT
Lot 11, MRO Centre,
Malaysia International Aerospace Centre,
Sultan Abdul Aziz Shah Airport,
47200 Subang, Selangor
Malaysia.
Attn : Zaty Nadhira binti Mohamed Zuhari

DN NUMBER : GAM/DN/BOB/22-037
OUR REFERENCE : 9M-BOB-9061
WO REFERENCE : 2021-9061
DATE COMPLETION: 12 APRIL 2022
AJL NUMBER : AJL 001141

A/C DETAILS							
A/C TYPE	A109E	A/C REG	9M-BOB	A/C S/N	11212		
OWNER / OPERATOR	FIRE AND RESCUE DEPT. OF MALAYSIA	A/C TOTAL TIME	3703:11	LANDINGS	4125		
ENGINE #1 S/N	PCE-BC0308	T.S.N	928:01	T.S.O	-		
ENGINE #2 S/N	PCE-BC0358	T.S.N	2906:41	T.S.O	-		
LIST OF TASK PERFORMED	WP NUMBER	NUMBER OF PAGES					
		*WS	*PR	*ARC	*S	*SBC	*OTH
EASA AD 2022-0037, CORRECTION ISSUE (15 MARCH 2022) ASB 109-EB-177 NEW ISSUE PART	001	1	1	-	-	1	-
*THIS IS TO CERTIFY THAT TASKS LISTED ABOVE HAS BEEN ACCOMPLISHED AS PER PO/WORK ORDER/SERVICE ORDER NO. AS ABOVE.							
NAME	NURUL LYANA MUHAMAD	SIGNATURE		DATE	25 APRIL 2022		
VERIFIED AND ACCEPTED BY				MUHAMMAD IHSAN MASRI CAMO Planner Galaxy Aerospace (M) Sdn. Bhd. (1040262-D)			
DATE				19 MAY 2022			

- *WS – WORKSHEET
- *PR – PART REPORT
- *ARC – AUTHORISED RELEASE CERTIFICATE
- *S – SERVICEABLE LABEL
- *SBC – SERVICE BULLETIN COMPLIANCE
- *OTH – OTHERS



WORK ORDER



To: GALAXY AEROSPACE (M) SDN. BHD.

<p>Address: Lot 11-14, MRO Centre, Malaysia International Aerospace Centre, SAAS Airport, Subang Malaysia</p> <p>Attention: Mr. Syafrul Yamani Engineering Manager syafrul@galaxy aerospace.my</p>	<p>Work Order Number: 2021-9061</p> <p>Work Pack Reference: 9M-BOB-9061</p> <p>Date Issued: 04/03/2022</p> <p>A/C Registration / SN: 9M-BOB/11212</p> <p>Sheet: 1 of 1</p>
--	---

Description:

Item	Description/Task/Inspection	Reference	Man Hours
1	EASA AD 2022-0037, CORRECTION ISSUE (15 MARCH 2022) / ASB 109EP-177 NEW ISSUE PART, ATA 62 - MAIN ROTOR SYSTEM - MAIN ROTOR ROTATING SCISSOR	EASA AD 2022-0037, CORRECTION ISSUE (15 MARCH 2022)	<u>3.0</u> (PLEASE ADVISE)

Due at 3706:20 FH // 10/04/2022

Remark/Notes:

1. State this Work Order reference on your Work Package. Should there is any additional job/defect (unless specified in the work package) the maintenance organization must notify GAM Continuing Airworthiness Manager prior to proceed with rectification.
2. Work must be carried out in accordance with approved data and perform by qualified personnel/ approved LAE from the maintenance organization.
3. Parts used must be written in Parts Report Form and accompanied by ARC, Serviceable Label or equivalent document.
4. Test report, parameter reading or any supporting data must be attached with the worksheet if applicable.
5. The maintenance organization shall be responsible for any damages made on the aircraft/ components during maintenance.
6. Softcopy of completed Work Package shall be submitted or as mutual agreed and GAM Continuing Airworthiness Manager must be informed once the aircraft is Release to Service.
7. Completed Work Package (original) must be submitted to GAM Continuing Airworthiness Manager office within 3 days of date of completion.

I hereby declare that an approved and up to date maintenance data has been referred for the issuance of this work order.

Thank you.
Best Regards,

Zaty Nadhira Mohamed Zuhari
Continuing Airworthiness Management Manager
Email: zaty@galaxy aerospace.my



CLIENT/OWNER: JABATAN BOMBA DAN PENYELAMAT MALAYSIA AIRCRAFT TYPE: A109E REGISTRATION: 9M-BOB BASE/FACILITY: MIAK DATE IN: REFER WORKPACK OUT: REFER WORKPACK	SERIAL NO.	HOURS	LDG/CYCLE		WORKSHEET NO: 9061-001
	AIRCRAFT	11212	REFER WORKPACK		WORK/INSP/DESC: EASA AD 2022-0037
	#1 ENGINE:	PCE-BC0308	REFER WORKPACK		WORKPACK REF: 9M-BOB-9061
	#2 ENGINE:	PCE-BC0358	REFER WORKPACK		AJL REF NO.: REFER WORKPACK
			NG / N1	NF / N2	SHEET: 1 OF 1

Reason for raising: EASA AD 2022-0037, CORRECTION ISSUE (15 MARCH 2022) / ASB 109EP-177 NEW ISSUE PART, ATA 62-MAIN ROTOR SYSTEM - MAIN ROTOR ROTATING SCISSOR TO BE CARRIED OUT IN ACCORDANCE WITH JBPM/CAMO/AMP/A109E ISSUE 2 REV 0 DATE 06 MAY 2021 A109E IETP - 32ND ISSUE: 2021-09-15 UPDATED: 2022-02-01 OR LATEST APPROVED REVISION	Raised by and date: CAMO; Muhammad Ihsan Masri 04/03/2022	Other requirements/information: NIL
---	---	--

Item	Description	Technician	* Eng. CRS	Date
1	EASA AD 2022-0037, CORRECTION ISSUE (15 MARCH 2022) / ASB 109EP-177 NEW ISSUE PART, ATA 62-MAIN ROTOR SYSTEM - MAIN ROTOR ROTATING SCISSOR TO BE CARRIED OUT IN ACCORDANCE WITH EASA AD 2022-0037, CORRECTION ISSUE (15 MARCH 2022) PART I COMPLIANCE INSTRUCTIONS REFERENCE: EASA AD 2022-0037, CORRECTION ISSUE (15 MARCH 2022) PART I REMARKS: C/O FOUND SATIS	 8093	 	1/4/22
1.1	THE DUPLICATE INSPECTION FOR NO1 DRIVE SHAFT INSTALLATION (CORRECT INSTALLATION, PROPER INSTALLATION AND SECURITY OF ATTACHMENT) CARRIED OUT IN ACCORDANCE WITH THE CAD 8601 PARA 5.12 (3) 1st Inspector Sign: Approval/Stamp: DATE: 1/4/22 2nd Inspector Sign: Approval/Stamp: DATE: 2/4/22	-	-	-

*The work recorded above has been carried out in accordance with the requirements of the Malaysian Civil Aviation Regulation for the time being in force and in that respect the aircraft / equipment is considered fit for release to service.

*The work recorded above has been carried out in accordance with the requirements of the _____ for the time being in force and in that respect the aircraft / equipment is considered fit for release to service.



TICK ✓ WHERE APPLICABLE

PARTS LABELED & RETURNED	DD RAISED	DUPLICATE INSP	GROUND RUN	FLIGHT TEST	TORQUE CHK	ADDITIONAL WORKSHEET	MONITORED DEFECT	PARTING FORECAST	DAILY UPDATE	STATUS UPDATE	DD STATUS	AIRCRAFT LOG BOOK	ENGINE LOG BOOK	PROPELLER LOG BOOK	LOG CARD	ITEM/COMP LOG CARD	MOD RECORD BOOK
--------------------------	-----------	----------------	------------	-------------	------------	----------------------	------------------	------------------	--------------	---------------	-----------	-------------------	-----------------	--------------------	----------	--------------------	-----------------

Please send to the following address: LEONARDO S.p.A. CUSTOMER SUPPORT & SERVICES - ITALY PRODUCT SUPPORT ENGINEERING & LICENSES DEPT. Via Giovanni Agusta, 520 21017 Cascina Costa di Samarate (VA) - ITALY Tel.: +39 0331 225036 Fax: +39 0331 225988	SERVICE BULLETIN COMPLIANCE FORM	Date: 1/4/22
	Number: ASB 109EP-177 NEW ISSUE PART I	
	Revision: -	

Customer Name and Address: GALAXY AEROSPACE (M) SDN BHD (GADING GROUP OF COMPANIES) Suite 11-14, Helicopter Centre, GALAXY AEROSPACE (M) SDN BHD Malaysia International Aerospace Centre, Sultan Abdul Aziz Shah Airport, 47200 Subang, SELANGOR DARUL EHSAN	Telephone: 603-7734 7226
	Fax: 603-7734 7226
	B.T. Compliance Date: 1/4/2022

Helicopter Model	S/N	Total Number	Total Hours	T.S.O.
A109E	11212	1		

Remarks: c/o FOUND SATIS.   1/4/2022

Information:

We request your cooperation in filling this form, in order to keep out statistical data relevant to aircraft configuration up-to-date. The form should be filled in all its parts and sent to the above address or you can communicate the application also via Technical Bulletin Application Communication Section placed in Leonardo AW Customer Portal - MyCommunications Area. We thank you beforehand for the information given.

