

GALAXY AEROSPACE (M) SDN. BHD. [1040262-D] Suite 11-14, Helicopter Centre, Malaysia International Aerospace Centre, Sultan Abdul Aziz Shah Airport, 47200 Subang, Selangor, Malaysia. Tel: +603 7734 7226 | Fax: +603 7734 7526 www.galaxyaerospace.my | enquiry@galaxyaerospace.my

WORK ORDER



To: GALA	XY AEROSPACE (M) SDN. BHD.				
Address:	Lot 11-14, MRO Centre, Malaysia	Work Order Number:	2023-14052		
	International Aerospace Centre, SAAS Airport, Subang	Work Pack Reference:	9M-DSJ-14052		
	Malaysia	Date Issued:	04/01/2023		
Attention:	Mr. Syafrul Yamani Engineering Manager	A/C Registration / SN:	9M-DSJ/6583		
	syafrul@galaxyaerospace.my	Sheet: 1 of	1		

Description:

ltem	Description/Task/Inspection	Reference			
1	CENTRAL FIREWALL STIFFENER - REPLACEMENT	AD No.: 2022-0231			

Man Hours

(PLEASE ADVISE)

Remark/Notes:

1. State this Work Order reference on your Work Package. Should there is any additional job/defect (unless specified in the work package) the maintenance organization must notify GAM Continuing Airworthiness Manager prior to proceed with rectification.

2. Work must be carried out in accordance with approved data and perform by qualified personnel/ approved LAE from the maintenance organization.

3. Parts used must be written in Parts Report Form and accompanied by ARC, Serviceable Label or equivalent document.

4. Test report, parameter reading or any supporting data must be attached with the worksheet if applicable.

5. The maintenance organization shall be responsible for any damages made on the aircraft/ components during maintenance.

6. Softcopy of completed Work Package shall be submitted or as mutual agreed and GAM Continuing Airworthiness Manager must be informed once the aircraft is Release to Service.

7. Completed Work Package (original) must be submitted to GAM Continuing Airworthiness Manager office within 3 days of date of completion.

I hereby declare that an approved and up to date maintenance data has been referred for the issuance of this work order.

Thank you. Best Regards,

Zaty Nadhira Mohamed Zuhari Continuing Airworthiness Management Manager Email: zaty@galaxyaerospace.my

	axyAerospace	Sultan Abdul Tel: +603 773	ROSPACE (M) SDN. Helicopter Centre, M Aziz Shah Airport, 4 34 7226 Fax: +603 aerospace.my enqu	Ialaysia Internatio 7200 Subang, So 7734 7526	onal Aerospace Cer elangor, Malaysia.	ntre,		WOR		
	OWNER: GADING AIR SERVICES		SERIAL NO.	HOURS	LDG/CY	CLE	WORKPACK N	IO: 9M-DSJ-1	4052	
	SDN. BHD.	AIRCRAFT	6583			-		DESC: CENTRAL FIREWALL		
	FT TYPE: EC155 B RATION: 9M-DSJ	#1 ENGINE:	24595				AERONET JOE	3 NO.: 2023-140	52	
	ACILITY: WMSA	#2 ENGINE:	24593				AJL REF NO.:			
ATE IN					NG / N1	NF / N2	SHEET:	1 of 1		
						Raised by and date: Other requirements/infor CAMO G.A; Ihsan Masri 04/01/2023				
List	of scheduled inspection and all w including indivi	under this wo	orkpack	DATE		Master Signature Schedule				
10.	INSPECTION / WO				_ INSPECTI COMPLET		NAME	SIGNATURE APP/STAME		
1	CENTRAL FIREWALL STIFFENER REPLACEMENT		14052							
						_				
						_				
						_				
S IS T	- AMO RELEASE STATEMENT O CERTIFY THAT ALL WORK LISTED ABOV NTRACTED AMO EXPOSITION AND PROCE			OMPLISHED IN	ACCORDANCE		NAME			
* OE	M PUBLICATION/REVISION AS PER REASC IFFERENT FROM ABOVE. OEM PUBLICATI	IN FOR RAISING A	BOVE			S	IGN & APPROVAL			
	CK ✓ WHERE APPLICABLE						DATE			
RT M -	CAMO ACCEPTANCE STATEMENT						NAME	SIGN & APPROVAL	DATE	
RT M - IIS IS T		WORK PACKAGE H	AS BEEN REVIEW	ED, CHECKED	FOR COMPLETIC)N	NAME	SIGN & APPROVAL	DATE	

	xyAerospace	Suite 11-14, H Sultan Abdul Tel: +603 773	OSPACE (M) SDN. E lelicopter Centre, Ma Aziz Shah Airport, 47 4 7226 Fax: +603 7 erospace.my enquir	alaysia Internatic 7200 Subang, Se 7734 7526	nal Aerospace Ce langor, Malaysia.	entre,							
CLIENT/C	WNER: GADING AIR SERVICES		SERIAL NO.	HOURS	LDG/0	CYCLE		WORKSHE	ET NO:	14052-001			
	SDN. BHD.	AIRCRAFT	6583	REFER W	/ORKPACK			WORK/INS	P/DESC			FIREWALL	
AIRCRAF REGISTR	T TYPE: EC155 B ATION [,] 9M-DSJ	#1 ENGINE:	24595	REFER W	ORKPACK			WORKPACK REF: 9M-DSJ-14052					
	CILITY: WMSA	#2 ENGINE:	24593	REFER W	ORKPACK			AJL REF N	IO.:	REFE	R WORK	(PACK	
DATE IN: REFER OUT: REFER WORKPACK NG / N1 NF / N2								SHEET:	1	OF		1	
Reason	or raising: FIREWALL STIFFENER - REPLACEMENT T	O BE CARRIED OU	T I.A.W AD No.: 20	022-0231	Raised by CAMO G.A 04/0			Other requ	uirement	s/inform	ation:		
lt e une		Daaa	uiusti e ue		1			Tachaicia	*	Eng C		Data	
Item 1	CENTRAL FIREWALL STIFFENER		ription					Technicia	n "	Eng. CF	15	Date	
	TO PERFORM REPLACEMENT OF FIREWALL WITH A TITANIUM STIF REF: AD No.: 2022-0231 ; ASB EC1 NOTE: CAMO TO RECORD EMBODI CHANGE UPON EMBODIMENT OF	ALUMINIUM STI FENER 55 71A015 R0 DIMENT OF MOD	FFENER ON TH		VEIGHT								
	REMARKS:												
the ai: Certi	fies that the work specified above, ex rcraft / aircraft component is conside fies that the work specified above, ex n respect to that work the aircraft / air	red ready for rele cept as otherwise	ease to service. specified, was o	carried out in	n accordance	with	A Malays	ia Requireme	ents and i	n respect	to that w	ork	
] тіск •	WHERE APPLICABLE												
ARTS ELED &		RQUE ADDITIONAL CHK. WORKSHEET		PLANNING DIA FORECAST UPD		D.D. STATUS	AIRCRAFT LOG BOOK	ENGINE LOG BOOK	PROPELLER LOG BOOK	LOG CARD	OEM/COMP LOG CARD	MOD RE BOO	

PARTS LABELED & RETURNED



GALAXY AEROSPACE (M) SDN. BHD. [1040262-D] Suite 11-14, Helicopter Centre, Malaysia International Aerospace Centre, Suitan Abdul Aziz Shah Airport, 47200 Subang, Selangor, Malaysia. Tel: +603 7734 7226 | Fax: +603 7734 7526 www.galaxyaerospace.my | enquiry@galaxyaerospace.my

PARTS REPORT

CLIENT/OWNER: GADING AIR SERVICES				;	SERIA									wc	WORKSHEET NO: 14052-001					
SDN. BHD. AIRCRAFT TYPE: EC155 B			AIR	CRAFT	65	83	REFER WORKPACK					wc	RK/IN	SP/DESC:	CEN	TRAL FIREW	VALL			
	REGISTRATION: 9M-DSJ				#1 I	ENGINE:	NE: 24595			ER WO	ORKPA	CK			WORKPACK REF: 9M-DSJ-14052					
BASE/FA					#2	ENGINE:	245	593	REFE	ER WO	ORKPA	CK			AJL	AJL REF NO.: REFER WORK SHEET: 1 OF				ACK
DATE IN:	REFER WC	RKPACK OL	JT: REFEF	R WORKPAG	ск						NG /	/ N1	NF /	′ N2	SH					1
REASON FOR RAISING: CENTRAL FIREWALL STIFFENER - REPLACEMENT TO BE CARRIED OUT I.A.W CENTRAL FIREWALL STIFFENER - REPLACEMENT					t I.A.W AI	AD No.: 2022-0231 AD No.: 2022-0231 AD No.: 2022-0231 Raised by and d CAMO G.A; Ihsan 04/01/2023					lhsan M	late: h Masri NII								
Item	Pa	ırt No			Descripti	on			Serial	1		Qty	Posit	tion	Reason		tem Informa		Release Re	eference
								Of	Ť		On			SITION Reason TSN/TSO/DUE/TIMEX Release Referen						
														_						
																			DATE	
NAME								FIRM					SIG	in & Af	PROVAL				DATE	
 *Certifies that the work specified above, except as otherwise specified, was carried out in accordance with CAA Malaysia Requirements and in respect to that work the aircraft / aircraft component is considered ready for release to service. *Certifies that the work specified above, except as otherwise specified, was carried out in accordance with 																				
	-			ie aircra	ait / alfCl	raft compo	nent IS	consid	erea re	auy fo	u reie	ase IO	SELAIC	e.						
									OEM/COMP LOG CARD	MOD RECORD BOOK										



GALAXY AEROSPACE (M) SDN. BHD. [1040262-D] Suite 11-14, Helicopter Centre, Malaysia International Aerospace Centre, Sultan Abdul Aziz Shah Airport, 47200 Subang, Selangor, Malaysia. Tet: +603 7734 7226 | Fax: +603 7734 7526 www.galaxyaerospace.my | enquiry@galaxyaerospace.my

Tools Report

Aircraft Serial No:	Work Pack No: 9M-DSJ-1405					
Aircraft Type:	EC155 B	DESC:	CENTRAL FIREWALL			
Aircraft Reg:	9M-DSJ	PAGE:	1 Of 1			
Description	Part No	Serial Number	Worksheet Re Item No.	f No. /	Calibration Due Date	