

Suite 11-14, Helicopter Centre, Malaysia International Aerospace Centre, Sultan Abdul Aziz Shah Airport, 47200 Subang, Selangor, Malaysia.
Tel: +603 7734 7226 | Fax: +603 7734 7526 www.galaxyaerospace.my | enquiry@galaxyaerospace.my

### **WORK ORDER**



To: GALAXY AEROSPACE (M) SDN. BHD.

Address: Lot 11-14, MRO Centre, Malaysia

International Aerospace Centre, SAAS Airport,

Subang Malaysia

Attention: Mr. Syafrul Yamani

Engineering Manager

syafrul@galaxyaerospace.my

Work Order Number:	2023-3966
Work Pack Reference:	9M-KEL-3966
Date Issued:	10/05/2023
A/C Registration / SN:	9M-KEL/6997
Sheet: 1 of	1

### Description:

Item	Description/Task/Inspection	Reference	Man Hours(PLEASE ADVISE)
1	EASA AD 2018-0263 PARA (5) (ASB 05A034 R5) - MAIN ROTOR DRIVE SYSTEM (55FH)	EASA AD 2018-0263 PARA (5) (ASB 05A034 R5)	
2	EASA AD 2012-0227 R1 PARA (3) (ASB 05A021 R1) - VISUAL CHECK OF THE 10-BLADE TRH (55FH)	EASA AD 2012-0227 R1 PARA (3) (ASB 05A021 R1)	
3	EASA AD 2022-0006 R2 (ASB 05A039) - INSPECTION OF THE FAN HUB (55FH)	EASA AD 2022-0006 R2 (ASB 05A039)	

### Remark/Notes:

- 1. State this Work Order reference on your Work Package. Should there is any additional job/defect (unless specified in the work package) the maintenance organization must notify GAM Continuing Airworthiness Manager prior to proceed with rectification.
- 2. Work must be carried out in accordance with approved data and perform by qualified personnel/ approved LAE from the maintenance organization.
- 3. Parts used must be written in Parts Report Form and accompanied by ARC, Serviceable Label or equivalent document.
- 4. Test report, parameter reading or any supporting data must be attached with the worksheet if applicable.
- 5. The maintenance organization shall be responsible for any damages made on the aircraft/ components during maintenance.
- 6. Softcopy of completed Work Package shall be submitted or as mutual agreed and GAM Continuing Airworthiness Manager must be informed once the aircraft is Release to Service.
- 7. Completed Work Package (original) must be submitted to GAM Continuing Airworthiness Manager office within 3 days of date of completion.

I hereby declare that an approved and up to date maintenance data has been referred for the issuance of this work order.

Thank you. Best Regards,

Zaty Nadhira Mohamed Zuhari

Continuing Airworthiness Management Manager

Email: zaty@galaxyaerospace.my



Suite 11-14. Helicopter Centre, Malaysia International Aerospaca, Centre Sultan Abeul Air Shah, Airport 47200 Soltang, Selanger, Malaysia, Tele 4603 1734 7226, I Fax: 4603 1734 7226, www.golasyserospace.my | enquiry golasyserospace.my



CLIENT/OWNER: UNITARA RESOURCES SERIAL NO. HOURS LDG/CYCLE WORKPACK NO: SDN BHD 757 6997 294:04 WORK/INSP/DESC: EASA AD 2022-0066 AIRCRAFT AIRCRAFT TYPE: EC155B1 AERONET JOB NO.: 2023-3966 #1 ENGINE: 294:04 REGISTRATION: 9M-KEL AJL REF NO .: 001841 BASE/FACILITY: WMSA #2 ENGINE: 26299 294:04 SHEET: 1 DATE IN: 30.05.21 OUT: 18.07.2) NG/N1 NF/N2 Other requirements/information: Reason for raising: Raised by and date: SCHEDULE INSPECTION PERFORM I.A.W AMP URM/CAMO/AMP/EC155B1 ISSUE 01 TR 001 DATED CAMO; Zulkarnaen NIL 16.02.2023, ORION EC155 009.00 UPDATE 02 DATED 2023-02-13, EMM ARRIEL 2C2 UPDATE 48.00 Ibrahim DATED 30.12.2022 OR LATER APPROVED REVISION 10/05/2023 List of scheduled inspection and all work carried out under this workpack Master Signature Schedule DATE including individual reference INSPECTION COMPLETED APP/STAMP NAME SIGNATURE NO. INSPECTION / WORK WORKSHEET REF EASA AD 2018-0263 PARA (5) (ASB 05A034 R5) -NITA ISMAIL 18.7.23 3966-001 1 MAIN ROTOR DRIVE SYSTEM (55FH) EASA AD 2012-0227 R1 PARA (3) (ASB 05A021 18.7.23 AMIR 2 R1) - VISUAL CHECK OF THE 10-BLADE TRH 3966-002 (55FH) MOHD EASA AD 2022-0006 R2 (ASB 05A039) -18.7.23 3 3966-003 INSPECTION OF THE FAN HUB (55FH) HUZAIRI Galaxy Aerospace (M) Sdn. Bhd. I hereby certify the following task has been performed and found satisfactory: 1) All the tools and equipment used for maintenance has been removed from aircraft. 2) All the access panels removed for maintenance access has been reinstalled. 3) All the excess spares and materials have been notified to AMO Planner for return plan 4) FOD check has been done. AM9/2016/02 NAME NITA I SMAIL PART 145 - AMO RELEASE STATEMENT THIS IS TO CERTIFY THAT ALL WORK LISTED ABOVE HAS BEEN INSPECTED AND ACCOMPLISHED IN ACCORDANCE WITH CONTRACTED AMO EXPOSITION AND PROCEDURE LATEST REVISION, AND SIGN & APPROVAL \* OEM PUBLICATION/REVISION AS PER REASON FOR RAISING ABOVE \*IF DIFFERENT FROM ABOVE. OEM PUBLICATION/REVISION....... GAM. FIRM DATE 18/7/23 \* TICK ✓ WHERE APPLICABLE PART M - CAMO ACCEPTANCE STATEMENT NAME SIGN & APPROVAL DATE THIS IS TO CERTIFY THAT THE ABOVE MENTIONED WORK PACKAGE HAS BEEN REVIEWED, CHECKED FOR COMPLETION AND UPDATED IN THE MAINTENANCE SOFTWARE. AUG 2023 ZULKARNAEN BIN IBRAHIM



GALAXY AEROSPACE (M) SDN. BHD. [1040262-D]
Suite 11:17. Helicopter Centre, Micloyala International Aerospace Centre.
Suita. Arcair Ayla Shirah Airport. 47260 Subang: Selangor, Malaysia
Tels. 4003.7734.7226. [Ers. +603.7734.7525]
www.gplaxyaerospace.my.] enquiry@galaxyaerospace.my.

## **Tools Report**



6997 9M-KEL-3966 Aircraft Serial No: Work Pack No: **SCHEDULE** Aircraft Type: EC155B1 DESC: Aircraft Reg: PAGE:

Aircraft Reg:		9M-KEL PAGE: 1 Of 1							
Description	Part No	Serial Number	Worksheet Ref No. / Item No.	Calibration Due Date					
	100 mg								
		1							



Suite 11-14. Helicopter Centre, Malaysia International Acrospace Centre Suitan Abdu Ariz Shah, Airport, 4720 Subang, Selanger, Malaysia, Tel. +603 7734 7226 | 1 ax +603 7734 7626



CLIENT/OWNER: UNITARA RESOURCES SDN WORKSHEET NO: HOURS LDG/CYCLE SERIAL NO. 3966-001 BHD WORK/INSP/DESC: 6997 REFER WORKPACK MAIN ROTOR DRIVE AIRCRAFT AIRCRAFT TYPE: EC155B1 WORKPACK REF: REGISTRATION: 9M-KEL #1 ENGINE: 26300 REFER WORKPACK 9M-KEL-3966 AJL REF NO.: N/A BASE/FACILITY: WMSA #2 ENGINE: 26299 REFER WORKPACK SHEET: DATE IN: REFER WORKPACK OUT: REFER 1 OF 1 NG / N1 NF / N2 Reason for raising: SCHEDULE INSPECTION PERFORM I.A.W AMP URM/CAMO/AMP/EC155B1 ISSUE 01 TR 001 DATED Raised by and date: Other requirements/information: CAMO; Zulkarnaen 16.02.2023 ORION EC155 009.00 UPDATE 02 DATED 2023-02-13. FMM ARRIEL 2C2 UPDATE 48.00 Ibrahim DATED 30.12.2022 OR LATER APPROVED REVISION MAIN ROTOR DRIVE SYSTEM (55FH) 10/05/2023 \* Eng. CRS Technician Date Item Description 1 EASA AD 2018-0263 PARA (3) // ASB EC155-05A034 (55FH) TO INSPECT THE MAIN GEARBOX (MGB) FILTER REFERENCE: EASA AD 2018-0263 PARA (3) // ASB EC155-05A034 R5 PARA 3.B.2.C REMARKS: CARRIED OUT. SATISFACTORY. Certifies that the work specified above, except as otherwise specified, was carried out in accordance with CAA Malaysia Requirements and in respect to that work the aircraft / aircraft component is considered ready for release to service. AMO/2016/02 \*Certifies that the work specified above, except as otherwise specified, was carried out in accordance with and in respect to that work the aircraft / aircraft component is considered ready for release to service. ☐ TICK ✓ WHERE APPLICABLE

2%	5,250	\$1.000	1000	aprova	MONTORES	CANUMS.	2,72	2.5	14(781)	Harana	Projection .	9473374	MOHER
44 (E)	450	1,1		27 44 SHEET	DEELC.	PORTOT I	J41941	SAME	.00500	570x			800



SALOVY AEROSTACE (M) SOUN. BAIL. [10-4026-1] Suite 11-14, Helicopter Centre, Malaysia International Aerospace Centre, Sultan Abdul Aziz Shah Airport, 47200 Subang, Selangor, Malaysia. Tel: +803 7734 7226 | Fax: +803 7734 7526 | swww.galaxyaerospace.my | enquiry@galaxyaerospace.my

## PARTS REPORT

CLIENT/OWNER: UNITARA RESOURCES SERIAL NO. HOURS LDG/CYCLE WORKSHEET NO: 3966-001 SDN BHD 6997 REFER WORKPACK WORK/INSP/DESC: MAIN ROTOR DRIVE **AIRCRAFT** AIRCRAFT TYPE: EC155B1 26300 REFER WORKPACK WORKPACK REF: 9M-KEL-3966 #1 FNGINE REGISTRATION: 9M-KEL 26299 REFER WORKPACK REFER WORKPACK AJL REF NO.: BASE/FACILITY: WMSA #2 ENGINE: DATE IN: REFER WORKPACK OUT: REFER WORKPACK SHEET: 1 3 NG / N1 NF/N2 REASON FOR RAISING: Raised by and date: CAMO: Zulkarnaen Other requirements/information: SCHEDULE INSPECTION PERFORM I.A.W AMP URM/CAMO/AMP/EC155B1 ISSUE 01 TR 001 DATED NIL 16.02.2023 , ORION EC155 009.00 UPDATE 02 DATED 2023-02-13, EMM ARRIEL 2C2 UPDATE 48.00 Ibrahim DATED 30.12.2022 OR LATER APPROVED REVISION MAIN ROTOR DRIVE SYSTEM (55FH) 10/05/2023 Serial Number Lifed Item Information Item Part No Description Qty Release Reference Position Reason TSN/TSO/DUE/TIMEX Off On SIGN & APPROVAL NAME 18/7/23 GAM NITA ISMAIL \*Certifies that the work specified above, except as otherwise specified, was carried out in accordance with CAA Malaysia Requirements and in respect to that work the aircraft / aircraft component is considered ready for release to service. AMO/2016/02 ↑ Certifies that the work specified above, except as otherwise specified, was carried out in accordance with and in respect to that work the aircraft / aircraft component is considered ready for release to service. ☐ TICK ✓ WHERE APPLICABLE



Suite 11-14 Helicocter Centre Malaysia International Acrospace Centre Subar Abou Aziz Shah Airport 47200 Subarg Selanger, Malaysia (et +505 7734 7226 ) Lox +605 7734 7426 (et +505 7734 7226 ) Hox +605 7734 7426 WORKSHEET

CLIENT/OWNER: UNITARA RESOURCES SDN WORKSHEET NO: SERIAL NO. HOURS LDG/CYCLE 3966-002 BHD WORK/INSP/DESC: AIRCRAFT 6997 REFER WORKPACK VISUAL CHECK OF THE 10 AIRCRAFT TYPE: EC155B1 WORKPACK REF: #1 ENGINE: 26300 REFER WORKPACK 9M-KEL-3966 REGISTRATION: 9M-KEL AJL REF NO.: N/A BASE/FACILITY: WMSA #2 ENGINE: 26299 REFER WORKPACK SHEET: DATE IN: REFER WORKPA OUT: REFER OF 1 NF / N2 NG/N1 Reason for raising: SCHEDULE INSPECTION PERFORM I.A.W AMP URM/CAMO/AMP/EC155B1 ISSUE 01 TR 001 DATED Raised by and date: Other requirements/information: CAMO; Zulkarnaen 16.02.2023, ORION EC155 009.00 UPDATE 02 DATED 2023-02-13, EMM ARRIEL 2C2 UPDATE 48.00 Ibrahim DATED 30.12.2022 OR LATER APPROVED REVISION VISUAL CHECK OF THE 10-BLADE TRH (55FH) 10/05/2023 Item Technician \* Eng. CRS Date Description 1 EASA AD 2012-0227 R1 PARA (3) // ASB EC155-05A021R1 (55FH) PERFORM DETAILED VISUAL INSPECTION OF THE TRH EASA AD 2012-0227 R1 PARA (3) // ASB EC155-05A021R1 PARA 3.B REMARKS: CARRIED OUT. SATISFACTORY \*Certifies that the work specified above, except as otherwise specified, was carried out in accordance with CAA Malaysia Requirements and in respect to that work the aircraft / aircraft component is considered ready for release to service. AMO/2016/02 \*Certifies that the work specified above, except as otherwise specified, was carried out in accordance with and in respect to that work the aircraft / aircraft component is considered ready for release to service. ☐ TICK ✓ WHERE APPLICABLE



Suite 11-14, Helicopter Centre, Malaysia International Aerospace Centre Suitan Abdia Abir Shah Airport, 4720F Subang, Selanger Malaysia Tel: ±663 7734 7828. [1 ax ±603 7734 7828] www.malaysia-genspace my/conceived captiviseros cape my.

# PARTS REPORT

CLIENT/OWNER: UNITARA RESOURCES SERIAL NO. HOURS LDG/CYCLE WORKSHEET NO: 3966-002 SDN BHD 6997 REFER WORKPACK VISUAL CHECK OF THE 10 AIRCRAFT WORK/INSP/DESC: AIRCRAFT TYPE: EC155B1 26300 REFER WORKPACK 9M-KEL-3966 WORKPACK REF: REGISTRATION: 9M-KEL #1 ENGINE: REFER WORKPACK 26299 AJL REF NO.: REFER WORKPACK BASE/FACILITY: WMSA #2 ENGINE: 3 SHEET: 2 OF DATE IN: REFER WORKPACK OUT: REFER WORKPACK NG/N1 NF/N2 REASON FOR RAISING: Raised by and date: CAMO; Zulkarnaen Other requirements/information: SCHEDULE INSPECTION PERFORM I.A.W AMP URM/CAMO/AMP/EC155B1 ISSUE 01 TR 001 DATED NIL 16.02.2023 , ORION EC155 009.00 UPDATE 02 DATED 2023-02-13, EMM ARRIEL 2C2 UPDATE 48.00 Ibrahim DATED 30.12.2022 OR LATER APPROVED REVISION VISUAL CHECK OF THE 10-BLADE TRH (55FH) 10/05/2023 Serial Number Lifed Item Information Part No. Item Description Qty Position Reason Release Reference TSN/TSO/DUE/TIMEX Off SIGN & APPROVAL DATE FIRM NAME 31/7/23. NITA GAM ISMAIL Certifies that the work specified above, except as otherwise specified, was carried out in accordance with CAA Malaysia Requirements and in respect to that work the aircraft / aircraft component is considered ready for release to service. AMO/2016/02 \*Certifies that the work specified above, except as otherwise specified, was carried out in accordance with \_ and in respect to that work the aircraft / aircraft component is considered ready for release to service. ■ TICK WHERE APPLICABLE



Suite 11-14, Feliconter Centre, Malaysia International Aerospace Centre, Buttos Abou Ariz Shah Airport, 47200 Subarg, Selongor, Matuvsia Tel. 4602 7734 7226. [ Lax. +602 7734 7626.

WORKSHEET

CLIENT/OWNER: UNITARA RESOURCES SDN WORKSHEET NO: LDG/CYCLE SERIAL NO. HOURS 3966-003 BHD WORK/INSP/DESC: **AIRCRAFT** 6997 REFER WORKPACK INSPECTION OF THE FAN AIRCRAFT TYPE: EC155B1 WORKPACK REF. 9M-KFI -3966 26300 REFER WORKPACK REGISTRATION: 9M-KEL #1 ENGINE: AJL REF NO.: N/A 26299 REFER WORKPACK BASE/FACILITY: WMSA #2 ENGINE: SHEET: DATE IN: REFER WORKPACK OUT: REFER OF NG / N1 NF/N2 Reason for raising: scheoule inspection perform i.a.w amp urm/camo/amp/ec155B1 ISSUE 01 TR 001 DATED Other requirements/information: Raised by and date: CAMO; Zulkarnaen 16.02.2023 , ORION EC155 009.00 UPDATE 02 DATED 2023-02-13, EMM ARRIEL 2C2 UPDATE 48.00 Ibrahim DATED 30.12.2022 OR LATER APPROVED REVISION INSPECTION OF THE FAN HUB (55FH) 10/05/2023 Technician \* Eng. CRS Date Item Description EASA AD 2022-0006 PARA (1) // ASB EC155-05A039 (55FH) 1 INSPECT THE AFFECTED PARTS AND THE AREA AROUND THE FAN HUB ATTACHMENT SCREW. REFERENCE: EASA AD 2022-0006 PARA (1) // ASB EC155-05A039 REV. 0 PART 3.B.2 REMARKS: CARRIED OUT SATSFACTORY. \*Certifies that the work specified above, except as otherwise specified, was carried out in accordance with CAA Malaysia Requirements and in respect to that work the aircraft / aircraft component is considered ready for release to service. AMO/2016/02 \*Certifies that the work specified above, except as otherwise specified, was carried out in accordance with and in respect to that work the aircraft / aircraft component is considered ready for release to service. ☐ TICK ✓ WHERE APPLICABLE

ATTES :	100	3.50.018	540.50 F	10- HSI	79-51		MARKET	1,717.146	55705	44.0-44		rement to	.00		
AMATES RE	EAGEL.	1.57	9,5		244	Vet-if			.40/1	CC 80%	FOR	155 h Ch	(14)	100000	
FE UPALT															



ter Centre, Malaysia International Aerospace Centre, ash Ament 47200 Subang, Selangor, Malaysia | Fax +603 7734 7526

## PARTS REPORT

CLIENT/OWNER: UNITARA RESOURCES SERIAL NO. HOURS LDG/CYCLE WORKSHEET NO: SDN BHD 6997 REFER WORKPACK INSPECTION OF THE FAN AIRCRAFT WORK/INSP/DESC: AIRCRAFT TYPE: EC155B1 26300 9M-KEL-3966 REFER WORKPACK WORKPACK REF: #1 ENGINE: REGISTRATION: 9M-KEL REFER WORKPACK 26299 REFER WORKPACK AJL REF NO.: BASE/FACILITY: WMSA #2 ENGINE: 3 SHEET: OF DATE IN: REFER WORKPACK OUT: REFER WORKPACK NF / N2 NG/N1 BEASON FOR BAISING: Raised by and date: CAMO; Zulkarnaen Other requirements/information: SCHEDULE INSPECTION PERFORM I.A.W AMP URM/CAMO/AMP/EC155B1 ISSUE 01 TR 001 DATED 16.02.2023, ORION EC155 009.00 UPDATE 02 DATED 2023-02-13, EMM ARRIEL 2C2 UPDATE 48.00 Ibrahim DATED 30.12.2022 OR LATER APPROVED REVISION INSPECTION OF THE FAN HUB (55FH) 10/05/2023 Serial Number Lifed Item Information Part No Release Reference Item Description Qty Position Reason TSN/TSO/DUE/TIMEX Off FIRM SIGN & APPROVAL NAME 18/7/23 17123 MITA CAM. LOMAIL Certifies that the work specified above, except as otherwise specified, was carried out in accordance with CAA Malaysia Requirements and in respect to that work the aircraft / aircraft component is considered ready for release to service. AMO/2016/02 Tertifies that the work specified above, except as otherwise specified, was carried out in accordance with and in respect to that work the aircraft / aircraft component is considered ready for release to service. ☐ TICK ✓ WHERE APPLICABLE