

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	1
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
SBS						
Types	SB Number	Subject	Last Done	Next Due	Interval	Limitation Notes
Repetitive SBs	SBA139-724 REV. B (EASA AD No.: 2022-0205)	ATA 64 - TAIL ROTOR DAMPER BRACKET INSPECTION	25/01/2023	25/07/2023	6	TIC-AW139-22-0158 DATED 28 JULY 2022 APPLICABLE DUE TO COMPONENT TAIL ROTOR DAMPER BRACKET ASSEMBLIE P/N 3G6420A06131 AND AFFECTED S/N FITTED ON AIRCRAFT 9M-PME-13206 AT 1327:15 FH ON 29/11/2022
Repetitive SBs	SBA139-724 REV. B (EASA AD No.: 2022-0205)	ATA 64 - TAIL ROTOR DAMPER BRACKET INSPECTION	1417:13	1467:13	50	TIC-AW139-22-0158 DATED 28 JULY 2022 APPLICABLE DUE TO COMPONENT TAIL ROTOR DAMPER BRACKET ASSEMBLIE P/N 3G6420A06131 AND AFFECTED S/N FITTED ON AIRCRAFT 9M-PME-13206 AT 1327:15 FH ON 29/11/2022
Repetitive SBs	SB 139-728, NEW ISSUE - PART III	SB 139-728 REV./ PART III - TAIL ROTOR DUPLEX BEARING R	0:00	0:00	300	
Repetitive SBs	SB 139-728, NEW ISSUE - PART III	SB 139-728 REV./ PART III - TAIL ROTOR DUPLEX BEARING R	-	00/00/0000	1	
Repetitive SBs	SB N° 139-728 PART I	TAIL ROTOR DUPLEX BEARING REPETITIVE INSPECTIONS	25/01/2023	25/03/2023	2	
Repetitive SBs	SB N° 139-728 PART I	TAIL ROTOR DUPLEX BEARING REPETITIVE INSPECTIONS	1417:13	1467:13	50	
Repetitive SBs	SBA139-661 REV.B PART II (EASA AD NO.: 2021-0044R1 PARA	300FH//1Y - ATA 24 OVERHEAD PANEL INSPECTION	1438:50	1738:50	300	TIC-AW139-22-0116 DATED 09 MAY 2022 9M-PME-10584 @ 1141:20 FH ON 10/05/2022 (AJL 01517)
Repetitive SBs	SBA139-661 REV.B PART II (EASA AD NO.: 2021-0044R1 PARA	300FH//1Y - ATA 24 OVERHEAD PANEL INSPECTION	15/02/2023	15/02/2024	1	

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	2
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Repetitive SBs	BT 139-443 REV A PART III	GOODRICH RESCUE HOIST OVERLOAD CLUTCH.	0:00	0:00	400	INITIAL COMPLIED: PLACARDS INSTALLED, AS PER Part I;CABLE INSPECTION ACCOMPLISHED, AS PER Part II;RESCUE HOIST GEARBOX OIL REPLACED, AS PER Part III;CABLE CONDITIONING LIFT CARRIED OUT, AS PER Part III;HOIST LOAD CHECK INSPECTION PERFORMED, TO BE REPEATED AS PER Part III;Part IV: COMPONENT NOT AFFECTED (REF. HELICOPTER LOGBOOK). INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Repetitive SBs	BT 139-443 REV A PART III	GOODRICH RESCUE HOIST OVERLOAD CLUTCH.	01/08/2021	00/00/0000	0	SN 40543 9M-PME-7480 ON 01/08/2021 @ 654:30FH
Repetitive SBs	BT 139-443 REV A PART III	GOODRICH RESCUE HOIST OVERLOAD CLUTCH.	-	-	6	INITIAL COMPLIED: PLACARDS INSTALLED, AS PER Part I;CABLE INSPECTION ACCOMPLISHED, AS PER Part II;RESCUE HOIST GEARBOX OIL REPLACED, AS PER Part III;CABLE CONDITIONING LIFT CARRIED OUT, AS PER Part III;HOIST LOAD CHECK INSPECTION PERFORMED, TO BE REPEATED AS PER Part III;Part IV: COMPONENT NOT AFFECTED (REF. HELICOPTER LOGBOOK) INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019. 9M-PME-6556 @ 541:10 FH ON 24/04/2021 (AJL 03946 SN: 40543)

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	3
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Repetitive SBs	50FH ASB139-654 PART II (EASA AD 2020-0271 PARA (2))	ATA 62 - MAIN ROTOR SWASHPLATE BOOT INSPECTION	1417:13	1467:13	50	TIC-AW139-20-199 DATED 02 DECEMBER 2020. 9M-PME-9837 @ 1019:50 FH ON 09/02/2022 (AJL 05915) 9M-PME-10187 @ 1057:55 FH ON 17/03/2022 (AJL 05933) 9M-PME-10572 @ 1104:15 FH ON 21/04/2022 (AJL 01504) 9M-PME-10978 @ 1141:20 FH ON 09/05/2022 (AJL 01517)
Repetitive SBs	BT 139-526 PART II	ATA 63 - MGB OIL COOLING FAN INSPECTION	1190:00	2390:00	1200	WP-PME-10895 @ 1190:00 FH ON 16.06.2022 (AJL 01542) (ON:141601113, OFF: 141601181)
Repetitive SBs	SB139-526 PART I	ATA 63 - MGB OIL COOLING FAN INSPECTION	1190:00	0:00	200	TERMINATING ACTION PART 1 WP-PME-10895 @ 1190:00 FH ON 16.06.2022 (AJL 01542)
Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	SB139-539 PART III (1500H//2Y)	ATA 53 - TRDL BEARING SUPPORT PANEL REINFORCEMENT	-	-	-/NOT APPLICABLE	TIC-AW139-22-0007 DATED 27 JANUARY 2022 NOT APPLICABLE DUE TO AFFECTED TAIL BOOM ASSY NOT FITTED ON AIRCRAFT.
Standard SBs	SB139-539 PART II (3M BEFORE COMPLIANCE PART III) (MMIR	ATA 53 - TRDL BEARING SUPPORT PANEL REINFORCEMENT	-	-	-/NOT APPLICABLE	TIC-AW139-22-0007 DATED 27 JANUARY 2022 NOT APPLICABLE DUE TO AFFECTED TAIL BOOM ASSY NOT FITTED ON AIRCRAFT.
Standard SBs	SB 139-516 PART I & II (NEW ISSUE)	ATA 95 EMERGENCY FLOTATION AND LIFE RAFT SYSTEMS CONVERSION TO DART INTEGRATED SYSTEM	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO COMPONENT PART NUMBER NOT AFFECTED. REFER TIC-AW139-22-0002 DATED 19.01.2022

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	4
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	SB NO. 139-407 REV C PART II AND III	ATA 71 - INSTALLATION OF INLET BARRIER FILTER	-	-	-/NOT APPLICABLE	TIC-AW139-21-0399 DATED 18 NOVEMBER 2021 OPTIONAL SB PART II: NOT APPLICABLE DUE TO COMPONENT IBF LH ASSY P/N 3G7160V03931 NOT INSTALLED ON AIRCRAFT PART III: NOT APPLICABLE DUE TO COMPONENT IBF COMPLETE PROVISION P/N 3G7160A07811 NOT INSTALLED ON AIRCRAFT
Standard SBs	SB NO. 139-623, REV. A	ATA 00 - MISCELLANEOUS RETROFIT	-	-	-/NOT APPLICABLE	TIC-AW139-22-0012 DATED 10 FEBRUARY 2022 NOT APPLICABLE DUE TO AIRCRAFT SERIAL NUMBER NOT AFFECTED COMPLIANCE: AT CUSTOMER'S OPTION
Standard SBs	SB NO. 139-709, NEW ISSUE	ATA 33 PLACARD PROVISION REMOVAL	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO AIRCRAFT SERIAL NUMBER NOT AFFECTED. REFER TO TIC-AW139-22-0015.
Standard SBs	SB NO. 139-577 PART II, NEW ISSUE	ATA 53 - LOWER INSPECTION COVER INSTALLATION	-	-	-/OPTIONAL	TIC-AW139-21-0345 DATED 28 SEPTEMBER 2021 PART II: APPLICABLE DUE TO AIRCRAFT SERIAL NUMBER AFFECTED COMPLIANCE: AT CUSTOMER'S OPTION (OPTIONAL SB)
Standard SBs	SB NO. 139-619, REV. B (PART I & II)	ATA 56 - REPLACEMENT OF BUBBLE WINDOW WITH STANDARD WINDOW	-	-	-/NOT APPLICABLE	TIC-AW139-22-0027 DATED 21 MARCH 2022 PART I: NOT APPLICABLE DUE TO AIRCRAFT SERIAL NUMBER NOT AFFECTED PART II: NOT APPLICABLE DUE TO AIRCRAFT SERIAL NUMBER NOT AFFECTED
Standard SBs	SB NO. 139-624, NEW ISSUE	ATA 23 - SATCOM SKYTRACK ISAT-200A KIT INSTALLATION	-	-	-/OPTIONAL	TIC-AW139-22-0026 DATED 21 MARCH 2022 APPLICABLE DUE TO AIRCRAFT SERIAL NUMBER AFFECTED COMPLIANCE: AT CUSTOMER'S OPTION (OPTIONAL SB)

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	5
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	SB NO. 139-406, REV. A (PART IV)	ATA 97 - KIT EXTERNAL VIDEO CAMERA	-	-	-/OPTIONAL	TIC-AW139-22-0025 DATED 21 MARCH 2022 PART IV: APPLICABLE DUE TO AIRCRAFT SERIAL NUMBER AFFECTED COMPLIANCE: AT CUSTOMER'S OPTION (OPTIONAL SB)
Standard SBs	SB NO. 139-406, REV. A (PART III)	ATA 97 - KIT EXTERNAL VIDEO CAMERA	-	-	-/OPTIONAL	TIC-AW139-22-0025 DATED 21 MARCH 2022 PART III: APPLICABLE DUE TO AIRCRAFT SERIAL NUMBER AFFECTED COMPLIANCE: AT CUSTOMER'S OPTION (OPTIONAL SB)
Standard SBs	SB NO. 139-406, REV. A (PART II)	ATA 97 - KIT EXTERNAL VIDEO CAMERA	-	-	-/NOT APPLICABLE	TIC-AW139-22-0025 DATED 21 MARCH 2022 PART II: NOT APPLICABLE DUE TO AIRCRAFT SERIAL NUMBER NOT AFFECTED
Standard SBs	SB NO. 139-406, REV. A (PART I)	ATA 97 - KIT EXTERNAL VIDEO CAMERA	-	-	-/NOT APPLICABLE	TIC-AW139-22-0025 DATED 21 MARCH 2022 PART I: NOT APPLICABLE DUE TO AIRCRAFT SERIAL NUMBER NOT AFFECTED
Standard SBs	SB NO. 139-586, NEW ISSUE	ATA 95 - DART INTEGRATED EMERGENCY FLOTATION AND LIFE RAFT SYSTEM KIT INSTALLATION	-	-	-/OPTIONAL	TIC-AW139-22-0133 DATED 16 JUNE 2022 APPLICABLE DUE TO AIRCRAFT SERIAL NUMBER AFFECTED
Standard SBs	SB 139-695 NEW ISSUE	ATA 56 - INSTALLATION OF ACRYLIC WINDSHIELDS	-	-	-/OPTIONAL	TIC-AW139-22-0131 DATED 09 JUNE 2022 APPLICABLE DUE TO AIRCRAFT SERIAL NUMBER AFFECTED
Standard SBs	SB 139-719 NEW ISSUE	ATA 93 OPLS LASER SENSOR UNIT FIRMWARE UPDATE.	-	-	-/NOT APPLICABLE	TIC-AW139-22-0130 DATED 01 JUNE 2022 NOT APPLICABLE DUE TO AIRCRAFT SERIAL NUMBER NOT AFFECTED
Standard SBs	SBEA 139-725 REV. A PART I (EASA AD 2022-0182 PARA 1)	ATA 64 - TAIL ROTOR DUPLEX BEARING INSPECTION AND REPLACEMENT	-	-	-/Required	
Standard SBs	SBEA 139-725 REV. A PART III (EASA AD 2022-0182)	ATA 64 - TAIL ROTOR DUPLEX BEARING INSPECTION AND REPLACEMENT	-	-	-/NOT APPLICABLE	
Standard SBs	SBEA 139-725 REV.A PART IV (EASA AD 2022-0182)	ATA 64 - TAIL ROTOR DUPLEX BEARING INSPECTION AND REPLACEMENT	0.00	2400.00	-/TO BE COMPLIED	

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	6
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	SB NO. 139-678 REV./ PART 1 (EASA AD 2020-0191 R1)	ATA 53 - MIDDLE PANEL RETROMOD INSTALLATION	-	-	-/NOT APPLICABLE	TIC-AW139-22-0143 DATED 05 JULY 2022 NOT APPLICABLE DUE TO AIRCRAFT CONFIGURATION INSTALLING 1ST ROW CENTRAL SEAT/SEATS FWD FACING IS NOT EQUIPPED ON AIRCRAFT.
Standard SBs	SB NO. 139-678 REV./ PART 2 (EASA AD 2020-0191 R1)	ATA 53 - MIDDLE PANEL RETROMOD INSTALLATION	-	-	-/NOT APPLICABLE	TIC-AW139-22-0143 DATED 05 JULY 2022 NOT APPLICABLE DUE TO AIRCRAFT CONFIGURATION INSTALLING 1ST ROW CENTRAL SEAT/SEATS FWD FACING IS NOT EQUIPPED ON AIRCRAFT.
Standard SBs	SB NO. 139-678 REV./ PART 3 (EASA AD 2020-0191 R1)	ATA 53 - MIDDLE PANEL RETROMOD INSTALLATION	-	-	-/NOT APPLICABLE	TIC-AW139-22-0143 DATED 05 JULY 2022 NOT APPLICABLE DUE TO AIRCRAFT CONFIGURATION INSTALLING 1ST ROW CENTRAL SEAT/SEATS FWD FACING IS NOT EQUIPPED ON AIRCRAFT.
Standard SBs	SB NO. 139-726, NEW ISSUE	MODULAR AVIONIC UNIT (MAU) MARKING	-	-	-/NOT APPLICABLE	TIC-AW139-22-0162 DATED 04 AUGUST 2022 NOT APPLICABLE DUE TO AIRCRAFT S/N NOT AFFECTED
Standard SBs	SB 139-699, NEW ISSUE	ATA 33 - TAIL ROTOR LIGHTS IMPROVEMENT	-	-	-/NOT APPLICABLE	TIC-AW139-22-0145 DATED 14 JULY 2022 NOT APPLICABLE DUE TO AIRCRAFT NOT FITTED WITH AFFECTED PART NUMBER.
Standard SBs	SB NO. 139-685, NEW ISSUE	LEONARDO HELICOPTERS - AW139 SERVICE BULLETIN ATA 93 - AIRCRAFT SURVIVABILITY EQUIPMENT (ASE) MODIFICATION	-	-	-/NOT APPLICABLE	TIC-AW139-22-0144 DATED 14 JULY 2022 NOT APPLICABLE DUE TO SERIAL NUMBER NOT AFFECTED.
Standard SBs	SB NO. 139-722, NEW ISSUE	MAIN ROTOR HEAD ASSY UPGRADE	-	-	-/NOT APPLICABLE	TIC-AW139-22-0170 DATED 22 AUGUST 2022 NOT APPLICABLE DUE TO COMPONENT MAIN ROTOR HEAD ASSEMBLIES P/N 3G6220A00132 NOT FITTED ON AIRCRAFT.
Standard SBs	SB NO. 139-692, NEW ISSUE	DRIVE PULLEY WASHER INSPECTION	-	-	-/FOR INFO ONLY	TIC-AW139-22-0192 DATED 07 SEPTEMBER 2022 NOT APPLICABLE DUE TO COMPRESSORS (FITTED ON AIRCRAFT) SERIAL NUMBER NOT AFFECTED.
Standard SBs	SBEA 139-731 REV./ PART II (EASA AD 2022-0209-E)	ATA 00 FORWARD CABIN ROOF CEILING HARNESS INSPECTION	-	-	-/Required	
Standard SBs	SBEA 139-731 REV./ PART I (EASA AD 2022-0209-E)	ATA 00 FORWARD CABIN ROOF CEILING HARNESS INSPECTION	-	-	-/Required	

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	7
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	SB NO. 139-564,NEW ISSUE	AV900 CABIN STATION, POWER SOCKET AND AVIONIC VARIANT INSTALLATION	-	-	-/Required	
Standard SBs	SB NO. 139-672, NEW ISSUE (PART I)	NUMBER 4 PUMP LINE INSTALLATION VISUAL INSPECTION AND MODIFICATION	-	-	-/Required	
Standard SBs	SB NO. 139-672, NEW ISSUE (PART II)	NUMBER 4 PUMP LINE INSTALLATION VISUAL INSPECTION AND MODIFICATION (MMIR)	-	-	-/Required	
Standard SBs	SB NO. 139-723, NEW ISSUE	CABIN PROVISION MODIFICATION	-	-	-/Required	
Standard SBs	SBEA 139-725 REV. A PART II (EASA AD2022-0182 PARA 2)	ATA 64- TAIL ROTOR DUPLEX BEARING INSPECTION AND REPLACEMENT	-	-	-/Required	
Standard SBs	EVERY 25FH INSPECTION SB139-539 PART I	ATA 53 - TRDL BEARING SUPPORT PANEL REINFORCEMENT (PART I COMPLIANCE UNTIL ACCOMPLISHMENT PART III)	-	-	-/NOT APPLICABLE	TIC-AW139-22-0007 DATED 27 JANUARY 2022 NOT APPLICABLE DUE TO AFFECTED TAIL BOOM ASSY NOT FITTED ON AIRCRAFT.
Standard SBs	25FH BT 139-467 PART I REV A	TAIL ROTOR DRIVE LINE (TRDL) BEARING SUPPORT BRACKET	-	-	-/CANCELLED	TIC-AW139-22-0006 DATED 27 JANUARY 2022 SB CANCELLED.
Standard SBs	SB 139-710, NEW ISSUE	ATA 23 - SATCOM FLIGHTCELL IMPROVEMENT	-	-	-/NOT APPLICABLE	TIC-AW139-22-0149 DATED 15 JULY 2022 NOT APPLICABLE TO THIS AIRCRAFT DUE TO AFFECTED ITEM NOT FITTED TO AIRCRAFT.
Standard SBs	SB139-569 REV.B PART I(AD2018-0292) COMPLIANCE	ATA 64 TAIL ROTOR SLIDER ASSY DETAILED INSPECTION	0.00	2400.00	-/TO BE COMPLIED	TIC-AW139-22-0155 DATED 26 JULY 2022 APPLICABLE DUE TO AIRCRAFT TYPE
Standard SBs	SB NO 139-569, REVISION B PART II	ATA 64 - TAIL ROTOR SLIDER ASSY DETAILED INSPECTION	-	-	-/ON CONDITION	TIC-AW139-22-0155 DATED 26 JULY 2022 APPLICABLE DUE TO AIRCRAFT TYPE
Standard SBs	SB NO. 139-647,NEW ISSUE	INTERSEAT CONSOLE CONNECTORS REPOSITIONING	-	-	-/NOT APPLICABLE	TIC-AW139-22-0118 DATED 11 MAY 2022 NOT APPLICABLE DUE TO AIRCRAFT S/N NOT AFFECTED
Standard SBs	SB NO. 139-669, NEW ISSUE	SATCOM FLIGHTCELL DZMX ELECTRICAL VARIANT INSTALLATION	-	-	-/NOT APPLICABLE	TIC-AW139-22-0129 DATED 01 JUNE 2022 NOT APPLICABLE DUE TO AIRCRAFT SERIAL NUMBER NOT AFFECTED
Standard SBs	SB NO. 139-035 REV D	ATA 25 - AUTOMATICALLY DEPLOYABLE ELT INSTALLATION.	-	-	-/OPEN	TIC-AW139-22-0028 DATED 21 MARCH 2022
Standard SBs	SB NO. 139-681, NEW ISSUE	ATA 33 - HELICOPTER EMERGENCY EXIT LIGHTS SYSTEM INSTALLATION.	-	-	-/NOT APPLICABLE	TIC-AW139-22-0029 DATED 21 MARCH 2022
Standard SBs	SB NO. 139-398 REV A	ATA 52 INSTALLATION OF FOOTSTEP FAST REMOVAL KIT.	-	-	-/OPEN	TIC-AW139-22-0052 DATED 24 MARCH 2022
Standard SBs	SB NO. 139-651, NEW ISSUE	ATA 34 - ENHANCED GROUND PROXIMITY WARNING SYSTEM (EGPWS) COMPUTER CONVERSION TO P/N 965-1595-034.	-	-	-/OPEN	TIC-AW139-22-0114 DATED 09 MAY 2022
Standard SBs	SB NO. 139-600, NEW ISSUE	ATA 46 - 'PRIMUS EPIC®' FLIGHT SOFTWARE RELEASE 8 UPGRADE.	-	-	-/OPEN	TIC-AW139-22-0113 DATED 09 MAY 2022

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	8
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	SB NO. 139-715, NEW ISSUE	ATA 62 - MAIN ROTOR BLADE S/N MARKING	-	-	-/OPEN	REFER TIC-AW139-22-0122 DATED 17 MAY 2022
Standard SBs	SB NO. 139-360 REV B PART III	ATA 24 - KIT BATTERY START IN PARALLEL 44 Ah AND 27 Ah	-	-	-/NOT APPLICABLE	TIC-AW139-22-0126 DATED 24 MAY 2022 PART III: NOT APPLICABLE TO THIS AIRCRAFT DUE TO SERIAL NUMBER NOT AFFECTED
Standard SBs	SB NO 139-546, NEW ISSUE	ATA 24 - AUXILIARY OVER HEAD PANEL RETRO MODIFICATION	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 03/12/2019.
Standard SBs	BT 139-038 REV G PART I, II AND III	ATA 31 - INSTALLATION OF KIT HEALTH AND USAGE MONITORING SYSTEM	-	-	-/OPTIONAL	INSTALLED COMPLETE PROVISION AND FIXED PARTS ONLY INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 03/12/2019.
Standard SBs	SB NO 139-137 REVISION C PART III	KIT POWERED PARKING BRAKE MODULE P/N 3G3240F00111, INSTALLATION OF.	-	-	-/OPTIONAL	AT CUSTOMERS OPTION. NOT REQUESTED BY WORK ORDER. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 03/12/2019.
Standard SBs	SB NO 139-258, REVISION A	ATA 33- INSTALLATION OF SX16 IFCO NVG VARIANT	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 03/12/2019.
Standard SBs	SB NO 139-590, NEW ISSUE	ATA 34 - INSTALLATION OF KIT DF	-	-	-/OPTIONAL	AT CUSTOMERS OPTION. NOT REQUESTED BY WORK ORDER. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 03/12/2019.
Standard SBs	SB NO 139-542, NEW ISSUE	ATA 25 - INSTALLATION OF KIT BAGGAGE BOX	-	-	-/OPTIONAL	AT CUSTOMERS OPTION. NOT REQUESTED BY CONTRACTED WORK ORDER INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 03/12/2019.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	9
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	SB NO 139-316, NEW ISSUE	ATA 53 - ANCHOR NUTS IN FUEL TANK AREA	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 03/12/2019.
Standard SBs	SB NO 139-541 PART I & II, NEW ISSUE	ATA 23 - KIT EXTERNAL LOUDSPEAKERS 900W	-	-	-/OPTIONAL	AT CUSTOMERS OPTION. NOT REQUESTED BY CONTRACTED WORK ORDER INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 03/12/2019.
Standard SBs	SB NO 139-603, NEW ISSUE	ATA 93 - FLIR SS380HDC TFU VARIANT	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 03/12/2019.
Standard SBs	SB139-591, NEW ISSUE	ATA 24 - CB PANEL VARIANT	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 03/12/2019.
Standard SBs	SB NO 139-487 PART II, NEW ISSUE	ATA 53 - BL 0.0 NOSE REINFORCEMENT RETROMOD	-	-	-/NOT APPLICABLE	HELICOPTER NOT AFFECTED BY SERIAL NUMBER INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 03/12/2019.
Standard SBs	SB NO 139-555, NEW ISSUE	ATA 00- INTERIORS RECONFIGURATION FROM VIP TO OFFSHORE	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 03/12/2019.
Standard SBs	SB NO 139-439, REVISION A	ATA 22 - INSTALLATION OF KIT FOUR AXIS ENHANCED FLIGHT DIRECTOR	-	-	-/OPTIONAL	DIFFERENT PART NUMBER INSTALLED INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 03/12/2019.
Standard SBs	SB NO 139-510, NEW ISSUE	ATA 34 - WEATHER RADAR (1500B+) 2ND CONTROL PANEL INSTALLATION	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 03/12/2019.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	10
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	SB 139-558, NEW ISSUE	ATA 24 - UTILITY CB PANEL LH RETROMOD	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 03/12/2019.
Standard SBs	SB139-525, REVISION A	ATA 95 - INSTALLATION OF INFLATION SERVICE CHARTS	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO COMPONENT NOT AFFECTED. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 03/12/2019.
Standard SBs	SB NO 139-579	ATA 99 INSTALLATION OF KIT SIAP AND RWR AND LWR	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 03/12/2019.
Standard SBs	SB NO. 139-153 REVISION A	LONGITUDINAL AUXILIARY FUEL TANK KIT P/N 4G2800F00111, INSTALLATION OF	-	-	-/OPTIONAL	TIC-AW139-20-PME-001 DATED 09 MARCH 2020 APPLICABLE TO AIRCRAFT SERIAL NUMBER
Standard SBs	SB NO 139-527, NEW ISSUE	ATA 95- INSTALLATION OF COCKPIT AND CABIN PASSENGER FLOOR BALLISTIC PROTECTION	-	-	-/NOT APPLICABLE	TIC-AW139-20-037-PME-002 DATED 09 MARCH 2020 NOT APPLICABLE DUE TO AIRCRAFT SERIAL NUMBER
Standard SBs	SBA 139-614, NEW ISSUE	ATA 26 FIRE EXTINGUISHER INSPECTION AND REPLACEMENT	-	-	-/NOT APPLICABLE	TIC-AW139-20-037-PME-006 DATED 09 MARCH 2020 NOT APPLICABLE DUE TO COMPONENT PART NUMBER P3APP003010A NOT FITTED ON AIRCRAFT. AIRCRAFT CURRENTLY FITTED WITH COMPONENT PART NUMBER P3APP003010D
Standard SBs	SB NO 139-607, NEW ISSUE	ATA 21- INSTALLATION OF DUAL ZONE HEATING CABIN DUCT VARIANT	-	-	-/NOT APPLICABLE	TIC-AW139-20-037-PME-007 DATED 09 MARCH 2020 NOT APPLICABLE DUE TO AIRCRAFT SERIAL NUMBER
Standard SBs	SB NO. 139-130, REVISION A	ATA 34- KIT 2ND GPS P/N 4G3450F00611 OR KIT GPS SBAS P/N 4G3450F00613	-	-	-/NOT APPLICABLE	TIC-AW139-20-053 DATED 26 MARCH 2020. NOT APPLICABLE BY HELICOPTER SERIAL NUMBER. COMPLIANCE AT CUSTOMER'S OPTION.
Standard SBs	SB NO. 41703, REVISION 1	TURBOSHAFT ENGINE - FUEL MANAGEMENT MODULE REPLACEMENT/	-	-	-/NOT APPLICABLE	REFER TO TIC-AW139-20-039 NOT APPLICABLE TO ENGINE S/N

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	11
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	BT 139-46-001	PART I: "PRIMUS EPIC" FLIGHT SW RELEASE 2.4.0. INSTALLATION. PART II: ANTENNA GPS P/N 567-1575-132 INSTALLATION OF. PART III: PILOT AND COPILOT MASTER CAUTION/ WARNING P/N 3G3150V00353 / -453 AND DIMMING SYSTEM CONTROL PANEL P/N 3G3320V00353. PART IV: MAIN ROTOR BLADES COLLECTIVE MINIMUM PITCH SETTING.	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	TMI 139-345 Rev B	REAR FUSELAGE CENTRAL FITTING AT STA8700 P/N 3P5340A14153 REPLACEMENT PROCEDURE AW139	-	-	-/FOR INFO ONLY	TIC-AW139-21-0266 APPLICABILITY: APPLICABLE DUE TO COMPONENT MIDDLE LEFT BRACKET STA 8700 P/N 3P5340A14153 AND REAR FUSELAGE ASSY P/N 3P5340A00133 FITTED ON AIRCRAFT WITHOUT REAR FITTING REINFORCEMENT RETRO-MOD P/N 3G5306P38811 (SB 1390418). REFER TO SB STATUS.
Standard SBs	TMI 139-475, REVISION C	ENGINE LH/RH REINFORCEMENT P/N 3P5333A15352 / 3P5333A15452 REPLACEMENT PROCEDURE	-	-	-/NOT APPLICABLE	TIC-AW139-20-159 DATED 22 SEPTEMBER 2020 NOT APPLICABLE DUE TO AIRCRAFT SERIAL NUMBER
Standard SBs	TMI 139-533, NEW ISSUE	FRAME STA 3120 - SPECIFIC REPAIR PROCEDURE	-	-	-/NOT APPLICABLE	
SERVICE BULLETIN AIRFRAME						
Standard SBs	SB 139-601 REV A PART I	ATA 33 - INSPECTION AND REINFORCEMENT OF SEARCHLIGHT SUPPORT	960.42	-	-/COMPLIED WITH	TIC-AW139-22-0119 DATED 12 MAY 2022. 9M-PME-9438 AT 960:25 FH ON 13/01/2022 (AJL 05893)
Standard SBs	SB 139-601 REV A PART I	ATA 33 - INSPECTION AND REINFORCEMENT OF SEARCHLIGHT SUPPORT	13/01/2022	-	-/COMPLIED WITH	TIC-AW139-22-0119 DATED 12 MAY 2022. 9M-PME-9438 AT 960:25 FH ON 13/01/2022 (AJL 05893)
Standard SBs	SB 139-601 REV A PART II	ATA 33 - INSPECTION AND REINFORCEMENT OF SEARCHLIGHT SUPPORT	-	20/06/2022	-/ON CONDITION	TIC-AW139-22-0119 DATED 12 MAY 2022. APPLICABLE. ORDINE DI LAVORO MARK: 429250/1. REFER TO PHYSICAL CHECK 9M-PME-9375 ON 13.01.2022 AT 960:25 FH (AJL 05893)

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	12
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	SB 139-696, NEW ISSUE	ATA 63 - MAIN GEAR BOX REMARKING	-	-	-/NOT APPLICABLE	TIC-AW139-21-0410 DATED 13 DECEMBER 2021. NOT APPLICABLE DUE TO COMPONENT MAIN GEARBOX PART NUMBER 3G6320A00134 WITH AFFECTED SERIAL NUMBER NOT FITTED ON THE AIRCRAFT.
Standard SBs	SB NO. 139-615 NEW ISSUE	ATA 00 INSTALLATION OF SPECIFIC VARIANTS FOR OFFSHORE CONFIGURATION	-	-	-/NOT APPLICABLE	TIC-AW139-21-0406 DATED 2 DECEMBER 2021 NOT APPLICABLE DUE TO AIRCRAFT SERIAL NUMBER NOT AFFECTED.
Standard SBs	SB NO. 139-503 REV. /	ATA 00 INTERIOR RECONFIGURATION FROM UTILITY TO VIP	-	-	-/NOT APPLICABLE	TIC-AW139-21-0398 DATED 18 NOVEMBER 2021 NOT APPLICABLE DUE TO AIRCRAFT SERIAL NUMBER NOT AFFECTED.
Standard SBs	SB NO. 139-502 REV./	ATA 95 - COCKPIT AND CABIN PASSENGER FLOOR BALLISTIC PROTECTIONS INSTALLATION	-	-	-/NOT APPLICABLE	TIC-AW139-21-0397 DATED 18 NOVEMBER 2021 NOT APPLICABLE DUE TO AIRCRAFT SERIAL NUMBER NOT AFFECTED.
Standard SBs	SB NO. 139-407 REV C PART I	ATA 71 - INSTALLATION OF INLET BARRIER FILTER	-	-	-/OPTIONAL	TIC-AW139-21-0399 DATED 18 NOVEMBER 2021. PART I: APPLICABLE DUE TO AIRCRAFT SERIAL NUMBER AFFECTED. COMPLIANCE AT CUSTOMER'S OPTION
Standard SBs	SB NO. 139-483	ATA 23- MR6000R RADIO SYSTEM INSTALLATION	-	-	-/OPTIONAL	TIC-AW139-21-0402 DATED 18 NOVEMBER 2021 APPLICABLE DUE TO AIRCRAFT SERIAL NUMBER AFFECTED. COMPLIANCE AT CUSTOMER'S OPTION.
Standard SBs	SB NO. 139-496	ATA 06 - AVIONIC VARIANT INSTALLATION	-	-	-/NOT APPLICABLE	TIC-AW139-21-0400 DATED 18 NOVEMBER 2021 NOT APPLICABLE DUE TO AIRCRAFT SERIAL NUMBER NOT AFFECTED.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	13
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	SB NO. 139-576	ATA 21-VENTILATION AND WATER DRAIN LINES VARIANT	-	-	-/NOT APPLICABLE	TIC-AW139-21-0401 DATED 18 NOVEMBER 2021 NOT APPLICABLE DUE TO AIRCRAFT SERIAL NUMBER NOT AFFECTED.
Standard SBs	SB NO. 139-684	ATA 93 - TURRET FLIR UNIT REPLACEMENT	-	-	-/NOT APPLICABLE	TIC-AW139-21-0394 DATED 11 NOVEMBER 2021 NOT APPLICABLE TO THIS AIRCRAFT SERIAL NUMBER.
Standard SBs	SB NO. 139-649, NEW ISSUE	ATA 67 TAIL ROTOR ACTUATOR UPGRADE	0.00	2087.57	-/TO BE COMPLIED	TIC-AW139-21-0393 APPLICABLE TO THIS AIRCRAFT DUE FITTED WITH PN 3G6730V00731 TO BE COMPLIED NEXT REPAIR/OVERHAUL
Standard SBs	ASB NO. 139-686, NEW ISSUE PART I (EASA AD 2021-0259)	ATA 53 - TAIL GEAR BOX FITTING INSPECTION	-	-	-/NOT APPLICABLE	TIC-AW139-21-0392 APPLICABILITY: NOT APPLICABLE DUE TO COMPONENT TGB FITTING P/N 3G5351A01152 FITTED ON AIRCRAFT IS NOT MORE THAN 3000FH. REFER LOG CARD
Standard SBs	ASB NO. 139-686, NEW ISSUE PART II	ATA 53 - TAIL GEAR BOX FITTING INSPECTION	-	-	-/NOT APPLICABLE	TIC-AW139-21-0392 APPLICABILITY: NOT APPLICABLE DUE TO COMPONENT TGB FITTING P/N 3G5351A01152 FITTED ON AIRCRAFT IS NOT MORE THAN 3000FH. REFER LOG CARD
Standard SBs	SB NO. 139-664	ATA 25 - D-LOCK HOOK BREEZE HOIST INSTALLATION	-	-	-/NOT APPLICABLE	TIC-AW139-21-0379 DATED 29 OCTOBER 2021 NOT APPLICABLE DUE TO COMPONENT BREEZE EASTERN 90M RESCUE HOIST KIT PART NUMBER 3G2591F00113 NOT FITTED ON AIRCRAFT.
Standard SBs	SB NO. 139-671, NEW ISSUE (ERRATA CORRIGE)	ATA 26- FIRE EXTINGUISHER REPLACEMENT (ERRATA CORRIGE)	-	-	-/NOT APPLICABLE	TIC-AW139-21-0373 NOT APPLICABLE DUE TO COMPONENT FIRE EXTINGUISHER P/N P3APP003010A NOT FITTED ON AIRCRAFT. (FITTED WITH PN P3APP003010D)

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	14
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	SB NO. 139-641, NEW ISSUE	ATA 25 - COLLECTIVE EMERGENCY LIFE-RAFT NEW HANDLE COVER	-	-	-/NOT APPLICABLE	REFER TIC-AW139-21-0372. NOT APPLICABLE DUE TO COMPONENT KIT EMERGENCY FLOAT AND LIFERAFTS P/N 3G9560F0011 NOT INSTALLED ON AIRCRAFT.
Standard SBs	SB NO. 139-515 REV B	ATA 46 - "PRIMUS EPIC®" FLIGHT SOFTWARE RELEASE 7.12.2 & 7.14.2 UPGRADE	-	-	-/NOT APPLICABLE	TIC-AW139-21-0353 DATED 06 OCTOBER 2021. PART I: NOT APPLICABLE DUE TO AIRCRAFT S/N NOT AFFECTED. PART II: NOT APPLICABLE DUE TO AIRCRAFT S/N NOT AFFECTED. PART III: NOT APPLICABLE DUE TO COMPONENT PRIMUS EPIC FLIGHT SOFTWARE RELEASE NOT AFFECTED. PART IV: NOT APPLICABLE DUE TO COMPONENT PRIMUS EPIC FLIGHT SOFTWARE RELEASE NOT AFFECTED. PART V: NOT APPLICABLE DUE TO COMPONENT PRIMUS EPIC FLIGHT SOFTWARE RELEASE NOT AFFECTED. PART VI: NOT APPLICABLE DUE TO COMPONENT PRIMUS EPIC FLIGHT SOFTWARE RELEASE NOT AFFECTED. COMPLIANCE IS AT CUSTOMER'S OPTION.
Standard SBs	SB NO. 139-642, REV A PART I	ATA 64 - TAIL ROTOR HEAD INSPECTION AND MODIFICATION	-	-	-/COMPLIED WITH	TIC-AW139-21-0349 DATED 28 SEPTEMBER 2021 PART I: APPLICABLE DUE TO AIRCRAFT TYPE CARRIED OUT: WP-PME-20-1440 ON 03.08.2020 AT 197:40 AFH
Standard SBs	SB NO. 139-660	ATA 46 - "PRIMUS EPIC" FLIGHT SOFTWARE RELEASE UPGRADE FROM PHASE 7.12 & 7.14 TO PHASE 7.12.2 & 7.14.2	-	-	-/OPTIONAL	TIC-AW139-21-0348 DATED 28 SEPTEMBER 2021 APPLICABLE DUE TO COMPONENT PRIMUS EPIC FLIGHT SOFTWARE RELEASE AFFECTED. COMPLIANCE AT CUSTOMER'S OPTION.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	15
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	SB NO. 139-670, NEW ISSUE	ATA 11 - ADDITIONAL MARKING PLACARD INSTALLATION	-	-	-/NOT APPLICABLE	REFER TO TIC-AW139-21-0347. NOT APPLICABLE DUE TO AIRCRAFT S/N NOT AFFECTED
Standard SBs	SB NO. 139-596, REVISION A	ATA 21 - INSTALLATION OF INSULATION TUBES ON ECS PIPE	-	-	-/NOT APPLICABLE	TIC-AW139-21-0346 DATED 28 SEPTEMBER 2021 NOT APPLICABLE DUE TO COMPONENT AIR CONDITIONING PART NUMBER 3G2150A04211, OR PART NUMBER 3G2150A04811, OR PART NUMBER 3G2150A05011, OR PART NUMBER 3G2150A05411, OR PART NUMBER 3G2150A05611 AND SUBSEQUENT NOT FITTED ON AIRCRAFT. COMPLIANCE: AT CUSTOMER'S OPTION
Standard SBs	SB NO. 139-577 PART I, NEW ISSUE	ATA 53 - LOWER INSPECTION COVER INSTALLATION	-	-	-/NOT APPLICABLE	TIC-AW139-21-0345 DATED 28 SEPTEMBER 2021 PART I: NOT APPLICABLE DUE TO AIRCRAFT SERIAL NUMBER NOT AFFECTED COMPLIANCE: AT CUSTOMER'S OPTION
Standard SBs	SB 139-675 NEW ISSUE	ATA 97 - KIT CABIN CAMERA SOFT LINER INSTALLATION	-	-	-/NOT APPLICABLE	TIC-AW139-21-0344 DATED 21 SEPTEMBER 2021 NOT APPLICABLE DUE TO AIRCRAFT SERIAL NUMBER NOT AFFECTED
Standard SBs	SB 139-656 NEW ISSUE	ATA 21 - INSTALLATION OF ENVIRONMENTAL CONTROL SYSTEM (ECS) HIGH EFFICIENCY PARTICULATE AIR (HEPA) FILTER	-	-	-/NOT APPLICABLE	PLEASE REFER TO TIC-AW139-21-0341 NOT APPLICABLE DUE TO AIRCRAFT SERIAL NUMBER NOT AFFECTED
Standard SBs	SBEA NO. 139-679, NEW ISSUE	ATA 25 - HOIST RATED LOAD CHECK (BREEZE)	-	-	-/NOT APPLICABLE	TIC-AW139-21-0267 NOT APPLICABLE DUE FITTED WITH GOODRICH HOIST (REFER LOG CARD/EQUIPMENT LIST)
Standard SBs	SB NO. 139-348, REV A PART III	ATA 34 - KIT TCAS II INSTALLATION	-	-	-/OPTIONAL	TIC-AW139-21-0259 DATED 13 JULY 2021 PART III: APPLICABLE DUE TO AIRCRAFT SERIAL NUMBER AFFECTED

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	16
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	SB NO. 139-348, REV A PART II	ATA 34 - KIT TCAS II INSTALLATION	-	-	-/OPTIONAL	TIC-AW139-21-0259 DATED 13 JULY 2021 PART II: APPLICABLE DUE TO AIRCRAFT SERIAL NUMBER AFFECTED
Standard SBs	SB NO. 139-348, REV A PART I	ATA 34 - KIT TCAS II INSTALLATION	-	-	-/NOT APPLICABLE	TIC-AW139-21-0259 DATED 13 JULY 2021 PART I: NOT APPLICABLE DUE TO AIRCRAFT SERIAL NUMBER NOT AFFECTED
Standard SBs	SB 139-667 NEW ISSUE	ATA 24 - AUXILIARY OVERHEAD PANEL AND INTERSEAT CONSOLE MODIFICATIONS	-	-	-/NOT APPLICABLE	TIC-AW139-21-0262 DATED 13 JULY 2021 NOT APPLICABLE DUE TO AIRCRAFT SERIAL NUMBER NOT AFFECTED
Standard SBs	SB NO. 139-271, REVISION A (PART III)	ATA 23 - INSTALLATION OF KIT RADIO V/UF FLEXCOMM II P/N 3G2310F00111	-	-	-/OPTIONAL	TIC-AW139-21-0260 DATED 13 JULY 2021 PART III: APPLICABLE DUE TO AIRCRAFT SERIAL NUMBER AFFECTED
Standard SBs	SB NO. 139-666, NEW ISSUE	ATA 23 - KIT SATCOM FLIGHTCELL DZMX (4G) INSTALLATION	-	-	-/NOT APPLICABLE	TIC-AW139-21-0261 OPTIONAL SB - NOT APPLICABLE DUE TO AIRCRAFT S/N NOT AFFECTED
Standard SBs	SB NO. 139-665 REV A	ATA 34 - EGPWS INSTALLATION, ATA 34 - ENHANCED GROUND PROXIMITY WARNING SYSTEM INSTALLATION	-	-	-/OPTIONAL	TIC-AW139-21-0258 OPTIONAL SB - APPLICABLE DUE TO AIRCRAFT S/N AFFECTED
Standard SBs	SB NO. 139-658, NEW ISSUE	ATA 23 - SATCOM FLIGHTCELL DZMX (4G) RETROMOD	-	-	-/NOT APPLICABLE	TIC-AW139-21-0256 NOT APPLICABLE DUE TO AIRCRAFT S/N NOT AFFECTED
Standard SBs	SB NO. 139-663, NEW ISSUE	ATA 30 - WIPER BLADESPRAY NOZZLE REPLACEMENT	-	-	-/NOT APPLICABLE	TIC-AW139-21-0257 NOT APPLICABLE DUE TO AIRCRAFT NOT FITTED WITH COMPONENT KIT WINDSHIELD WASHING P/N 4G3040F00116, WIPER BLADE SPRAY NOZZLE P/N 3G3040V01151 & WIPER BLADE ASSY P/N 3G3040A02931 OR P/N 3G3040A03031.
Standard SBs	SB NO. 139-518, NEW ISSUE	ATA 33 - HELICOPTER EMERGENCY EXIT LIGHTS SYSTEM INSTALLATION	-	-	-/NOT APPLICABLE	TIC-AW139-21-0247 OPTIONAL SB - NOT APPLICABLE DUE TO AIRCRAFT S/N NOT AFFECTED
Standard SBs	SB NO. 139-559, NEW ISSUE PART III	ATA 71 - FIREWALLS RETROMOD	-	-	-/NOT APPLICABLE	TIC-AW139-21-0246 OPTIONAL SB - PART III: NOT APPLICABLE DUE TO AIRCRAFT S/N NOT AFFECTED

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	17
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	SB NO. 139-674, NEW ISSUE	ATA 93 - AIRCRAFT SURVIVABILITY EQUIPMENT (ASE) RETROMOD	-	-	-/NOT APPLICABLE	TIC-AW139-21-0245 NOT APPLICABLE DUE TO AIRCRAFT S/N NOT AFFECTED
Standard SBs	SB NO. 139-625, NEW ISSUE	ATA 33 - UTILITY LIGHT IMPROVEMENT	-	-	-/NOT APPLICABLE	TIC-AW139-21-0243 NOT APPLICABLE DUE TO COMPONENT NVG UTILITY LIGHT P/N 3G3310A00231 OR LIGHT ASSY P/N 90-004-1 NOT EQUIPPED ON AIRCRAFT.
Standard SBs	SB NO. 139-455 PART IV, REVISION A	ATA 53 - TRANSMISSION DECK AND MGB REINFORCEMENT FITTINGS REPLACEMENT	-	-	-/OPTIONAL	TIC-AW139-21-0237 DATED 08 JUNE 2021 PART IV: APPLICABLE DUE TO AIRCRAFT SERIAL NUMBER AFFECTED.
Standard SBs	SB NO. 139-636 ,NEW ISSUE	ATA 78 - REAR FIREWALL MODULE ASSY RETROMOD INSTALLATION	-	-	-/OPTIONAL	TIC-AW139-21-0232 DATED 12 MAY 2021 APPLICABLE TO THIS AIRCRAFT WITH THIS SERIAL NUMBER. AIRCRAFT IS FITTED WITH PART NUMBER 3G7810A02033, PART NUMBER 3G7810A02034 AND PART NUMBER 3G7810A02035. COMPLIANCE TIME AT CUSTOMER OPTION.
Standard SBs	SB NO. 139-578, NEW ISSUE	ATA 23 KIT RADIO MOTOROLA XiR 8268 PROVISION INSTALLATION	-	-	-/NOT APPLICABLE	TIC-AW139-21-0226 DATED 27 APRIL 2021 OPTIONAL SB - NOT APPLICABLE DUE TO AIRCRAFT S/N NOT AFFECTED
Standard SBs	SB NO. 139-553, REVISION A	ATA 23 - KIT RADIO MOTOROLA XiR INSTALLATION	-	-	-/OPTIONAL	TIC-AW139-21-0224 DATED 27 APRIL 2021 APPLICABLE DUE TO AIRCRAFT SERIAL NUMBER AFFECTED
Standard SBs	SB NO. 139-575, NEW ISSUE	ATA 23 COMMUNICATION CUSTOMIZATION RETROMOD	-	-	-/NOT APPLICABLE	TIC-AW139-21-0225 OPTIONAL SB - NOT APPLICABLE DUE TO AIRCRAFT S/N NOT AFFECTED
Standard SBs	SB NO. 139-629, REVISION A	ATA 95 FORWARD FLOATS COVERS UPGRADE	-	-	-/NOT APPLICABLE	TIC-AW139-21-0220 DATED 21 APRIL 2021. NOT APPLICABLE DUE TO COMPONENT LEFT HAND FORWARD COVER ASSY PART NUMBER 3G9560V04131 & RIGHT HAND FORWARD COVER ASSY PART NUMBER 3G9560V04231 NOT FITTED ON AIRCRAFT. (APPLICABLE FOR FLOAT DART SYSTEM)

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	18
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	ASB NO. 139-609, REVISION A (EASA AD 2020-0011R1)	ATA 63 - MGB BEARING LOCK-NUT REPLACEMENT	0.00	6000.00	-/TO BE COMPLIED	TIC-AW139-21-0218 DATED 14 APRIL 2021. APPLICABLE DUE TO AFFECTED MAIN GEARBOX PART NUMBER 3G6320A00135 FITTED ON AIRCRAFT.
Standard SBs	ASB NO. 139-609, REVISION A (EASA AD 2020-0011R1)	ATA 63 - MGB BEARING LOCK-NUT REPLACEMENT	0.00	28000.00	-/TO BE COMPLIED	TIC-AW139-21-0218 DATED 14 APRIL 2021. APPLICABLE DUE TO AFFECTED MAIN GEARBOX PART NUMBER 3G6320A00135 FITTED ON AIRCRAFT.
Standard SBs	SB NO. 139-613, NEW ISSUE	ATA 95 - IMPROVEMENT OF EMERGENCY FLOATS RIGID COVER	-	-	-/OPTIONAL	TIC-AW139-21-0216 APPLICABLE DUE TO COMPONENT FLOAT RIGID COVERS P/N & S/N LISTED IN TABLE 1 OF THE SB FITTED ON AIRCRAFT
Standard SBs	SB NO. 139-240, REVISION D	ATA 67 - INSTALLATION OF PILOT/CO-PILOT COLLECTIVE GRIP P/N 3G6711V00951 AND P/N 3G6711V01051	-	-	-/OPTIONAL	TIC-AW139-21-0214 DATED 12 APRIL 2021 APPLICABLE DUE TO AIRCRAFT SERIAL NUMBER AFFECTED.
Standard SBs	SB NO. 139-646, NEW ISSUE	ATA 23 - RADIO HARRIS KIT INSTALLATION	-	-	-/Required	
Standard SBs	SB NO. 139-587, NEW ISSUE	ATA 30 - WINDSHIELD WASHING SYSTEM INSTALLATION	-	-	-/OPTIONAL	TIC-AW139-21-0206 APPLICABILITY: OPTIONAL SB AND WP# 9M-PME-6517 ISSUE FOR PHYSICAL CX
Standard SBs	SB NO. 139-588, NEW ISSUE	ATA 28 - AUXILIARY LONGITUDINAL FUEL TANK COMPLETION	-	-	-/NOT APPLICABLE	TIC-AW139-21-0205 COMPLIANCE: OPTIONAL SB - NOT APPLICABLE DUE TO A/C SERIAL NUMBER NOT AFFECTED
Standard SBs	SB NO. 139-581, NEW ISSUE	ATA 21 - VENTILATION INSULATION IMPROVEMENT	-	-	-/NOT APPLICABLE	TIC-AW139-21-0207 COMPLIANCE: NOT APPLICABLE DUE TO A/C SERIAL
Standard SBs	SB NO. 139-617, NEW ISSUE	ATA 62 - MAIN ROTOR BLADE LIGHTNING STRIP CORROSION PROTECTION IMPROVEMENT	24/03/2022	-	-/COMPLIED WITH	TIC-AW139-21-0208 DATED 31 MARCH 2021 APPLICABLE DUE TO MAIN ROTOR BLADE PART NUMBER AND SERIAL NUMBER CARRIED OUT IN 9M-PME-8555 (AJL 05938) AT 1067:05 FH ON 24/03/2022

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	19
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	SB NO. 139-574, NEW ISSUE	ATA 24 LH UTILITY CB PANEL RETROMOD	-	-	-/NOT APPLICABLE	TIC-AW139-21-0079 DATED 11 MARCH 2021 COMPLIANCE: OPTIONAL SB AND NOT APPLICABLE DUE TO AIRCRAFT SN NOT AFFECTED TO ALL AW139 UNDER CAMO
Standard SBs	SB NO. 139-605, REVISION A	ATA 32 - ELECTRICAL WHEEL BRAKE CABLE ASSY REPLACEMENT	-	-	-/NOT APPLICABLE	TIC-AW139-21-0078 DATED 10 MARCH 2021 COMPLIANCE: NOT APPLICABLE DUE COMPONENT KIT POWERED PARKING BRAKE MODULE P/N 3G3240F00111 NOT FITTED ON AIRCRAFT AND NOT COMPLY WITH SB 139-137 BEFORE ITS REVISION C
Standard SBs	SB NO. 139-464, NEW ISSUE	ATA 93 - INSTALLATION OF KIT SKYFORCE DIGITAL MAP	-	-	-/OPTIONAL	TIC-AW139-21-0037 DATED 01 MARCH 2021 APPLICABLE DUE TO AIRCRAFT SERIAL NUMBER AFFECTED
Standard SBs	SB NO. 139-462, NEW ISSUE	ATA 25 - INSTALLATION OF ACTIVE NOISE REDUCTION HEADSET	-	-	-/OPTIONAL	TIC-AW139-21-0034 DATED 01 MARCH 2021 APPLICABLE TO AIRCRAFT SERIAL NUMBER.
Standard SBs	SB NO 139-474, NEW ISSUE	ATA 97 - INSTALLATION OF MAX VIZ UNDER FUSELAGE	-	-	-/OPTIONAL	TIC-AW139-21-0036 DATED 01 MARCH 2021 APPLICABLE DUE TO AIRCRAFT SERIAL NUMBER
Standard SBs	SB NO. 139-463, NEW ISSUE	ATA 46 - INSTALLATION OF KIT CENTRAL DISPLAY	-	-	-/OPTIONAL	TIC-AW139-21-0035 DATED 01 MARCH 2021 APPLICABLE DUE TO AIRCRAFT SERIAL NUMBER AFFECTED - COMPONENT KIT CENTRAL DISPLAY SIRIO PANEL PART NUMBER 4G630F00312 ALREADY FITTED TO AIRCRAFT

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	20
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	SB NO. 139-548, REVISION A - PART 1	ATA 30 - LH VERNIER ICE DETECTOR WITH LIGHT	-	-	-/NOT APPLICABLE	TIC-AW139-21-0033 DATED 26 FEBRUARY 2021 PART I : NOT APPLICABLE DUE TO AIRCRAFT SERIAL NUMBER NOT AFFECTED PART II: NOT APPLICABLE DUE TO AIRCRAFT SERIAL NUMBER NOT AFFECTED PART III: NOT APPLICABLE DUE TO AIRCRAFT SERIAL NUMBER NOT AFFECTED
Standard SBs	SB NO. 139-643, NEW ISSUE	ATA 25 - SINGLE TO DOUBLE HOIST CONVERSION	-	-	-/NOT APPLICABLE	TIC-AW139-21-0030 DATED 22 FEBRUARY 2021 NOT APPLICABLE DUE TO AIRCRAFT SERIAL NUMBER NOT AFFECTED COMPLIANCE: AT CUSTOMER'S OPTION
Standard SBs	SB NO. 139-545 REVISION A	ATA 78 - EXHAUST RETROMOD	-	-	-/OPEN	TIC-AW139-21-0075 DATED 08 MARCH 2021 TIC OPEN. COMPLIANCE AT CUSTOMER'S OPTION.
Standard SBs	ASB NO. 139-662, NEW ISSUE	ATA 25 - LIFERAFT RESERVOIR INSPECTION & REPLACEMENT	-	-	-/NOT APPLICABLE	TIC-AW139-21-0024 DATED 15 FEBRUARY 2020. NOT APPLICABLE DUE TO COMPONENT LIFERAFT RESERVOIR PART NUMBER 3G2560V01251 AND PART NUMBER 3G2560V01951 NOT FITTED ON AIRCRAFT.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	21
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	ASB NO. 139-648, REVISION A	ATA 25 - LIFERAFT RESERVOIR INSPECTION AND REPLACEMENT	-	-	-/NOT APPLICABLE	<p>TIC-AW139-21-0023 DATED 15 FEBRUARY 2021</p> <p>PART I: NOT APPLICABLE DUE TO COMPONENT LIFERAFT RESERVOIR PART NUMBER 3G2560V01251 AND PART NUMBER 3G2560V01951 NOT FITTED ON AIRCRAFT</p> <p>PART II: NOT APPLICABLE DUE TO COMPONENT KIT EMERGENCY FLOAT PART NUMBER 4G9560F00111 AND PART NUMBER 4G9560F00211 NOT FITTED ON AIRCRAFT</p> <p>PART III: NOT APPLICABLE DUE TO COMPONENT KIT EMERGENCY FLOAT PART NUMBER 4G9560F00111 AND PART NUMBER 4G9560F00211 NOT FITTED ON AIRCRAFT</p> <p>AIRCRAFT FITTED WITH EMERGENCY FLOAT KIT PART NUMBER 3G9560F00212. (REFER ATTACHEMENT)</p>
Standard SBs	SB NO. 139-543, NEW ISSUE	ATA 71 - TUNNEL ASSY AND FIREWALLS RETROMOD	-	-	-/OPTIONAL	<p>TIC-AW139-21-0018 DATED 05 FEBRUARY 2021</p> <p>PART I: REQUEST FOR PHYSICAL INSPECTION FOR COMPONENT REAR FIREWALL MODULE.</p> <p>PART II: REQUEST FOR PHYSICAL INSPECTION FOR COMPONENT TUNNEL ASSY AND REAR EXHAUST MODULES.</p> <p>COMPLIANCE: AT CUSTOMER'S OPTION</p>

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	22
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	SB NO. 139-630, NEW ISSUE	ATA 46 COMPLETION OF KIT PRIMUS EPIC PHASE 8 SOFTWARE RELEASE INSTALLATION	-	-	-/NOT APPLICABLE	TIC-AW139-21-0007 DATED 26 JANUARY 2021. NOT APPLICABLE DUE ONLY APPLICABLE TO AIRCRAFT SERIAL NUMBER NOT INCLUDED IN SERVICE BULLETIN SERIAL NUMBER EFFECTIVITY (SERVICE BULLETIN SERIAL NUMBER EFFECTIVITY: 31869).
Standard SBs	SB NO 139-554, REVISION B	ATA 28 FEEDING LINE FUEL DRAIN INSTALLATION.	-	-	-/NOT APPLICABLE	TIC-AW139-20-214 DATED 24 DECEMBER 2020. NOT APPLICABLE DUE AIRCRAFT NOT OPERATED UNDER ANAC ADMINISTRATION
Standard SBs	SB NO. 139-639, NEW ISSUE	ATA 53 UPPER DECK PANEL REINFORCEMENT	-	-	-/OPTIONAL	TIC-AW139-20-215 DATED 24 DECEMBER 2020. APPLICABLE TO 9M-PME (31855) DUE TO AIRCRAFT SERIAL NUMBER AND COMPONENT KIT AIR CONDITIONING PART NUMBER 3G2150F00512 FITTED ON AIRCRAFT.
Standard SBs	SB NO. 139-622, NEW ISSUE	ATA 28 - KIT CLOSED CIRCUIT REFUELLING RECEIVER (CCRR)	-	-	-/OPTIONAL	TIC-AW139-20-211 DATED 22 DECEMBER 2020. APPLICABLE DUE TO AIRCRAFT SERIAL NUMBER AFFECTED. COMPLIANCE AT CUSTOMER'S OPTION.
Standard SBs	SB NO. 139-157, REV C	ATA 46 - "PRIMUS EPIC®" FLIGHT SOFTWARE RELEASE 5.6.0	-	-	-/NOT APPLICABLE	TIC-AW139-20-196 DATED 26 NOVEMBER 2020. NOT APPLICABLE DUE TO AIRCRAFT SERIAL NUMBER. COMPLIANCE: AT CUSTOMER'S OPTION
Standard SBs	SB NO. 139-284 REV F	ATA 31 - INSTALLATION OF FDR AND RIPS VARIANTS P/N 3G3106P01311 AND P/N 3G3106P01312	-	-	-/NOT APPLICABLE	TIC-AW139-20-197 DATED 26 NOVEMBER 2020. PART I: NOT APPLICABLE DUE TO AIRCRAFT SERIAL NUMBER. PART II: NOT APPLICABLE DUE TO AIRCRAFT SERIAL NUMBER.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	23
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	SB NO. 139-620, REVISION B PART II	ATA 31 - INSTALLATION OF MPFR P/N D51615-142-090	-	-	-/NOT APPLICABLE	TIC-AW139-20-198 DATED 26 NOVEMBER 2020. PART II: APPLICABLE IF COMPLIANCE TO PART I OF THIS SERVICE BULLETIN
Standard SBs	SB NO. 139-620, REVISION B PART I	ATA 31 - INSTALLATION OF MPFR P/N D51615-142-090	-	-	-/NOT APPLICABLE	TIC-AW139-20-198 DATED 26 NOVEMBER 2020. PART I: NOT APPLICABLE DUE TO COMPONENT MPFR PART NUMBER D51615-1142 FITTED ON AIRCRAFT.
Standard SBs	SB NO. 139-584, NEW ISSUE	ATA 25 - KIT PILOT/COPILOT GENERAL HOLDERS	-	-	-/OPTIONAL	TIC-AW139-20-191 DATED 13 NOVEMBER 2020. APPLICABLE TO 9M-PME (31855) DUE TO COMPONENTS CHART HOLDER PART NUMBER 4G2510F00112. COMPLIANCE: AT CUSTOMER'S OPTION
Standard SBs	SB NO. 139-655, NEW ISSUE	ATA 63 - MGB INPUT MODULES MARKING	-	-	-/NOT APPLICABLE	TIC-AW139-20-190 DATED 13 NOVEMBER 2020 NOT APPLICABLE DUE TO COMPONENT INPUT MODULE ASSY SERIAL NUMBER LISTED IN TABLE 1 ARE NOT FITTED ON AIRCRAFT
Standard SBs	SB NO. 139-512, NEW ISSUE	ATA 53 TAIL PLANE FITTING BUSHINGS INSPECTION	-	-	-/NOT APPLICABLE	TIC-AW139-20-185 DATED 22 OCTOBER 2020 NOT APPLICABLE TO 9M-PME (31855) DUE TO FITTING ASSEMBLIES HAVE NEVER BEEN REPLACED IN SERVICE.
Standard SBs	SB NO. 139-634, NEW ISSUE	ATA 34 - ENHANCED GROUND PROXIMITY WARNING SYSTEM (EGPWS)	-	-	-/OPTIONAL	TIC-AW139-20-186 DATED 22 OCTOBER 2020. APPLICABLE TO 9M-PME (31855), DUE TO COMPONENT EGPWS PART NUMBER 965-1595-030 FITTED ON AIRCRAFT. COMPLIANCE AT CUSTOMER'S OPTION.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	24
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	SBA 139-637 REV. A (EASA AD 2020-0131)	ATA 25 HOIST CABLE CUTTER FRAME INSTALLATION			-	-/COMPLIED WITH TIC-AW139-20-187 DATED 22 OCTOBER 2020. COMPLIED WITH PREVIOUS REVISION (SERVICE BULLETIN 139-637 NEW ISSUE DATE 05.06.2020). REFER WP-PME-20-1115 FOR COMPLIANCE WORKPACK. WP-PME-20-1115 AT 265:00 FLIGHT HOURS ON 03/09/2020 (AJL 03213)
Standard SBs	SB NO. 139-358 REV. B	ATA 71 - EXHAUST DUCTS AND REAR FIREWALL RETROMOD			-	-/NOT APPLICABLE TIC-AW139-20-180 DATED 19 OCTOBER 2020. NOT APPLICABLE DUE TO COMPONENT NOT FITTED ON AIRCRAFT.
Standard SBs	SB NO.139-599 PART II	ATA 18 - ACTIVE VIBRATION CONTROL SYSTEMS (AVCS) OMNI CONTROL PANEL & SOFTWARE UPGRADE			-	-/OPTIONAL TIC-AW139-20-181 DATED 19 OCTOBER 2020. APPLICABLE TO 9M-PME (31855) DUE TO AIRCRAFT SERIAL NUMBER AND COMPONENT AVCS CC APPLICATION SOFTWARE PART NUMBER 3G1830VA0100 AND COMPONENT CGF COMMAND LANE SOFTWARE PART NUMBER 3G1830VS0100 FITTED ON AIRCRAFT.
Standard SBs	SB 139-635 REV./	ATA 29 TORQUE CHECK OF THE POWER CONTROL MODULE BOLTS			-	-/COMPLIED WITH TIC-AW139-20-162 DATED 22 SEPTEMBER 2020. WP-PME-20-1901 @ 333:10 FH ON 08/11/2020 (AJL 03249)
Standard SBs	SB 139-635 REV./	ATA 29 TORQUE CHECK OF THE POWER CONTROL MODULE BOLTS	08/11/2020		-	-/COMPLIED WITH TIC-AW139-20-162 DATED 22 SEPTEMBER 2020. WP-PME-20-1901 @ 333:10 FH ON 08/11/2020 (AJL 03249)
Standard SBs	ASB NO. 139-633, REV A	ATA 25 - RESTRICTION IN FORWARD FACING PASSENGER SEATS INSTALLATION			-	-/NOT APPLICABLE TIC-AW139-20-131 DATED 03 SEPTEMBER 2020. NOT APPLICABLE DUE TO AIRCRAFT SEAT CONFIGURATION NOT INSTALLED FACING FORWARD.
Standard SBs	SB NO. 139-631, NEW ISSUE	ATA 33 - HELICOPTER EMERGENCY EXIT LIGHT SYSTEM (HEELS) INSTALLATION			-	-/NOT APPLICABLE TIC-AW139-20-129 DATED 01 SEPTEMBER 2020. NOT APPLICABLE DUE TO AIRCRAFT SERIAL NUMBER.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	25
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	SB NO. 139-583 (PART I)	ATA 62 - ROTATING SWASHPLATE ASSY P/N 3G6230A00333	-	-	-/NOT APPLICABLE	TIC-AW139-20-125 DATED 13 AUGUST 2020. PART I AND II: NOT APPLICABLE DUE TO COMPONENT PART NUMBER 3G6230A00333 ALREADY FITTED ON AIRCRAFT. PART III: NOT APPLICABLE DUE TO AIRCRAFT SERIAL NUMBER.
Standard SBs	SB NO.139-585 (PART II)	ATA 95 - RIGHT AFT FLOAT INSPECTION AND BAGGAGE FLOOR PANEL RETROMODIFICATION	-	-	-/NOT APPLICABLE	TIC-AW13-20-102 DATED 26 JUNE 2020. NOT APPLICABLE DUE TO AIRCRAFT SERIAL NUMBER.
Standard SBs	SB NO. 139-334 REV B	ATA 23 - VHF/FM NAT NPX138 KIT P/N 4G2310F02411	-	-	-/OPTIONAL	TIC-AW139-20-103 DATED 26 JUNE 2020. APPLICABLE DUE TO AIRCRAFT SERIAL NUMBER. AT CUSTOMER'S OPTION
Standard SBs	SB NO. 139-471	ATA 52 - SOFT COVER FAIRING LIFERAFT RETROMOD	-	-	-/NOT APPLICABLE	TIC-AW139-20-104 DATED 26 JUNE 2020. NOT APPLICABLE DUE TO COMPONENT PART NUMBER NOT FITTED ON AIRCRAFT.
Standard SBs	SB NO 139-544, REV A	ATA 25 - INSTALLATION OF KIT LIFE RAFTS	-	-	-/OPTIONAL	TIC-AW139-20-105 DATED 26 JUNE 2020. APPLICABLE DUE TO AIRCRAFT SERIAL NUMBER. COMPLIANCE AT CUSTOMER'S OPTION
Standard SBs	SB139-626 REV./	ATA 23 PROVISION INSTALLATION FOR KIT SATCOM SKYCONNECT ON REPLACEMENT TAIL ASSEMBLY	-	-	-/NOT APPLICABLE	TIC-AW139-20-099 DATED 18 JUNE 2020. NOT APPLICABLE KIT SATCOM SKYCONNECT PART NUMBER 4G2310F01115 NOT FITTED ON AIRCRAFT.
Standard SBs	SB NO. 139-627, NEW ISSUE	ATA 93 PROVISION INSTALLATION FOR KIT FLIR SAFIRE 380 HD ON REPLACEMENT TAIL ASSEMBLY	-	-	-/NOT APPLICABLE	TIC-AW139-20-100 DATED 18 JUNE 2020. NOT APPLICABLE DUE FLIR KIT SAFIRE HD PART NUMBER 4G9350F0111 NOT FITTED ON AIRCRAFT.
Standard SBs	SB139-628 REV./	ATA 23 PROVISION INSTALLATION FOR KIT HF ON REPLACEMENT TAIL ASSEMBLY	-	-	-/NOT APPLICABLE	TIC-AW139-20-101 DATED 18 JUNE 2020 (OPTIONAL SB) NOT APPLICABLE DUE TO KIT COMPLETE PROVISIONS PART NUMBER 4G2310A01314 ALREADY FITTED ON AIRCRAFT.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	26
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	BT 139-557	ATA 25 - HOIST CABLE CUTTER FRAME INSTALLATION	-	-	-/OPTIONAL	AT CUSTOMER'S OPTION. NOT REQUESTED BY CONTRACTED WORK ORDER. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	SB139-557 REV. A	ATA 25 HOIST CABLE CUTTER FRAME INSTALLATION	-	-	-/CANCELLED	TIC-AW139-21-0016 SB139-557 REV. A IS TO CANCELLED SB139-557 REV./
Standard SBs	BT 139-396 REV. B	ATA 25 - INSTALLATION OF KIT SINGLE HOIST GOODRICH	-	-	-/NOT APPLICABLE	TIC-AW139-20-095 DATED 10 JUNE 2020. NOT APPLICABLE TO AIRCRAFT SERIAL NUMBER. COMPLIANCE AT CUSTOMER'S OPTION.
Standard SBs	SB NO. 139-608, NEW ISSUE	ATA 53 INSPECTION OF BL 275 (LH/RH) AT STA 3500	-	-	-/NOT APPLICABLE	TIC-AW139-20-087 DATED 15 MAY 2020. NOT APPLICABLE TO ALL AIRCRAFT SERIAL NUMBER.
Standard SBs	SB NO. 139-148, REVISION A	ATA 25 - COMPLETE PROVISION FOR EMS (MEDEVAC) P/N 4G2564F00211	-	-	-/NOT APPLICABLE	TIC-AW139-20-086 DATED 14 MAY 2020 NOT APPLICABLE DUE TO AIRCRAFT SERIAL NUMBER.
Standard SBs	SB NO. 139-537, NEW ISSUE	ATA 95 - DART EMERGENCY FLOTATION LIFE RAFT IMPROVEMENT	-	-	-/NOT APPLICABLE	TIC-AW139-20-080 DATED 02 MAY 2020. NOT APPLICABLE DUE TO COMPONENT P/N 4G9560F00111 OR P/N 4G9560F00211 NOT FITTED ON AIRCRAFT.
Standard SBs	SB139-540 REV./	ATA 25 - BREEZE HOIST CHANGE FROM 90M TO 75M	-	-	-/NOT APPLICABLE	TIC-AW139-20-076 DATED 26 APRIL 2020 NOT APPLICABLE DUE FITTED WITH GOODRICH HOIST. COMPLIANCE AT CUSTOMER'S REQUEST.
Standard SBs	SB NO. 139-604 REV./	ATA 66 INSTALLATION OF KIT MOORING	-	-	-/OPTIONAL	TIC-AW139-20-071 DATED 18 APRIL 2020 APPLICABLE TO AIRCRAFT SERIAL NUMBER. COMPLIANCE AT CUSTOMER'S REQUEST.
Standard SBs	SB NO. 139-570, NEW ISSUE	ATA 95 EFS FLOAT ASSY INFLATION SYSTEM NEW THERMOMANOMETER	-	-	-/NOT APPLICABLE	TIC-AW139-20-069 DATED 10 APRIL 2020 NOT APPLICABLE DUE TO COMPONENT FITTED ON AIRCRAFT. COMPLIANCE AT CUSTOMER'S REQUEST.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	27
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	BT 139-132 REV A	COLLECTIVE EMERGENCY LIFERAFT CONVERSION.	-	-	-/NOT APPLICABLE	TIC-AW139-20-067 DATED 07 APRIL 2020. REFERENCE: TIC-AW139-20-060 DATED 27 MARCH 2020. NOT APPLICABLE DUE TO KIT NOT INSTALLED.
Standard SBs	SB NO. 139-550, NEW ISSUE	ATA 93 - INSTALLATION OF KIT FLIR WESCAM MX-10	-	-	-/NOT APPLICABLE	TIC-AW139-20-062 DATED 31 MARCH 2020. NOT APPLICABLE TO AIRCRAFT SERIAL NUMBER. COMPLIANCE AT CUSTOMER'S OPTION
Standard SBs	SB139-551 REVISION A	ATA 93 - INSTALLATION OF KIT FLIR WESCAM MX-10	-	-	-/NOT APPLICABLE	REFER TO TIC-AW139-20-063. NOT APPLICABLE TO AIRCRAFT S/N. COMPLIANCE AT CUSTOMERS OPTION
Standard SBs	SB NO. 139-563, NEW ISSUE	ATA 93 - AVIONIC VARIANT	-	-	-/NOT APPLICABLE	REFER TIC-AW139-20-061 DATED 31 MARCH 2020. NOT APPLICABLE TO AIRCRAFT S/N. COMPLIANCE: AT CUSTOMER'S OPTION
Standard SBs	SB NO. 139-595, NEW ISSUE	ATA 52 - COCKPIT DOOR EMERGENCY RELEASE MECHANISM CHECK	-	-	-/NOT APPLICABLE	REFER TIC-AW139-20-058 DATED 26 MARCH 2020. NOT APPLICABLE DUE TO COMPONENT P/N 4G9580F00412 NOT FITTED ON AIRCRAFT. COMPLIANCE: WITHIN AND NOT LATER THAN 50 FLIGHT HOURS OR 2 MONTHS WHICHEVER OCCURS FIRST AFTER THE ISSUE OF THIS SERVICE BULLETIN.
Standard SBs	SB NO. 139-598, NEW ISSUE (PART I & II)	ATA 78 - INSTALLATION OF EXHAUST NOZZLE BLANKET	-	-	-/OPTIONAL	APPLICABLE TO 9M-PMA, 9M-PMB, 9M-PMC, 9M-PMD, 9M-PME DUE TO COMPONENT P/N 3G7800L00732 FITTED ON AIRCRAFT. COMPLIANCE AT CUSTOMER'S OPTION

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	28
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	SB NO. 139-598, NEW ISSUE (PART III & IV)	ATA 78 - INSTALLATION OF EXHAUST NOZZLE BLANKET	-	-	-/OPTIONAL	APPLICABLE TO 9M-PMA, 9M-PMB, 9M-PMC, 9M-PMD & 9M-PME DUE TO COMPONENT P/N 3G7800L00632 FITTED ON AIRCRAFT. COMPLIANCE: AT CUSTOMER'S OPTION.
Standard SBs	SB NO. 139-357, REVISION B	ATA 34 - KIT 2ND GPS P/N 4G3450F00611 OR KIT 2ND SBAS P/N 4G3450F00613	-	-	-/NOT APPLICABLE	TIC-AW139-20-056 DATED 26 MARCH 2020. NOT APPLICABLE DUE TO HELICOPTER SERIAL NUMBER.
Standard SBs	BT 139-580	ATA 64 - FIPS TAIL ROTOR BLADES INSPECTION	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO KIT FIPS NOT INSTALLED. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-573	ATA 31 - KIT HUMS COMPLETION	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-572	ATA 25 - FORWARD FACING 1ST ROW PASSENGER SEATS	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-571	ATA 64 - DUPLEX BEARING P/N 3G6430V00153 RECALL	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO COMPONENT NOT AFFECTED. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-569 REV B PART II	ATA 64 - TAIL ROTOR SLIDER ASSY DETAILED INSPECTION	-	-	-/OPEN	IMMEDIATELY AFTER COMPLIANCE WITH PART I, IF EVIDENCE OF CORROSION IS FOUND DURING THE INSPECTION. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	29
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	SB NO. 139-037 NEW ISSUE	ATA 53 - NLG ACTUATOR FITTING RETRO MODIFICATION	-	-	-/NOT APPLICABLE	REFER TIC-AW139-20-038 DATE ISSUE 09 MARCH 2020. REFER TIC-AW139-20-028 DATE ISSUE 04 MARCH 2020. NOT APPLICABLE TO AIRCRAFT S/N.
Standard SBs	SB 139-083, REVISION A	ATA 25 - FAST ROPING KIT P/N 4G2590F00211.	-	-	-/COMPLIED WITH	REFER TO TIC-AW139-20-023 DATE ISSUE 25 FEBRUARY 2020. APPLICABLE DUE TO COMPONENT ALREADY FITTED ON AIRCRAFT BY MANUFACTURER. COMPLIANCE IS AT CUSTOMER'S OPTION. NOT REQUESTED BY CONTRACTED WORK ORDER.
Standard SBs	SB NO. 139-524 REV A	ATA 25 - LIFERAFT RESERVOIR ASSEMBLY ALIGNMENT LABEL POSITIONING	-	-	-/NOT APPLICABLE	TIC-AW139-20-022 DATE ISSUE 25 FEBRUARY 2020. NOT APPLICABLE DUE TO COMPONENT PART NUMBER NOT FITTED ON AIRCRAFT.
Standard SBs	SB NO. 139-612	ATA 11 - FAST ROPING DECAL REPLACEMENT	-	-	-/COMPLIED WITH	TIC-AW139-20-024 DATED 25 FEBRUARY 2020 APPLICABLE DUE TO COMPONENT PN 4G2590F00211 FITTED ON AIRCRAFT
Standard SBs	SB NO. 139-621, NEW ISSUE	ATA 71- INSTALLATION OF EAPS REMOVABLE PARTS	-	-	-/NOT APPLICABLE	REFER TO TIC-AW139-20-021 DATE ISSUE 25 FEBRUARY 2020. NOT APPLICABLE TO AIRCRAFT SERIAL NUMBER. COMPLIANCE: AT CUSTOMER'S OPTION.
Standard SBs	SB NO. 139-597 NEW ISSUE	ATA 31 - KIT FAMILY HUMS RETROMOD	-	-	-/NOT APPLICABLE	REFER TIC-AW139-20-036 DATE ISSUE 09 MARCH 2020. NOT APPLICABLE TO AIRCRAFT S/N. COMPLIANCE IS AT CUSTOMER'S OPTION.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	30
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	SB NO 139-594, NEW ISSUE (PART I AND II)	ATA 32 - INSPECTION OF MAIN LANDING GEAR ACTUATOR BOLTS	-	-	-/NOT APPLICABLE	REFER TIC-AW139-20-037-PME-004 DATE ISSUE 09 MARCH 2020. NOT APPLICABLE TO AIRCRAFT S/N. COMPLIANCE IS AT CUSTOMER'S OPTION.
Standard SBs	SBA NO. 139-610, NEW ISSUE	ATA 95 - EMERGENCY FLOATATION SYSTEM, FLOAT SUPPLY HOSE INSPECTION OF.	247.83	-	-/COMPLIED WITH	TIC-AW139-20-037-PME-003 DATED 09 MARCH 2020. REFER TO WP-PME-20-1526 @ 247:50 FH ON 27/08/2020 (AJL 03207). NOT APPLICABLE DUE TO SB 025-69-19 HAS BEEN CARRY OUT BY OEM.
Standard SBs	SBA NO. 139-610, NEW ISSUE	ATA 95 - EMERGENCY FLOATATION SYSTEM, FLOAT SUPPLY HOSE INSPECTION OF.	27/08/2020	-	-/COMPLIED WITH	TIC-AW139-20-037-PME-003 DATED 09 MARCH 2020. REFER TO WP-PME-20-1526 @ 247:50 FH ON 27/08/2020 (AJL 03207). NOT APPLICABLE DUE TO SB 025-69-19 HAS BEEN CARRY OUT BY OEM.
Standard SBs	BT 139-593 REV A	ATA 71 - ENGINE MOUNTING RODS REPLACEMENT	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO COMPONENT NOT AFFECTED. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-567 REV B	ATA 63 - MGB BEARING LOCK-NUT REPLACEMENT	0.00	28000.00	-/TO BE COMPLIED	FOR MGB HAVING LOGGED LESS THAN TWENTY EIGHT THOUSAND (28000) LANDINGS FROM NEW: WITHIN TWO THOUSAND (2000) LANDINGS UPON REACHING TWENTY EIGHT THOUSAND (28000) LANDINGS OR AT NEXT OVERHAUL, WHICHEVER OCCURS FIRST. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 03/12/2019.
Standard SBs	BT 139-566	ATA 99 - EWP/CDU SOFTWARE UPGRADE	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	31
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	BT 139-561	ATA 93 - VIDEO CUSTOMIZATION AND CB PANEL REPLACEMENT	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-560	ATA 25 - INSTALLATION OF THE TWO-PIECE DRESS COVER AND CUSHION ONOFFSHORE PASSENGER SEAT	-	-	-/NOT APPLICABLE	HELICOPTER NOT AFFECTED. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-556	ATA 64 - TAIL ROTOR BLADE LIGHTNING STRIPS P/N 3G6410A03053	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO KIT FIPS NOT INSTALLED. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-552	ATA 93 - AVIONIC VARIANT	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-549	ATA 97 - INSTALLATION OF KIT AVALEX DIGITAL VIDEO AUDIO RECORDER	-	-	-/OPTIONAL	AT CUSTOMER'S OPTION. NOT REQUESTED BY CONTRACTED WORK ORDER. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-536	ATA 23 - ICS CABIN STATION 4 REPOSITIONING	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-535	ATA 23 - INSTALLATION OF KIT EXTERNAL LOUDSPEAKERS	-	-	-/OPTIONAL	AT CUSTOMER'S OPTION - NOT REQUESTED BY CONTRACTED WORK ORDER. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	32
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	BT 139-534	ATA 53 - STA 3120 FRAME INSPECTION	-	-	-/NOT APPLICABLE	HELICOPTER NOT AFFECTED BY S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-533	ATA 95 - EFS AFT FLOAT ASSY INFLATION SYSTEM RESET PROCEDURE	-	-	-/NOT APPLICABLE	N/A DUE TO DIFFERENT P/N INSTALLED. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-532	ATA 99 - INSTALLATION OF KIT SIAP AND RWR AND LWR	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-531	ATA 99 - SDU SUPPORT IMPROVEMENT	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-530	ATA 22 - REPLACEMENT OF AUTO FLIGHT TRIM ACTUATOR	-	-	-/NOT APPLICABLE	N/A DUE TO COMPONENT NOT AFFECTED. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-529	ATA 97 - INSTALLATION OF KIT AVALEX DIGITAL VIDEO AUDIO RECORDER	-	-	-/OPTIONAL	AT CUSTOMER'S OPTION - NOT REQUESTED BY CONTRACTED WORK ORDER. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-528	ATA 62 - MAIN ROTOR SLIP RING CONNECTOR MODIFICATION	-	-	-/NOT APPLICABLE	KIT FIPS NOT INSTALLED. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	33
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	BT 139-526 PART I (INITIAL - WITHIN 50FH ONCE REACH 70	ATA 63 - MGB OIL COOLING FAN INSPECTION	640.75	-	-/COMPLIED WITH	<p>WHEN REACH 700 FH, AND THEN REPETITIVE EVERY 200 FH, UNTIL FIRST ACCOMPLISHMENT OF PART II ON THE AFFECTED COMPONENT.</p> <p>INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.</p> <p>9M-PME-6427 @ 640:45 FH ON 27/07/2021 (AJL 04303), TO REPEAT PART I THIS SB EVERY 200FH AFTER THIS INITIAL COMPLIANCE OF PART I UNTIL FIRST COMPLIANCE OF PART II THIS SB (DUE AT 1200 FH)</p> <p>FOR 9M-PME, TERMINATING ACTION FOR PART I WILL BE THE INITIAL COMPLIANCE OF PART II (DUE 1200:00FH)- CARRIED OUT IN</p> <p>INITIAL COMPLIANCE PART 1 9M-PME-6427 @ 640:45 FH ON 27/07/2021 (AJL 04303)</p> <p>REPETITIVE 200 FH FOR PART 1 2ND DUE ON 840:45 FH (CARRIED OUT IN)</p> <p>REPETITIVE 1200 FH FOR PART 1 INITIAL COMPLIANCE (DUE AT 1200:00 FH); 2ND DUE ON 3RD DUE ON 4TH DUE ON</p>
Standard SBs	SB NO. 139-592	ATA 21 - ECS FIRE BLANKET IMPROVEMENT	-	-	-/OPTIONAL	<p>NOT REQUESTED BY CONTRACTED WORK ORDER. COMPLIANCE IS AT CUSTOMER'S OPTION. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 03/12/2019.</p>

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	34
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	BT 139-523	ATA 25 - HELICOPTERS SOUNDPROOFING REPLACEMENT	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-521	ATA 28 - INSTALLATION OF MAIN LH AND RH SELF-SEALING FUEL TANKS	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-520	ATA 62 - MAIN ROTOR BLADE TIP CAP RECURRENT INSPECTION	-	-	-/NOT APPLICABLE	MR BLADES NOT AFFECTED. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-517	ATA 25 - INSTALLATION OF KIT SACKSAFOAM	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-514	ATA 52 - INSTALLATION OF KIT SAR PROTECTION STEP	-	-	-/NOT APPLICABLE	NOT APPLICABLE PER HELICOPTER CONFIGURATION. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-513	ATA 30 - INSTALLATION OF WINDSHIELD WASHING SYSTEM	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-511	ATA 53 - REMOVABLE PANELS RETROMOD	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	35
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	BT 139-509	ATA 71 - INSTALLATION OF EAPS REMOVABLE PARTS	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-508	ATA 62 - MAIN ROTOR BLADE TIP CAP INSPECTION	-	-	-/NOT APPLICABLE	MR BLADES NOT AFFECTED. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-507	ATA 24 - AUX O/H CB PANEL RETRO MODIFICATION	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-506	ATA 30 - WIPERS AND WASHING SYSTEM RETROMOD	-	-	-/NOT APPLICABLE	HELICOPTER NOT EQUIPPED WITH WINDSHIELD WASHING KIT. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-505	ATA 21 - VCS CONDENSER PACK RETROMOD	-	-	-/NOT APPLICABLE	KIT P/N 3G2150F00511 NOT INSTALLED. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-504	ATA 00 - HELICOPTER S/N 31724 RECONFIGURATION	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-501 REV B	ATA 62 - MAIN ROTOR BLADE ASSY UPGRADE	-	-	-/NOT APPLICABLE	MR BLADES NOT AFFECTED. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	36
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	BT 139-500	ATA 46 - "PRIMUS EPIC®" FLIGHT SOFTWARE RELEASE 7.12 & 7.14 UPGRADE	-	-	-/COMPLIED WITH	COMPLIED WITH BY MANUFACTURER. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-499	ATA 30 - ROTORS ICE PROTECTION CABLES CONNECTORS	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-498	ATA 32 - NLG SERVICING PLATE REPLACEMENT	-	-	-/NOT APPLICABLE	HELICOPTER NOT AFFECTED. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-497	ATA 00 - CORROSION PROTECTION IMPROVEMENT	-	-	-/OPTIONAL	AT CUSTOMER'S OPTION. NOT REQUESTED BY CONTRACTED WORK ORDER. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-495 REV A	ATA 31 - FDR AND RIPS VARIANT ULB REPLACEMENT	-	-	-/NOT APPLICABLE	HELICOPTER NOT AFFECTED. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-494	ATA 71 - INSTALLATION OF THE EJECTION SPRING ASSY	-	-	-/NOT APPLICABLE	NOT APPLICABLE PER HELICOPTER CONFIGURATION. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-493	ATA 25 - INSTALLATION OF KIT CHART HOLDER	-	-	-/OPTIONAL	AT CUSTOMER'S OPTION. NOT REQUESTED BY CONTRACTED WORK ORDER. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	37
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	BT 139-492	ATA 29 - INSTALLATION OF HYDRAULIC PULSATION DAMPENER	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICAL STATUS LIST DATED 08/10/2019.
Standard SBs	SB NO. 139-491	ATA 63 - AGB INPUT MODULE ASSY VARIANT	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO KIT FIPS NOT INSTALLED ON AIRCRAFT. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICAL STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-490 PART I AND II	ATA 63 - MGB OIL COOLING FAN INSPECTION	0.00	600.00	-/SUPERSEDED	SUPERSEDED AND REPLACED BY SB 139-526 DATED 10.04.2018
Standard SBs	BT 139-489	ATA 46 - INSTALLATION OF KIT CENTRAL DISPLAY SIRIO PANEL	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICAL STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-489	ATA 46 - INSTALLATION OF KIT CENTRAL DISPLAY SIRIO PANEL	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N (16/06/2020)
Standard SBs	BT 139-485	ATA 98 - INSTALLATION OF LIGHTNING SENSOR SYSTEM	-	-	-/OPTIONAL	AT CUSTOMER'S OPTION. NOT REQUESTED BY CONTRACTED WORK ORDER. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICAL STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-485 REV. /	ATA 98 - INSTALLATION OF LIGHTNING SENSOR SYSTEM	-	-	-/OPTIONAL	
Standard SBs	BT 139-155 REV B PART II	ATA 33 - 2ND ANTICOLLISION LIGHT KITS	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-155 REV B PART I AND III	ATA 33 - 2ND ANTICOLLISION LIGHT KITS	-	-	-/OPTIONAL	AT CUSTOMER'S OPTION. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI STATUS LIST DATED 08/10/2019.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	38
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	BT 139-486	ATA 25 - INSTALLATION OF KIT ELT			- /-COMPLIED WITH	COMPLIED WITH BY MANUFACTURER. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-484	ATA 18 - INSTALLATION OF ACTIVE VIBRATION CONTROL SYSTEM OMNI (SAR) KIT P/N 4G1830F00611			- /-OPTIONAL	AT CUSTOMER'S OPTION. NOT REQUESTED BY CONTRACTED WORK ORDER. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-482	ATA 29 - INSTALLATION OF KIT HYDRAULIC PULSATION DAMPENER			- /-OPTIONAL	AT CUSTOMER'S OPTION. NOT REQUESTED BY CONTRACTED WORK ORDER. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-481	ATA 33 - INSTALLATION OF PULSE LIGHTS ON SPONSONS			- /-OPTIONAL	AT CUSTOMER'S OPTION. NOT REQUESTED BY CONTRACTED WORK ORDER. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-480	ATA 31 - HUMS Upload of On-Board System Configuration (OBSC)			- /-COMPLIED WITH	COMPLIED WITH BY MANUFACTURER. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-479	ATA 21 - REMOVAL OF ENVIRONMENTAL CONTROL SYSTEM			- /-NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	39
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	BT 139-478	ATA 52 - INSTALLATION OF KIT NOSE LANDING GEAR DOORS	-	-	-/OPTIONAL	AT CUSTOMER'S OPTION - NOT REQUESTED BY CONTRACTED WORK ORDER. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-477	ATA 53 - RH SHACKLE TIEDOWN FITTINGS	-	-	-/OPTIONAL	AT CUSTOMER'S OPTION - NOT REQUESTED BY CONTRACTED WORK ORDER. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	SB NO. 139-475 PART II	ATA 23 - INSTALLATION OF KIT ICS 9000 CABIN STATION 4	-	-	-/OPTIONAL	APPLICABLE TO AIRCRAFT SERIAL NUMBER. COMPLIANCE IS AT CUSTOMER'S OPTION. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 03/12/2019.
Standard SBs	SB NO. 139-475 PART I	ATA 23 - INSTALLATION OF KIT ICS 9000 CABIN STATION 4	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO AIRCRAFT SERIAL NUMBER. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 03/12/2019.
Standard SBs	BT 139-473 REV A PART I, II AND III	ATA 53 - CABIN DRAIN HOLES RETROMOD	-	-	-/NOT APPLICABLE	INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-472	ATA 62 - MAIN ROTOR SLIP RING	-	-	-/NOT APPLICABLE	KIT FIPS NOT INSTALLED. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-470	TAIL/REAR FUSELAGE ATTACHMENT FITTINGS	-	-	-/NOT APPLICABLE	HELICOPTER EQUIPPED WITH TAIL ASSY P/N 3G5350A00136. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	40
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	BT 139-469	ATA 30 - PASSENGER CABIN DRAINAGES INSTALLATION.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-468	ATA 26 - LEFT AND RIGHT FIRE DETECTION SYSTEM	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-467 PART II REV A	TAIL ROTOR DRIVE LINE (TRDL) BEARING SUPPORT BRACKET	-	-	-/CANCELLED	TIC-AW139-22-0006 DATED 27 JANUARY 2022 SB CANCELLED.
Standard SBs	BT 139-467 PART II REV A	TAIL ROTOR DRIVE LINE (TRDL) BEARING SUPPORT BRACKET	-	-	-/CANCELLED	TIC-AW139-22-0006 DATED 27 JANUARY 2022 SB CANCELLED.
Standard SBs	BT 139-466	MAIN ROTOR (MR) SERVOACTUATOR DOWEL PINS	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY COMPONENT S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-465 REV A	TAIL ROTOR DRIVE SHAFT (TRDS) INTERFERENCE	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-461	ATA 00 - JOINT AVIATION COMMAND (JAC) RE-CONFIGURATION	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-460	BREEZE RESCUE HOIST EXTENDED CABLE LENGTH KIT COMPLETION	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	41
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	BT 139-459	ATA 71 - EAPS TO IBF RETROFIT	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-457 REV A	ATA 25 - INSTALLATION OF BREEZE-EASTERN EXTERNAL HOIST	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER SERIAL NUMBER INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 03/12/2019.
Standard SBs	BT 139-456	KIT SATCOM LATITUDE	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-454	KIT ICS 9000 CABIN STATION 4 P/N 4G2350F00911	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-453 REV A	ATA 32 - LEFT AND RIGHT MAIN LANDING GEAR UPGRADE	-	-	-/NOT APPLICABLE	DIFFERENT P/N INSTALLED. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-452 REV B PART II	ATA 62 - MAIN ROTOR DAMPER INSPECTION AND REPLACEMENT	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO MR DAMPERS NOT AFFECTED BY P/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-452 REV B PART I	ATA 62 - MAIN ROTOR DAMPER INSPECTION AND REPLACEMENT	-	-	-/COMPLIED WITH	COMPLIED WITH BY MANUFACTURER. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	42
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	BT 139-451 REV A	ATA 28 - INSTALLATION OF KIT AUXILIARY FUEL TANK	-	-	-/COMPLIED WITH	COMPLIED WITH BY MANUFACTURER. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-450 REV D	ATA 62 - MAIN ROTOR DAMPER INSPECTIONS	-	-	-/NOT APPLICABLE	MR DAMPER NOT AFFECTED BY P/N . INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-449 REV A	ATA 31 - INSTALLATION OF QUICK ACCESS RECORDER	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-448	GOODRICH HOIST PENDANT VARIANT	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-446	MAIN ROTOR (MR) DAMPER INSPECTIONS.	-	-	-/SUPERSEDED	SUPERSEDED AND CANCELLED BY BT139-450. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-445	ELT EQUIPMENT COMPLETION OF.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-444 REV C	ATA 78 - EXHAUST DUCTS AND REAR FIREWALL RETROMOD	-	-	-/NOT APPLICABLE	INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-442	ATA 25 - DEPLOYABLE ELT INSTALLATION	-	-	-/NOT APPLICABLE	HELICOPTER NOT EQUIPPED WITH KIT ELT DEPLOYABLE P/N 3G2560F00311. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	43
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	BT 139-441 REV A	ATA 34 - ENHANCED GROUND PROXIMITY WARNING SYSTEM (EGPWS) SOFTWARE	-	-	-/NOT APPLICABLE	INSTALLED EGPWS COMPUTER NOT AFFECTED. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-440	PRIMUS EPIC WIRINGS	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-438	KIT RH UTILITY CB PANEL.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-437	ATA 53 - INSPECTION AND REPLACEMENT OF LIGHTNING SENSOR SYSTEM SUPPORT ASSY P/N 3G5315A82231	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-436	R4A AIRBORNE AIS TRANSPONDER - SOFTWARE UPDATE	-	-	-/NOT APPLICABLE	HELICOPTER NOT EQUIPPED WITH AIS TRANSPONDER P/N 7001-000-111 OR P/N 7001-000-112 INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-435	DISPLAY INSTALLATION UPDATE	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-434 REV A	ATA 71 - TUNNEL ASSY RETROMOD	-	-	-/NOT APPLICABLE	HELICOPTER NOT EQUIPPED WITH TUNNEL ASSY P/N 3G7130A13431. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	44
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	BT 139-433	VHF/FM NAT NPX138 RETROMOD	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-432	POWER LINE DETECTOR RETROMOD	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-431	DEPLOYABLE EMERGENCY LOCATOR TRANSMITTER (ELT) SYSTEM INTERFACE UNIT (SIU)	-	-	-/NOT APPLICABLE	ELT DEPLOYABLE P/N 3G2560F00311 NOT INSTALLED. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-430	GOODRICH RESCUE HOIST OVERLOAD CLUTCH.	-	-	-/SUPERSEDED	SUPERSEDED AND CANCELLED BY BT 139-443. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-429	WEIGHT EXTENSION 7000 KG	-	-	-/COMPLIED WITH	COMPLIED WITH BY MANUFACTURER. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-428	SIMOCO SRM9000 AND MOTOROLA XTL5000 RADIO EQUIPMENTS	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-427	POWER CONTROL MODULE	-	-	-/NOT APPLICABLE	PCM P/N 3G2900V00651 NOT INSTALLED. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	45
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	BT 139-426	FLIR WESCAM MX-15I HD RETROMOD.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-425	MAIN ROTOR ACTUATOR (MRA) P/N 3G6730V00531	-	-	-/NOT APPLICABLE	MRA P/N 3G6730V00531 NOT INSTALLED. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-424	"PRIMUS EPIC®" FLIGHT SOFTWARE RELEASE 7.10 (PHASE 7 V4)	-	-	-/OPTIONAL	SEE SB 139-500. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-422	EMERGENCY MEDICAL SERVICE (EMS) MEDEVAC PROVISION	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-420	VADU FAREM ELECTRICAL VARIANT P/N 3G9310P00212	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-419 PART I, II AND III	TAIL STRUCTURE ASSY IMPROVEMENT	-	-	-/NOT APPLICABLE	TAIL ASSY NOT AFFECTED BY P/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-418	REAR FUSELAGE STRUCTURE ASSY IMPROVEMENT	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	46
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	BT 139-417	NEW ELASTOMERIC TAIL ROTOR DAMPER	-	-	-/NOT APPLICABLE	HELICOPTER NOT EQUIPPED WITH TR ELASTOMERIC DAMPER P/N 3G6420V00455. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-414	BRACKETS NOSE INSTALLATION	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-413	KIT SATCOM SKYCONNECT (PTA12-300) P/N 4G2310F01111	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-412	CABIN LOAD INSTALLATION	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-410 REV A	MAIN ROTOR (MR) DAMPER SPHERICAL BEARINGS AND ROD END INSPECTION	-	-	-/SUPERSEDED	SUPERSEDED AND CANCELLED BY BT139-450. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-409	RADIO TETRA EADS (THR9I)	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-408	FULL ICE PROTECTION SYSTEM (FIPS) TAIL ROTOR (TR) SLIP RING CABLES	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	47
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	BT 139-404	FULL ICE PROTECTION SYSTEM (FIPS) TAIL ROTOR (TR) SLIP RING	-	-	-/NOT APPLICABLE	HELICOPTER NOT EQUIPPED WITH KIT FIPS. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-403	ROTOR ANALYSIS DIAGNOSTIC SYSTEM - ADVANCED TECHNOLOGY (RADS-AT) RETROMOD P/N 3G3130P00311	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-402	MAIN ROTOR (MR) DAMPER BOLT P/N 3G6220A01252	-	-	-/NOT APPLICABLE	HELICOPTER NOT EQUIPPED WITH MR DAMPER BOLTS P/N 6G6220A01251. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-401	KIT COCKPIT LIPSTICK CAMERA	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-400	"PRIMUS EPIC®" FLIGHT SOFTWARE RELEASE 7.7 (PHASE 7 VERSION 3), INSTALLATION OF.	-	-	-/NOT APPLICABLE	HELICOPTER EQUIPPED WITH NEW RELEASE OF FLIGHT SOFTWARE. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-397	MAIN LANDING GEAR (MLG) SHOCK ABSORBER SCREWS REPLACEMENT	-	-	-/NOT APPLICABLE	HELICOPTER NOT EQUIPPED WITH KIT INCREASED GROSS WEIGHT 6800 KG. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-396 REV A	ATA 25 - INSTALLATION OF KIT SINGLE HOIST GOODRICH	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	48
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	BT 139-395 REV A	KIT TCAS II P/N 4G3450F00211	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-394	CIRCULAR FORCE (CF) ACTIVE VIBRATION CONTROL SYSTEM (AVCS) SOFTWARE	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-393	SLIDING PASSENGER DOOR ASSEMBLY IMPROVEMENT	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-392 REV A	MAIN ROTOR (MR) SCISSOR LEVER BEARING P/N 3G6230V00654	-	-	-/NOT APPLICABLE	HELICOPTER NOT AFFECTED. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-391	TAIL ROTOR (TR) SHUT-OFF VALVE (SOV) P/N 3G2910V00231	-	-	-/NOT APPLICABLE	INSTALLED TR SOV NOT AFFECTED. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-390 REV A	GOODRICH RESCUE HOIST OVERLOAD CLUTCH.	-	-	-/SUPERSEDED	SUPERSEDED AND CANCELLED BY BT139-430. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-389 REV A	GASKETS ANTENNA, LIGHTS AND ELECTRICAL EQUIPMENTS INSTALLATION.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	49
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	BT 139-388	EXHAUST NOZZLE BLANKET REPLACEMENT RH P/N 3G7810P00131 OR P/N 3G7810P00132 AND LH P/N 3G7810P00231 OR P/N 3G7810P00232.	-	-	-/NOT APPLICABLE	APPLICABLE ONLY IN CASE OF NON REPAIRABLE DAMAGES OF THE THERMAL BLANKETS. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-387	SMA CONFIGURATION.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-385	ATA 93 - INSTALLATION OF KIT VIDEO MODULE INTERFACE P/N 3G9310F00212,4G9310F00211 OR P/N 4G9310F00212	-	-	-/COMPLIED WITH	COMPLIED WITH BY MANUFACTURER. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-384	INSTALLATION OF HEATED WINDSHIELDS KIT P/N 3G5610F00611.	-	-	-/OPTIONAL	AT CUSTOMER'S OPTION - NOT REQUESTED BY CONTRACTED WORK ORDER. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-382 REV B PART II	ATA 34 - INSTALLATION OF KIT 2ND TRANSPONDER ADS-B OUT	-	-	-/OPTIONAL	AT CUSTOMER'S OPTION. NOT REQUESTED BY CONTRACTED WORK ORDER. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-382 REV B PART I AND III	ATA 34 - INSTALLATION OF KIT 2ND TRANSPONDER ADS-B OUT	-	-	-/NOT APPLICABLE	PART I: NOT APPLICABLE BY HELICOPTER S/N. PART III: NOT APPLICABLE. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	50
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	BT 139-381	FULLY ADJUSTABLE PILOT SEAT P/N 3G2510V01631 AND CO-PILOT SEAT P/N 3G2510V01731.	-	-	-/OPTIONAL	AT CUSTOMER'S OPTION - NOT REQUESTED IN CONTRACTED WORK ORDER. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-380	AUXILIARY CB PANEL KIT.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-379 REV A	ATA 98 - INSTALLATION OF LIGHTNING SENSOR SYSTEM KIT	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-377	RETROMOD REWORKED PIPE ASSEMBLY LEFT P/N 3G7806P06031 AND RIGHT P/N 3G7806P06131 AND THERMAL BLANKET REPLACEMENT.	-	-	-/NOT APPLICABLE	NOT APPLICABLE PER ENHANCED FUSELAGE. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-376	VIDEO DOWNLINK 4.5 GHz RETROMOD P/N 3G9306P04211	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-375 PART I, II, III, AND IV	ATA 24 - AUXILIARY CIRCUIT-BREAKER PANEL MODIFICATIONS	-	-	-/NOT APPLICABLE	INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-374	EMERGENCY FLOATS CONTROL PANEL P/N 3G9560V00556 (NIGHT VISION GOGGLE - NVG) AND P/N 3G9560V00557 (STANDARD - STD).	-	-	-/NOT APPLICABLE	HELICOPTER NOT EQUIPPED WITH EMERGENCY FLOGAT CONTROL PANEL P/N 3G9560V00556 OR P/N 3G9560V00557. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	51
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	BT 139-373 REV A	LEFT ENGINE ASSY FUEL INLET HOSE AND FIREWALL/FIRE DETECTION SYSTEM.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICAL STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-372 REV A	FULL ICE PROTECTION SYSTEM (FIPS) TAIL GEARBOX (TGB) FAIRING	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICAL STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-371	HOIST PENDANT VARIANT P/N 3G2591A08211, INSTALLATION OF.	-	-	-/NOT APPLICABLE	HELICOPTER NOT EQUIPPED WITH THE COMPONENTS IN SUBJECT. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICAL STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-370	RIGHT ENGINE ASSY FUEL INLET HOSE, INSPECTION OF.	-	-	-/COMPLIED WITH	MODIFICATION ALREADY INCORPORATED ON THE HELICOPTER. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICAL STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-369	EMS FLOOR MODIFICATION.	-	-	-/NOT APPLICABLE	NOT APPLICABLE PER HELICOPTER CONFIGURATION. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICAL STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-368	INSPECTION / REPLACEMENT OF LOWER HALF SCISSOR SPHERICAL BEARING P/N 3G6230V00654.	-	-	-/NOT APPLICABLE	INSTALLED COMPONENTS NOT AFFECTED. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICAL STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-367	TAIL ROTOR (TR) SERVOACTUATOR, MEASUREMENT OF LAYSHAFT PLAY.	-	-	-/NOT APPLICABLE	HELICOPTER INSTALLING TR SERVOACTUATOR NOT AFFECTED. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICAL STATUS LIST DATED 08/10/2019.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	52
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	BT 139-366 REV A	LH (COPILOT) COLLECTIVE TORQUE TUBE COVER AND UNDERLYING CABLE ASSY	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-365	ALGERIAN DEPARTMENT OF DEFENCE HELICOPTERS CONFIGURATION.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-364	TRAKKA SEARCHLIGHT ASSEMBLY	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-363	PILOTS FOOTSTEPS KIT.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	SB NO. 139-362, REV A	ATA 76 - ENGINE CONTROL MECHANICAL BACKUP	-	-	-/NOT APPLICABLE	INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-361	COMPRESSOR PACK ASSY AND AIR CONDITIONING RELIABILITY, IMPROVEMENT OF.	-	-	-/NOT APPLICABLE	HELICOPTER NOT EQUIPPED WITH COMPRESSOR PACK ASSY P/N 3G2150V01153. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-359	LH REAR PANEL ASSY RETROMOD P/N 3G5306P52711 AND RH REAR PANEL ASSY RETROMOD P/N 3G5306P52811 OR P/N 3G5306P53211.	-	-	-/COMPLIED WITH	MODIFICATION ALREADY INCORPORATED ON HELICOPTER. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	53
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	BT 139-357 REV A	KIT 2ND GPS P/N 4G3450F00611 OR 2ND GPS SBAS P/N 4G3450F00613.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-355	EXHAUST DUCT SUPPORTS RETROMOD P/N 3G7806P08811.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-354	RESCUE HOIST CLUTCH LOAD CHECK	-	-	-/SUPERSEDED	SUPERSEDED BY BT 139-390. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-353	KIT REMOVABLE RIGID HANDLE PASSENGER LH P/N 4G5212F00511 AND RH P/N 4G5212F00611, INSTALLATION OF.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-352	ATA 32 - INSTALLATION OF SLUMP PROTECTION PADS	-	-	-/OPTIONAL	AT CUSTOMER'S OPTION - NOT REQUESTED BY CONTRACTED WORK ORDER. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-350 PART II	TGB/IGB AND TAIL PLANE FITTINGS RETROMODIFICATIONS.	-	-	-/OPTIONAL	PROVIDES INSTRUCTION TO REPLACE THE EXISTING TGB FITTING ASSEMBLIES WITH A NEW ONE, IN CASE OF DAMAGED COMPONENTS. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	54
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	BT 139-350 PART I AND III	TGB/IGB AND TAIL PLANE FITTINGS RETROMODIFICATIONS.	-	-	-/NOT APPLICABLE	HELICOPTER EQUIPPED WITH TAIL ASSY HAVING DIFFERENT P/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-349	DEPARTMENT OF CIVIL AVIATION (DCA) MALAYSIA VARIANT P/N 3G0206P01611 AND OWNER/OPERATOR PLACARD RETROMOD P/N 3G0206P01811, INSTALLATION OF.	-	-	-/COMPLIED WITH	REFER GAM-WO-20-255 (2020/PME/007-001) ON 09/03/2020 @ 16:25 FH. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICAL STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-347 REV A	ATA 46 - REMOVABLE PARTS OF MISSION EQUIPMENTS	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICAL STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-345	PENALTY FACTORS.	-	-	-/COMPLIED WITH	COMPLIED WITH BY MANUFACTURER. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICAL STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-344	INCREASE OF MAIN GEARBOX (MGB) OVERHAUL INTERVAL FROM 5000 FH TO 6000 FH.	-	-	-/COMPLIED WITH	COMPLIED WITH BY MANUFACTURER. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICAL STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-343	ACCESSORY DRIVE ECS COMPRESSOR VISUAL INSPECTION AND MODIFICATION.	-	-	-/NOT APPLICABLE	HELICOPTER NOT EQUIPPED WITH MGB ACCESSORY DRIVE IN SUBJECT. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICAL STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-342	FULL ICE PROTECTION SYSTEM (FIPS) TAIL ROTOR (TR) BLADES ASSY SEALING MODIFICATION.	-	-	-/NOT APPLICABLE	INSTALLED T/R BLADES WITH DIFFERENT P/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICAL STATUS LIST DATED 08/10/2019.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	55
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	BT 139-341 REV A	ATA 62 - INSTALLATION OF MAIN ROTOR SCISSORS P/N 3G6230A00733	-	-	-/NOT APPLICABLE	HELICOPTER NOT EQUIPPED WITH M/R SCISSORS P/N 3G6230A00732. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-340 REV B	FULL ICE PROTECTION SYSTEM (FIPS) AC GENERATOR CONTROL UNIT (GCU)	-	-	-/NOT APPLICABLE	HELICOPTER NOT EQUIPPED WITH KIT FIPS. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-339 REV B	FULL ICE PROTECTION SYSTEM (FIPS) AUTO TRANSFORMER RECTIFIER UNIT (ATRU) REPLACEMENT.	-	-	-/NOT APPLICABLE	HELICOPTER NOT EQUIPPED WITH KIT FIPS. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-338	FULL ICE PROTECTION SYSTEM (FIPS) MAIN ROTOR SLIP RING HALF BUMPER RINGS, INSTALLATION OF	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-337	FULL ICE PROTECTION SYSTEM (FIPS) TAIL ROTOR (TR) SLIP RING, IMPROVEMENT OF.	-	-	-/NOT APPLICABLE	HELICOPTER NOT EQUIPPED WITH KIT FIPS. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-336 REV A	FULL ICE PROTECTION SYSTEM (FIPS) MAIN ROTOR (MR) CABLES REPLACEMENT.	-	-	-/NOT APPLICABLE	HELICOPTER NOT EQUIPPED WITH KIT FIPS. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-335 REV A	KIT SATCOM SKYTRAC ISAT-200 P/N 4G2310F03011	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	56
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	BT 139-333	2ND DISTANCE MEASURING EQUIPMENT (DME) KIT P/N 4G3450F00111, INSTALLATION OF.	-	-	-/OPTIONAL	AT CUSTOMER'S OPTION - NOT REQUESTED BY CONTRACTED WORK ORDER. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-332	SUN GEAR OIL NOZZLES VARIANT P/N 3G6306P01511, INSTALLATION OF.	-	-	-/NOT APPLICABLE	MGB ASSEMBLY NOT AFFECTED. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-331 REV B	MAIN ROTOR (MR) SERVOACTUATOR, MEASUREMENT OF LAYSHAFT PLAY.	-	-	-/NOT APPLICABLE	INSTALLED MR SERVOACTUATOR NOT AFFECTED. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-330	FULL ICE PROTECTION SYSTEM (FIPS) TAIL ROTOR DISTRIBUTOR (TRD) REPLACEMENT.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-329 REV A	CARGO HOOK KIT P/N 3G2592F00111, LONGERON BL +/-275 RETROMOD.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-327 REV A	SECONDARY FUEL PROBE P/N 3G2840V01051 (AERAZUR P/N 506252 OR P/N 506252A) HEAD SEALING, IMPROVEMENT OF.	-	-	-/COMPLIED WITH	MODIFICATION ALREADY INCORPORATED ON HELICOPTER. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-326	RESCUE HOIST ASSEMBLY PART REPLACEMENT	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY RESCUE HOIST S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	57
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	MSB NO. 139-325, REVISION A	MAIN ROTOR SERVOACTUATOR INSPECTION AND REPAIR	-	-	-/NOT APPLICABLE	TIC-AW139-20-128 NOT APPLICABLE TO 9M-PME (31855), DUE TO COMPONENT P/N 3G6730V00532 FITTED ON AIRCRAFT.
Standard SBs	BT 139-324 REV A	MR FULL ICE PROTECTION SYSTEM (FIPS) CABLES, INSPECTION OF.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-323	WEATHER RADAR PRIMUS 701 INSTALLATION P/N 4G3441A00611, IMPROVEMENT OF.	-	-	-/COMPLIED WITH	MODIFICATION ALREADY INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-322	UTILITY CB PANEL KIT P/N 4G2460F00523 IN UTILITY CB PANEL KIT P/N 4G2460F00518, UPGRADE OF.	-	-	-/NOT APPLICABLE	HELICOPTER NOT EQUIPPED WITH UTILITY CB PANEL KIT P/N 4G2460F00523. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-321 REV B	INSPECTION OF THE RESCUE HOIST.	-	-	-/SUPERSEDED	SUPERSEDED BY BT 139-354. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-320	FIPS TAIL ROTOR SLIP RING DRIVE INSTALLATION IMPROVEMENT.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-319	NIGHT VISION GOGGLES (NVG) RE-CONFIGURATION.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	58
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	BT 139-317	KIT PARTIAL CABIN EXTENSION P/N 4G5340F00211, INSTALLATION OF.	-	-	-/OPTIONAL	AT CUSTOMER'S OPTION - NOT REQUESTED BY CONTRACTED WORK ORDER. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-315 REV B	"PRIMUS EPIC®" FLIGHT SOFTWARE RELEASE 7.4 (PHASE 7 VERSION 1), INSTALLATION OF.	-	-	-/NOT APPLICABLE	NEW RELEASE OF FLIGHT SOFTWARE INSTALLED. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-314	FLOOR REMOVABLE PANELS RETROMODIFICATION.	-	-	-/NOT APPLICABLE	KIT VIP FIVE STAR PROVISION NOT INSTALLED. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-313 REV A	ATA 34 - INSTALLATION OF TRANSPONDER (XPDR) WITH ADS-B OUT	-	-	-/NOT APPLICABLE	HELICOPTER NOT AFFECTED. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-312	AW139 HEALTH AND USAGE MONITORING SYSTEM (HUMS) - ON BOARD SYSTEM CONFIGURATION (OBSC) FILE VERSION 5.3.0 OR AGB4 UPLOAD ON HUMS DATA ACQUISITION UNIT (DAU) AND AW139 CONFIGURED HUMS GROUND STATION (HGS) SOFTWARE RELEASE V4.1.0 INSTALLATION OF.	-	-	-/OPEN	SEE SB 139-480. TO RAISE TIC. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-311 REV B	SUBFLOOR FRAME STA2105 RETROMODIFICATION P/N 3G5306P47211, INSTALLATION OF.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	59
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	BT 139-310 REV A	KIT LOW SPEED LANDING AURAL WARNING P/N 4G2350F01512, INSTALLATION OF.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-308	VISUAL INSPECTION OF THE COLLECTIVE AND CYCLIC STICKS INSTALLATIONS.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-307	HYDRAULIC SYSTEM FEXIBLE HOSES REPLACEMENT IN THE UPPER DECK AREA.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-306	NOSE LANDING GEAR, INSPECTION OF ARMS PIN INSTALLATION.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-305	TAIL ROTOR BEARING SUPPORT BRACKET INSPECTION.	-	-	-/SUPERSEDED	SUPERSEDED BY BT 139-296. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-304	2ND ADDITIONAL LANDING LIGHT KIT P/N 4G3340F01812, INSTALLATION OF.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-303	MAIN GEARBOX (MGB) INPUT MODULES BEARINGS	-	-	-/NOT APPLICABLE	INSTALLED MGB INPUT MODULE NOT AFFECTED. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	60
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	BT 139-302	PEDAL SET ASSY INSPECTION AND RECONFIGURATION.	-	-	-/NOT APPLICABLE	APPLICABLE ONLY TO HELICOPTERS IN SERVICE. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-301	INSTALLATION OF POSITION LIGHTS OR POSITION/STROBE LIGHTS ON TAIL PLANE WINGLETS, IMPROVEMENT OF.	-	-	-/COMPLIED WITH	MODIFICATION ALREADY INCORPORATED ON HELICOPTER. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-300	EMERGENCY FLOATATION SYSTEM (EFS) CONNECTIONS MODIFICATION	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-299	DIGITAL VIDEO-AUDIO RECORDER (DVAR) HD RECORDING	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER CONFIGURATION. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-298	MISSION DISPLAY P/N LCD1507-300 AND P/N LCD1507-340 MOD STATE C.	-	-	-/NOT APPLICABLE	HELICOPTER NOT EQUIPPED WITH THE MISSION DISPLAY. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-297 REV A	TRAKKA A800 SEARCHLIGHT KITS P/N 4G3340F02411 AND P/N 4G3340F02412	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-296 REV A	TAIL ROTOR (TR) SHAFT REINFORCEMENT RETROMODIFICATION P/N 3G5306P42512	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	61
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	BT 139-295	ADS-B UNIVERSAL ACCESS TRANSCEIVER (UAT) FREE FLIGHT EQUIPMENT P/N 3G3450A04411, INSTALLATION OF.	-	-	-/NOT APPLICABLE	HELICOPTER NOT EQUIPPED WITH ADS-B FREE FLIGHT COMPLETE PROVISION IN SUBJECT. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-294	HEELS CABIN DOORS/WINDOWS LIGHTS INSPECTION.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-293 REV A	GPS L1-L2 ANTENNA, INSTALLATION OF.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-292	NUMBER 2 DRAIN LINE INSTALLATION MODIFICATION.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-291	EMS MEDEVAC PROVISION KIT P/N 4G2564F00213, INSTALLATION OF.	-	-	-/OPTIONAL	AT CUSTOMER'S OPTION - NOT REQUESTED BY CONTRACTED WORK ORDER. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-290	PASSENGER SEAT KIT P/N 4G2520F05911 OR P/N 4G2520F05811, INSTALLATION OF.	-	-	-/COMPLIED WITH	COMPLIED WITH BY MANUFACTURER. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-289	NOSE LANDING GEAR, ALTERNATIVE SHIMMY DAMPER FLUID.	-	-	-/NOT APPLICABLE	HELICOPTER EQUIPPED WITH NLG ASSY NOT AFFECTED. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	62
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	BT 139-288 PART III	TAIL ROTOR CONTROL DUPLEX BEARING.	-	-	-/NOT APPLICABLE	APPLICABLE ON SPARE PARTS KEPT IN STOCK. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-288 PART II	TAIL ROTOR CONTROL DUPLEX BEARING.	-	-	-/OPEN	APPLICABLE FOR TAIL ROTOR CONTROL DUPLEX BEARING HAVE ACCUMULATED 3000 FLIGHT HOURS (OR MORE) SINCE INSTALLATION. COMPLY WITHIN THE NEXT 600 FLIGHT HOURS OR 6 MONTH FROM THE RECEIPT OF THIS SERVICE BULLETIN WHICHEVER OCCUR FIRST. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-288 PART I	TAIL ROTOR CONTROL DUPLEX BEARING.	-	-	-/OPEN	APPLICABLE FOR TAIL ROTOR CONTROL DUPLEX BEARING HAVE ACCUMULATED 3000 FLIGHT HOURS (OR MORE) SINCE INSTALLATION. COMPLY WITHIN THE NEXT 200 FLIGHT HOURS AND THEN REPETITIVE 200 FLIGHT HOURS. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-287	USB VARIANT	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	63
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	BT 139-286 REV B	PRECAUTIONARY INSPECTION AND QUARANTINE LIMIT OF IMPROVED TAIL ROTOR BLADES P/N 3G6410A00133 AND P/N 4G6410A00133.	-	-	-/NOT APPLICABLE	REVISION B CANCELS AND SUPERSEDES THE REV. A.THE AIRWORTHINESS OF THE IMPROVED TAIL ROTOR BLADES IN SUBJECT IS NOW MANAGED THROUGH THE AIRWORTHINESS LIMITATIONS SECTION OF THE AW139 AMPI MANUAL LATEST REVISION. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-285 REV B	PRECAUTIONARY INSPECTION AND QUARANTINE OF IMPROVED TAIL ROTOR BLADES P/N 3G6410A00132 AND P/N 4G6410A00132.	-	-	-/NOT APPLICABLE	HELICOPTER EQUIPPED WITH IMPROVED T/R BLADES HAVING DIFFERENT P/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-283	LH AIR INTAKE FAIRING RETROMOD P/N 3G5306P47411, INSTALLATION OF.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-282	28VDC ACTIVE NOISE REDUCTION (ANR) HEADSET RETROMOD P/N 3G2306P10111, INSTALLATION OF.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-281	SX16 SEARCH LIGHT KIT P/N 3G3340F00111, INSTALLATION OF.	-	-	-/OPTIONAL	AT CUSTOMER'S OPTION - NOT REQUESTED BY CONTRACTED WORK ORDER. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-280	CORROSION PROTECTION IMPROVEMENT.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	64
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	BT 139-279 REV A	ATA 71 - ADDITIONAL COWLING LATCHES KIT	-	-	-/OPTIONAL	AT CUSTOMER'S OPTION - NOT REQUESTED BY CONTRACTED WORK ORDER. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-278	SIMOCO SRM 9000 MOBILE RADIOS	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-277	LONGITUDINAL LITTERS RETROMODIFICATION.	-	-	-/NOT APPLICABLE	HELICOPTER NOT EQUIPPED WITH THE KIT IN SUBJECT. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-276	VISUAL INSPECTION OF THE CYCLIC CONTROL SYSTEM.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-275	VISUAL INSPECTION OF THE COLLECTIVE CONTROL SYSTEM.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-274	TAIL GEAR BOX (TGB) CENTRAL HOUSING	-	-	-/NOT APPLICABLE	HELICOPTER EQUIPPED WITH TGB ASSY NOT AFFECTED. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-273	AW139 HEALTH AND USAGE MONITORING SYSTEM (HUMS) - ON BOARD SYSTEM CONCONFIGURATION (OBSC) FILE VERSION 5.1.0 OR AGB2 UPLOAD ON HUMS DATA ACQUISITION UNIT (DAU) AND AW139 CONFIGURED HUMS GROUND STATION (HGS) SOFTWARE RELEASE V4.0.0 INSTALLATION OF.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	65
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	BT 139-272 REV A	KIT MAX VIZ CAMERA ENHANCED VISION SYSTEM (EVS) 1500 UNDER FUSELAGE P/N 4G9750F00312, INSTALLATION OF.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-270	TAIL ROTOR SLIP RING MOUNTING PLATE INSTALLATION IMPROVEMENT	-	-	-/NOT APPLICABLE	HELICOPTER NOT EQUIPPED WITH KIT FIPS. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-269	OPERATIONAL CHECK OF NR.1 AND NR.2 HYDRAULIC SYSTEM.	-	-	-/NOT APPLICABLE	FUNCIONAL SYSTEM TEST ALREADY PERFORMED. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-268	UPPER REAR PANEL	-	-	-/OPTIONAL	AT CUSTOMER'S OPTION - NOT REQUESTED BY CONTRACTED WORK ORDER. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-267	INSTRUMENT PANEL IMPROVED FIXING SUPPORTS, INSTALLATION OF.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-266 REV A	ATA 25 - INSTALLATION OF KIT BAMBI BUCKET PROVISION	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-265 REV B	PRECAUTIONARY INSPECTION AND QUARANTINE OF TAIL ROTOR BLADES P/N 3G6410V00131 AND P/N 4G6410V00131.	-	-	-/NOT APPLICABLE	HELICOPTER EQUIPPED WITH IMPROVED T/R BLADES HAVING DIFFERENT P/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	66
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	BT 139-264	ACTIVE VIBRATION CONTROL SYSTEM KIT P/N 4G1830F00111 (AVCS 2+2) OR P/N 4G1830F00211 (AVCS 3+1), INSTALLATION OF.	-	-	-/OPTIONAL	AT CUSTOMER'S OPTION - NOT REQUESTED BY CONTRACTED WORK ORDER. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-263	TAIL ROTOR FIPS SLIP RING DRIVE INSTALLATION IMPROVEMENT	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-262	REAR UPPER DECK PANEL ASSY P/N 3P5340A01131, P/N 3P5340A01132, P/N 3P5340A01133 OR P/N 3P5340A01135, REPLACEMENT OF.	-	-	-/NOT APPLICABLE	HELICOPTER EQUIPPED WITH TAIL ROTOR DRIVE SHAFT INSTALLATION P/N 4G6500A00212 - BT NOT APPLICABLE. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-261	TAIL ROTOR FIPS INSTALLATION IMPROVEMENT	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-260	QUICK ACCESS RECORDER KIT P/N 4G3130F00411, INSTALLATION OF.	-	-	-/OPTIONAL	AT CUSTOMER'S OPTION - NOT REQUESTED BY CONTRACTED WORK ORDER. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-259	MAIN ROTOR FIPS INSTALLATION IMPROVEMENT	-	-	-/SUPERSEDED	SUPERSEDED BY BT 139-336. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	67
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	BT 139-257	BREEZE-EASTERN RESCUE HOIST - BL-7720 BUMPER ASSEMBLY - OVER TRAVEL BUMPER REPLACEMENT	-	-	-/NOT APPLICABLE	HELICOPTER NOT EQUIPPED WITH BREEZE-EASTERN RESCUE HOIST KIT. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-256 REV A	NUMBER 4 PUMP LINE INSTALLATION VISUAL INSPECTION AND MODIFICATION	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-255	EXHAUST DUCT BAY VENTILATION RETROMOD P/N 3G7806P00811, INSTALLATION OF.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-254 REV A	ENGINE STARTER GENERATOR V-BAND CLAMP VISUAL INSPECTION	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-253	RESCUE HOIST ASSEMBLY P/N 3G2591V01531 AND CONTROL PENDANT ASSEMBLY P/N 3G2591V02151, IMPROVEMENT OF	-	-	-/COMPLIED WITH	MODIFICATION ALREADY INCORPORATED. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-252	DATA MANAGEMENT UNIT KIT P/N 4G4620F00211, INSTALLATION OF	-	-	-/OPTIONAL	AT CUSTOMER'S OPTION - NOT REQUESTED BY CONTRACTED WORK ORDER. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-251	TAIL ROTOR BLADES ASSY PRECAUTIONARY INSPECTION	-	-	-/SUPERSEDED	SUPERSEDED BY BT 139-265 INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	68
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	BT 139-250	ECS HD VIDEO UP/DOWNLINK RETRO-MODIFICATION P/N 3G9306P01711	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-249	SOLDER SPLICES P/N D-110-41 INSPECTION	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-248	TAIL ROTOR BEARING SUPPORT INSPECTION	-	-	-/SUPERSEDED	SUPERSEDED BY BT 139-305. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-247	44Ah MAIN BATTERY ADDITION AL CELL MODIFICATION (CONVERSION FROM 19-CELL INTO 20-CELL)	-	-	-/NOT APPLICABLE	HELICOPTER EQUIPPED WITH MAIN BATTERY HAVING DIFFERENT P/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-246	SX 16 SEARCHLIGHT ELEVATION ENVELOPE, EXTENSION OF	-	-	-/NOT APPLICABLE	KIT NOT INSTALLED. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-245	FUEL TANK ANGLE RETROMODIFICATION P/N 3G5306P33211 AND 3G5306P33212.	-	-	-/COMPLIED WITH	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-244	MGB ROD BACK UP STRUCTURE CRUCIFORM FITTING RETROMODIFICATION P/N 3G5306P36711, INSTALLATION OF	-	-	-/COMPLIED WITH	MODIFICATION ALREADY INCORPORATED ON HELICOPTER. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	69
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	BT 139-243	MODIFICATION OF TAIL UNIT ASSEMBLY	-	-	-/NOT APPLICABLE	HELICOPTER EQUIPPED WITH TAIL ASSEMBLY HAVING DIFFERENT P/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-239	HEATING/FORCED VENTILATION SYSTEMS JET PUMP P/N 3G2140V00851, IMPROVEMENT OF	-	-	-/NOT APPLICABLE	HELICOPTER NOT EQUIPPED WITH THE KIT IN SUBJECT. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-238 REV A	CONTROL ROD ASSY YAW6 AND YAW9 INSPECTION	-	-	-/NOT APPLICABLE	COMPONENT NOT AFFECTED. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-237 REV A	ATA 23 - INSTALLATION OF KIT STATIC DISCHARGE	-	-	-/OPTIONAL	AT CUSTOMER'S OPTION - NOT REQUESTED BY CONTRACTED WORK ORDER. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-236	MAIN ROTOR PITCH LINK ASSY P/N 3G6230A01032, UPGRADE OF	-	-	-/NOT APPLICABLE	HELICOPTER EQUIPPED WITH MR PITCH LINK ASSY HAVING DIFFERENT P/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-235 REV A	INTERMEDIATE GEARBOX (IGB) FITTING ASSEMBLY REWORK	-	-	-/NOT APPLICABLE	HELICOPTER EQUIPPED WITH TAIL ASSEMBLY HAVING DIFFERENT P/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	70
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	BT 139-234	DF935-11 DIRECTION FINDING SYSTEM KIT P/N 4G3450F00711, INSTALLATION OF	-	-	-/OPTIONAL	AT CUSTOMER'S OPTION - NOT REQUESTED BY CONTRACTED WORK ORDER. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-233 REV A	HYDRAULIC SYSTEM HOSE INSPECTION AND REPLACEMENT IN THE UPPER DECK AREA	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-232	REMARKING OF PALL AEROSPACE P/N ON THE ENGINE AIR PARTICLE SEPARATOR LEFT AND RIGHT.	-	-	-/NOT APPLICABLE	HELICOPTER NOT EQUIPPED WITH THE EAPS KIT. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-231	SPECTROLAB NIGHTSUN II XP, GIMBAL DUAL LOCKING DEVICE	-	-	-/NOT APPLICABLE	HELICOPTER NOT EQUIPPED WITH KIT NIGHTSUN XP II SEARCHLIGHT. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-230	DIODE SUPPORT RETROMODIFICATION.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-229	INTEGRATED SECONDARY FLIGHT DISPLAY SOFTWARE MODIFICATION.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-228	POSITION LIGHTS AND POSITION/STROBE LIGHTS ON TAIL PLANE WINGLETS, IMPROVEMENT OF.	-	-	-/SUPERSEDED	SUPERSEDED BY BT 139-301. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	71
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	BT 139-227	NUMBER 2 AC GENERATOR (25 KVA) INLET DUCT ASSY P/N 4G2420A04931, REPLACEMENT OF.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-226	NEW SBAS (WAAS) CAPABLE GPS.	-	-	-/OPTIONAL	HELICOPTER EQUIPPED WITH KIT 2ND GPS HAVING DIFFERENT P/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-225 REV A	MISSION BUS (NON ESS 2) VARIANT P/N 3G2406P02511, INSTALLATION OF	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-224	ENHANCED GROUND PROXIMITY WARNING SYSTEM (EGPWS) MAINTENANCE CONNECTOR, REPOSITIONING OF.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-222 REV A	CEILING LINER SPLIT RETRO-MODIFICATION P/N 3G2506P07811 OR P/N 3G2506P07812, INSTALLATION OF.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-221 REV B	RETROMOD EXHAUST DUCT BLANKET REPLACEMENT LEFT P/N 3G7806P01531 OR P/N 3G7806P01532 AND RIGHT P/N 3G7806P01631 OR P/N 3G7806P01632.	-	-	-/NOT APPLICABLE	EXHAUST PIPES NOT AFFECTED. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-220	DOOR STEP ASSY RETROMOD P/N 3G2506P07011 / 3G2506P07111.	-	-	-/NOT APPLICABLE	HELICOPTER NOT EQUIPPED WITH DOOR STEP LH AND RH ASSY AFFECTED P/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	72
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	BT 139-219	SINGLE HOIST ELECTRICAL PROVISION MODIFICATION.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-218	DOUBLE HOIST ELECTRICAL PROVISION MODIFICATION.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-217	INSTALLATION OF HINGE BAGGAGE DOOR RETROFIT KIT P/N 3G5230F00111.	-	-	-/NOT APPLICABLE	NOT APPLICABLE PER ENHANCED FUSELAGE. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-216	SEARCH AND RESCUE WEATHER RADAR PRIMUS 701 KIT P/N 4G3441F00111, INSTALLATION OF.	-	-	-/COMPLIED WITH	COMPLIED WITH BY MANUFACTURER. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-215	ATA 33 - INSTALLATION OF HID STEERABLE LANDING LIGHTS	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-214 REV A	REPLACEMENT OF STANDBY ATTITUDE DIRECTOR INDICATOR P/N 501-1860-0201/-0601 PRE-MOD #17	-	-	-/NOT APPLICABLE	DIFFERENT P/N INSTALLED. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-213 REV A	GENERAL VISUAL INSPECTION OF NLG ACTUATOR FITTING AREA	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	73
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	BT 139-212	HOIST PENDANT SUPPORT ASSY P/N 3G2591A05431, REPLACEMENT OF.	-	-	-/NOT APPLICABLE	HELICOPTER NOT EQUIPPED WITH EXTERNAL RESCUE HOIST INSTALLATION. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-211 REV A	BEARING P/N 3G6320V01252	-	-	-/NOT APPLICABLE	MAIN GEARBOX SERIAL NUMBER NOT AFFECTED. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-210	CABIN DOUBLE LAYER WINDOWS	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-209	TAIL CABLE ASSY INSTALL ATION IMPROVEMENT	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-208 REV B	DIODE SUPPORT IMPROVEMENT.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-207 REV B	KIT FANS FOR REAR AVIONIC BAYS P/N 4G2150F00311, INSTALLATION OF.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-206	LANDING GEAR CONTROL PANEL P/N 3G3230V00632, FRONT PANEL UPGRADE.	-	-	-/COMPLIED WITH	MODIFICATION ALREADY INCORPORATED ON THE HELICOPTER. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	74
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	BT 139-205 REV A	CHAFING BETWEEN ENGINE FUEL SUPPLY TUBE AND HEATING SYSTEM TUBE ASSY.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICAL STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-203 REV A	BATTERY PANEL REINFORCEMENT RETROMOD P/N 3G5306P26511.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICAL STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-202	INSTALLATION OF BREEZE HOIST 90 M CABLE LENGTH.	-	-	-/NOT APPLICABLE	HELICOPTER NOT EQUIPPED WITH KIT EXTERNAL HOIST P/N 3G2591F00111. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICAL STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-201	PASSENGER CABIN UTILITY SOCKET, UPGRADING OF MAXIMUM CURRENT RATING FROM 5A TO 15A.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICAL STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-200	TAILBOOM REINFORCEMENT STRUCTURAL RETRO-MODIFICATION	-	-	-/NOT APPLICABLE	HELICOPTER EQUIPPED WITH TAIL ASSEMBLY HAVING DIFFERENT P/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICAL STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-199	TELEPHONICS 1500B+ WEATHER AND SEARCH RADAR, REPLACEMENT OF INTERFACE UNIT MOUNTING TRAY.	-	-	-/NOT APPLICABLE	HELICOPTER NOT EQUIPPED WITH TELEPHONICS 1500B+ WEATHER AND SEARCH RADAR. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICAL STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-198 REV B	ATA 53 - SECONDARY AVIONIC BAY MODIFICATION	-	-	-/NOT APPLICABLE	INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICAL STATUS LIST DATED 08/10/2019.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	75
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	BT 139-197	REPLACEMENT OF THE EXISTING HOIST SEARCH LIGHTS WITH THE NEW HID STEERABLE LIGHT.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-196	REPLACEMENT OF THE EXISTING LEFT AND RIGHT ADDITIONAL LANDING LIGHTS WITH THE NEW HID STEERABLE LIGHTS.	-	-	-/NOT APPLICABLE	NOT APPLICABLE PER ENHANCED FUSELAGE. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-195 REV B	TAIL ASSY INSPECTION.	-	-	-/NOT APPLICABLE	HELICOPTER EQUIPPED WITH TAIL ASSEMBLY HAVING DIFFERENT P/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-194	TAIL ASSY INSPECTION.	-	-	-/SUPERSEDED	SUPERSEDED BY BT 139-195. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-193	TAIL ASSY INSPECTION.	-	-	-/SUPERSEDED	SUPERSEDED BY BT 139-195. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-192	SLIDING PASSENGER DOOR CHECK AND ADJUSTMENT	-	-	-/NOT APPLICABLE	BT APPLICABLE ONLY ON HELICOPTERS IN SERVICE. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-191	INSTALLATION OF SEARCH LIGHT C/A EXTENSION RETROMOD 3G3306P01711.	-	-	-/NOT APPLICABLE	NOT APPLICABLE PER ENHANCED FUSELAGE. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	76
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	BT 139-190	DATA ACQUISITION UNIT (DAU) MOUNTING WEDGES RIVET INSPECTION AND MODIFICATION.	-	-	-/NOT APPLICABLE	HELICOPTER EQUIPPED WITH KIT HUMS HAVING DIFFERENT P/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-189	INCREASE OF TAIL ROTOR PITCH ANGLE BY APPLICATION OF THE KIT P/N 4G6722F00111.	-	-	-/COMPLIED WITH	MODIFICATION ALREADY INCORPORATED ON THE HELICOPTER. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-188	VHF COMM 4 (ERICSSON C54) RETRO MOD P/N 3G2306P04211.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-187 REV B	MAIN ROTOR DAMPER EYE END INSPECTION.	-	-	-/NOT APPLICABLE	HELICOPTER EQUIPPED WITH MAIN ROTOR DAMPERS HAVING DIFFERENT PART NUMBER. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-186	MISSION CONSOLE RH RACK RETROMODIFICATION P/N 3G5306P40111, INSTALLATION OF.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-185	WATER SEPARATOR ASSEMBLY P/N 3G2120A01331, INSTALLATION OF.	-	-	-/NOT APPLICABLE	HELICOPTER NOT EQUIPPED WITH FORCED VENTILATION AND HEATING KIT P/N 3G2141F00114. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	77
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	BT 139-184	MGB INPUT MODULE ASSY P/N 3K6320A00135, IMPROVEMENT OF.	-	-	-/COMPLIED WITH	COMPLIED WITH BY MANUFACTURER. MAIN GEARBOX INPUT MODULE ASSY PART NUMBER 3K6320A00136 INSTALLED WITH SEAL ASSY PART NUMBER 3K6320V00952 ALREADY EMBEDDED. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-183	EMERGENCY EXIT DECALS.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-182 REV A	ATA 98 - INSTALLATION OF LIGHTNING SENSOR SYSTEM KIT	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-181	PACKING POSITION OF CONDUIT/FIRING CABLE FOR THE LEFT LIFERAFTS.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-180	UPPER COWLING ASSY RETROMODIFICATION P/N 3G7106P08431, INSTALLATION OF.	-	-	-/NOT APPLICABLE	NOT APPLICABLE PER ENHANCED FUSELAGE. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-179	SINGLE HOIST ELECTRICAL PROVISION MODIFICATION.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	78
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	BT 139-178	RELOCATION OF HEELS BT7 BATTERY.	-	-	-/NOT APPLICABLE	HELICOPTER NOT EQUIPPED WITH KIT HEELS. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-177	ELECTRICALH ARNESS CHAFING.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-176	TAIL ROTOR DRIVE MGB ADAPTER VARIANT P/N 3G6306P01011, INSTALLATION OF	-	-	-/COMPLIED WITH	MODIFICATION ALREADY INCORPORATED ON THE HELICOPTER. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-175 REV B	STARTER-GENERATOR GROUNDING CHECK AND IMPROVEMENT	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-174	HINGED WINDOWS IN CREW DOORS, INSTALLATION OF.	-	-	-/OPTIONAL	AT CUSTOMER'S OPTION - NOT REQUESTED BY CONTRACTED WORK ORDER. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-173 REV C PART II	ATA 22 - INSTALLATION OF KIT 4 AXIS ENHANCED FLIGHT DIRECTOR WITH SAR MODES	-	-	-/COMPLIED WITH	COMPLIED WITH BY MANUFACTURER. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	79
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	BT 139-173 REV C PART I,III AND IV	ATA 22 - INSTALLATION OF KIT 4 AXIS ENHANCED FLIGHT DIRECTOR WITH SAR MODES	-	-	-/NOT APPLICABLE	PART I AND II : NOT APPLICABLE BY HELICOPTER S/N. PART IV : NOT APPLICABLE DUE TO RESCUE HOIST KIT P/N 3G2591F00111 NOT INSTALLED. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-172	ROTOR BRAKE RUBBER STOP ADJUSTMENT AND INSTALLATION PROCEDURE.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-171 REV B	OVERHEAD CB PANEL VARIANT	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-170	DOUBLE HOIST ELECTRICAL PROVISION MODIFICATION.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-169	2nd SEARCH LIGHT KIT P/N 4G3340F01811, INSTALLATION OF	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-168	VIDEO MAN AGEMENT UNIT KIT P/N 4G9310F00611, INSTALLATION OF.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-167	LIFE-RAFTS INFLATION SYSTEM VALVE INSPECTION.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	80
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	BT 139-166	MODULAR AVIONIC UNITS	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-165	FLIGHT CONTROL BALANCE SYSTEM INSTALLATION, IMPROVEMENT OF.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-164	RIGID HANDLE INSTALLATION KIT P/N 4G5212F00311.	-	-	-/OPTIONAL	AT CUSTOMER'S OPTION - NOT REQUESTED BY CONTRACTED WORK ORDER. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-163 REV A	TAIL ROTOR BLADE LIGHTNING STRIP, IMPROVEMENT OF.	-	-	-/NOT APPLICABLE	INSTALLED TAIL ROTOR BLADES P/N 3G6410A00133. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-162	INSTALLATION OF N°2 ICS ADDITIONAL HEADSETS IN AW139 PASSENGER'S CABIN WITH THE APPLICATION OF THE ICS EMS VARIANT CABLE ASSY P/N 3G9B02B03001.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-161 REV A	HIGH INTENSITY LANDING LIGHT VARIANT P/N 3G3306P01411 AND HIGH INTENSITY SECONDARY LANDING LIGHT VARIANT P/N 3G3306P05611, INSTALLATION OF.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-160	PEDAL ASSY EXCESSIVE FORCE KIT P/N 3G6706P01531	-	-	-/NOT APPLICABLE	HELICOPTER NOT EQUIPPED WITH PEDAL ASSY P/N 3E6721A00137. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	81
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	BT 139-159 REV B	TAIL BOOM RETRO-MODIFICATION PROCEDURE.	-	-	-/NOT APPLICABLE	DIFFERENT P/N OF TAIL BOOM ASSEMBLY INSTALLED. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-158 REV A	KIT RIGID HANDLE ON PASSENGER DOORS	-	-	-/OPTIONAL	APPLICABLE TO AIRCRAFT SERIAL NUMBER. PART NUMBER KIT RIGID HANDLE FOR PASSENGER DOORS 4G5212F00211 IS NOT FITTED ON AIRCRAFT. COMPLY UPON CUSTOMER REQUEST.
Standard SBs	BT 139-156 REV A	ATA 23 - INSTALLATION OF EADS TETRA RADIO KIT	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-154	SATCOM WIRELESS TELEPHONE, INSTALLATION OF.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-152	FORWARD LONGERON - END CONE PANEL	-	-	-/NOT APPLICABLE	INSTALLED TAIL BOOM ASSEMBLY WITH DIFFERENT P/N. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-151	AW 139 HEALTH AND USAGE MONITORING SYSTEM (HUMS), UPLOAD OF THE NEW ON BOARD SYSTEM CONFIGURATION (OBSC) FILE VERSION AGB2 ON HUMS DATA ACQUISITION UNIT (DAU) AND INSTALLATION OF THE AW 139 CONFIGURED HUMS GROUND STATION (HGS) V4.0.0.	-	-	-/NOT APPLICABLE	HELICOPTER NOT EQUIPPED WITH MGB P/N 4G6320A00132. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-150	CARGO HOOK CALIBRATION CONFIRMATION.	-	-	-/NOT APPLICABLE	CARGO HOOK NOT AFFECTED BY S/N. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECHNICI STATUS LIST DATED 08/10/2019.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	82
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	BT 139-149	EGPWS (ENHANCED GROUND PROXIMITY WARNING SYSTEM) AURAL WARNING INHIBIT CABLE.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-147	ENHANCED GROUND PROXIMITY WARNING SYSTEM (EGPWS) KIT P/N 3G3440F00211, INSTALLATION OF.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-146	INTEGRATED ENVIRONMENTAL CONTROL SYSTEM (ECS) MODIFICATION.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-145	INTERMEDIATE GEARBOX (IGB) FITTING ASSEMBLY	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-144	KIT TRAFFIC ALERT AND COLLISION AVOIDANCE SYSTEM (TCAS) P/N 3G3450F00311, INSTALLATION OF.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-143	ATA 28 - KIT CLOSE CIRCUIT REFUEL RECEIVER P/N 4G2820F00211	-	-	-/OPTIONAL	AT CUSTOMER'S OPTION - NOT REQUESTED BY CONTRACTED WORK ORDER. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-142	FIRE DETECTION/EXTINGUISHING CONTROL PANEL P/N 3G2600V00252.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	83
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	BT 139-141 REV. /	ATA 25 - CHART HOLDER REPLACEMENT	-	-	-/NOT APPLICABLE	KIT CHART HOLDER P/N 4G2510F00112 ALREADY IN CONFIGURATION. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-140 REV C	INCREASE OF AIRCRAFT MAXIMUM TAKE-OFF WEIGHT (mtow) UP TO 6800 KG.	-	-	-/OPTIONAL	AT CUSTOMER'S OPTION - NOT REQUESTED BY CONTRACTED WORK ORDER. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-139	POWER CONTROL MODULE 1 & 2 FILTER DIFFERENTIAL PRESSURE INDICATOR SWITCHES REPLACEMENT.	-	-	-/COMPLIED WITH	MODIFICATION ALREADY INCORPORATED ON THE HELICOPTER. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-138	27 Ah AUXILIARY BATTERY, INSTALLATION OF.	-	-	-/OPTIONAL	AT CUSTOMER'S OPTION - NOT REQUESTED BY CONTRACTED WORK ORDER. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-136	CIRCUIT BREAKER CB27 REPLACEMENT.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	SB NO. 139-135 REVISION A PART I, II, V	WIRE STRIKE PROTECTION SYSTEM (WSPS) KIT	-	-	-/OPTIONAL	TIC-AW139-22-0013 DATED 11 FEBRUARY 2022 PART I: APPLICABLE DUE TO AIRCRAFT S/N AFFECTED PART II: APPLICABLE DUE TO AIRCRAFT S/N AFFECTED PART V: APPLICABLE DUE TO AIRCRAFT S/N AFFECTED COMPLIANCE: AT CUSTOMER'S OPTION

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	84
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	BT 139-134	TAIL ASSY INSPECTION.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-133 REV A	GENERATOR CONTROL UNIT (GCU) P/N 1152550-5.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-131	PEDAL ASSY P/N 3E6721A00137 CHECK REPLACEMENT.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-129 REV A	COCKPIT DOORS WINDOWS REPLACEMENT.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-128	FLOOR PANEL RETRO MODIFICATION P/N 3P5306P03011 OR P/N 3P5306P02911.	-	-	-/NOT APPLICABLE	NOT APPLICABLE PER ENHANCE FUSELAGE. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-127 REV A	RADIO TALON RT-8108 KIT P/N 3G2310F00311, INSTALLATION OF.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-126	WIRE STRIKE PROTECTION SYSTEM (WSPS) TOP CABLE CUTTER ASSY P/N 423-83001-1 REWORK.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	85
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	BT 139-125	NI-900 NETWORK INTERFACE MODULE ASSEMBLY (NIM) P/N 7517964-914.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-124	BATTERY CABLE ASSEMBLY INSTALL ATION RETROMODIFICATION.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-123	ACTIVE VIBRATION CONTROL SYSTEM KIT P/N 4G1830F00211, INSTALLATION OF.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-122	FISCHER LIGHT-WEIGHT PILOT SEATS KIT P/N 4G2510F00211 OR P/N 4G2510F00311, INSTALLATION OF.	-	-	-/COMPLIED WITH	COMPLIED WITH BY MANUFACTURER. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-121	STATIC INVERTER P/N 1152572-1, REPLACEMENT OF	-	-	-/COMPLIED WITH	MODIFICATION ALREADY INCORPORATED ON HELICOPTER. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-120	PASSENGER FIXED FOOTSTEP PROTECTION KIT P/N 3G5260A20611, INSTALLATION OF.	-	-	-/COMPLIED WITH	COMPLIED WITH BY MANUFACTURER. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-119	SECONDARY LANDING LIGHT AND SX16 SEARCH LIGHT SYSTEMS CONTROL, IMPROVEMENT OF.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	86
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	BT 139-118 REV B	PASSENGER DOOR INSTALLATION VISUAL INSPECTION AND REINFORCEMENT INSTALLATION.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-117	TCAS TOP ANTENNA GROUNDING IMPROVEMENT.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-116 REV A	RIGHT AFT FLOAT RETRO-MODIFICATION P/N 3G5306P47011, INSTALLATION OF.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-115 REV D PART II AND III	MAST VIBRATION ABSORBER KIT P/N 4G1860F00113, INSTALLATION OF.	-	-	-/NOT APPLICABLE	INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-114	ACCESSIBILITY IMPROVEMENT.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-113	FULL CABIN EXTENSION KIT P/N 4G5340F00111, INSTALLATION OF.	-	-	-/OPTIONAL	AT CUSTOMER'S OPTION - NOT REQUESTED BY CONTRACTED WORK ORDER. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-112 REV A	ELECTRICAL MODIFICATIONS ON LONG NOSE HELICOPTERS.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-111 REV A	2nd GPS WIRING DIAGRAM MODIFICATION.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	87
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	BT 139-110	MLG SPONSON REAR FAIRING STEP AREA EXTENSION.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-109 REV B	ENGINE EXHAUST PIPE FAIRING, MODIFICATION OF.	-	-	-/COMPLIED WITH	MODIFICATION ALREADY INCORPORATED ON THE HELICOPTER. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-108	ADDITIONAL LOWER MOORING INSTALLATION P/N 3G5330A12011.	-	-	-/OPTIONAL	AT CUSTOMER'S OPTION - NOT REQUESTED BY CONTRACTED WORK ORDER. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-107 REV B	STROBE LIGHT UNDER FUSELAGE KIT, INSTALLATION OF.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-106	AIR CONDITIONING SYSTEM COCKPIT AND CABIN EVAPORATORS, IMPROVEMENT OF.	-	-	-/NOT APPLICABLE	HELICOPTER NOT EQUIPPED WITH AIR CONDITIONING SYSTEM KIT P/N 3G2150F00114. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-105 REV A	AIRCRAFT WATERPROOFING IMPROVEMENT.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	88
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	BT 139-104	INTEGRATED ECS MAINTENANCE AND SERVICE PANEL, INSTALLATION OF	-	-	-/NOT APPLICABLE	HELICOPTER NOT EQUIPPED WITH ECS KIT P/N 3G2150F00114. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-103 REV A	QUICK ACCESS RECORDER P/N 4G3130F00311 INSTALLATION.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-102	INSTALLATION OF THE KIT RADS-AT WITH FUSELAGE BASIC CABLE ASSY ON THE AW139 HELICOPTERS, WITH THE APPLICATION OF THE RETROFIT KIT P/N 3G3130F00412.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-101	VIP CABIN INTERFACES WIRING DIAGRAM MODIFICATION.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-100	MAIN ROTOR FIPS INSTALLATION, REPLACEMENT OF THE SLIP RING ASSY BOLTS	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-099	TO PROVIDE THE INSTRUCTIONS FOR INSTALLATION OF THE CENTRAL DISPLAY KIT P/N 4G4630F00111.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-098	FLOAT SWITCH P/N 3G9560V01151.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	89
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	BT 139-097 REV A	TAIL GEARBOX FITTING INSPECTION.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-096	FLIR (SEAFLIR II) STRUCTURAL AND ELECTRICAL PROVISIONS INSTALLATION OF.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-095 REV A	W/D HYDRAULIC SYSTEM	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-094	PILOT DOOR EXTERNAL HANDLE RETRO MODIFICATION P/N 3G5206P05511.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-093	CHART HOLDER PLT/CPLT KIT, INSTALLATION OF.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-092	WINDSHIELD WASHING KIT, INSTALLATION OF.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-090 REV A	"PRIMUS EPIC®" FLIGHT SOFTWARE RELEASE 4.8.0 INSTALLATION (4 AXIS BASIC FLIGHT DIRECTOR KIT P/N 4G2210F00311).	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	90
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	BT 139-089	FRAME STA 3900 AND FRAME STA 5700 STRUCTURAL REPAIR RETROMODIFICATION	-	-	-/NOT APPLICABLE	INSTALLED NEW P/N FRAMES 3900 AND FRAMES 5700 (SEE HELICOPTER LOGBOOK). INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-088	MAIN ROTOR BLADE ELECTRICAL BONDING.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-087 REV A	PART I: DIMENSIONAL CHECK OF COCKPIT DOOR AND WINDOWS INSTALLATION. COCKPIT DOOR WINDOWS SEAL REPLACEMENT.PART II: SLIDING WINDOW REINFORCEMENT INSTALLATION.	-	-	-/SUPERSEDED	SUPERSEDED BY BT 139-129. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-086	CIRCUIT BREAKER ENGINE IGNITER 1&2 (CB107 AND CB108).	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-085	FIRE EXTINGUISHER BOTTLE ASSY P/N 3G2620V00131.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-084	POWER C/A (B1A18) P/N 3G9B11A01804.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-082	ELASTOMERIC BEARINGS P/N 3G6220V00154.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	91
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	BT 139-081	Y9/Y10 BELLCRANK ASSY RETRO MODIFICATION P/N 3G6706P00611.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-080 REV A	PART I:REPLACEMENT OF TRANSPONDER TOP ANTENNA COAXIAL CABLES.PART II: REPLACEMENT OF TRANSPONDER P/N 7517400-885 PRE-MODY.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-079	TAIL POSITION LIGHT ADAPTER, INSTALLATION OF.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-078	REAR FUSULAGE LONGERONS RETRO MODIFICATION.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-077 REV A	INSTALLATION OF VIP CABIN PASSENGER ELECTRICAL PROVISION P/N 3G2520A00311 (COMPLETE PROVISION FOR 115V AC POWER INSTALLATION).	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-076	KIT BAGGAGE COMPARTMENT ANCHOR SYSTEM P/N 3G2550F00113.	-	-	-/COMPLIED WITH	INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-075	KIT ICS PASSENGER CABIN (12/16 Pax) P/N 4G2350F00411.	-	-	-/OPTIONAL	AT CUSTOMER'S OPTION - NOT REQUESTED BY CONTRACTED WORK ORDER. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	92
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	BT 139-074 REV C	AW139/AB139 HEALTH AND USAGE MONITORING SYSTEM (HUMS), UPLOAD OF THE NEW ON BOARD SYSTEM CONFIGURATION (OBSC) FILE VERSION 5.1.0 ON HUMS DATA ACQUISITION UNIT (DAU) AND INSTALLATION OF THE AW139/AB139 CONFIGURED HUMS GROUND STATION (HGS) V3.6.0.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-073	RAPELLING KIT P/N 4G2590F00111.	-	-	-/COMPLIED WITH	INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-072	PART I: WULFSBERG V/UHF FLEXCOMM II 2ND CONTROL PANEL KIT P/N 3G2310F00711 INSTALLATION.PART II: AUXILIARY O/H PANEL RETRO-MODIFICATION.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-071	DC GENERATOR MAX LOADING PLACARD P/N 3G1130L00551, INSTALLATION OF.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-070	"PRIMUS EPIC®" SOFTWARE RELEASE 3.6.0. NVG KIT INSTALLATION.	-	-	-/NOT APPLICABLE	NOT APPLICABLE TO 'LONG NOSE' CONFIGURATION. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-069 REV B	TAILPIPE ASSY LH P/N 3G7800L00131 AND TAILPIPE ASSY RH P/N 3G7800L00231.	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO DIFFERENT PART NUMBER INSTALLED. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-068	EXTERNAL HOIST INSTALLATION P/N 3G2591F00111 (Breezeeastern P/N HS-20200-421-02) INSPECTION OF.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	93
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	BT 139-067	VHF COMM 5 EMS AND UHF/VHF COMM 3/4 EMS, INSTALLATION OF.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-066 REV A	UNDERWATER ACOUSTIC BEACON	-	-	-/OPTIONAL	AT CUSTOMER'S OPTION - NOT REQUESTED BY CONTRACTED WORK ORDER. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-065 REV A	KIT NOSE LANDING GE AR DOORS P/N 3G5280F00111 AND P/N 4G5280F00111, INSTALLATION OF.	-	-	-/NOT APPLICABLE	NOT APPLICABLE ON ENHANCED PLUS FUSELAGE. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-064 REV A	HEELS COCKPIT DOORS LIGHTS P/N 3G3350A00411 INSPECTION	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-063 REV. /	FIRE PANEL CONNECTIONS	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-062	ROTOR BRAKE CABLE ASSEMBLY VARIANT, INSTALLATION OF.	-	-	-/COMPLIED WITH	MODIFICATION ALREADY INCORPORATED ON THE HELICOPTER. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-061 REV A	KIT 2ND GPS P/N 4G3450F00611 OR KIT 2ND GPS SBAS P/N 4G3450F00613, INSTALLATION OF	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	94
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	BT 139-060	TAIL ROTOR DRIVE SHAFT ASSY N. 2 AND N. 3.	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO DIFFERENT P/N INSTALLED(SEE HELICOPTER LOGBOOK). INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-059 REV A	PART I: REPLACEMENT OF DEFECTIVE PRESSURE SWITCH P/N 70797-85 OF THE NUMBER 1 HYDRAULIC POWER SYSTEM.PART II: REPLACEMENT OF DEFECTIVE PRESSURE SWITCHES P/N 70797-85 OF THE NUMBER 2 HYDRAULIC POWER SYSTEM.	-	-	-/COMPLIED WITH	MODIFICATION ALREADY INCORPORATED ON THE HELICOPTER. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-058 REV A	NI-900 NETWORK INTERFACE MODULE ASSEMBLY (NIM) P/N 7517964-912 MOD AH.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-057 REV B	INTRODUCTION OF VARIANT P/N 3G0206P00311 / 3G0206P00312 ON TCCA REGISTERED AIRCRAFT.	-	-	-/NOT APPLICABLE	HELICOPTER NOT REGISTERED TCCA. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-056	KIT RADIO NAT NTX VHF/FM P/N 4G2310F00111 INSTALLATION OF.	-	-	-/OPTIONAL	AT CUSTOMER'S OPTION - NOT REQUESTED BY CONTRACTED WORK ORDER. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-055	FISHER PILOT SEATS KIT P/N 3G2510F00211 INSTALLATION.	-	-	-/OPTIONAL	AT CUSTOMER'S OPTION - NOT REQUESTED BY CONTRACTED WORK ORDER. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	95
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	BT 139-054 REV A	PART I: FLIGHT DATA RECORDER POWER SUPPLY MODIFICATION PART II: DC BATTERY AND EXTERNAL POWER STARTER MODIFICATION	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-053	NIC-200 (NETWORK INTERFACE CONTROLLER) P/N 7026542-1901 REPLACEMENT.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-052	KIT ACRYLIC WINDSHIELD P/N 3G5610F00211.	-	-	-/COMPLIED WITH	INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-051 REV A	WEATHER RADAR PRIMUS 701 KIT P/N 4G3441F00111 INSTALLATION.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-050	DIRECTION FINDER KIT P/N 3G3450F00911 INSTALLATION OF.	-	-	-/OPTIONAL	AT CUSTOMER'S OPTION - NOT REQUESTED BY CONTRACTED WORK ORDER. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-049 REV A	WATER ACTIVATED SWITCH P/N 503-23 REPLACEMENT.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-048	MAIN LANDING GEAR PN 3G3210V00133 (LH) AND P/N 3G3210V00233 (RH), REPLACEMENT WITH THE SUPERSEDING P/N 3G3210V00135 (LH) AND P/N 3G3210V00235 (RH).	-	-	-/COMPLIED WITH	MODIFICATION ALREADY INCORPORATED ON THE HELICOPTER. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	96
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	BT 139-047 REV A	MGB COOLING FAN P/N 3G6320V03853 REPLACEMENT.	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO COMPONENT NOT AFFECTED. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-046	4 AXIS AUTOPILOT KIT P/N 3G2210F00211, INSTALLATION OF.	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO DIFFERENT P/N INSTALLED. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-045	ALTERNATIVE 27Ah AUXILIARY BATTERY INSTALLATION KIT P/N 4G2430F00112.	-	-	-/OPTIONAL	AT CUSTOMER'S OPTION - NOT REQUESTED BY CONTRACTED WORK ORDER. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-043 REV A PART IV	HEATED WINDSHIELDS KIT P/N 3G5610F00611, INSTALLATION OF.	-	-	-/OPTIONAL	AT CUSTOMER'S OPTION - NOT REQUESTED BY CONTRACTED WORK ORDER. INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-042	2ND TRANSPONDER KIT P/N 3G3450F00512 INSTALLATION.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-041	NVG LIGHTS KIT P/N 4G3360F00111 INSTALLATION.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	97
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	BT 139-040 REV B	WIRE STRIKE PROTECTION KIT P/N 4G9540F00211 INSTALLATION	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-039	INSTALLATION OF SEARCH LIGHT SX16 KIT P/N 3G3340F00111.	-	-	-/OPTIONAL	AT CUSTOMER'S OPTION - NOT REQUESTED BY CONTRACTED WORK ORDER INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	SB139-038 REV G PART IV	HUMS CAMERA TRACKER INSTALLATION	-	-	-/OPTIONAL	INSTALLED COMPLETED PROVISION AND FIXED PARTS ONLY INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 03/12/2019.
Standard SBs	BT 139-036 REV A	EXTERNAL AND INTERNAL PUBLIC ADDRESS SYSTEM P/N 3G2350F00211 INSTALLATION OF.	-	-	-/OPTIONAL	AT CUSTOMER'S OPTION - NOT REQUESTED BY CONTRACTED WORK ORDER. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-034 REV C	HF SYSTEM KIT P/N 3G2310F00211.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-033	FLIR SAFIRE III HD WITH CEU P/N 3203134-340, IMPROVEMENT OF.	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO KIT NOT INSTALLED. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-032 REV B	RETROFIT FUEL DISTRIBUTION, INSTALLATION OF NEW MANIFOLD P/N 3G2820V00731.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	98
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	BT 139-031 REV A	KIT EXTERNAL HOIST (FEET FOUR WAY) P/N 3G2591F00111 INSTALLATION OF.	-	-	-/OPTIONAL	AT CUSTOMER'S OPTION - NOT REQUESTED BY CONTRACTED WORK ORDER INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-030 REV A	KIT WEATHER RADAR PRIMUS 660 P/N 3G3441F00112 INSTALLATION OF.	-	-	-/NOT APPLICABLE	NOT APPLICABLE TO 'LONG NOSE' CONFIGURATION. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-029 REV A	SNOW SKIS AND SLUMP PADS PROTECTION INSTALLATION.	-	-	-/NOT APPLICABLE	AT CUSTOMER'S OPTION - NOT REQUESTED BY CONTRACTED WORK ORDER INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-028 REV B	ENHANCED GROUND PROXIMITY WARNING SYSTEM (EGPWS).	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-027 REV B	ATA 25 - INSTALLATION OF CARGO HOOK AND CARGO HOOK VIDEO CAMERA	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-026	STROBE LIGHTS KIT P/N 3G3340F00411 INSTALLATION.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-025 REV A	ATA 34 - INSTALLATION OF THE KIT KTA 970 TCAS I SYSTEM	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	99
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	BT 139-024	DIGITAL MAP KIT P/N 3G9310F00112 INSTALLATION.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-023	ENGINE PARTICLE SEPARATOR KIT P/N 3G7160F00114 INSTALLATION.	-	-	-/OPTIONAL	AT CUSTOMER'S OPTION - NOT REQUESTED BY CONTRACTED WORK ORDER INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-022 REV C	EMERGENCY FLOATS AND LIFE RAFTS P/N 3G9560F00111 INSTALLATION OF.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-021 REV B	AUXILIARY FUEL TANK KIT P/N 3G2800F00111 INSTALLATION OF.	-	-	-/OPTIONAL	SEE BT 139-451 INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-020 REV C	PART I: LIFE LIMIT OF THE FIN ASSY. PART II: FIN ASSY INSPECTION.	-	-	-/CANCELLED	NOT APPLICABLE DUE TO BT CANCELLED. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-019	REPLACEMENT OF THE PILOT AND COPILOT ICS PANEL P/N 7511900-982 OR 7511900-98201 WITH THE NEW PILOT AND COPILOT ICS PANEL P/N 7511900-98202.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-018 REV C	MIDDLE SECTION FRAME 5700 INSPECTION.	-	-	-/CANCELLED	CANCELLED. ITS TECHNICAL CONTENT IS SUPERSEDED BY AMPI MANDATORY INSPECTION MI53-12 (REF. DM 39-A-04-20-00-00A-028E-P). INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	100
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	BT 139-017	EJECTOR DUCTS RETRO MODIFICATION DRAWING P/N 3G7800P00711.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-016 REV B	REPLACEMENT OF THE PEDAL ASSY P/N P/N 3E6721A00135 WITH THE NEW ASSY P/N 3E6721A00136.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-015	REAR FUSELAGE AND TAILBOOM RETROMODIFICATIONS.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-014 REV B	"PRIMUS EPIC®" FLIGHT SOFTWARE RELEASE 3.3.0 INSTALLATION OF.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-013 REV B	WIRING DIAGRAM DC EXTERNAL POWER P/N 3G240W00101.	-	-	-/COMPLIED WITH	MODIFICATION ALREADY INCORPORATED ON THE HELICOPTER. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-012	P/N1-8486-3 SMART LINEAR ACTUATOR (LATERAL). P/N 2-8486-3 SMART LINEAR ACTUATOR (TAIL ROTOR). P/N 8486-3 SMART LINEAR ACTUATOR (LONGITUDINAL).	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-011 REV C	FAIRING ASSY LH P/N 3G5306P02233 OR 3P5330A31131.	-	-	-/NOT APPLICABLE	NOT APPLICABLE BY HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	101
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	BT 139-010 REV A	REPLACEMENT OF THE VNE PLACARD ILLUMINATED P/N 3G1130L00152 WITH NEW VNE PLACARD ILLUMINATED P/N 3G1130L00155.	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-009 REV A	PART I: INSPECTION OF THE LEFT AND RIGHT BRAKE PEDAL ASSY PILOT AND COPILOT P/N 3E6721A01432 E - 1532.PART II: REWORK LEFT AND RIGHT BRAKE PEDAL ASSY PILOT AND COPILOT P/N 3E6721A01432 AND - 1532.	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-008 REV A	OVERHEAD CB PANEL ASSY DRAWING P/N 3G2490A00233, REPLACEMENT OF THE AUTO BREAKER TRIM P/N MS3320-5 CON P/N MS3320-7-1/2.	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-007 REV A	CS TROUBLESHOOTING DRAWING P/N 3G2350W00102.	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-006	NEW PITCH & ROLL TRIM ACTUATOR P/N 3G2220V00137, YAW TRIM ACTUATOR P/N 3G2220V00136 AND COLLECTIVE TRIM ACTUATOR P/N 3G2220V00234, INSTALLATION OF.	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-005 REV A	OPERATIONAL ENVELOPE EXPANSION.PART I: REPLACEMENT OF THE SLIDING RING ASSY P/N 3G6220A00432.PART II: REPLACEMENT OF THE MAIN BRAKE ASSY P/N 3G3240V00332.	-	-	-/COMPLIED WITH	MODIFICATION ALREADY INCORPORATED ON THE HELICOPTER. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	102
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	BT 139-004	UPPER DECK INSULATING COVERS P/N 3G5306P07511, INSTALLATION OF	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-003 REV A	VARIANT 4TH FLAT PANEL DISPLAY P/N 3G4630F00111 INSTALLATION OF.	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
Standard SBs	BT 139-64-002 REV B	PART I: INSPECTION OF SLIDER ASSY P/N 3G6430A00131 AND OF THE SPIDER & SLIDER ASSY P/N 3G6430A01931.PART II: SOSTITUZIONE DELLO SLIDER BUSHING P/N 3G6430V00251.	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO HELICOPTER S/N. INFO IS REFERRED FROM LEONARDO HELICOPTERS ANNEX 2 - BOLLETTINI TECNICI STATUS LIST DATED 08/10/2019.
SERVICE BULLETIN ENGINE						
ENGINE #1						
Standard SBs	NO. 1 ENGINE ~ SB NO. 41120, REVISION 2	PT6C-67C BS963 AND BS1019 TO PT6C-67C1 BS1447 AND BS1448 - CONVERSION OF	-	-	-/NOT APPLICABLE	TIC-AW139-21-0248 (REV.0) TIC-AW139-21-0270 (REV.1) CATEGORY 8 - NOT APPLICABLE DUE TO ENGINE S/N NOT AFFECTED.
Standard SBs	NO. 1 ENGINE ~ SB NO. 41119, REVISION 4	PT6C-67C SERVICE BULLETIN IGNITION EXCITER - REPLACEMENT OF	-	-	-/Category 7	TIC-AW139-21-0249 DATED 30 JUNE 2021 APPLICABLE DUE TO ENGINE BUILD SPEC AND SERIAL NUMBER AFFECTED. COMPLIANCE: CATEGORY 7 - YOU CAN DO THIS SB WHEN THE SUPPLY OF THE SUPERSEDED PARTS IS FULLY USED.
Standard SBs	NO. 1 ENGINE ~ SB NO. 41112, REVISION 1	TURBOSHAFT ENGINE - FUEL MANAGEMENT MODULE (FMM) - REPLACEMENT / MODIFICATION	-	-	-/Category 7	TIC-AW139-21-0240 DATED 11 JUNE 2021 APPLICABLE DUE TO BUILD SPEC AND ENGINE SERIAL NUMBER AFFECTED. CONCURRENT REQUIREMENT: NONE.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	103
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	NO. 1 ENGINE ~ SB NO. 41114 REV. 2	ENGINE INSULATION BLANKET	-	-	-/OPTIONAL	REFERENCE: TIC-AW139-21-0241 APPLICABLE DUE TO ENGINE BUILD SPEC AND SERIAL NUMBER AFFECTED COMPLIANCE: CATEGORY 7: YOU CAN DO THIS SERVICE BULLETIN WHEN THE SUPPLY OF SUPERSEDED PARTS IS FULLY USED
Standard SBs	NO. 1 ENGINE ~ SB NO. 41110 REVISION 2	PERMANENT MAGNETIC ALTERNATOR GEARSHAFT AND ROLLER BEARING REPLACEMENT OF	-	-	-/Category 7	TIC-AW139-21-0239 DATED 11 JUNE 2021 APPLICABLE DUE TO ENGINE BUILD SPECT AND SERIAL NUMBER AFFECTED COMPLIANCE: CATEGORY 7 - YOU CAN DO THIS SERVICE BULLETIN WHEN THE SUPPLY OF SUPERSEDED PARTS IS FULLY USED.
Standard SBs	NO.1 ENGINE ~ SB NO. 41121 REV. 2	PT6C-67C SERVICE BULLETIN - HOUSINGS FOR ACCESSORY GEARBOX AND INLET CASE - IDENTIFICATION OF	-	-	-/Category 5	TIC-AW139-22-0112 DATED 27 APRIL 2022 CATEGORY 5. APPLICABLE DUE TO ENGINE TYPE AFFECTED.
Standard SBs	NO. 1 ENG - SB NO. 41057, REVISION 6	PT6C-67C SERVICE BULLETIN SHROUD HOUSING, COMPRESSOR TURBINE - REPLACEMENT/MODIFICATION OF	-	-	-/NOT APPLICABLE	TIC-AW139-21-0031 NOT APPLICABLE DUE TO ENGINE S/N (PCE-KB2214) NOT AFFECTED
Standard SBs	NO. 1 ENGINE ~ SB NO. 41118, REV. 3	TURBOSHAFT ENGINE - CENTRIFUGAL IMPELLER - REPLACEMENT OF	-	-	-/NOT APPLICABLE	TIC-AW139-20-217 DATED 31 DECEMBER 2020 CATEGORY 7, APPLICABILITY: NOT APPLICABLE DUE TO AFFECTED SERIAL NUMBER ENGINE NOT FITTED ON AIRCRAFT.
Standard SBs	NO. 1 ENGINE ~ SB NO. 41103, REVISION 1	TURBOSHAFT ENGINE - CHECK VALVE ASSEMBLY - REPLACEMENT OF	-	-	-/COMPLIED WITH	TIC-AW139-20-188 DATED 02 NOVEMBER 2020 COMPLIED BY OEM.
Standard SBs	NO. 1 ENGINE ~ SB NO. 41100, REVISION 8	TURBOSHAFT ENGINE - NO. 5 BEARING OUTPUT SHAFT SEAL - REPLACEMENT/MODIFICATION OF	-	-	-/Category 8	TIC-AW139-20-090 DATED 02 JUNE 2020 APPLICABLE DUE TO ENGINE BUILD SPECIFICATION. COMPLIANCE: CATEGORY 8
Standard SBs	NO. 1 ENGINE ~ SB NO. 41073, REVISION 1	TURBOSHAFT ENGINE - FUEL MANAGEMENT MODULE - REPLACEMENT/MODIFICATION OF	-	-	-/NOT APPLICABLE	TIC-AW139-20-039 DATED 11 MARCH 2020 NOT APPLICABLE DUE TO ENGINE SERIAL NUMBER.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	104
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	NO. 1 ENGINE ~ SB NO 41116, REVISION 1	TURBOSHAFT ENGINE FUEL MANAGEMENT MODULE VENT PACKING KIT - INTRODUCTION OF	-	-	-/FOR INFO ONLY	TIC-AW139-20-048 APPLICABLE TO ENGINE BUILD SPEC (BS1019, BS963) COMPLIANCE: CATEGORY 9- SPARE PARTS INFORMATION
Standard SBs	NO. 1 ENGINE ~ SB NO. 41066 REVISION 5	POWER TURBINE SHAFT AND STATOR ASSEMBLIES - REPLACEMENT OF	-	-	-/NOT APPLICABLE	TIC-AW139-19-054 DATED 01 AUGUST 2019 NOT APPLICABLE DUE TO ENGINE SERIAL NUMBER.
Standard SBs	P&WC SB NO. 41113 REV. 1 - ENG #1	TURBOSHAFT ENGINE COUPLING NUT TORQUE, FUEL LINE - INSP	-	-	-/NOT APPLICABLE	COMPLIANCE CATEGORY 3. NOT APPLICABLE DUE TO ENGINE NOT AFFECTED. INFO IS REFERRED FROM LEONARDO HELICOPTER PWC PT6C-67C SERVICE BULLETINS STATUS LIST DATED 08/10/2019.
Standard SBs	NO. 1 ENGINE ~ SB NO. 41065, REVISION 3	POWER TURBINE VANE RING - REPLACEMENT/MODIFICATION OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 05.12.2018.
Standard SBs	NO. 1 ENGINE ~ SB NO. 41111	TURBOSHAFT ENGINE- DIAMETRICAL GROWTH DIMENSION COMPRESSOR TURBINE DISK - CORRECTION OF	-	-	-/NOT APPLICABLE	TIC-AW139-20-044 DATED 11 MARCH 2020 NOT APPLICABLE TO ALL SERIAL NUMBER ENGINE TYPE.
Standard SBs	NO. 1 ENGINE ~ SB NO. 41109 REVISION 0	FUEL HEATER - MODIFICATION/REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 05.12.2018.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	105
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	NO. 1 ENGINE ~ SB NO. 41056, REVISION 6	POWER TURBINE SHAFT HOUSING ASSEMBLY NO.3 BEARING SEAL RUNNER AND TURBINE SHAFT SPACER TURBINE EXHAUST DUCT - REPLACEMENT/MODIFICATION OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 05.12.2018.
Standard SBs	ENGINE NO. 1 ~ SB NO. 41052 REVISION 1	OIL TRAY ACCESSORY GEARBOX - REPLACEMENT/MODIFICATION OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 05.12.2018.
Standard SBs	NO. 1 ENGINE ~ SB NO. 41049 REVISION 2	SCAVENGE PUMP ASSEMBLY - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 05.12.2018.
Standard SBs	NO. 1 ENGINE ~ SB NO. 41094, REVISION 3	TURBOSHAFT ENGINE BLEED VALVE - INSPECTION/MODIFICATION OF	-	-	-/NOT APPLICABLE	TIC-AW139-20-042 DATED 11 MARCH 2020 NOT APPLICABLE DUE TO ENGINE SERIAL NUMBER.
Standard SBs	P&WC SB NO. 41101 REV. 3 - ENG #1	FUEL MANAGEMENT MODULE - MODE SELECT SOLENOID - SEALING	-	-	-/NOT APPLICABLE	COMPLIANCE CATEGORY 3. NOT APPLICABLE DUE TO FMM NOT AFFECTED. INFO IS REFERRED FROM LEONARDO HELICOPTER PWC PT6C-67C SERVICE BULETTINS STATUS LIST DATED 08/10/2019.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	106
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	P&WC SB NO. 41108 REV. 0 - ENG #1	T5 TERMINAL NUTS - INSPECTION OF	-	-	-/NOT APPLICABLE	COMPLIANCE CATEGORY 3. APPLICABLE ON ENGINES ENTERED IN SERVICE BEFORE DECEMBER 31, 2017.. INFO IS REFERRED FROM LEONARDO HELICOPTER PWC PT6C-67C SERVICE BULLETINS STATUS LIST DATED 08/10/2019.
Standard SBs	NO. 1 ENGINE ~ SB NO. 41030, REVISION 1	CHECK VALVE ASSEMBLY - INSPECTION OF	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO MODIFICATION FOLLOWING SERVICE BULLETIN 41042 INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 3 - PWC PT6C-67C SERVICE BULLETIN STATUS LIST DATED 03.12.2019.
Standard SBs	NO. 1 ENGINE ~ SB NO. 41107	DATA COLLECTION UNIT - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 05.12.2018.
Standard SBs	P&WC SB NO. 41095 REV. 1 - ENG #1	POWER TURBINE SHAFT - INSPECTION OF	-	-	-/NOT APPLICABLE	REFER TIC-AW139-20-018-PME-009 DATE ISSUE 20 FEBRUARY 2020. NOT APPLICABLE TO NEW ENGINE. COMPLIANCE AT CATEGORY 4.
Standard SBs	NO. 1 ENGINE ~ SB NO. 41104 REVISION 1	TURBOSHAFT ENGINE FUEL MANAGEMENT MODULE - REPLACEMENT/MODIFICATION OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 05.12.2018.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	107
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	NO. 1 ENGINE ~ SB NO. 41092 REVISION 1	GASKET DATA COLLECTION UNIT (DCU) - INTRODUCTION OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 05.12.2018.
Standard SBs	41098 REV 1	GAS GENERATOR CASE P3 HOLES - INSPECTION/CLEANING OF	-	-	-/NOT APPLICABLE	REFER TO TIC-AW139-20-043. NOT APPLICABLE TO ALL SERIAL NUMBER ENGINE TYPE
Standard SBs	P&WC SB NO. 41081 REV. 4 - ENG #1	ELECTRONIC ENGINE CONTROL - REPROGRAMING/REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIANCE CATEGORY 3. COMPLIED WITH AS PER PWC SB LIST ATTACHED TO ENGINE LOGBOOK. INFO IS REFERRED FROM LEONARDO HELICOPTER PWC PT6C-67C SERVICE BULETTINS STATUS LIST DATED 08/10/2019.
Standard SBs	NO. 1 ENGINE ~ SB NO. 41105	OIL NOZZLE ASSEMBLY ACCESSORY DRIVE - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 05.12.2018.
Standard SBs	SB NO. 41089, REVISION 3	TURBOSHAFT ENGINE - CHECK VALVE PLATE- REPLACEMENT OF	-	-	-/FOR INFO ONLY	REFER TO TIC-AW139-20-040 APPLICABLE TO ALL SERIAL NUMBER ENGINE TYPE.
Standard SBs	NO. 1 ENGINE ~ SB NO. 41102	INSULATION BLANKET ASSEMBLY POWER SECTION - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 05.12.2018.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	108
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	NO. 1 ENGINE ~ SB NO. 41099	FIRST AND SECOND STAGE COMPRESSOR STATOR ASSEMBLIES - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 05.12.2018.
Standard SBs	NO. 1 ENGINE ~ SB NO. 41096	COMPRESSOR STATOR ASSEMBLY - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 05.12.2018.
Standard SBs	NO. 1 ENGINE ~ SB NO. 41097	SUPPORT BRACKET FUEL ACCUMULATOR - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 05.12.2018.
Standard SBs	SB NO 41093, NEW ISSUE	TURBOSHAFT ENGINE - ROLLER BEARING OPTION (IC)- REPLACE	-	-	-/PARTS IS FULLY USED	REFER TO TIC-AW139-20-041. APPLICABLE TO ALL SERIAL NUMBER ENGINE TYPE. SUPPLY OF SUPERSEDED PARTS IS FULLY USED.
Standard SBs	41085 REV 0	FUEL HEATER - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 05.12.2018.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	109
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	P&WC SB NO. 41088 REV. 1 - ENG#1	TURBOSHAFT ENGINE TORQUE (Q/NPT) SENSORS -	-	-	-/NOT APPLICABLE	COMPLIANCE CATEGORY 3. NOT APPLICABLE DUE TO ON NEW ENGINE. INFO IS REFERRED FROM LEONARDO HELICOPTER PWC PT6C-67C SERVICE BULETTINS STATUS LIST DATED 08/10/2019.
Standard SBs	P&WC SB NO. A41060 REV. 5 - ENG #1	RETAINING RING POWER TURBINE BAFFLE - INSPECTION OF	-	-	-/NOT APPLICABLE	COMPLIANCE CATEGORY 3. NOT APPLICABLE DUE TO ENGINE POST SB 41056. INFO IS REFERRED FROM LEONARDO HELICOPTER PWC PT6C-67C SERVICE BULETTINS STATUS LIST DATED 08/10/2019.
Standard SBs	41091 REV 0	FUEL MANIFOLD - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 05.12.2018.
Standard SBs	41090 REV 0	FIRST AND SECOND STAGE COMPRESSOR STATOR ASSEMBLY - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 05.12.2018.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	110
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	P&WC SB NO. 41086 REV. 0 - ENG #1	TURBOSHAFT ENGINE FUEL MANIFOLD - INSPECTION OF	-	-	-/NOT APPLICABLE	COMPLIANCE CATEGORY 3. NOT APPLICABLE DUE TO NEW ENGINE MOUNTING ROD ASSY P/N 3G7120V00132 ALREADY INSTALLED. INFO IS REFERRED FROM LEONARDO HELICOPTER PWC PT6C-67C SERVICE BULETTINS STATUS LIST DATED 08/10/2019.
Standard SBs	41047 REV 3	ELECTRONIC ENGINE CONTROL - REPROGRAMMING/REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 05.12.2018.
Standard SBs	NO. 1 ENGINE ~ SB NO. 41067 REVISION 1	INTERSTAGE AIR-SEAL HOUSING ASSY AND PT VANE RING REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 05.12.2018.
Standard SBs	NO. 1 ENGINE ~ SB NO. 41087	ROTOR COMPRESSOR TIE RODS - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 05.12.2018.
Standard SBs	41050 REV 1	FUEL NOZZLE CONFIGURATION AND ECOLOGY SYSTEM ACCUMULATOR - REPLACEMENT/MODIFICATION OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 05.12.2018.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	111
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	P&WC SB NO. 41079 - ENG #1	X-RAY INSPECTION OF THE NO. 2 BEARING OIL-PRESSURE-TUBE	-	-	-/NOT APPLICABLE	REFER TIC-AW139-20-018-PME-008 DATE ISSUE 20 FEBRUARY 2020. NOT APPLICABLE DUE TO ENGINE S/N. COMPLIANCE AT CATEGORY 6.
Standard SBs	SB NO. 41079, NEW ISSUE	TURBOSHAFT ENGINE X-RAY INSPECTION OF THE NO.2 BEARING OIL-PRESSURE-TUBE BOSS OF THE GAS GENERATOR CASE	-	-	-/NOT APPLICABLE	
Standard SBs	NO. 1 ENGINE ~ SB NO. 41084	OIL PRESSURE SENSOR - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 05.12.2018.
Standard SBs	41082 REV 0	CLAMPING RING TURBINE-VANE - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 05.12.2018.
Standard SBs	P&WC SB NO. 41021 REV. 1 - ENG #1	FUEL SYSTEM - INSPECTION OF	-	-	-/NOT APPLICABLE	COMPLIANCE CATEGORY 3. NOT APPLICABLE DUE TO MODIFICATION FOLLOWING SB41069 (SEE PWC SB LIST). INFO IS REFERRED FROM LEONARDO HELICOPTER PWC PT6C-67C SERVICE BULETTINS STATUS LIST DATED 08/10/2019.
Standard SBs	NO. 1 ENGINE ~ SB NO. 41083	SEALS OIL TANK FILLER CAP AND OIL LEVEL INDICATOR - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 05.12.2018.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	112
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	NO. 1 ENGINE ~ SB. NO 41077	ENGINE SHIPPING CONTAINER ASSEMBLY - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 05.12.2018.
Standard SBs	NO. 1 ENGINE ~ SB NO. 41076	SPEED SENSOR NG - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 05.12.2018.
Standard SBs	NO. 1 ENGINE ~ SB NO. 41075	NPT TORQUE SENSOR - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 05.12.2018.
Standard SBs	P&WC SB NO. 41064 REV. 2 - ENG #1	FUEL HEATER - MODIFICATION/REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIANCE CATEGORY 3,7. COMPLIED WITH AS PER PWC SB LIST ATTACHED TO ENGINE LOGBOOK. INFO IS REFERRED FROM LEONARDO HELICOPTER PWC PT6C-67C SERVICE BULETTINS STATUS LIST DATED 08/10/2019.
Standard SBs	P&WC SB NO. 41074 REV. 0 - ENG #1	FUEL-COOLED OIL COOLER - INSPECTION OF	-	-	-/NOT APPLICABLE	REFER TIC-AW139-20-018-PME-007 DATE ISSUE 20 FEBRUARY 2020. NOT APPLICABLE DUE TO COMPONENT SERIAL NUMBER NOT FITTED ON AIRCRAFT. COMPONENT FITTED ON AIRCRAFT ARE S/N WA58563 AND S/N WA58832. COMPLIANCE AT CATEGORY 6.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	113
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	SB NO. 41074, NEW ISSUE	TURBOSHAFT ENGINE FUEL-COOLED OIL COOLER - INSPECTION OF	-	-	-/NOT APPLICABLE	
Standard SBs	NO. 1 ENGINE ~ SB NO. 41069	FUEL MANAGEMENT MODULE AND CHIP DETECTOR VALVE AND PLUG - REPLACEMENT/MODIFICATION OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 05.12.2018.
Standard SBs	NO. 1 ENGINE ~ SB NO. 41068	DATA COLLECTION UNIT - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 05.12.2018.
Standard SBs	P&WC SB NO. 41035 REV. 4 - ENG #1	THERMOCOUPLE WIRING HARNESS - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIANCE CATEGORY 3. COMPLIED WITH AS PER PWC SB LIST ATTACHED TO ENGINE LOGBOOK. INFO IS REFERRED FROM LEONARDO HELICOPTER PWC PT6C-67C SERVICE BULETTINS STATUS LIST DATED 08/10/2019.
Standard SBs	P&WC SB NO. A41059 REV. 1 - ENG #1	POWER TURBINE BAFFLE - INSPECTION OF	-	-	-/NOT APPLICABLE	COMPLIANCE CATEGORY 3. NOT APPLICABLE PER ENGINE S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER PWC PT6C-67C SERVICE BULETTINS STATUS LIST DATED 08/10/2019.
Standard SBs	NO. 1 ENGINE ~ SB NO. 41054 REVISION 1	ACCESSORY GEARBOX DIAPHRAGM ASSEMBLY - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 05.12.2018.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	114
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	NO. 1 ENGINE ~ SB. NO. 41051 REVISION 1	COMPRESSOR TURBINE BLADES - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 05.12.2018.
Standard SBs	NO. 1 ENGINE ~ SB NO. 41062	HOSE NON-METALLIC - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 05.12.2018.
Standard SBs	NO. 1 ENGINE ~ SB NO. 41063	HOSE NON-METALLIC - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 05.12.2018.
Standard SBs	P&WC SB NO. 41061 REV. 0 - ENG #1	FUEL FILTER - INSPECTION OF	-	-	-/NOT APPLICABLE	REFER TIC-AW139-20-018-PME-006 DATE ISSUE 20 FEBRUARY 2020. NOT APPLICABLE DUE TO ENGINE S/N. COMPLIANCE AT CATEGORY 6.
Standard SBs	P&WC SB NO. 41055 REV. 0 - ENG #1	ACCESSORY GEARBOX DIAPHRAGM - REPLACEMENT/MODIFICATION	-	-	-/NOT APPLICABLE	REFER TIC-AW139-20-018-PME-005 DATE ISSUE 20 FEBRUARY 2020. NOT APPLICABLE DUE TO ENGINE S/N. COMPLIANCE AT CATEGORY 7.
Standard SBs	SB NO. 41055, NEW ISSUE	TURBOSHAFT ENGINE ACCESORY GEARBOX DIAPHRAGM - REPLACEMENT/MODIFICATION OF	-	-	-/NOT APPLICABLE	NOT APPLICABLE TO ENGINE S/N. COMPLIANCE: CATEGORY 7 - YOU CAN DO THIS SERVICE BULLETIN WHEN THE SUPPLY OF SUPERSEDED PARTS IS FULLY USED.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	115
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	P&WC SB NO. A41053 REV. 0 - ENG #1	FUEL FILTER INSPECTION OF	-	-	-/NOT APPLICABLE	COMPLIANCE CATEGORY 3. NOT APPLICABLE DUE TO ENGINE NOT AFFECTED. INFO IS REFERRED FROM LEONARDO HELICOPTER PWC PT6C-67C SERVICE BULETTINS STATUS LIST DATED 08/10/2019.
Standard SBs	P&WC SB NO. 41048 REV. 0 - ENG #1	PT SPEED AND TORQUE SENSOR LEFT HAND - REPLACEMENT OF	-	-	-/NOT APPLICABLE	COMPLIANCE CATEGORY 3. NOT APPLICABLE DUE TO ENGINE PRE SB41046. INFO IS REFERRED FROM LEONARDO HELICOPTER PWC PT6C-67C SERVICE BULETTINS STATUS LIST DATED 08/10/2019.
Standard SBs	P&WC SB NO. 41046 REV. 2 - ENG #1	PT SPEED AND TORQUE SENSOR LEFT HAND - REPLACEMENT OF	-	-	-/FOR INFO ONLY	REFER TIC-AW139-20-018-PME-004 DATE ISSUE 20 FEBRUARY 2020. APPLICABLE DUE TO ENGINE POST SB-41045. COMPLIANCE IS AT CATEGORY 10 - FOR INFORMATION ONLY.
Standard SBs	NO. 1 ENGINE ~ SB NO. 41045 REVISION 1	NO. 5 BEARING HOUSING SUPPORT AND PT ROTOR BALANCING ASSEMBLY - REPLACEMENT/MODIFICATION OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 05.12.2018.
Standard SBs	NO. 1 ENGINE ~ SB. NO 41044	IGNITION EXCITER - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 05.12.2018.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	116
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	NO. 1 ENGINE ~ SB. NO 41043	CHIP DETECTOR VALVE - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 05.12.2018.
Standard SBs	NO. 1 ENGINE ~ SB. NO 41040	ROTOR AIR SEAL AND TURBINE SPACER - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 05.12.2018.
Standard SBs	P&WC SB NO. 41041 REV. 1 - ENG #1	TURBOSHAFT ENGINE - ROTOR AIR SEAL AND TURBINE SPACER -	-	-	-/NOT APPLICABLE	REFER TIC-AW139-20-018-PME-003 DATE ISSUE 20 FEBRUARY 2020. NOT APPLICABLE DUE TO ENGINE S/N. COMPLIANCE IS AT CATEGORY 10.
Standard SBs	TURBOSHAFT ENGINE - ROTOR AIR SEAL AND TURBINE SPACER -	P&WC SB NO. 41041 REV. 1 - ENG #2	-	-	-/NOT APPLICABLE	REFER TIC-AW139-20-018-PME-003 DATE ISSUE 20 FEBRUARY 2020. NOT APPLICABLE DUE TO ENGINE S/N. COMPLIANCE IS AT CATEGORY 10.
Standard SBs	NO. 1 ENGINE ~ SB. NO 41042	CHECK VALVE ASSEMBLY - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 05.12.2018.
Standard SBs	41031 REV 1	PREFORMED PACKING - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 05.12.2018.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	117
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	41039 REV 0	IGNITERS - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 05.12.2018.
Standard SBs	41037 REV 0	COMPRESSOR INLET CASE ASSEMBLY AND RETAINING PLATE FOR REAR SCAVENGE OIL TUBE - REPLACEMENT/MODIFICATION OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 05.12.2018.
Standard SBs	P&WC SB NO. 41028 REV. 1 - ENG #1	CENTRIFUGAL IMPELLER - REPLACEMENT OF	-	-	-/NOT APPLICABLE	REFER TIC-AW139-20-018-PME-001 DATE ISSUE 20 FEBRUARY 2020. NOT APPLICABLE TO ENGINE S/N. COMPLIANCE IS AT CATEGORY 10 - FOR INFORMATION AND CONFIGURATION PURPOSES ONLY.
Standard SBs	41038 REV 0	AIR SEAL COMPRESSOR TURBINE STATOR - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 05.12.2018.
Standard SBs	P&WC SB NO. 41036 REV. 0 - ENG #1	TRIPLE FUNCTION FUEL-SWITCH - REPLACEMENT OF	-	-	-/NOT APPLICABLE	REFER TIC-AW139-20-018-PME-002 DATE ISSUE 20 FEBRUARY 2020. NOT APPLICABLE DUE TO THIS SB INTENDED FOR PT6C-67C WITH BUILD SPECIFICATION BS1136 AND BS1137. ENGINE S/N PCE-KB2214 IS BS 963 WHILE PCE-KB2224 IS BS 1019. COMPLIANCE AT CATEGORY 7.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	118
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	41034 REV 0	FUEL SWITCH IMPENDING BYPASS AND TEMPERATURE - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 05.12.2018.
Standard SBs	41033 REV 0	SCREEN ASSEMBLY AIR INLET - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 05.12.2018.
Standard SBs	41032 REV 0	WIRING HARNESS T1 SENSOR - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 05.12.2018.
Standard SBs	41020 REV 2	ELECTRONIC ENGINE CONTROL - REPROGRAMMING/REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 05.12.2018.
Standard SBs	41026 REV 0	FUEL MANAGEMENT MODULE - REPLACEMENT	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 05.12.2018.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	119
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	41027 REV 0	PT HOUSING SEALING-RING - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 05.12.2018.
Standard SBs	41025 REV 0	COLD START VALVE HOUSING - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 05.12.2018.
Standard SBs	41024 REV 0	TURBINE EXHAUST DUCT ASSEMBLY SINGLE PORT - REPLACEMENT	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 05.12.2018.
Standard SBs	41023 REV 0	DATA COLLECTION UNIT - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 05.12.2018.
Standard SBs	41019 REV 0	OIL SWITCH (LOP) - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 05.12.2018.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	120
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	P&WC SB NO. 41018 REV. 1 - ENG #1	BLOWDOWN VALVE HOUSING - INSPECTION/REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIANCE CATEGORY 3. COMPLIED WITH AS PER PWC SB LIST ATTACHED TO ENGINE LOGBOOK. INFO IS REFERRED FROM LEONARDO HELICOPTER PWC PT6C-67C SERVICE BULETTINS STATUS LIST DATED 08/10/2019.
Standard SBs	41017 REV 0	COMPRESSOR TURBINE BAFFLE RETAINING BOLT - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 05.12.2018.
Standard SBs	41015 REV 0	OIL TANK DRAIN ADAPTER AND FIREWALL BRACKET - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 05.12.2018.
Standard SBs	P&WC SB NO. 41016 REV. 0 - ENG #1	INCREASED COMPRESSOR TURBINE TIP CLEARANCE - INTRODUCTI	-	-	-/COMPLIED WITH	COMPLIANCE CATEGORY 3. COMPLIED WITH AS PER PWC SB LIST ATTACHED TO ENGINE LOGBOOK. INFO IS REFERRED FROM LEONARDO HELICOPTER PWC PT6C-67C SERVICE BULETTINS STATUS LIST DATED 08/10/2019.
Standard SBs	41014 REV 0	FUEL LINES FROM FUEL MANAGEMENT MODULE TO FUEL HEATER - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 05.12.2018.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	121
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	41011 REV 0	IMPROVED HEAT TRANSFER REDUCTION CONFIGURATION AT NO. 3 BEARING AREA AND EXHAUST DUCT SEALING FACE PROPERTIES - INTRODUCTION OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 05.12.2018.
Standard SBs	41013 REV 0	OIL SYSTEM PREFORMED PACKING - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 05.12.2018.
Standard SBs	41012 REV 1	ACCESSORY GEARBOX DIAPHRAGM ASSEMBLY - REPLACEMENT/MODIFICATION OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 05.12.2018.
Standard SBs	41010 REV 0	POWER TURBINE OUTPUT SHAFT - INSPECTION/REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 05.12.2018.
Standard SBs	41008 REV 1	WIRING HARNESS SUPPORT BRACKET AND FUEL HEATER COVER ATTACHING WASHERS - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 05.12.2018.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	122
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	P&WC SB NO. 41009 REV. 1 - ENG #1	FUEL HEATER - MODIFICATION/REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 05.12.2018.
Standard SBs	41007 REV 0	POWER TURBINE SHAFT SPACER - MODIFICATION/REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 05.12.2018.
Standard SBs	41001 REV 0	EXHAUST DUCT ASSEMBLY - MODIFICATION/REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 05.12.2018.
Standard SBs	41002 REV 0	FUEL MANIFOLD - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 05.12.2018.
Standard SBs	41005 REV 0	OIL FEED ADAPTER ASSEMBLY - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 05.12.2018.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	123
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	41003 REV 0	DATA COLLECTION UNIT - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 05.12.2018.
Standard SBs	41004 REV 0	COMPRESSOR TURBINE BLADES - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 05.12.2018.
Standard SBs	P&WC SB NO. 41006 REV. 0 - ENG #1	AIR LIMITATION RESTRICTION LIFTED	-	-	-/NOT APPLICABLE	COMPLIANCE CATEGORY 3. NOT APPLICABLE PER ENGINE S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER PWC PT6C-67C SERVICE BULETTINS STATUS LIST DATED 08/10/2019.
ENGINE #2						
Standard SBs	NO. 2 ENGINE ~ SB NO. 41120, REVISION 2	PT6C-67C BS963 AND BS1019 TO PT6C-67C1 BS1447 AND BS1448 - CONVERSION OF	-	-	-/NOT APPLICABLE	TIC-AW139-21-0248 (REV.0) TIC-AW139-21-0270 (REV.1) CATEGORY 8 - NOT APPLICABLE DUE TO ENGINE S/N NOT AFFECTED.
Standard SBs	NO. 2 ENGINE ~ SB NO. 41119, REVISION 4	PT6C-67C SERVICE BULLETIN IGNITION EXCITER - REPLACEMENT OF	-	-	-/Category 7	TIC-AW139-21-0249 DATED 30 JUNE 2021 APPLICABLE DUE TO ENGINE BUILD SPEC AND SERIAL NUMBER AFFECTED. COMPLIANCE: CATEGORY 7 - YOU CAN DO THIS SB WHEN THE SUPPLY OF THE SUPERSEDED PARTS IS FULLY USED.
Standard SBs	NO. 2 ENGINE ~ SB NO. 41112, REVISION 1	TURBOSHAFT ENGINE - FUEL MANAGEMENT MODULE (FMM) - REPLACEMENT / MODIFICATION	-	-	-/Category 7	TIC-AW139-21-0240 DATED 11 JUNE 2021 APPLICABLE DUE TO BUILD SPEC AND ENGINE SERIAL NUMBER AFFECTED. CONCURRENT REQUIREMENT: NONE.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	124
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	NO. 2 ENGINE ~ SB NO. 41114 REV. 2	ENGINE INSULATION BLANKET	-	-	-/OPTIONAL	REFERENCE: TIC-AW139-21-0241 APPLICABLE DUE TO ENGINE BUILD SPEC AND SERIAL NUMBER AFFECTED COMPLIANCE: CATEGORY 7: YOU CAN DO THIS SERVICE BULLETIN WHEN THE SUPPLY OF SUPERSEDED PARTS IS FULLY USED
Standard SBs	NO. 2 ENGINE ~ SB NO. 41110 REVISION 2	PERMANENT MAGNETIC ALTERNATOR GEARSHAFT AND ROLLER BEARING REPLACEMENT OF	-	-	-/Category 7	TIC-AW139-21-0239 DATED 11 JUNE 2021 APPLICABLE DUE TO ENGINE BUILD SPECT AND SERIAL NUMBER AFFECTED COMPLIANCE: CATEGORY 7 - YOU CAN DO THIS SERVICE BULLETIN WHEN THE SUPPLY OF SUPERSEDED PARTS IS FULLY USED.
Standard SBs	NO. 2 ENGINE ~ SB NO. 41121 REV. 2	PT6C-67C SERVICE BULLETIN - HOUSINGS FOR ACCESSORY GEARBOX AND INLET CASE - IDENTIFICATION OF	-	-	-/Category 5	TIC-AW139-22-0112 DATED 27 APRIL 2022 CATEGORY 5. APPLICABLE DUE TO ENGINE TYPE AFFECTED.
Standard SBs	NO. 2 ENG - SB NO. 41057, REVISION 6	PT6C-67C SERVICE BULLETIN SHROUD HOUSING, COMPRESSOR TURBINE - REPLACEMENT/MODIFICATION OF	-	-	-/NOT APPLICABLE	TIC-AW139-21-0031 NOT APPLICABLE DUE TO AIRCRAFT S/N (PCE-KB2224) NOT AFFECTED
Standard SBs	NO. 2 ENGINE ~ SB NO. 41118, REV. 3	TURBOSHAFT ENGINE - CENTRIFUGAL IMPELLER - REPLACEMENT OF	-	-	-/NOT APPLICABLE	TIC-AW139-20-217 CATEGORY 7, APPLICABILITY: NOT APPLICABLE DUE TO AFFECTED ENGINE SERIAL NUMBER NOT FITTED ON AIRCRAFT.
Standard SBs	NO. 2 ENGINE ~ SB NO. 41103, REVISION 1	CHECK VALVE ASSEMBLY - REPLACEMENT OF	-	-	-/COMPLIED WITH	TIC-AW139-20-188 DATED 02 NOVEMBER 2020 COMPLIED BY OEM.
Standard SBs	NO. 2 ENGINE ~ SB NO. 41100, REVISION 8	TURBOSHAFT ENGINE NO. 5 BEARING OUTPUT SHAFT SEAL - REPLACEMENT/MODIFICATION OF	-	-	-/Category 8	TIC-AW139-20-090 DATED 02 JUNE 2020 APPLICABLE DUE TO ENGINE BUILD SPECIFICATION. COMPLIANCE: CATEGORY 8
Standard SBs	NO. 2 ENGINE ~ SB NO. 41073, REVISION 1	TURBOSHAFT ENGINE - FUEL MANAGEMENT MODULE - REPLACEMENT/MODIFICATION OF	-	-	-/NOT APPLICABLE	TIC-AW139-20-039 DATED 11 MARCH 2020 NOT APPLICABLE DUE TO ENGINE SERIAL NUMBER.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	125
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	NO. 2 ENGINE ~ SB NO. 41116, REVISION 1	TURBOSHAFT ENGINE FUEL MANAGEMENT MODULE VENT PACKING KIT - INTRODUCTION OF	-	-	-/FOR INFO ONLY	TIC-AW139-20-048 APPLICABLE TO ENGINE BUILD SPEC (BS1019, BS963) COMPLIANCE: CATEGORY 9- SPARE PARTS INFORMATION
Standard SBs	NO. 2 ENGINE ~ SB NO. 41066 REVISION 5	POWER TURBINE SHAFT AND STATOR ASSEMBLIES - REPLACEMENT OF	-	-	-/NOT APPLICABLE	TIC-AW139-19-054 DATED 01 AUGUST 2019 NOT APPLICABLE DUE TO ENGINE SERIAL NUMBER.
Standard SBs	TURBOSHAFT ENGINE COUPLING NUT TORQUE, FUEL LINE - INSP	P&WC SB NO. 41113 REV. 1 - ENG #2	-	-	-/NOT APPLICABLE	COMPLIANCE CATEGORY 3. NOT APPLICABLE DUE TO ENGINE NOT AFFECTED. INFO IS REFERRED FROM LEONARDO HELICOPTER PWC PT6C-67C SERVICE BULLETINS STATUS LIST DATED 08/10/2019.
Standard SBs	NO. 2 ENGINE ~ SB NO. 41065, REVISION 3	POWER TURBINE VANE RING - REPLACEMENT/MODIFICATION OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 11.01.2019.
Standard SBs	NO. 2 ENGINE ~ SB NO. 41111	TURBOSHAFT ENGINE - DIAMETRICAL GROWTH DIMENSION, COMPRESSOR TURBINE DISK - CORRECTION OF	-	-	-/NOT APPLICABLE	TIC-AW139-20-044 DATED 11 MARCH 2020 NOT APPLICABLE TO ALL SERIAL NUMBER ENGINE TYPE.
Standard SBs	NO. 2 ENGINE - SB NO. 41109 REVISION 0	IGNITION EXCITER - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 11.01.2019.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	126
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	NO. 2 ENGINE ~ SB NO. 41056, REVISION 6	POWER TURBINE SHAFT HOUSING ASSEMBLY NO.3 BEARING SEAL RUNNER AND TURBINE SHAFT SPACER TURBINE EXHAUST DUCT - REPLACEMENT/MODIFICATION OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 11.01.2019.
Standard SBs	ENGINE NO. 2 ~ SB NO. 41052 REVISION 1	OIL TRAY ACCESSORY GEARBOX - REPLACEMENT/MODIFICATION OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 11.01.2019.
Standard SBs	NO. 2 ENGINE ~ SB NO. 41049 REVISION 2	SCAVENGE PUMP ASSEMBLY - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 11.01.2019.
Standard SBs	NO. 2 ENGINE ~ SB NO. 41094, REVISION 3	TURBOSHAFT ENGINE BLEED VALVE - INSPECTION/MODIFICATION OF	-	-	-/NOT APPLICABLE	TIC-AW139-20-042 DATED 11 MARCH 2020 NOT APPLICABLE DUE TO ENGINE SERIAL NUMBER.
Standard SBs	FUEL MANAGEMENT MODULE - MODE SELECT SOLENOID - SEALING	P&WC SB NO. 41101 REV. 3 - ENG #2	-	-	-/NOT APPLICABLE	COMPLIANCE CATEGORY 3. NOT APPLICABLE DUE TO FMM NOT AFFECTED. INFO IS REFERRED FROM LEONARDO HELICOPTER PWC PT6C-67C SERVICE BULETTINS STATUS LIST DATED 08/10/2019.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	127
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	T5 TERMINAL NUTS - INSPECTION OF	P&WC SB NO. 41108 REV. 0 - ENG #2	-	-	-/NOT APPLICABLE	COMPLIANCE CATEGORY 3. APPLICABLE ON ENGINES ENTERED IN SERVICE BEFORE DECEMBER 31, 2017. INFO IS REFERRED FROM LEONARDO HELICOPTER PWC PT6C-67C SERVICE BULLETINS STATUS LIST DATED 08/10/2019.
Standard SBs	NO. 2 ENGINE ~ SB NO. 41030, REVISION 1	CHECK VALVE ASSEMBLY - INSPECTION OF	-	-	-/NOT APPLICABLE	NOT APPLICABLE DUE TO MODIFICATION FOLLOWING SERVICE BULLETIN 41042 INFO IS REFERRED FROM LEONARDO HELICOPTER ANNEX 3 - PWC PT6C-67C SERVICE BULLETIN STATUS LIST DATED 03.12.2019.
Standard SBs	NO. 2 ENGINE ~ SB NO. 41107, REVISION 0	DATA COLLECTION UNIT - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 11.01.2019.
Standard SBs	POWER TURBINE SHAFT - INSPECTION OF	P&WC SB NO. 41095 REV. 1 - ENG #2	-	-	-/NOT APPLICABLE	REFER TIC-AW139-20-018-PME-009 DATE ISSUE 20 FEBRUARY 2020.. NOT APPLICABLE TO NEW ENGINE. COMPLIANCE AT CATEGORY 4.
Standard SBs	NO. 2 ENGINE ~ SB NO. 41104, REVISION 1	TURBOSHAFT ENGINE FUEL MANAGEMENT MODULE - REPLACEMENT/MODIFICATION OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 11.01.2019.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	128
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	NO. 2 ENGINE ~ SB NO. 41092 REVISION 1	GASKET DATA COLLECTION UNIT (DCU) - INTRODUCTION OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 11.01.2019.
Standard SBs	SB NO. 41098, REVISION 1	TURBOSHAFT ENGINE GAS GENERATOR CASE P3 HOLES - INSPECTION/CLEANING OF	-	-	-/NOT APPLICABLE	
Standard SBs	ELECTRONIC ENGINE CONTROL - REPROGRMING/REPLACEMENT OF	P&WC SB NO. 41081 REV. 4 - ENG #2	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 11.01.2019.
Standard SBs	NO. 2 ENGINE ~ SB NO. 41105 REVISION 0	OIL NOZZLE ASSEMBLY ACCESSORY DRIVE - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 11.01.2019.
Standard SBs	SB NO. 41089, REVISION 3	TURBOSHAFT ENGINE CHECK VALVE PLATE - REPLACEMENT OF	-	-	-/FOR INFO ONLY	
Standard SBs	NO. 2 ENGINE ~ SB NO. 41102 REVISION 0	INSULATION BLANKET ASSEMBLY POWER SECTION - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 11.01.2019.
Standard SBs	NO. 2 ENGINE ~ SB NO. 41099 REVISION 0	FIRST AND SECOND STAGE COMPRESSOR STATOR ASSEMBLIES - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 11.01.2019.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	129
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	NO. 2 ENGINE ~ SB NO. 41096 REVISION 0	COMPRESSOR STATOR ASSEMBLY - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 11.01.2019.
Standard SBs	NO. 2 ENGINE ~ SB NO. 41097	SUPPORT BRACKET FUEL ACCUMULATOR - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 11.01.2019.
Standard SBs	SB NO. 41093, REVISION 1	TURBOSHAFT ENGINE ROLLER BEARING OPTION (IC) - REPLACEMENT OF	-	-	-/FOR INFO ONLY	
Standard SBs	NO. 2 ENGINE ~ SB NO. 41085 REVISION 0	FUEL HEATER - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 11.01.2019.
Standard SBs	TURBOSHAFT ENGINE TORQUE (Q/NPT) SENSORS -	P&WC SB NO. 41088 REV. 1 - ENG #2	-	-	-/NOT APPLICABLE	COMPLIANCE CATEGORY 3. NOT APPLICABLE DUE TO ON NEW ENGINE. INFO IS REFERRED FROM LEONARDO HELICOPTER PWC PT6C-67C SERVICE BULETTINS STATUS LIST DATED 08/10/2019.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	130
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	RETAINING RING POWER TURBINE BAFFLE - INSPECTION OF	P&WC SB NO. A41060 REV. 5 - ENG #2	-	-	-/NOT APPLICABLE	COMPLIANCE CATEGORY 3. NOT APPLICABLE DUE TO ENGINE POST SB 41056. INFO IS REFERRED FROM LEONARDO HELICOPTER PWC PT6C-67C SERVICE BULETTINS STATUS LIST DATED 08/10/2019.
Standard SBs	NO. 2 ENGINE ~ SB NO. 41091 REVISION 0	FUEL MANIFOLD - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 11.01.2019.
Standard SBs	NO. 2 ENGINE ~ SB NO. 41090 REVISION 0	FIRST AND SECOND STAGE COMPRESSOR STATOR ASSEMBLY - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 11.01.2019.
Standard SBs	TURBOSHAFT ENGINE FUEL MANIFOLD - INSPECTION OF	P&WC SB NO. 41086 REV. 0 - ENG #2	-	-	-/NOT APPLICABLE	COMPLIANCE CATEGORY 3. NOT APPLICABLE DUE TO NEW ENGINE MOUNTING ROD ASSY P/N 3G7120V00132 ALREADY INSTALLED. INFO IS REFERRED FROM LEONARDO HELICOPTER PWC PT6C-67C SERVICE BULETTINS STATUS LIST DATED 08/10/2019.
Standard SBs	NO. 2 ENGINE - SB NO. 41047 REVISION 3	ELECTRONIC ENGINE CONTROL - REPROGRAMMING/REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 11.01.2019.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	131
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	NO. 2 ENGINE ~ SB NO. 41067 REVISION 1	INTERSTAGE AIR-SEAL HOUSING ASSY AND PT VANE RING REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 11.01.2019.
Standard SBs	NO. 2 ENGINE ~ SB NO. 41087	ROTOR COMPRESSOR TIE RODS - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 11.01.2019.
Standard SBs	NO. 2 ENGINE ~ SB NO. 41050 REVISION 1	FUEL NOZZLE CONFIGURATION AND ECOLOGY SYSTEM ACCUMULATOR - REPLACEMENT/MODIFICATION OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 11.01.2019.
Standard SBs	X-RAY INSPECTION OF THE NO. 2 BEARING OIL-PRESSURE-TUBE	P&WC SB NO. 41079 - ENG #2	-	-	-/NOT APPLICABLE	REFER TIC-AW139-20-018-PME-008 DATE ISSUE 20 FEBRUARY 2020. NOT APPLICABLE DUE TO ENGINE S/N. COMPLIANCE AT CATEGORY 6.
Standard SBs	NO. 2 ENGINE - SB NO. 41084	OIL PRESSURE SENSOR - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 11.01.2019.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	132
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	NO. 2 ENGINE ~ SB NO. 41082 REVISION 0	CLAMPING RING TURBINE-VANE - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 11.01.2019.
Standard SBs	FUEL SYSTEM - INSPECTION OF	P&WC SB NO. 41021 REV. 1 - ENG #2	-	-	-/NOT APPLICABLE	COMPLIANCE CATEGORY 3. NOT APPLICABLE DUE TO MODIFICATION FOLLOWING SB41069 (SEE PWC SB LIST). INFO IS REFERRED FROM LEONARDO HELICOPTER PWC PT6C-67C SERVICE BULETTINS STATUS LIST DATED 08/10/2019.
Standard SBs	NO. 2 ENGINE ~ SB NO. 41083	SEALS OIL TANK FILLER CAP AND OIL LEVEL INDICATOR - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 11.01.2019.
Standard SBs	NO. 2 ENGINE ~ SB. NO 41077	ENGINE SHIPPING CONTAINER ASSEMBLY - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 11.01.2019.
Standard SBs	NO. 2 ENGINE ~ SB. NO 41076	SPEED SENSOR NG - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 11.01.2019.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	133
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	NO. 2 ENGINE ~ SB. NO 41075	NPT TORQUE SENSOR - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 11.01.2019.
Standard SBs	FUEL HEATER - MODIFICATION/REPLACEMENT OF	P&WC SB NO. 41064 REV. 2 - ENG #2	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 11.01.2019.
Standard SBs	FUEL-COOLED OIL COOLER - INSPECTION OF	P&WC SB NO. 41074 REV. 0 - ENG #2	-	-	-/NOT APPLICABLE	REFER TIC-AW139-20-018-PME-007 DATE ISSUE 20 FEBRUARY 2020. NOT APPLICABLE DUE TO COMPONENT SERIAL NUMBER NOT FITTED ON AIRCRAFT. COMPONENT FITTED ON AIRCRAFT ARE S/N WA58563 AND S/N WA58832. COMPLIANCE AT CATEGORY 6.
Standard SBs	NO. 2 ENGINE ~ SB. NO 41069	FUEL MANAGEMENT MODULE AND CHIP DETECTOR VALVE AND PLUG - REPLACEMENT/MODIFICATION OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 11.01.2019.
Standard SBs	NO. 2 ENGINE ~ SB. NO 41068	DATA COLLECTION UNIT - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 11.01.2019.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	134
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	POWER TURBINE BAFFLE - INSPECTION OF	P&WC SB NO. A41059 REV. 1 - ENG #2	-	-	-/NOT APPLICABLE	COMPLIANCE CATEGORY 3. NOT APPLICABLE PER ENGINE S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER PWC PT6C-67C SERVICE BULETTINS STATUS LIST DATED 08/10/2019.
Standard SBs	NO. 2 ENGINE ~ SB. NO 41054	ACCESSORY GEARBOX DIAPHRAGM ASSEMBLY - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 11.01.2019.
Standard SBs	NO. 2 ENGINE ~ SB. NO 41051 REVISION 1	COMPRESSOR TURBINE BLADES - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 11.01.2019.
Standard SBs	NO. 2 ENGINE ~ SB. NO 41062	HOSE NON-METALLIC - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 11.01.2019.
Standard SBs	NO. 2 ENGINE ~ SB. NO 41063	HOSE NON-METALLIC - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 11.01.2019.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	135
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	FUEL FILTER - INSPECTION OF	P&WC SB NO. 41061 REV. 0 - ENG #2	-	-	-/NOT APPLICABLE	REFER TIC-AW139-20-018-PME-006 DATE ISSUE 20 FEBRUARY 2020. NOT APPLICABLE DUE TO ENGINE S/N. COMPLIANCE AT CATEGORY 6.
Standard SBs	ACCESSORY GEARBOX DIAPHRAGM - REPLACEMENT/MODIFICATION	P&WC SB NO. 41055 REV. 0 - ENG #2	-	-	-/NOT APPLICABLE	REFER TIC-AW139-20-018-PME-005 DATE ISSUE 20 FEBRUARY 2020. NOT APPLICABLE DUE TO ENGINE S/N. COMPLIANCE AT CATEGORY 7.
Standard SBs	FUEL FILTER INSPECTION OF	P&WC SB NO. A41053 REV. 0 - ENG #2	-	-	-/NOT APPLICABLE	COMPLIANCE CATEGORY 3. NOT APPLICABLE DUE TO ENGINE NOT AFFECTED. INFO IS REFERRED FROM LEONARDO HELICOPTER PWC PT6C-67C SERVICE BULETTINS STATUS LIST DATED 08/10/2019.
Standard SBs	PT SPEED AND TORQUE SENSOR LEFT HAND - REPLACEMENT OF	P&WC SB NO. 41048 REV. 0 - ENG #2	-	-	-/NOT APPLICABLE	COMPLIANCE CATEGORY 3. NOT APPLICABLE DUE TO ENGINE PRE SB41046. INFO IS REFERRED FROM LEONARDO HELICOPTER PWC PT6C-67C SERVICE BULETTINS STATUS LIST DATED 08/10/2019.
Standard SBs	PT SPEED AND TORQUE SENSOR LEFT HAND - REPLACEMENT OF	P&WC SB NO. 41046 REV. 2 - ENG #2	-	-	-/FOR INFO ONLY	REFER TIC-AW139-20-018-PME-004 DATE ISSUE 20 FEBRUARY 2020. APPLICABLE DUE TO ENGINE POST SB-41045. COMPLIANCE IS AT CATEGORY 10 - FOR INFORMATION ONLY.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	136
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	NO. 2 ENGINE ~ SB. NO 41045 REVISION 1	NO. 5 BEARING HOUSING SUPPORT AND PT ROTOR BALANCING ASSEMBLY - REPLACEMENT/MODIFICATION OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 11.01.2019.
Standard SBs	NO. 2 ENGINE ~ SB. NO 41044	IGNITION EXCITER - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 11.01.2019.
Standard SBs	NO. 2 ENGINE ~ SB. NO 41043	CHIP DETECTOR VALVE - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 11.01.2019.
Standard SBs	NO. 2 ENGINE ~ SB. NO 41040	ROTOR AIR SEAL AND TURBINE SPACER - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 11.01.2019.
Standard SBs	NO. 2 ENGINE ~ SB. NO 41042	CHECK VALVE ASSEMBLY - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED WITH MANUFACTURER.
Standard SBs	NO. 2 ENGINE ~ SB NO. 41031, REVISION 1	PREFORMED PACKING - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 11.01.2019.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	137
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	NO. 2 ENGINE ~ SB NO. 41039, REVISION 0	IGNITERS - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 11.01.2019.
Standard SBs	NO. 2 ENGINE ~ SB NO. 41037, REVISION 0	COMPRESSOR INLET CASE ASSEMBLY AND RETAINING PLATE FOR REAR SCAVENGE OIL TUBE - REPLACEMENT/MODIFICATION OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 11.01.2019.
Standard SBs	CENTRIFUGAL IMPELLER - REPLACEMENT OF	P&WC SB NO. 41028 REV. 1 - ENG #2	-	-	-/NOT APPLICABLE	REFER TIC-AW139-20-018-PME-001 DATE ISSUE 20 FEBRUARY 2020. NOT APPLICABLE TO ENGINE S/N. COMPLIANCE IS AT CATEGORY 10 - FOR INFORMATION AND CONFIGURATION PURPOSES ONLY.
Standard SBs	NO. 2 ENGINE ~ SB NO. 41038, REVISION 0	AIR SEAL COMPRESSOR TURBINE STATOR - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 11.01.2019.
Standard SBs	TRIPLE FUNCTION FUEL-SWITCH - REPLACEMENT OF	P&WC SB NO. 41036 REV. 0 - ENG #2	-	-	-/NOT APPLICABLE	REFER TIC-AW139-20-018-PME-002 DATE ISSUE 20 FEBRUARY 2020. NOT APPLICABLE DUE TO THIS SB INTENDED FOR PT6C-67C WITH BUILD SPECIFICATION BS1136 AND BS1137. ENGINE S/N PCE-KB2214 IS BS 963 WHILE PCE-KB2224 IS BS 1019. COMPLIANCE AT CATEGORY 7.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	138
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	NO. 2 ENGINE ~ SB NO. 41034, REVISION 0	FUEL SWITCH IMPENDING BYPASS AND TEMPERATURE - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 11.01.2019.
Standard SBs	NO. 2 ENGINE ~ SB NO. 41033, REVISION 0	SCREEN ASSEMBLY AIR INLET - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 11.01.2019.
Standard SBs	NO. 2 ENGINE ~ SB NO. 41032, REVISION 0	WIRING HARNESS T1 SENSOR - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 11.01.2019.
Standard SBs	NO. 2 ENGINE ~ SB NO. 41020, REVISION 2	ELECTRONIC ENGINE CONTROL - REPROGRAMMING/REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 11.01.2019.
Standard SBs	NO. 2 ENGINE ~ SB NO. 41026, REVISION 0	FUEL MANAGEMENT MODULE - REPLACEMENT	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 11.01.2019.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	139
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	NO. 2 ENGINE ~ SB NO. 41027, REV 0	PT HOUSING SEALING-RING - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 11.01.2019.
Standard SBs	NO. 2 ENGINE ~ SB NO. 41025, REVISION 0	COLD START VALVE HOUSING - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 11.01.2019.
Standard SBs	NO. 2 ENGINE ~ SB NO. 41024, REVISION 0	TURBINE EXHAUST DUCT ASSEMBLY SINGLE PORT - REPLACEMENT	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 11.01.2019.
Standard SBs	NO. 2 ENGINE ~ SB NO. 41023 REVISION 0	DATA COLLECTION UNIT - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 11.01.2019.
Standard SBs	NO. 2 ENGINE ~ SB NO. 41019 REVISION 0	OIL SWITCH (LOP) - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 11.01.2019.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	140
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	BLOWDOWN VALVE HOUSING - INSPECTION/REPLACEMENT OF	P&WC SB NO. 41018 REV. 1 - ENG #2	-	-	-/COMPLIED WITH	COMPLIANCE CATEGORY 3. COMPLIED WITH AS PER PWC SB LIST ATTACHED TO ENGINE LOGBOOK. INFO IS REFERRED FROM LEONARDO HELICOPTER PWC PT6C-67C SERVICE BULETTINS STATUS LIST DATED 08/10/2019.
Standard SBs	NO. 2 ENGINE ~ SB NO. 41017 REVISION 0	COMPRESSOR TURBINE BAFFLE RETAINING BOLT - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 11.01.2019.
Standard SBs	NO. 2 ENGINE ~ SB NO. 41015 REVISION 0	OIL TANK DRAIN ADAPTER AND FIREWALL BRACKET - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 11.01.2019.
Standard SBs	INCREASED COMPRESSOR TURBINE TIP CLEARANCE - INTRODUCTI	P&WC SB NO. 41016 REV. 0 - ENG #2	-	-	-/COMPLIED WITH	COMPLIANCE CATEGORY 3. COMPLIED WITH AS PER PWC SB LIST ATTACHED TO ENGINE LOGBOOK. INFO IS REFERRED FROM LEONARDO HELICOPTER PWC PT6C-67C SERVICE BULETTINS STATUS LIST DATED 08/10/2019.
Standard SBs	NO. 2 ENGINE ~ SB NO. 41014 REVISION 0	FUEL LINES FROM FUEL MANAGEMENT MODULE TO FUEL HEATER - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 11.01.2019.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	141
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	NO. 2 ENGINE ~ SB NO. 41011 REVISION 0	IMPROVED HEAT TRANSFER REDUCTION CONFIGURATION AT NO. 3 BEARING AREA AND EXHAUST DUCT SEALING FACE PROPERTIES - INTRODUCTION OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 11.01.2019.
Standard SBs	NO. 2 ENGINE ~ SB NO. 41013 REVISION 0	OIL SYSTEM PREFORMED PACKING - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 11.01.2019.
Standard SBs	NO. 2 ENGINE ~ SB NO. 41012 REVISION 1	ACCESSORY GEARBOX DIAPHRAGM ASSEMBLY - REPLACEMENT/MODIFICATION OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 11.01.2019.
Standard SBs	NO. 2 ENGINE ~ SB NO 41010 REVISION 0	POWER TURBINE OUTPUT SHAFT - INSPECTION/REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 11.01.2019.
Standard SBs	NO. 2 ENGINE ~ SB NO. 41008 REVISION 1	WIRING HARNESS SUPPORT BRACKET AND FUEL HEATER COVER ATTACHING WASHERS - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 11.01.2019.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	142
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	FUEL HEATER - MODIFICATION/REPLACEMENT OF	P&WC SB NO. 41009 REV. 1 - ENG #2	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 11.01.2019.
Standard SBs	NO. 2 ENGINE ~ SB NO. 41007 REVISION 0	POWER TURBINE SHAFT SPACER - MODIFICATION/REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 11.01.2019.
Standard SBs	NO. 2 ENGINE ~ SB NO. 41001 REVISION 0	EXHAUST DUCT ASSEMBLY - MODIFICATION/REPLACEMENT OF	-	-	-/COMPLIED WITH	PCE-KB2224 COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 11.01.2019.
Standard SBs	NO. 2 ENGINE ~ SB NO. 41002 REVISION 0	FUEL MANIFOLD - REPLACEMENT OF	-	-	-/COMPLIED WITH	PCE-KB2224 COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 11.01.2019.
Standard SBs	NO. 2 ENGINE ~ SB NO. 41005 REVISION 0	OIL FEED ADAPTER ASSEMBLY - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 11.01.2019.

Aircraft Registration:	9M-PME	Serial No:	31855	Date:	28/02/2023	Page No:	143
Aircraft Hours:	1457:28	Landings:	2156.00	Engine 1:	1457:33	Engine 2:	1457:33

Types	SB Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
Standard SBs	NO. 2 ENGINE - SB NO. 41003 REVISION 0	DATA COLLECTION UNIT - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 11.01.2019.
Standard SBs	NO. 2 ENGINE - SB NO. 41004 REVISION 0	COMPRESSOR TURBINE BLADES - REPLACEMENT OF	-	-	-/COMPLIED WITH	COMPLIED WITH. INCORPORATED BY MANUFACTURER. INFO IS REFERRED FROM ENGINE TECHNICAL RECORD LOG PRATT AND WHITNEY CANADA ENGINE BUILD STATUS RECORD DATED 11.01.2019.
Standard SBs	AIR LIMITATION RESTRICTION LIFTED	P&WC SB NO. 41006 REV. 0 - ENG #2	-	-	-/NOT APPLICABLE	COMPLIANCE CATEGORY 3. NOT APPLICABLE PER ENGINE S/N. INFO IS REFERRED FROM LEONARDO HELICOPTER PWC PT6C-67C SERVICE BULETTINS STATUS LIST DATED 08/10/2019.
Types	SB Number	Subject	Last Done	Next Due	Interval	Limitation Notes
Component SBs	SB 139-526 REV / PART II	ATA 63 MGB OIL COOLING FAN INSPECTION	-	-	0	9M-PME-10895 AT 1190:00 ON 16/06/2022