

A/C TYPE EC155B
 A/C REGN 9M-SAS S/N 6583
 TYPE OF CHECK _____



EUROCOPTER SOUTH EAST ASIA PTE LTD
 48 Loyang Way Singapore 508740
 Company Registration No.: 197702516C

NO: **19070** FORM NO: M/003

(REF TO CRS #19461)

JOB NO. _____

PAGE _____ OF _____

DEFECT AND RECTIFICATION WORKSHEET/CERTIFICATE OF RELEASE TO SERVICE

ITEM NO.	REPORTED BY DATE	DEFECT/WORK REQUIRED	ACTION TAKEN	COMPONENT CHANGES		G.I.N.NO. OR O-HAUL REPORT NO.	MAN HOURS	MECH	LIC/ APP NO. DATE
				S/N OFF	S/N ON				
1.	SEW LAY 02/3/06	COMPLY WITH EMERGENCY AD 2006-0052-E - CABIN SLIDING DOOR (REF. ASB 52A018 R2)	N/A DUE SLIDING DOOR NOT INSTALLED Buy.						 22/3/06 A1788
2.	SEW LAY 10/3/06	COMPLY WITH ASB 05A011 - TRB CHECK	AMENDED AL7 TLX 05A011 TO ASB 05A011 INCORPORATED IN POST FLIGHT INSP. OF MAINT. SCHEDULE REF. ESEA/EC155B/ ISS 2 ON 10-03-06 Buy.						 22/3/06 A1788
3.	SEW LAY 10/3/06	COMPLY WITH SB 29-005 - REPLACEMENT OF PRESSURE SWITCHES	N/A TO PRESSURE SWITCHES P/N MA143-01 S/N 0621 & S/N 0580 INSTALLED (POST MOD 0729560) Buy.						 22/3/06 A1788

CERTIFIES THAT THE WORK SPECIFIED EXCEPT AS OTHERWISE SPECIFIED WAS CARRIED OUT IN ACCORDANCE WITH THE FOLLOWING REQUIREMENTS AND IN RESPECT TO THAT WORK THE AIRCRAFT/AIRCRAFT COMPONENT IS CONSIDERED READY FOR RELEASE TO SERVICE:

- | | | |
|--|---|--------------------------------|
| <input type="checkbox"/> SAR-145 & SINGAPORE ANO | <input type="checkbox"/> EASA PART-145: EASA.145.0056 | <input type="checkbox"/> _____ |
| <input checked="" type="checkbox"/> MALAYSIAN CIVIL AVIATION REGULATIONS | <input type="checkbox"/> MANUFACTURER'S PUBLICATIONS | |