

A/C TYPE EC155B  
 A/C REGN 9M-SAS-5N 6583  
 TYPE OF CHECK \_\_\_\_\_



EUROCOPTER SOUTH EAST ASIA PTE LTD  
 48 Loyang Way Singapore 508740  
 Company Registration No.: 197702516C

NO: **19066** FORM NO: M/003

JOB NO. \_\_\_\_\_

PAGE \_\_\_\_\_ OF \_\_\_\_\_

DEFECT AND RECTIFICATION WORKSHEET/CERTIFICATE OF RELEASE TO SERVICE

ITEM NO.	REPORTED BY DATE	DEFECT/WORK REQUIRED	ACTION TAKEN	COMPONENT CHANGES		G.I.N.NO. OR O/HAUL REPORT NO.	MAN HOURS	MECH	LIC/ APP NO. DATE
				S/N OFF	S/N ON				
1.	STEWLAY 20/2/06	COMPLY WITH AD UF-2006-042 - (CHECK OF FLEXIBLE HYDRAULIC PIPES AND THEIR ATTACHMENT CLAMPS (MUD 0729B65)	COMPLIED WITH ALT FLX 29A 001 ON 29-07-04 @ 538:25 A/F HRS (REF. CRS #17015) <i>By</i>						<i>[Signature]</i> 20/2/06 A1719
2.	STEWLAY 20/2/06	COMPLY WITH AD UF-2004-115 R1 - (CHECK OF FLEXIBLE HYDRAULIC PIPES & THEIR ATTACHMENT CLAMPS - CANCELLATION NOTICE	NOTED - AD UF-2004-115 R1 REPLACED BY AD UF-2006-042 <i>By</i>						<i>[Signature]</i> 20/2/06 A1719
3.	STEWLAY 20/2/06	COMPLY WITH SB 52-022 R1 - MICRO-SWITCH, SOLID WITH THE LOWER CATCH	N/A DUE CABIN SLIDING DOOR NOT INSTALLED <i>By</i>						<i>[Signature]</i> 20/2/06 A1719

CERTIFIES THAT THE WORK SPECIFIED EXCEPT AS OTHERWISE SPECIFIED WAS CARRIED OUT IN ACCORDANCE WITH THE FOLLOWING REQUIREMENTS AND IN RESPECT TO THAT WORK THE AIRCRAFT/AIRCRAFT COMPONENT IS CONSIDERED READY FOR RELEASE TO SERVICE:

- SAR-145 & SINGAPORE ANO
- MALAYSIAN CIVIL AVIATION REGULATIONS
- EASA PART-145: EASA.145.0056
- MANUFACTURER'S PUBLICATIONS