


DELIVERY NOTE WP

DELIVER TO :

GALAXY AEROSPACE (M) SDN. BHD.
CAMO DEPARTMENT
Lot 11, MRO Centre,
Malaysia International Aerospace Centre,
Sultan Abdul Aziz Shah Airport,
47200 Subang, Selangor
Malaysia.
Attn : Zaty Nadhira binti Mohamed Zuhari

DN NUMBER : GAM/DN/YTL-22-125
OUR REFERENCE : 9M-YTL-12678
WO REFERENCE : 2022-12678
DATE COMPLETION: 09 SEPT 2022
AJL NUMBER : 1562

A/C DETAILS								
A/C TYPE	AW139	A/C REG	9M-YTL		A/C S/N	41358		
OWNER / OPERATOR	YTL POWER GENERATION SDN. BHD	A/C TOTAL TIME	348:40		LANDINGS	530		
ENGINE #1 S/N	PCE-KB1443	T.S.N	348:40		T.S.O	-		
ENGINE #2 S/N	PCE-KB1457	T.S.N	348:40		T.S.O	-		
LIST OF TASK PERFORMED	WP NUMBER	NUMBER OF PAGES						
		*WS	*PR	*TR	*ARC	*S	*SBC	*OTH
TAIL ROTOR - DUPLEX BEARINGS - INSPECTION/REPLACEMENT // ROTOR FLIGHT CONTROL - TAIL ROTOR ACTUATOR - INSPECTION/REPLACEMENT (PARA 1)	-001	1	1	1	-	-	1	-
*THIS IS TO CERTIFY THAT TASKS LISTED ABOVE HAS BEEN ACCOMPLISHED AS PER PO/WORK ORDER/SERVICE ORDER NO. 1AS ABOVE.								
NAME	NAAIM HAFIZ SHAH	SIGNATURE			DATE	28 OCTOBER 2022		
VERIFIED AND ACCEPTED BY				THAVAMALAR A/P KUMARAVELU CAMO Planner Galaxy Aerospace (M) Sdn Bhd (1040262-D)				
DATE				31 OCT 2022				

- *WS – WORKSHEET
- *PR – PART REPORT
- *ARC – AUTHORISED RELEASE CERTIFICATE
- *S – SERVICEABLE LABEL
- *SBC – SERVICE BULLETIN COMPLIANCE
- *OTH – OTHERS
- *TR – TOOLS REPORT



WORK ORDER



To: GALAXY AEROSPACE (M) SDN. BHD.

Address: Lot 11-14, MRO Centre, Malaysia
International Aerospace Centre, SAAS Airport,
Subang
Malaysia

Attention: Mr. Syafrul Yamani
Engineering Manager
syafrul@galaxyaerospace.my

Work Order Number: 2022-12678

Work Pack Reference: 9M-YTL-12678

Date Issued: 06/09/2022

A/C Registration / SN: 9M-YTL/41358

Sheet: 1 of 1

Description:

Item	Description/Task/Inspection	Reference	Man Hours
1	TAIL ROTOR - DUPLEX BEARINGS - INSPECTION/REPLACEMENT // ROTOR FLIGHT CONTROL - TAIL ROTOR ACTUATOR - INSPECTION/REPLACEMENT (PARA 1)	EASA AD NO. 2022-0182-E, NEW ISSUE (SBEA 139-725 REV.A)	1-0 (PLEASE ADVISE)

Remark/Notes:

1. State this Work Order reference on your Work Package. Should there is any additional job/defect (unless specified in the work package) the maintenance organization must notify GAM Continuing Airworthiness Manager prior to proceed with rectification.
2. Work must be carried out in accordance with approved data and perform by qualified personnel/ approved LAE from the maintenance organization.
3. Parts used must be written in Parts Report Form and accompanied by ARC, Serviceable Label or equivalent document.
4. Test report, parameter reading or any supporting data must be attached with the worksheet if applicable.
5. The maintenance organization shall be responsible for any damages made on the aircraft/ components during maintenance.
6. Softcopy of completed Work Package shall be submitted or as mutual agreed and GAM Continuing Airworthiness Manager must be informed once the aircraft is Release to Service.
7. Completed Work Package (original) must be submitted to GAM Continuing Airworthiness Manager office within 3 days of date of completion.



I hereby declare that an approved and up to date maintenance data has been referred for the issuance of this work order.

Thank you.
Best Regards,

Zaty Nadhira Mohamed Zuhari
Continuing Airworthiness Management Manager
Email: zaty@galaxyaerospace.my






Aircraft Serial No:	41358	Work Pack No:	9M-YTL-12678
Aircraft Type:	AW139	DESC:	AD2022-0152 PART I
Aircraft Reg:	9M-YTL	PAGE:	1 Of 1

Description	Part No	Serial Number	Worksheet Ref No. / Item No.	Calibration Due Date
  09 SEP 2022				



CLIENT/OWNER: YTL POWER GENERATION SDN BHD AIRCRAFT TYPE: AW139 REGISTRATION: 9M-YTL BASE/FACILITY: WMSA DATE IN: REFER WORKPACK OUT: REFER WORKPACK	SERIAL NO.	HOURS	LDG/CYCLE	WORKSHEET NO:	12678-001	
	AIRCRAFT	41358	REFER WORKPACK	WORK/INSP/DESC:	AD2022-0152 PART I	
	#1 ENGINE: PCE-KB1443	REFER WORKPACK	WORKPACK REF:	9M-YTL-12678	AJL REF NO.:	REFER WORKPACK
	#2 ENGINE: PCE-KB1457	REFER WORKPACK	NG / N1	NF / N2	SHEET:	1 OF 1

Reason for raising: INSPECTION TO BE CARRIED OUT I.A.W EASA AD 2022-0152-E NEW ISSUE DATED 26-JULY-2022, EASB 139-725 REV. A DATE 9-AUG-2022, AW139 IETP - 41ST ISSUE DATED 2022-06-28 UPDATE DATE 2022-07-20 OR LATER APPROVED REVISIONS. TAIL ROTOR - DUPLEX BEARINGS - INSPECTION/REPLACEMENT // ROTOR FLIGHT CONTROL - TAIL ROTOR ACTUATOR - INSPECTION/REPLACEMENT (PARA 1)	Raised by and date: CAMO; Thavamalar 06/09/2022	Other requirements/information: NIL
---	---	--

Item	Description	Technician	* Eng. CRS	Date
1	INSPECTION TAIL ROTOR DUPLEX BEARING CARRY OUT INSPECTION AS PER EASA AD 2022-0182-E NEW ISSUE PARA 1 (EASB 139-725 REV. A PART 1). NOT EXCEED 10 FH. TO PERFORM PART 1, TO APPLY A SLIPPAGE MARK BETWEEN THE PCR AND THE TRUNION INSTALLED ON THE BACK-END OF THE TRA AND TO PERFORM REPETITIVE INSPECTIONS FOR ABSENCE OF ROTATION PARTS. IF THE INSPECTION FAILS, THE BEARING MUST BE REPLACED IMMEDIATELY. IF ROTATION IS FOUND, ALSO THE TRA P/N 3G6730V00731 OR P/N 3G6730V00732 MUST BE REPLACED BEFORE NEXT FLIGHT. REMARKS: <i>TAIL CARRIED OUT FOUND 8ATLS.</i>	 8111	 	9/9/22

*Certifies that the work specified above, except as otherwise specified, was carried out in accordance with CAA Malaysia Requirements and in respect to that work the aircraft / aircraft component is considered ready for release to service.

*Certifies that the work specified above, except as otherwise specified, was carried out in accordance with _____ and in respect to that work the aircraft / aircraft component is considered ready for release to service.

TICK ✓ WHERE APPLICABLE

PARS CHECKED & RETURNED	CO. CHECKED	Duplicate TOP	GROUND RUN	FLIGHT TEST	TROUBLE SHOOT	ADDITIONAL WORKSHEET	MANAGED DEFECT	PLANNING FORECAST	DAYS UPDATE	STATUS UPDATE	DD STATUS	AIRCRAFT LOGBOOK	ENGINE LOG BOOK	PROPELLER LOGBOOK	LOG CARD	HEMI/COMP LOG CARD	MISC RECORD BOOK
-------------------------	-------------	---------------	------------	-------------	---------------	----------------------	----------------	-------------------	-------------	---------------	-----------	------------------	-----------------	-------------------	----------	--------------------	------------------



CLIENT/OWNER: YTL POWER GENERATION SDN BHD	SERIAL NO.	HOURS	LDG/CYCLE	WORKSHEET NO:	12678-001
AIRCRAFT TYPE: AW139	AIRCRAFT: 41358	REFER WORKPACK		WORK/INSP/DESC:	AD2022-0152 PART I
REGISTRATION: 9M-YTL	#1 ENGINE: PCE-KB1443	REFER WORKPACK		WORKPACK REF:	9M-YTL-12678
BASE/FACILITY: WMSA	#2 ENGINE: PCE-KB1457	REFER WORKPACK		AJL REF NO.:	REFER WORKPACK
DATE IN: REFER WORKPACK OUT: REFER WORKPACK				SHEET:	1 OF 1
			NG / N1		NF / N2

REASON FOR RAISING: INSPECTION TO BE CARRIED OUT I.A.W EASA AD 2022-0152-E NEW ISSUE DATED 26-JULY-2022, EASB 139-725 REV. A DATE 9-AUG-2022, AW139 IETP - 41ST ISSUE DATED 2022-06-28 UPDATE DATE 2022-07-20 OR LATER APPROVED REVISIONS. TAIL ROTOR - DUPLEX BEARINGS - INSPECTION/REPLACEMENT // ROTOR FLIGHT CONTROL - TAIL ROTOR ACTUATOR -	Raised by and date: CAMO; Thavamalar 06/09/2022	Other requirements/information: NIL
---	---	--

Item	Part No	Description	Serial Number		Qty	Position	Reason	Lifed Item Information TSN/TSO/DUE/TIMEX	Release Reference
			Off	On					
Table content is crossed out with a diagonal line.									

NAME	FIRM	SIGN & APPROVAL	DATE
Sukumar Perumudurai	GAM		2/9/22

*Certifies that the work specified above, except as otherwise specified, was carried out in accordance with CAA Malaysia Requirements and in respect to that work the aircraft / aircraft component is considered ready for release to service.

*Certifies that the work specified above, except as otherwise specified, was carried out in accordance with _____ and in respect to that work the aircraft / aircraft component is considered ready for release to service.


TICK WHERE APPLICABLE



DATE ISSUED & RETURNED	DD INDEXED	DUPPLICATE INP	GROUND RULY	FLIGHT TEST	TURBINE OIL	ADDITIONAL WORKSHEET	MANUALS CHECK	PLANNING FORECAST	DIARY UPDATE	STATUS UPDATE	DEL. DATE	AIRCRAFT JOURNAL	ENGINE LOG BOOK	PROPELLER LOGBOOK	LOG SHEET	REMOVAL LOGCARD	MOD RECORD BOOK
------------------------	------------	----------------	-------------	-------------	-------------	----------------------	---------------	-------------------	--------------	---------------	-----------	------------------	-----------------	-------------------	-----------	-----------------	-----------------

Please send to the following address: LEONARDO S.p.A. CUSTOMER SUPPORT & SERVICES - ITALY PRODUCT SUPPORT ENGINEERING & LICENSES DEPT. Via Giovanni Agusta, 520 21017 Cascina Costa di Sarnate (VA) - ITALY Tel.: +39 0331 225036 Fax: +39 0331 225988	SERVICE BULLETIN COMPLIANCE FORM	Date: 9/8/22
	Number: 139-725	
	Revision: A	

Customer Name and Address: GALAXY AEROSPACE (M) SDN BHD Suite 11-14, Helicopter Centre, Malaysia International Aerospace Centre, Sultan Abdul Aziz Shah Airport, 47200 Subang, SELANGOR DARUL EHSAN	Telephone: 603-7734 7226
	Fax: 603-7734 7226
	B.T. Compliance Date:

Helicopter Model	S/N	Total Number	Total Hours	T.S.O.
AW139	41358	-	348:15	-

E.V.E.  9/8/22
 Remarks: **Apply Application of SUPPAGE MARK CARRIED OUT 1. AW PART 1 OF REF SB 139-725 REV. A Dtd. 9/8/22 - FOUND SATISFACTORY.**

 
19 OCT 2022

Information:

 We request your cooperation in filling this form, in order to keep out statistical data relevant to aircraft configuration up-to-date. The form should be filled in all its parts and sent to the above address or you can communicate the application also via Technical Bulletin Application Communication Section placed in Leonardo AW Customer Portal - MyCommunications Area. We thank you beforehand for the information given.