


DELIVERY NOTE WP

DELIVER TO :

GALAXY AEROSPACE (M) SDN. BHD.
CAMO DEPARTMENT
Lot 11, MRO Centre,
Malaysia International Aerospace Centre,
Sultan Abdul Aziz Shah Airport,
47200 Subang, Selangor
Malaysia.
Attn : Zaty Nadhira binti Mohamed Zuhari

DN NUMBER : GAM/DN/YTL-23-025
OUR REFERENCE : 9M-YTL-13905
WO REFERENCE : 2023-13905
DATE COMPLETION: 23 MARCH 2023
AJL NUMBER : 1614

A/C DETAILS								
A/C TYPE	AW139	A/C REG	9M-YTL	A/C S/N	41358			
OWNER / OPERATOR	YTL POWER GENERATION SDN. BHD	A/C TOTAL TIME	376:14	LANDINGS	575			
ENGINE #1 S/N	PCE-KB1443	T.S.N	376:14	T.S.O	-			
ENGINE #2 S/N	PCE-KB1457	T.S.N	376:14	T.S.O	-			
LIST OF TASK PERFORMED	WP NUMBER	NUMBER OF PAGES						
		*WS	*PR	*TR	*ARC / COC	*S	*SBC	*OTH
SB 139-672 REV./ PART I & II ATA 29 NUMBER 4 PUMP LINE INSTALLATION VISUAL INSPECTION AND MODIFICATION	001	1	1	1	-	-	-	-
*THIS IS TO CERTIFY THAT TASKS LISTED ABOVE HAS BEEN ACCOMPLISHED AS PER PO/WORK ORDER/SERVICE ORDER NO. 1AS ABOVE.								
NAME	NAAIM HAFIZ SHAH	SIGNATURE		DATE	29 MARCH 2023			
VERIFIED AND ACCEPTED BY				THAVAMALAR A/P KUMARAVELU CAMO Planner Galaxy Aerospace (M) Sdn Bhd (1040262-D)				
DATE				03 APR 2023				

*WS – WORKSHEET

*S – SERVICEABLE LABEL

*TR – TOOLS REPORT

*PR – PART REPORT

*SBC – SERVICE BULLETIN COMPLIANCE

*ARC – AUTHORISED RELEASE CERTIFICATE

*OTH – OTHERS



WORK ORDER



To: GALAXY AEROSPACE (M) SDN. BHD.

Address: Lot 11-14, MRO Centre, Malaysia
International Aerospace Centre, SAAS Airport,
Subang
Malaysia

Attention: Mr. Syafrul Yamani
Engineering Manager
syafrul@galaxyaerospace.my

Work Order Number: 2022-13905

Work Pack Reference: 9M-YTL-13905

Date Issued: 20/12/2022

A/C Registration / SN: 9M-YTL/41358

Sheet: 1 of 1

Description:

Item	Description/Task/Inspection	Reference	Man Hours
1	SB 139-672 REV./ PART I AND PART II - ATA 29 - NUMBER 4 PUMP LINE INSTALLATION VISUAL INSPECTION AND MODIFICATION	SB NO. 139-672, NEW ISSUE (PART I & PART II)	<u>1 - 0</u> (PLEASE ADVISE)

Remark/Notes:

1. State this Work Order reference on your Work Package. Should there is any additional job/defect (unless specified in the work package) the maintenance organization must notify GAM Continuing Airworthiness Manager prior to proceed with rectification.
2. Work must be carried out in accordance with approved data and perform by qualified personnel/ approved LAE from the maintenance organization.
3. Parts used must be written in Parts Report Form and accompanied by ARC, Serviceable Label or equivalent document.
4. Test report, parameter reading or any supporting data must be attached with the worksheet if applicable.
5. The maintenance organization shall be responsible for any damages made on the aircraft/ components during maintenance.
6. Softcopy of completed Work Package shall be submitted or as mutual agreed and GAM Continuing Airworthiness Manager must be informed once the aircraft is Release to Service.
7. Completed Work Package (original) must be submitted to GAM Continuing Airworthiness Manager office within 3 days of date of completion.

I hereby declare that an approved and up to date maintenance data has been referred for the issuance of this work order.

Thank you.
Best Regards,

Zaty Nadhira Mohamed Zuhari
Continuing Airworthiness Management Manager
Email: zaty@galaxyaerospace.my



CLIENT/OWNER: YTL POWER GENERATION SDN BHD AIRCRAFT TYPE: AW139 REGISTRATION: 9M-YTL BASE/FACILITY: WMSA DATE IN: 23/03/23 OUT: 23/03/23	SERIAL NO.	HOURS	LDG/CYCLE		WORKPACK NO:	9M-YTL-13905
	AIRCRAFT	41358	376:14	575	WORK/INSP/DESC:	SB 139-672 REV./
	#1 ENGINE: PCE-KB1443	376:14	-	-	AERONET JOB NO.:	2022-13905
	#2 ENGINE: PCE-KB1457	376:14	-	-	AJL REF NO.:	1014
			NG / N1	NF / N2	SHEET:	1 OF 1

Reason for raising: SB 139-672 REV./ PART I AND PART II - ATA 29 - NUMBER 4 PUMP LINE INSTALLATION VISUAL INSPECTION AND MODIFICATION TO BE CARRIED OUT I.A.W. AW139 IETP 41st ISSUE 2022-06-28 UPDATED 2022-11-16, AMP NO.YTLPG/CAMO/AMP/AW139 ISSUE 1 REV. 2.	Raised by and date: CAMO; Thavamalar 20/12/2022	Other requirements/information: NIL
--	---	--

List of scheduled inspection and all work carried out under this workpack including individual reference			DATE INSPECTION COMPLETED	Master Signature Schedule		
NO.	INSPECTION / WORK	WORKSHEET REF		NAME	SIGNATURE	APP/STAMP
1	SB 139-672 REV./ PART I AND PART II - ATA 29 - NUMBER 4 PUMP LINE INSTALLATION VISUAL INSPECTION AND MODIFICATION	13905-001	23/03/23	SHAHROL ASWAD		
				JEE BOON HONG		8106

<p>PART 145 - AMO RELEASE STATEMENT AMO/2016/02</p> <p>THIS IS TO CERTIFY THAT ALL WORK LISTED ABOVE HAS BEEN INSPECTED AND ACCOMPLISHED IN ACCORDANCE WITH CONTRACTED AMO EXPOSITION AND PROCEDURE LATEST REVISION, AND 23/03/2023</p> <p><input checked="" type="checkbox"/> OEM PUBLICATION/REVISION AS PER REASON FOR RAISING ABOVE</p> <p><input checked="" type="checkbox"/> IF DIFFERENT FROM ABOVE. OEM PUBLICATION/REVISION... AW139 IETP 42ND ISSUE 2022-12-01 UPDATED 002 DATED 2023-02-28</p> <p><input type="checkbox"/> * TICK ✓ WHERE APPLICABLE</p>	NAME	SHAHROL ASWAD
	SIGN & APPROVAL	
	FIRM	GAM
	DATE	23/03/23

<p>PART M - CAMO ACCEPTANCE STATEMENT</p> <p>THIS IS TO CERTIFY THAT THE ABOVE MENTIONED WORK PACKAGE HAS BEEN REVIEWED, CHECKED FOR COMPLETION AND UPDATED IN THE MAINTENANCE SOFTWARE.</p>	NAME	THAVAMALAR A/P KUMARAVELU
	SIGN & APPROVAL	
	DATE	27/3/2023



Aircraft Serial No:	41358	Work Pack No:	9M-YTL-13905
Aircraft Type:	AW139	DESC:	SB 139-672 REV./
Aircraft Reg:	9M-YTL	PAGE:	1 Of 1

Description	Part No	Serial Number	Worksheet Ref No. / Item No.	Calibration Due Date
(The table body is currently empty and contains a large diagonal line from the top-left to the bottom-right corner.)				

CLIENT/OWNER: YTL POWER GENERATION SDN BHD AIRCRAFT TYPE: AW139 REGISTRATION: 9M-YTL BASE/FACILITY: WMSA DATE IN: REFER WORKPACK OUT: REFER WORKPACK	SERIAL NO.	HOURS	LDG/CYCLE		WORKSHEET NO:	9M-YTL-13905
	AIRCRAFT	41358	REFER WORKPACK		WORK/INSP/DESC:	SB 139-672 REV./
	#1 ENGINE:	PCE-KB1443	REFER WORKPACK		WORKPACK REF:	2022-13905
	#2 ENGINE:	PCE-KB1457	REFER WORKPACK		AJL REF NO.:	REFER WORKPACK
			NG / N1	NF / N2	SHEET:	1 OF 1

Reason for raising: SB 139-672 REV./ PART I AND PART II - ATA 29 - NUMBER 4 PUMP LINE INSTALLATION VISUAL INSPECTION AND MODIFICATION TO BE CARRIED OUT I.A.W. AW139 IETP 41st ISSUE 2022-06-28 UPDATED 2022-11-16, AMP NO.YTLPG/CAMO/AMP/AW139 ISSUE 1 REV. 2.	Raised by and date: CAMO; Thavamalar 20/12/2022	Other requirements/information: NIL
--	---	--

Item	Description	Technician	* Eng. CRS	Date
1	TO PERFORM INSPECTION OF THE HYDRAULIC LINES CONNECTING POWER CONTROL MODULE 2 TO PUMP NUMBER 4. NOTE: REPLACEMENT OF PIPES WITH NEW ONES MAY BE REQUIRED IN CASE DAMAGE IS FOUND. REF: SB NO.139-672, NEW ISSUE (PART I) REMARKS: TASK CARRIED OUT POUND SATISFACTORY	8106		23/03/22

2	PERFORM INSTALLATION OF RETROMOD P/N 3G2900P00711 TO REPLACES EXISTING CLAMP PIN A295A3002AAND BRACKET PIN 3G2920A12251 WITH NEW AND IMPROVED VERSIONS THAT PREVENT CHAFING. REF: SB NO.139-672, NEW ISSUE (PART II) REMARKS: NOT APPLICABLE DUE TO SATISFACTION OF PART I.	-		23/03/22
---	---	---	--	----------

*Certifies that the work specified above, except as otherwise specified, was carried out in accordance with CAA Malaysia Requirements and in respect to that work the aircraft / aircraft component is considered ready for release to service. **AMO/2016/02**

*Certifies that the work specified above, except as otherwise specified, was carried out in accordance with _____ and in respect to that work the aircraft / aircraft component is considered ready for release to service.

TICK ✓ WHERE APPLICABLE

PARTS LABELLED & RETURNED	D.D. RAISED	DUPLICATE INSP	GROUND RUN	FLIGHTTEST	TORQUE CHK	ADDITIONAL WORKSHEET	MONITORED DEFECT	PLANNING FORECAST	DIARY UPDATE	STATUS UPDATE	D.D. STATUS	AIRCRAFT LOG BOOK	ENGINE LOG BOOK	PROPELLER LOG BOOK	LOG CARD	DEM/CORR LOG CARD	MOD. RECORD BOOK
---------------------------	-------------	----------------	------------	------------	------------	----------------------	------------------	-------------------	--------------	---------------	-------------	-------------------	-----------------	--------------------	----------	-------------------	------------------



CLIENT/OWNER: YTL POWER GENERATION SDN BHD AIRCRAFT TYPE: AW139 REGISTRATION: 9M-YTL BASE/FACILITY: WMSA DATE IN: REFER WORKPACK OUT: REFER WORKPACK	SERIAL NO.	HOURS	LDG/CYCLE		WORKSHEET NO:	9M-YTL-13905	
	AIRCRAFT	41358	REFER WORKPACK		WORK/INSP/DESC:	SB 139-672 REV./	
	#1 ENGINE:	PCE-KB1443	REFER WORKPACK		WORKPACK REF:	2022-13905	
	#2 ENGINE:	PCE-KB1457	REFER WORKPACK		AJL REF NO.:	REFER WORKPACK	
					NG / N1	NF / N2	SHEET: 1 OF 1

REASON FOR RAISING: SB 139-672 REV./ PART I AND PART II - ATA 29 - NUMBER 4 PUMP LINE INSTALLATION VISUAL INSPECTION AND MODIFICATION TO BE CARRIED OUT I.A.W. AW139 IETP 41st ISSUE 2022-06-28 UPDATED 2022-11-16, AMP NO.YTLPG/CAMO/AMP/AW139 ISSUE 1 REV. 2.	Raised by and date: CAMO; Thavamalar 20/12/2022	Other requirements/information: NIL
---	---	--

Item	Part No	Description	Serial Number		Qty	Position	Reason	Lifed Item Information TSN/TSO/DUE/TIMEX	Release Reference
			Off	On					
(Table content is crossed out with a diagonal line)									

NAME	FIRM	SIGN & APPROVAL	DATE
MOHD SHAHRUL ASWAD	GAM		23/03/23

*Certifies that the work specified above, except as otherwise specified, was carried out in accordance with CAA Malaysia Requirements and in respect to that work the aircraft / aircraft component is considered ready for release to service. **AMO/2016/02**

*Certifies that the work specified above, except as otherwise specified, was carried out in accordance with _____ and in respect to that work the aircraft / aircraft component is considered ready for release to service.

TICK WHERE APPLICABLE

PARTS LABELLED & RETURNED	D.D. RAISED	DUPLICATE INFO	GROUND RUN	FLIGHTTEST	TORQUE CHK	ADDITIONAL WORKSHEET	MONITORED DEFECT	PLANNING FORECAST	DIARY UPDATE	STATUS UPDATE	D.D. STATUS	AIRCRAFT LOG BOOK	ENGINE LOG BOOK	PROPELLER LOG BOOK	LOG CARD	GEN/COMP LOG CARD	MOD RECORD BOOK
---------------------------	-------------	----------------	------------	------------	------------	----------------------	------------------	-------------------	--------------	---------------	-------------	-------------------	-----------------	--------------------	----------	-------------------	-----------------

SB 139-672 – Inspection Report		
Date	23/03/23	
Helicopter S/N	41352	
Flight Hours	376 = 14	
Customer	YTL	
Pipe P/N	Worn diameter [mm]	Intact diameter [mm]
NIL	NIL	NIL
Notes: TASK CARRIED OUT FOUND SATISFACTORY		

Figure 9

Please send to the following address: LEONARDO S.p.A. CUSTOMER SUPPORT & SERVICES - ITALY PRODUCT SUPPORT ENGINEERING & LICENSES DEPT. Via Giovanni Agusta, 520 21017 Cascina Costa di Samarate (VA) - ITALY Tel.: +39 0331 225036 Fax: +39 0331 225988		SERVICE BULLETIN COMPLIANCE FORM		Date: 23 MAR 2023	
		Number:		SB 139-672	
		Revision:			
		Customer Name and Address: GALAXY AEROSPACE (M) SDN BHD Suite 11-14, Helicopter Centre, Malaysia International Aerospace Centre, Sultan Abdul Aziz Shah Airport, 47200 Subang, SELANGOR DARUL EHSAN		Telephone:	
Fax:				603-7734 7226	
B.T. Compliance Date:				23 MAR 2023	
Helicopter Model	S/N	Total Number	Total Hours	T.S.O.	
AW139	41358	-	376:14	-	
Remarks: THE FOLLOWING SERVICE BULLETIN - NUMBER 4 PUMP LINE INSTALLATION VISUAL INSPECTION AND MODIFICATION PART 1 DATED OCTOBER 3, 2022 CARRIED OUT AND FOUND SATISFACTORY					
Information: We request your cooperation in filling this form, in order to keep out statistical data relevant to aircraft configuration up-to-date. The form should be filled in all its parts and sent to the above address or you can communicate the application also via Technical Bulletin Application Communication Section placed in Leonardo AW Customer Portal - MyCommunications Area. We thank you beforehand for the information given.					