

ADS AIRWORTHINESS DIRECTIVES (AD'S) STATUS LIST

Aircraft Registration:	9M-JAG	Serial No:	1153	Date: 01/07/20)22 Page No:	2
Aircraft Hours:	4.01	Landings:	0.00	Engine 1: 4	.01 Engine 2:	0.00

Types	AD Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes			
Standard ADs	AD NO. 2019-07-02, NEW ISSUE	FAA - R66 AIRWORTHINESS DIRECTIVES ENGINE OIL STORAGE (AIRFRAME FURNISHED)	-	-	-/NOT APPLICABLE	TIC-R66-22-0039 (2-Aug-2022)			
		, , , , , , , , , , , , , , , , , , ,				Not applicable to aircraft S/N.			
						This AD requires inspecting the oil tank			
						outlet's fitting color. If the fitting is blue, this AD			
						requires replacing the tank with an oil tank that			
						lacks a blue fitting. This AD also requires			
						determining the revision letter on the ink			
						stamp, and installing an oil tank angle based			
						on that determination.			
Standard ADs	AD NO. 2016-26-04, NEW ISSUE	FAA - R66 AIRWORTHINESS DIRECTIVES	-	-	-/NOT APPLICABLE	TIC-R66-22-0038 (2-Aug-2022)			
		MAIN ROTOR BLADES							
						NOT APPLICABLE due to aircraft fitted with			
						Main Rotor Blade Revision K.			
						The AD is issued to perform inspection to			
						MRB. The proposed requirement were			
						intended to prevent an MRB fatigue crack,			
						which could lead to MRB failure and			
						subsequent loss of helicopter control.			
ENGINE AD									
Standard ADs	FAA AD NO: 2017-18-14	TURBINE SECTION	-	-	-/ SUPERSEDED	TIC-R66-22-0042 (2-AUG-2022)			
						THIS AD HAS BEEN SUPERSEDED BY AD			
						2022-10-06. REFER SENTENCING IN TIC-			
						R66-22-0041.			

 Verified by (Sign/Stamp):
 Report Date: 08/09/2022
 Time: 09:03:56
 GAM/CAMO-017R2