



TURBOMECA SERVICE BULLETINS

31-May-22

AIRBUS EC155B1, S/N 6997, REG N155HH

TURBOMECA ARRIEL 2C2, L/H ENGINE S/N 26300 & R/H ENGINE S/N 26299

ARRIEL 2C2 SB No. X292 N6 980 2, 2022-03-16

SERVICE BULLETIN CODE 1

RH ENGINE: 26299

SB, CODE 1	DATE	REV	FAA AD'S	EASA AD'S	SUBJECT	APPLICABILITY	ENG TT	DATE	ORGANISATION	NOTE
A292 72 5166	22-Nov-16	C	2012-18-18	2012-0124R1	MODULE M03 (GAS GENERATOR). HP BLADE DAMPERS. APPLICATION OF MODIFICATION TU 166.	MODULE M03 SN 8901, TU166 FOUND EMBODIED AT TIME OF MANUFACTURE.	0	6-Feb-14	SAFRAN MANUFACTURER	TU166 EMBODIED
292 72 2817	24-Aug-21	C	-	-	RETURN TO SERVICE FOR CIVIL OPERATION OF AN ARRIEL 2 ENGINE ORIGINATING FROM AN OPERATOR NOT CONTROLLED BY A CIVIL AUTHORITY (MILITARY, PARAMILITARY, ETC.).	N/A, AIRCRAFT NOT OPERATING BY OPERATOR NOT CONTROLLED BY A CIVIL AUTHORITY.	244.5	31-May-22	MARK D. MCGREGOR A&P 2523065	N/A
292 73 2822	28-Feb-17	G	2014-12-05	-	VISUAL INSPECTION OF ADJUSTED HYDROMECHANICAL METERING UNIT (HMU) DRIVE-LINK SPLINES.	VISUAL INSPECTION OF ADJUSTED HYDROMECHANICAL METERING UNIT (HMU) P/N 0292861920, S/N 33001 DRIVE-LINK SPLINES CARRIED OUT I.A.W SB 292 73 2822 § 2.B UNDER 316-WO-2201-KTSB-6997	244.5	31-May-22	MARK D. MCGREGOR A&P 2523065	WITHIN 225 & BETWEEN 500FH TO 700FH
A292 73 2845	22-Nov-16	B	-	-	IDENTIFICATION AND REMOVAL FROM SERVICE OF NON-COMPLIANT	N/A, DECU S/N 12356 INSTALLED AT THAT TIME.	244.5	31-May-22	MARK D. MCGREGOR A&P 2523065	N/A
292 72 2860	30-Jan-17	B	2016-03-02	-	CHECK TORQUE CONFORMATION BOX RESISTANCE VALUES.	SB IS DELETED AND INCORPORATED INTO THE MAINTENANCE MANUAL				
292 72 2861	23-Sep-16	D	2016-25-13	2016-0055R1	ACCESSORY GEARBOX FRONT COVER. DETECTION OF WEAR ON THE 41- OR 42- THOOOTH GEAR FRONT BEARING HOUSING.	ACCESSORY GEARBOX FRONT COVER, DETECTION OF WEAR ON THE 41- OR 42- TOOTH GEAR FRONT BEARING HOUSING CARRIED OUT I.A.W SB 292 72 2861 § 2.4.2. BOTH L/H AND R/H WEAR INSPECTIONS FOUND COMPLIANT (≤ 0.15 MM). INSPECTION CARRIED OUT BY SAFRAN TECH GTA CP01.	244.5	31-May-22	MARK D. MCGREGOR A&P 2523065	NEXT : 800FH
292 73 2869	5-Jul-19	B	2021-13-03	2019-0180	CHECK OF THE PRE-BLOCKAGE PRESSURE SWITCH OF THE FUEL FILTER	APPLICABLE AS PRESSURE SWITCH P/N 9550172000 AND S/N 11091 CURRENTLY INSTALLED. CHECK OF THE PRE-BLOCKAGE PRESSURE SWITCH OF THE FUEL FILTER CARRIED OUT I.A.W SB 292 73 2869 § 2.3.1 (TASK 73-23-XX-750-801 OF THE MM) UNDER 316-WO-2201-KTSB-6997.	244.5	31-May-22	MARK D. MCGREGOR A&P 2523065	ONE TIME WITHIN HMU OPERATING 300FH/6M