

ASB	REV	DATE	FAA AD	EASA	SUBJECT	APPLICABILITY	AFTT	DATE	ORGANISATION	NOTE
05A034	5	13-Jun-17	2021-22-16	2018-0263	PERIODIC CHECK OF MGB MAGNETIC PLUGS, OF THE OIL FILTER, CHECK THAT THERE ARE NO PARTICLES IN THE BOTTOM HOUSING, AND, REPLACEMENT OF MGB PLANET GEARS	MGB P/N 365A32-9001-00, S/N 02231 EQUIPPED WITH 5 TYPE Z PLANET GEAR ASSEMBLIES (S/N FAFW6915, FAG27702, FAG69116, FAG27649 & FAG44824 INSTALLED). INSPECTION OF THE OIL FILTER CARRIED OUT I.A.W ASB 05A034 § 3.B.2.c UNDER 316-WO-2201-KTSB-6997. NO PARTICLES FOUND AT THIS TIME.	244.5	7-Jul-22	MARK D. MCGREGOR A&P 2523065	§ 3.B.2.a EVERY 10FH NEXT DUE AFTT: 254.5H § 3.B.2.c & 3.B.2.b EVERY 55FH NEXT DUE AFTT: 299.5H
05A039		6-Jan-22	-	2022-0006R2	INSPECTION OF THE FAN HUB	VISUAL INSPECTION TO BE CARRIED OUT I.A.W ASB 05A039, § 3.B.2.a WITHIN 55H FROM THE DATE OF REV 0 (NO LATER THAN AFTT 299.5H).	244.5	ONE TIME	MARK D. MCGREGOR A&P 2523065	WITHIN 55FH NO LATER THAN 299.5FH EVERY 55 FH
24A011	1	11-Mar-04	2006-06-01	F-2004-057 R1	ELECTRICAL AND ELECTRONIC PANELS - PROTECTION OF PANEL 12 ALPHA WIRING	NOT APPLICABLE, MOD 0739C28 EMBODIED.	0.0	10-Jun-15	AIRBUS HELICOPTER MANUFACTURER	N/A
25A064		3-Jun-04	-	2010-0014	"HOIST OPERATOR'S BELT" SNAP HOOK LOCKING	NOT APPLICABLE, EQUIPMENT NOT INSTALLED.	0.0	10-Jun-15	AIRBUS HELICOPTER MANUFACTURER	N/A
25A069		26-Jun-06	-	-	HOIST OPERATOR SAFETY BELT REINFORCEMENT	NOT APPLICABLE, EQUIPMENT NOT INSTALLED.	0.0	10-Jun-15	AIRBUS HELICOPTER MANUFACTURER	N/A
25A085		1-Jun-07	2009-06-01	2007-0159-E	ELECTRICAL BONDING OF THE HOIST CUT-OFF CONNECTOR	NOT APPLICABLE, AIRCRAFT SN 6997.	0.0	10-Jun-15	AIRBUS HELICOPTER MANUFACTURER	N/A
25A087		26-May-08	-	2008-0096-E	CPI 503 CRASH POSITION INDICATOR BEACON	NOT APPLICABLE, EQUIPMENT NOT INSTALLED.	0.0	10-Jun-15	AIRBUS HELICOPTER MANUFACTURER	N/A
25A090		13-Jan-09	-	-	REPLACEMENT OF CLASS 2 HOIST POWER CONNECTOR	NOT APPLICABLE, EQUIPMENT NOT INSTALLED.	0.0	10-Jun-15	AIRBUS HELICOPTER MANUFACTURER	N/A
25A100		22-Mar-10	-	2010-0052-E	EXTERNAL LIFE RAFT: CHECK OF THE MOORING LINE ATTACHMENT POINT	NOT APPLICABLE, EQUIPMENT NOT INSTALLED.	0.0	10-Jun-15	AIRBUS HELICOPTER MANUFACTURER	N/A
25A114	1	14-May-12	2013-19-07	2012-0206	INSPECTION OF THE REAR BEAM OF THE SEAT	NOT APPLICABLE, PART NUMBER NOT INSTALLED.	0.0	10-Jun-15	AIRBUS HELICOPTER MANUFACTURER	N/A
25A120	1	20-Dec-13	-	2015-0075	IDENTIFICATION AND REPLACEMENT OF EMERGENCY LOCATOR TRANSMITTERS (MP/N) 503-16 WHICH DO NOT COMPLY WITH THE AIRBUS HELICOPTERS APPROVED DESIGN	NOT APPLICABLE, EQUIPMENT NOT INSTALLED.	0.0	10-Jun-15	AIRBUS HELICOPTER MANUFACTURER	N/A
25A124		19-Dec-13	-	2014-0231	VIP BENCH SAFETY BELTS	NOT APPLICABLE, AIRCRAFT SN 6997.	0.0	10-Jun-15	AIRBUS HELICOPTER MANUFACTURER	N/A
25A128	1	29-Sep-14	2020-15-01 2016-05-10	2018-0069 2015-0048	IMPROVED EXTERNAL LIFE RAFT DEPLOYMENT CONTROLS	NOT APPLICABLE, EQUIPMENT NOT INSTALLED.	0.0	10-Jun-15	AIRBUS HELICOPTER MANUFACTURER	N/A