

Last Checked

S/N 31807

AIRWORTHINESS DIRECTIVES

| | | | |
|------------|-----------|------------|----------|
| TCCA | EASA | FAA | ENAC |
| CF-2018-23 | 2018-0203 | 2018-04-11 | 2017/003 |

| AUTHORITY | AD | DATE | TITLE | STATUS | NOTES | SIGNATURE |
|-----------|-------------|------------|---|--------|---|-----------|
| EASA | 2013-0298 | 16/12/2013 | ICE AND RAIN PROTECTION – FULL ICING PROTECTION SYSTEM / CABLE INSPECTION – TAIL ROTOR DISTRIBUTOR REPLACEMENT / AUTO TRANSFORMER RECTIFIER UNIT REPLACEMENT AND REPETITIVE CHECK / AC GENERATOR CONTROL UNIT REPLACEMENT | N.A. | SUPERSEDED BY EASA AD 2014-0028 | |
| EASA | 2014-0019 | 17/01/2014 | EQUIPMENT / FURNISHINGS – CRASH POSITION INDICATOR – MODIFICATION AIRCRAFT FLIGHT MANUAL – AMENDMENT | N.A. | SUPERSEDED BY EASA AD 2014-0095 | |
| EASA | 2014-0028 | 30/01/2014 | ICE AND RAIN PROTECTION – FULL ICING PROTECTION SYSTEM / CABLE INSPECTION – TAIL ROTOR DISTRIBUTOR REPLACEMENT / AUTO TRANSFORMER RECTIFIER UNIT REPLACEMENT AND REPETITIVE CHECK / AC GENERATOR CONTROL UNIT REPLACEMENT | N.A. | SUPERSEDED BY EASA AD 2014-0172 | |
| EASA | 2014-0048 | 04/03/2014 | FUSELAGE – SUBFLOOR FRAME STA 2105 – INSPECTION / MODIFICATION | N.A. | NOT APPLICABLE PER HELICOPTER S/N: MODIFICATION ALREADY INCORPORATED. | |
| EASA | 2014-0073-E | 20/03/2014 | MAIN ROTOR – ROTATING CONTROLS – LOWER HALF SCISSOR SPHERICAL BEARING – INSPECTION / REPLACEMENT | N.A. | SUPERSEDED BY EASA AD 2014-0215-E | |
| EASA | 2014-0095R1 | 12/05/2014 | EQUIPMENT / FURNISHINGS – CRASH POSITION INDICATOR – MODIFICATION AIRCRAFT FLIGHT MANUAL – AMENDMENT | N.A. | KIT ELT DEPLOYABLE NOT INSTALLED | |
| EASA | 2014-0125 | 15/05/2014 | EQUIPMENT / FURNISHINGS – CRASH POSITION INDICATOR SYSTEM; AIRCRAFT FLIGHT MANUAL – AMENDMENT | N.A. | KIT ELT DEPLOYABLE NOT INSTALLED | |
| EASA | 2014-0172 | 17/07/2014 | ICE AND RAIN PROTECTION – FULL ICING PROTECTION SYSTEM / CABLE INSPECTION – TAIL ROTOR DISTRIBUTOR REPLACEMENT / AUTO TRANSFORMER RECTIFIER UNIT REPLACEMENT | N.A. | NOT APPLICABLE: KIT FIPS NOT INSTALLED. | |
| EASA | 2014-0201 | 08/09/2014 | EQUIPMENT / FURNISHING - HOIST - TEST / REPLACEMENT | N.A. | SUPERSEDED BY EASA AD 2014-0254 | |
| EASA | 2014-0215-E | 24/09/2014 | MAIN ROTOR – ROTATING SCISSORS – INSPECTION / MODIFICATION | N.A. | SUPERSEDED BY EASA AD 2017-0028-E | |
| EASA | 2014-0254 | 21/11/2014 | EQUIPMENT / FURNISHING - HOIST - TEST / REPLACEMENT | N.A. | SUPERSEDED BY EASA AD 2015-0069 | |
| EASA | 2015-0069 | 29/04/2015 | EQUIPMENT / FURNISHING - HOIST - TEST / REPLACEMENT | N.A. | SUPERSEDED BY EASA AD 2015-0160 | |
| EASA | 2015-0155 | 28/07/2015 | ICE AND RAIN PROTECTION– FULL ICE PROTECTION SYSTEM TAIL ROTOR SLIP RING – INSPECTION / REPLACEMENT | N.A. | NOT APPLICABLE: KIT FIPS NOT INSTALLED. | |
| EASA | 2015-0160 | 04/08/2015 | EQUIPMENT / FURNISHING - HOIST - TEST / REPLACEMENT | N.A. | SUPERSEDED BY EASA AD 2015-0226 | |



Status Legend:

N/A=Not Applicable CW=Complied With NCW=Not Complied With