

## ADS AIRWORTHINESS DIRECTIVES (AD'S) STATUS LIST

Aircraft Registration:	9M-PMB	Serial No:	31726	Date:	01/09/2022	Page No:	1
Aircraft Hours:	1792:39	Landings:	3173.00	Engine 1:	1792:39	Engine 2:	1792:39

Types	AD Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
<b>ADs</b>						
Types	AD Number	Subject	Last Done	Next Due	Interval	Limitation Notes
Repetitive ADs	EASA AD 2015-0226 REV 7 PARA 7	2600HL/36M HOIST CLUCTH REPLACEMENT - ATA 25 EQUIPMENT / FURNISHINGS HOIST TEST / REPLACEMENT	-	00/00/0000	0	TIC-AW139-21-0436 DATED 21 DECEMBER 2021 APPLICABLE TO DUE TO COMPONENT GOOGRICH HOIST P/N 44316-12-104 FITTED ON AIRCRAFT.
Repetitive ADs	EASA AD No.: 2022-0154 (SBA 139-724 REV./)	ATA 64 - TAIL ROTOR DAMPER BRACKET INSPECTION	1780:34	1830:34	50	TIC-AW139-22-0160 DATED 02 AUGUST 2022 9M-PMB-12342 @ 1780:35 FH ON 24.08.2022 9AJL 00538) - 1ST COMPLIANCE
Repetitive ADs	EASA AD No.: 2022-0154 (SBA 139-724 REV./)	ATA 64 - TAIL ROTOR DAMPER BRACKET INSPECTION	24/08/2022	24/02/2023	6	TIC-AW139-22-0160 DATED 02 AUGUST 2022 9M-PMB-12342 @ 1780:35 FH ON 24.08.2022 9AJL 00538) - 1ST COMPLIANCE
Repetitive ADs	EASA AD 2022-0152-E PARA (2)(SBEA 139-725 REV/PART 2)	ATA 64-TAIL ROTOR DUPLEX BEARING INSPECTION AND REPLACEMENT(WITHIN 10FH AND EVERY 50FH)	-	-	0	TIC-AW139-22-0157 DATED 27 JULY 2022 APPLICABLE DUE TO AIRCRAFT TYPE AFFECTED
Repetitive ADs	EASA AD 2022-0152 PARA 1 (EASB139-725 REV./ PART1	ATA 64-TAIL ROTOR DUPLEX BEARING INSPECTION AND REPLACEMENT (BFF AND EVERY 10FH)	-	-	0	TIC-AW139-22-0157 DATED 27 JULY 2022 APPLICABLE DUE TO AIRCRAFT TYPE AFFECTED 9M-PMB-12170 (AJL 00519) @ 1739:05 FH ON 27.07.2022
Repetitive ADs	EASA AD 2021-0044 REV 1 PARA (2) (ASB139-661 REV. B)	ATA 24 OVERHEAD PANEL INSPECTION 300H/12M REPETITIVE PART II COMPLIANCE	31/05/2022	31/05/2023	12	TIC-AW139-22-0120 NEXT DUE (1908:00FH,10/02/2021) CALCULATE FROM LAST DONE EASA AD NO. 2021-0044 REVISION 0 PART 1 >>> (9M -PMB-5802, 1608:00 FH ON 10/02/2021)
Repetitive ADs	EASA AD 2021-0044 REV 1 PARA (2) (ASB139-661 REV. B)	ATA 24 OVERHEAD PANEL INSPECTION 300H/12M REPETITIVE PART II COMPLIANCE	1694:50	1994:50	300	TIC-AW139-22-0120 NEXT DUE (1908:00FH,10/02/2021) CALCULATE FROM LAST DONE EASA AD NO. 2021-0044 REVISION 0 PART 1 >>> (9M -PMB-5802, 1608:00 FH ON 10/02/2021)
Repetitive ADs	EASA AD 2020-0271 NEW ISSUE PARA (2) (ASB139-654 PART I	50FH - ATA 62 MAIN ROTOR SWASHPLATE BOOT INSPECTION	1780:34	1830:34	50	TIC-AW139-20-201 9M-PMB-11931 @ 1737:45 FH ON 24.07.2022 (AJL 00516) 9M-PMB-12049 @ 1780:35 FH ON 24.08.2022 (AJL 00538)