

## ADS AIRWORTHINESS DIRECTIVES (AD'S) STATUS LIST

Aircraft Registration:	9M-PMF	Serial No:	31913	Date:	01/09/2022	Page No:	1
Aircraft Hours:	736:14	Landings:	1378.00	Engine 1:	736:14	Engine 2:	736:14

Types	AD Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
<b>ADs</b>						
Types	AD Number	Subject	Last Done	Next Due	Interval	Limitation Notes
Repetitive ADs	AD 2022-0152-E PARA (7), (SBEA 139-725 REV./ PART IV)	ATA 64-TAIL ROTOR DUPLEX BEARING INSPECTION AND REPLACEMENT	0:00	0:00	0	TIC-AW139-22-0157 DATED 27 JULY 2022 APPLICABLE DUE TO AIRCRAFT TYPE AFFECTED
Repetitive ADs	EASA AD No.: 2022-0154 (SBA 139-724 REV./I)	ATA 64 - TAIL ROTOR DAMPER BRACKET INSPECTION	-	-	50	TIC-AW139-22-0160 DATED 02 AUGUST 2022 NOT APPLICABLE DUE TO AFFECTED S/N OF COMPONENT TAIL ROTOR DAMPER BRACKET ASSEMBLY P/N 3G8420A06131 NOT EQUIPPED ON AIRCRAFT.
Repetitive ADs	EASA AD No.: 2022-0154 (SBA 139-724 REV./I)	ATA 64 - TAIL ROTOR DAMPER BRACKET INSPECTION	-	-	0	TIC-AW139-22-0160 DATED 02 AUGUST 2022 NOT APPLICABLE DUE TO AFFECTED S/N OF COMPONENT TAIL ROTOR DAMPER BRACKET ASSEMBLY P/N 3G8420A06131 NOT EQUIPPED ON AIRCRAFT.
Repetitive ADs	EASA AD 2022-0152-E PARA (2)(SBEA 139-725 REV/PART 2)	ATA 64-TAIL ROTOR DUPLEX BEARING INSPECTION AND REPLACEMENT(WITHIN 10FH AND EVERY 50FH)	-	-	0	TIC-AW139-22-0157 DATED 27 JULY 2022 APPLICABLE DUE TO AIRCRAFT TYPE AFFECTED
Repetitive ADs	EASA AD 2022-0152 PARA 1 (EASB139-725 REV./ PART1	ATA 64-TAIL ROTOR DUPLEX BEARING INSPECTION AND REPLACEMENT (BFF AND EVERY 10FH)	-	-	0	TIC-AW139-22-0157 27 JULY 2022 APPLICABLE DUE TO AIRCRAFT TYPE AFFECTED
Repetitive ADs	EASA AD 2015-0226R7 CORRECTION 20 DECEMBER 2021 (SB139-	ATA 25 - EQUIPMENT / FURNISHINGS HOIST TEST / REPLACEMENT	-	-	0	
Repetitive ADs	EASA AD 2021-0044 REV 1 PARA (2) (ASB139-661 REV. B)	ATA 24 OVERHEAD PANEL INSPECTION 300H/12M REPETITIVE PART II COMPLIANCE	27/05/2022	26/05/2023	12	TIC-AW139-22-0120 DATED 13 MAY 2022 9M-PMF-10822 (AJL 02111) AT 578:50FH ON 27/05/2022
Repetitive ADs	EASA AD 2021-0044 REV 1 PARA (2) (ASB139-661 REV. B)	ATA 24 OVERHEAD PANEL INSPECTION 300H/12M REPETITIVE PART II COMPLIANCE	578:50	878:50	300	TIC-AW139-22-0120 DATED 13 MAY 2022 9M-PMF-10822 (AJL 02111) AT 578:50FH ON 27/05/2022
Repetitive ADs	EASA AD 2020-0271 NEW ISSUE PARA (2) (ASB139-654 PART I	50FH - ATA 62 MAIN ROTOR SWASHPLATE BOOT INSPECTION	709:45	759:45	50	TIC-AW139-20-201 DATED 9 DECEMBER 2020 9M-PMF-11899 (AJL 02158) AT 678:30 FH ON 31.07.2022 9M-PMF-12350 (AJL 02171) AT 709:45 FH ON 14.08.2022