

HIGHLIGHT

AMM AMMPM-BB1-HIGHLIGHT

Publication Title AMM EC155 B-B1
NR011

Publication Date 2022.02.01

THE DOCUMENT REFERENCE IS AVAILABLE ONLINE. PLEASE CHECK IF THE ONLINE DOCUMENTATION CORRESPONDS TO THE PRINTED VERSION

Documentary Unit	Title	NRD	Publication Date	Type of change	Reason for update	Maintenance Work Affected
AMM 00-00-00	LIST OF ILLUSTRATIONS	N	2022.02.01			
AMM 00-00-00	INTRODUCTION	R	2022.01.13			
AMM 05-21-00-214	Inspection - Optional Systems	R	2022.01.10	I	Information added	Yes
AMM 05-22-00-213	DELETED	D	2020.12.01			
AMM 05-22-00-213A	15-hour inspection	N	2021.11.18	M	Aircraft build standard changed	Yes
AMM 05-22-00-213B	15-hour inspection - MGB POST 0763C88	N	2022.01.05	R	New document unit	Yes
AMM 05-39-00-221	Maintenance Checks at Calendar Intervals - Power Transmission System Components	R	2021.12.08	I	Information added	No
AMM 05-50-00-222	DELETED	D	2011.11.09			
AMM 05-50-00-222A	Procedure After Vibrations, Resonance or an Abnormal Dynamic Phenomenon	N	2022.01.10	I	Information added	No
AMM 05-50-00-222B	Procedure After Vibrations, Resonance or an Abnormal Dynamic Phenomenon - MGB POST 0763C88	N	2021.12.22	R	New document unit	Yes
AMM 05-50-01-211	DELETED	D	2019.08.01			
AMM 05-50-01-211A	Measures to be taken when particles are found on the magnetic plugs and / or oil filter of the gear boxes	N	2022.01.10	R	New document unit	No
AMM 05-50-01-211B	Measures to be taken after particles are found on the magnetic plugs and / or the oil filter of the MGB - MGB POST 0763C88	N	2022.01.07	R	New document unit	Yes
AMM 05-50-01-213	Measures to be taken after an in-flight collision - MGB POST 0763C88	N	2022.01.04	R	New document unit	Yes

THE DOCUMENT REFERENCE IS AVAILABLE ONLINE. PLEASE CHECK IF THE ONLINE DOCUMENTATION CORRESPONDS TO THE PRINTED VERSION

Documentary Unit	Title	NRD	Publication Date	Type of change	Reason for update	Maintenance Work Affected
AMM 05-50-01-214	Measures to be taken after an MGB overtemperature POST 0763C88	N	2021.11.26	R	New document unit	Yes
AMM 05-50-01-215	Measures to be taken after a "PRESSURE CAUTION" on the MGB oil system POST 0763C88	N	2021.12.21	R	New document unit	Yes
AMM 05-50-01-216	Measures to be taken after a "PRESSURE WARNING" on the MGB oil system POST 0763C88	N	2021.12.21	R	New document unit	Yes
AMM 05-50-02-212	DELETED	D	2013.11.07			
AMM 05-50-02-212A	Measures to be taken if there is an overtorque	N	2021.12.22	R	New document unit	No
AMM 05-50-02-212B	Measures to be taken if there is an overtorque - MGB POST 0763C88	N	2021.12.22	R	New document unit	Yes
AMM 05-50-02-213	DELETED	D	2017.06.07			
AMM 05-50-02-213A	Procedure After Rotor Overspeed	N	2021.12.17	R	New document unit	Yes
AMM 05-50-02-213B	Procedure After Rotor Overspeed - MGB POST 0763C88	N	2021.12.17	R	New document unit	Yes
AMM 05-50-02-221	DELETED	D	2011.11.09			
AMM 05-50-02-221A	Procedure after the Brake is Suddenly Applied to the Main Rotor	N	2021.12.22	R	New document unit	No
AMM 05-50-02-221B	Procedure after the Brake is Suddenly Applied to the Main Rotor - MGB POST 0763C88	N	2022.01.10	R	New document unit	Yes
AMM 05-50-03-711	Measures to be taken for negative torque or temperature result of the in-flight Engine Power Check	R	2021.07.19	R	New document unit	Yes
AMM 05-50-05-221	DELETED	D	2016.09.05			

THE DOCUMENT REFERENCE IS AVAILABLE ONLINE. PLEASE CHECK IF THE ONLINE DOCUMENTATION CORRESPONDS TO THE PRINTED VERSION

Documentary Unit	Title	NRD	Publication Date	Type of change	Reason for update	Maintenance Work Affected
AMM 05-50-05-221A	Procedure following a hard landing	N	2021.12.20	C	Discrepancy corrected	Yes
AMM 05-50-05-221B	Procedure After a Hard Landing - MGB POST 0763C88	N	2022.01.10	C	Discrepancy corrected	Yes
AMM 05-50-08-221	DELETED	D	2016.04.01			
AMM 05-50-08-221A	Measures to be taken if there are jerks on the free wheel	N	2021.12.22	R	New document unit	No
AMM 05-50-08-221B	Measures to be taken if there are jerks on the free wheel - MGB POST 0763C88	N	2021.12.22	R	New document unit	Yes
AMM 05-50-09-223	DELETED	D	2015.04.16			
AMM 05-50-09-223A	Measures to be taken if lightning strikes the aircraft	N	2021.11.08	R	New document unit	Yes
AMM 05-50-09-223B	Measures to be taken if lightning strikes the aircraft - MGB POST 0763C88	N	2021.12.08	R	New document unit	Yes
AMM 09-10-00-581	Towing the helicopter	R	2021.10.27	I	Information added	Yes
AMM 09-10-00-583	Towing the helicopter during maintenance	N	2021.10.27	R	New document unit	Yes
AMM 10-10-00-221	Inspection - Short-Term Storage	R	2021.07.27	I	Information added	No
AMM 12-20-00-211	DELETED	D	2019.08.20			
AMM 12-20-00-211A	Inspection - Magnetic plugs	N	2021.12.15	M	Aircraft build standard changed	No
AMM 12-20-00-211B	Inspection of the magnetic plugs - MGB POST 0763C88	N	2021.11.23	R	New document unit	Yes
AMM 12-30-00-171	DELETED	D	2012.12.13			
AMM 12-30-00-171A	Washing the MGB / TGB for oil change	N	2021.11.29	M	Aircraft build standard changed	No
AMM 12-30-00-171B	Washing the MGB / TGB for oil change - MGB POST 0763C88	N	2021.11.25	R	New document unit	Yes

THE DOCUMENT REFERENCE IS AVAILABLE ONLINE. PLEASE CHECK IF THE ONLINE DOCUMENTATION CORRESPONDS TO THE PRINTED VERSION

Documentary Unit	Title	NRD	Publication Date	Type of change	Reason for update	Maintenance Work Affected
AMM 21-51-00-724	Functional Tests - Ventilation System Drainage	R	2021.07.19	R	New document unit	Yes
AMM 22-11-01-062	Removal / Installation - Pitch Trim Actuator	R	2022.01.10	M	Aircraft build standard changed	Yes
AMM 22-11-02-062	Removal / Installation - Roll Trim Actuator	R	2022.01.11	M	Aircraft build standard changed	Yes
AMM 22-11-03-062	Removal / Installation - Collective Trim Actuator	R	2022.01.11	M	Aircraft build standard changed	Yes
AMM 22-11-04-062	Removal / Installation - Yaw Trim Actuator	R	2022.01.11	M	Aircraft build standard changed	Yes
AMM 23-00-00-991	Installation of radio-communication antennas	N	2021.01.26	R	New document unit	No
AMM 24-00-00-761	Measurements - Electrical bonding	R	2021.12.10	I	Information added	No
AMM 26-21-00-061	Removal / Installation - Engine Fire Extinguisher	R	2021.11.08	I	Information added	Yes
AMM 28-11-00-351	Bonding the half-moon restrictor into the interconnecting tube between fuel tanks	R	2021.10.19	C	Discrepancy corrected	Yes
AMM 29-11-00-066	DELETED	D	2020.11.16			
AMM 29-11-00-066A	Removal / Installation - RH hydraulic pump spacer	N	2021.12.23	R	New document unit	No
AMM 29-11-00-066B	Removal / Installation - RH hydraulic pump spacer - MGB POST 0763C88	N	2021.12.23	R	New document unit	Yes
AMM 29-11-00-066C	Removal / Installation - RH hydraulic pump spacer - POST 0763C95	N	2021.12.23	R	New document unit	Yes
AMM 29-11-00-612	Draining and Filling - Right Hydraulic System	R	2021.07.19	I	Information added	Yes
AMM 29-12-00-066	DELETED	D	2020.11.16			
AMM 29-12-00-066A	Removal / Installation - LH hydraulic pump spacer	N	2021.12.23	R	New document unit	No

Documentary Unit	Title	NRD	Publication Date	Type of change	Reason for update	Maintenance Work Affected
AMM 29-12-00-066B	Removal / Installation - LH hydraulic pump spacer - MGB POST 0763C88	N	2021.12.23	R	New document unit	Yes
AMM 29-12-00-612	Draining and Filling - LH Hydraulic Reservoir	R	2021.10.18	I	Information added	No
AMM 32-10-01-612	Filling - Main Landing Gear Shock-Absorber	R	2021.07.19	I	Information added	No
AMM 32-10-02-061	Removal / Installation - Main Landing Gear Strut Actuator	R	2021.12.08	C	Discrepancy corrected	Yes
AMM 32-20-00-221	Inspection - Nose Landing Gear	R	2021.08.17	I	Information added	Yes
AMM 32-60-00-721	Functional Test - Landing Gear Not-Extended Alarm	R	2021.07.28	R	New document unit	No
AMM 33-13-00-821	Harmonization - Integrated Lighting System	R	2021.04.08	I	Information added	Yes
AMM 33-50-03-062	Removal / Installation - Helicopter Emergency Exit Lights (HEEL) Power Supply Unit	R	2022.01.10	I	Information added	Yes
AMM 33-50-03-721	Functional Tests - Helicopter Emergency Exit Lights (HEEL)	R	2022.01.10	I	Information added	Yes
AMM 33-50-03-722	Operational tests - Battery of the Helicopter Emergency Exit Lights (HEEL) power supply unit	N	2022.01.10	R	New document unit	Yes
AMM 33-50-03-961	Removal / Installation - Battery of Helicopter Emergency Exit Lights (HEEL) Power Supply Unit	N	2022.01.10	R	New document unit	Yes
AMM 34-12-01-061	Removal / Installation - Air Data Unit (ADU)	R	2021.12.08	C	Discrepancy corrected	Yes
AMM 34-44-02-721	TAS 9900BX functional tests	R	2021.12.14	I	Information added	No
AMM 34-51-04-721	Functional Test - GTX 33H	R	2021.10.21	I	Information added	No
AMM 45-11-04-060	Removal / Installation - Amplifier	N	2021.10.14	R	New document unit	Yes

THE DOCUMENT REFERENCE IS AVAILABLE ONLINE. PLEASE CHECK IF THE ONLINE DOCUMENTATION CORRESPONDS TO THE PRINTED VERSION

Documentary Unit	Title	NRD	Publication Date	Type of change	Reason for update	Maintenance Work Affected
AMM 45-11-04-061	Removal / Installation - SSCVFDR	R	2021.10.14	C	Discrepancy corrected	Yes
AMM 45-11-04-062	Removal / Installation - RIPS module	R	2021.10.14	C	Discrepancy corrected	Yes
AMM 45-11-04-063	Removal / Installation - Water immersion sensor	N	2021.10.14	R	New document unit	Yes
AMM 45-11-04-064	Removal / Installation - Water immersion sensor unit	N	2021.10.15	R	New document unit	Yes
AMM 45-11-04-065	Removal / Installation - Inertia switch	N	2021.10.15	R	New document unit	Yes
AMM 45-11-04-066	Removal / Installation - Data Transfer Unit (MFDAU)	N	2021.10.15	R	New document unit	Yes
AMM 45-11-04-067	Removal / Installation of the SSCVFDR control unit	N	2021.10.15	R	New document unit	Yes
AMM 45-11-04-068	Removal / Installation - Ambiance microphone	N	2021.10.18	R	New document unit	Yes
AMM 45-11-04-069	Removal / Installation - Data Transfer Unit (DTU)	N	2021.10.18	R	New document unit	Yes
AMM 45-11-04-721	Downloading of SSCVFDR L3COM Recorded Data	R	2021.10.27	C	Discrepancy corrected	Yes
AMM 45-11-04-722	Functional Tests - Check of Discrete Signals	R	2021.11.23	C	Discrepancy corrected	Yes
AMM 45-11-04-723	Test of the RIPS module	R	2021.10.28	C	Discrepancy corrected	Yes
AMM 45-11-04-724	Test of the erase function	R	2021.10.28	C	Discrepancy corrected	Yes
AMM 45-11-04-725	Functional test of the water immersion sensor	R	2021.10.28	C	Discrepancy corrected	Yes
AMM 45-11-04-726	Functional test of the SSCVFDR - L3COM	R	2021.10.29	C	Discrepancy corrected	Yes
AMM 45-11-04-726B	DELETED	D	2017.08.24			
AMM 45-11-04-727	Inspection of FDR and CVR data	R	2021.11.08	C	Discrepancy corrected	Yes
AMM 45-11-04-728	Functional Tests - Data Transfer Unit (DTU)	R	2021.11.08	C	Discrepancy corrected	Yes

THE DOCUMENT REFERENCE IS AVAILABLE ONLINE. PLEASE CHECK IF THE ONLINE DOCUMENTATION CORRESPONDS TO THE PRINTED VERSION

Documentary Unit	Title	NRD	Publication Date	Type of change	Reason for update	Maintenance Work Affected
AMM 45-11-04-729	MFDAU configuration	N	2021.11.08	R	New document unit	Yes
AMM 45-11-04-730	Test of the SSCVFDR control unit	N	2021.10.28	R	New document unit	Yes
AMM 45-11-04-811	Fault isolation - SSCVFDR L3COM	N	2021.12.20	R	New document unit	Yes
AMM 45-11-04-860	DELETED	D	2017.08.24			
AMM 52-12-00-221	Detailed inspection - Sliding doors	R	2021.07.09	C	Discrepancy corrected	Yes
AMM 52-12-00-811	Fault Isolation - Sliding Doors	R	2021.03.31	C	Discrepancy corrected	Yes
AMM 52-12-00-822	Adjust Sliding Door Position on the Helicopter	R	2021.07.19	I	Information added	No
AMM 52-12-01-061B	Removal / Installation - Hinged Door POST OP53C80	R	2021.08.27	I	Information added	Yes
AMM 52-12-01-063B	Removal / Installation - inner handle assembly of the hinged door POST OP53C80	R	2021.10.20	I	Information added	Yes
AMM 52-12-01-221B	Detailed Inspection - Hinged Doors POST OP53C80	R	2021.08.27	I	Information added	Yes
AMM 52-12-01-721B	Functional Test - Hinged Doors POST OP53C80	R	2021.08.17	I	Information added	Yes
AMM 52-12-01-723B	Adjustment - Linkage POST OP53C80 and POST 0752C76	R	2021.10.21	I	Information added	Yes
AMM 52-12-01-724C	Microswitch adjustment POST 0752C60	R	2021.07.19	I	Information added	Yes
AMM 52-12-01-962B	Replacement - Microswitch POST OP53C80	R	2021.08.17	C	Discrepancy corrected	Yes
AMM 52-12-01-964B	Replacement - Lock POST OP53C80	R	2021.10.25	I	Information added	Yes
AMM 52-12-01-965B	Replacement - Cable POST OP53C80	R	2021.10.25	C	Discrepancy corrected	Yes
AMM 53-20-00-221	DELETED	D	2011.11.09			

THE DOCUMENT REFERENCE IS AVAILABLE ONLINE. PLEASE CHECK IF THE ONLINE DOCUMENTATION CORRESPONDS TO THE PRINTED VERSION

Documentary Unit	Title	NRD	Publication Date	Type of change	Reason for update	Maintenance Work Affected
AMM 53-20-00-221A	Detailed Inspection - Canopy and Nose Structure PRE 0756B32	N	2021.03.11	R	New document unit	Yes
AMM 53-20-00-221B	Detailed Inspection - Canopy and Nose Structure POST 0756B32	N	2021.12.02	R	New document unit	Yes
AMM 53-20-00-223	DELETED	D	2015.06.16			
AMM 53-20-00-223A	Detailed inspection of the cabin / carbon connection and the 12° and 25° frames	N	2021.12.13	C	Discrepancy corrected	No
AMM 53-20-00-223B	Detailed inspection of the cabin / carbon connection and the 12° and 25° frames POST 0756B32	N	2021.12.02	R	New document unit	Yes
AMM 53-50-00-221	Detailed inspection - Cowlings and Fairings	R	2021.10.20	I	Information added	Yes
AMM 53-53-00-061	Removal / Installation - MGB Cowlings	R	2021.10.27	I	Information added	No
AMM 53-54-00-061	Removal / Installation - Engine Cowlings	R	2021.10.27	I	Information added	Yes
AMM 53-54-00-351	Repair - MI15 thermal protection	N	2021.10.20	R	New document unit	Yes
AMM 53-60-00-226	Inspection of the external skins of the luggage compartment between the X4630 and X6630 frames	N	2021.03.10	R	New document unit	Yes
AMM 53-60-00-334	Repair of a debonded area on the external skin of the luggage compartment between the X4630 and X6630 frames from inside the luggage compartment	N	2021.03.08	R	New document unit	Yes
AMM 53-60-00-335	Repair of a debonded area on the external skin of the luggage compartment between frames X4630 and X6630 from outside the luggage compartment	N	2021.03.09	R	New document unit	Yes

Documentary Unit	Title	NRD	Publication Date	Type of change	Reason for update	Maintenance Work Affected
AMM 53-60-00-336	Repair of dent on the internal skin of the rear structure	N	2022.01.03	R	New document unit	Yes
AMM 53-60-00-337	Repair of dent on the external skin of the rear structure	N	2022.01.03	R	New document unit	Yes
AMM 53-60-00-341	Repair of debonding of the external upper skin between frames X4630 and X5915	R	2021.09.23	C	Discrepancy corrected	Yes
AMM 53-60-00-355	Replacement of bottom structure lower splices at frame X4630	N	2021.10.11	R	New document unit	Yes
AMM 53-80-00-335	Repair following impact mark on inner skin	R	2021.10.27	I	Information added	Yes
AMM 56-10-00-066	Protective films on glass windshield POST OP56B30 or POST 0756B31: Removal - Installation	R	2021.12.02	I	Information added	No
AMM 56-10-00-351	Procedure for re-bonding protective film on the glass windshield POST OP56B30 or POST 0756B31	R	2021.10.22	I	Information added	No
AMM 56-10-01-061	Removal / Installation - Windshield POST 0756B31	N	2021.11.16	R	New document unit	Yes
AMM 56-10-01-062	Removal / Installation - Cockpit upper window POST 0756B31	N	2021.11.16	R	New document unit	Yes
AMM 56-20-00-062	Removal / Installation Jettisonable Window fixed panels	R	2021.12.21	I	Information added	Yes
AMM 60-00-00-911	General Safety Instructions - Power Transmission Systems	R	2021.07.19	I	Information added	Yes
AMM 62-10-00-351	Replacement - Blade Root Polyurethane Cover-Strip	R	2021.11.04	C	Discrepancy corrected	No
AMM 62-20-00-061	DELETED	D	2019.08.21			
AMM 62-20-00-061A	Removal / Installation - Rotor Hub / Mast Assembly	N	2022.01.12	R	New document unit	Yes

Documentary Unit	Title	NRD	Publication Date	Type of change	Reason for update	Maintenance Work Affected
AMM 62-20-00-061B	Removal / Installation - Rotor Hub / Mast Assembly - MGB POST 0763C88	N	2022.01.04	R	New document unit	Yes
AMM 62-21-00-061	Disassembly / Assembly - Equipped rotor mast	R	2021.10.05	I	Information added	Yes
AMM 62-22-00-991	Inspection criteria - Flared Housing	R	2021.10.05	I	Information added	No
AMM 62-23-01-961	Replacement - Bush in Scissors Upper Link	R	2022.01.12	I	Information added	Yes
AMM 62-23-02-061	Disassembly / Assembly - Swashplates	R	2021.10.06	I	Information added	No
AMM 62-24-01-061	Removal / Installation - Blade Sleeves Assembly	R	2021.11.02	I	Information added	No
AMM 62-26-01-061	Removal / Installation - Pitch Change Rod	R	2021.10.07	C	Discrepancy corrected	No
AMM 62-26-01-062	Removal / Installation Pitch Change Rod End-Fittings	R	2021.10.07	C	Discrepancy corrected	No
AMM 62-26-01-991	Inspection Criteria - Pitch Change Rod Assembly	R	2021.10.12	I	Information added	Yes
AMM 62-40-02-061	Removal / Installation - Second Rotor-RPM Sensor	R	2021.10.08	C	Discrepancy corrected	Yes
AMM 63-00-00-061	DELETED	D	2019.08.21			
AMM 63-00-00-061A	Removal / Installation - MGB / MRH Assembly	N	2022.01.03	R	New document unit	Yes
AMM 63-00-00-061B	Removal / Installation - MGB / MRH Assembly - MGB POST 0763C88	N	2022.01.03	R	New document unit	Yes
AMM 63-10-00-281	Inspection - Engine-to-MGB Alignment	R	2021.11.17	C	Discrepancy corrected	No
AMM 63-10-02-211	Inspection - Engine-to-MGB Coupling Shaft Flexible Couplings	R	2021.12.22	C	Discrepancy corrected	Yes
AMM 63-10-60-221	Detailed inspection - Engine / MGB coupling - MGB POST 0763C88	N	2021.12.07	R	New document unit	Yes

Documentary Unit	Title	NRD	Publication Date	Type of change	Reason for update	Maintenance Work Affected
AMM 63-10-60-281	Inspection - Engine-to-MGB Alignment - MGB POST 0763C88	N	2021.11.17	R	New document unit	Yes
AMM 63-10-60-991	Inspection criteria - Engine-MGB link - POST 0763C88	N	2022.01.05	R	New document unit	Yes
AMM 63-10-61-061	Removal / Installation - Coupling shaft - MGB POST 0763C88	N	2021.11.30	R	New document unit	Yes
AMM 63-10-62-211	Visual inspection of the flexible couplings - MGB POST 0763C88	N	2021.12.22	R	New document unit	Yes
AMM 63-10-62-221	Detailed Inspection - Flexible Couplings - MGB POST 0763C88	N	2022.01.03	R	New document unit	Yes
AMM 63-10-62-991	Inspection criteria for MGB flexible couplings POST 0763C88	N	2021.12.14	R	New document unit	Yes
AMM 63-10-63-061	Removal / Installation - Drive Flange - MGB POST 0763C88	N	2021.12.13	R	New document unit	Yes
AMM 63-10-64-061	Removal / Installation - Flange of the gimbal joint assembly - MGB POST 0763C88	N	2021.12.01	R	New document unit	Yes
AMM 63-10-64-222	Detailed inspection - Gimbal joint assembly - MGB POST 0763C88	N	2022.01.12	R	New document unit	Yes
AMM 63-10-64-721	Check of the tightening torque on the gimbal joint assembly - MGB POST 0763C88	N	2021.12.14	R	New document unit	Yes
AMM 63-10-64-991	Inspection criteria - Gimbal joint assembly - MGB POST 0763C88	N	2022.01.11	R	New document unit	Yes
AMM 63-20-00-061	Removal / Installation - MGB	R	2021.09.02	I	Information added	No
AMM 63-20-00-552	Packing / Unpacking - MGB in Safelog container X632P6019101	N	2021.09.29	R	New document unit	Yes
AMM 63-20-60-061	Removal / Installation - MGB POST 0763C88	N	2021.12.10	R	New document unit	Yes

THE DOCUMENT REFERENCE IS AVAILABLE ONLINE. PLEASE CHECK IF THE ONLINE DOCUMENTATION CORRESPONDS TO THE PRINTED VERSION

Documentary Unit	Title	NRD	Publication Date	Type of change	Reason for update	Maintenance Work Affected
AMM 63-20-60-062	Disassembly / Assembly - MGB POST 0763C88	N	2022.01.07	R	New document unit	Yes
AMM 63-20-60-063	Removal / Installation - Equipped oil cooler-MGB POST 0763C88	N	2021.11.29	R	New document unit	Yes
AMM 63-20-60-064	Removal / Installation - Seal holder and dynamic seal of the MGB input power take-off POST 0763C88	N	2022.01.06	R	New document unit	Yes
AMM 63-20-60-211	Visual inspection of the MGB housing couplings POST 0763C88	N	2022.01.10	R	New document unit	Yes
AMM 63-20-60-212	Visual inspection of the upper cover - MGB POST 0763C88	N	2022.01.04	R	New document unit	Yes
AMM 63-20-60-213	Inspection after Removal / Installation of the MGB POST 0763C88	N	2022.01.05	R	New document unit	Yes
AMM 63-20-60-215	Visual inspection of the MGB POST 0763C88 - Search for seepage	N	2022.01.11	R	New document unit	Yes
AMM 63-20-60-216	General visual inspection of the MGB POST 0763C88 after maintenance work on its lubrication system	N	2021.11.18	R	New document unit	Yes
AMM 63-20-60-217	Visual inspection of the MGB housing POST 0763C88	N	2021.12.22	R	New document unit	Yes
AMM 63-20-60-219	Visual inspection of the MGB POST 0763C95 - Search for seepage	N	2021.12.13	R	New document unit	Yes
AMM 63-20-60-221	Detailed inspection of the MGB POST 0763C88	N	2022.01.10	R	New document unit	Yes
AMM 63-20-60-222	Detailed inspection of the brackets and bolts of the rotor actuators - MGB POST 0763C88	N	2021.12.10	R	New document unit	Yes

THE DOCUMENT REFERENCE IS AVAILABLE ONLINE. PLEASE CHECK IF THE ONLINE DOCUMENTATION CORRESPONDS TO THE PRINTED VERSION

Documentary Unit	Title	NRD	Publication Date	Type of change	Reason for update	Maintenance Work Affected
AMM 63-20-60-282	Spectrometric analysis of MGB oil POST 0763C88	N	2022.01.03	R	New document unit	Yes
AMM 63-20-60-551	Storage / Destorage - MGB POST 0763C88	N	2021.11.22	R	New document unit	Yes
AMM 63-20-60-611	Draining and Filling the MGB POST 0763C88	N	2022.01.12	R	New document unit	Yes
AMM 63-20-60-721	Check of the tightening torques of the MGB housing links POST 0763C88	N	2022.01.11	R	New document unit	Yes
AMM 63-20-60-722	Check of the tightening torque of the rotor actuator bracket links and of the epicyclic module links - MGB POST 0763C88	N	2021.12.02	R	New document unit	Yes
AMM 63-20-60-723	Check of tightening torques - MGB POST 0763C88	N	2022.01.06	R	New document unit	Yes
AMM 63-20-60-991	MGB visual inspection criteria POST 0763C88 - Leaks and seepage	N	2022.01.06	R	New document unit	Yes
AMM 63-20-60-992	MGB detailed and visual inspection criteria POST 0763C88	N	2022.01.10	R	New document unit	Yes
AMM 63-20-60-993	Inspection criteria - General - MGB POST 0763C88	N	2022.01.04	R	New document unit	Yes
AMM 63-21-61-721	Check of the tightening torque - MGB POST 0763C88	N	2021.12.23	R	New document unit	Yes
AMM 63-21-62-061	Removal / Installation of the filtering cartridge - MGB POST 0763C88	N	2021.10.15	R	New document unit	Yes
AMM 63-21-62-062	Removal / Installation of the oil filter non-return valve - MGB POST 0763C88	N	2021.10.14	R	New document unit	Yes
AMM 63-21-62-211	Visual inspection of the oil filter pre-clogging indicator - MGB POST 0763C88	N	2021.10.20	R	New document unit	Yes

THE DOCUMENT REFERENCE IS AVAILABLE ONLINE. PLEASE CHECK IF THE ONLINE DOCUMENTATION CORRESPONDS TO THE PRINTED VERSION

Documentary Unit	Title	NRD	Publication Date	Type of change	Reason for update	Maintenance Work Affected
AMM 63-21-62-221	Detailed inspection of the oil filter - MGB POST 0763C88	N	2021.10.20	R	New document unit	Yes
AMM 63-21-62-991	Inspection criteria for the oil filter - MGB POST 0763C88	N	2021.10.25	R	New document unit	Yes
AMM 63-21-63-061	Removal / Installation - Oil level indicator - MGB POST 0763C88	N	2021.12.10	R	New document unit	Yes
AMM 63-21-64-061	Removal / Installation - Equipped filler cap - MGB POST 0763C88	N	2022.01.07	R	New document unit	Yes
AMM 63-22-00-061A	Removal / Installation - Fan Assembly	R	2021.12.17	C	Discrepancy corrected	Yes
AMM 63-22-00-061B	Removal / Installation - Fan Assembly POST 0779B26	R	2021.12.17	C	Discrepancy corrected	Yes
AMM 63-22-60-061	Removal / Installation - Fan assembly - MGB POST 0763C88	N	2021.12.20	R	New document unit	Yes
AMM 63-22-60-221	Detailed inspection of the fan assembly - MGB POST 0763C88	N	2021.11.24	R	New document unit	Yes
AMM 63-22-60-991	Inspection criteria - Fan assembly - MGB POST 0763C88	N	2021.12.13	R	New document unit	Yes
AMM 63-23-00-061	Removal / Installation - Rotor Brake Assembly	R	2022.01.03	C	Discrepancy corrected	Yes
AMM 63-23-00-821	Adjustment - Rotor Brake Control	R	2022.01.03	C	Discrepancy corrected	Yes
AMM 63-23-60-061	Removal / Installation - Rotor Brake Assembly POST 0763C86	N	2021.12.08	R	New document unit	Yes
AMM 63-23-60-062	Disassembly / Assembly of the Rotor Brake Assembly POST 0763C86	N	2021.12.14	R	New document unit	Yes
AMM 63-23-60-221	Rotor brake detailed inspection POST 0763C86	N	2022.01.11	R	New document unit	Yes
AMM 63-23-60-222	Inspection - Rotor Brake Control Adjustment POST 0763C86	N	2022.01.07	R	New document unit	Yes

Documentary Unit	Title	NRD	Publication Date	Type of change	Reason for update	Maintenance Work Affected
AMM 63-23-60-551	Storage / Destorage of a removed rotor brake - POST 0763C86	N	2021.11.24	R	New document unit	Yes
AMM 63-23-60-821	Adjustment of the rotor brake control POST 0763C86	N	2022.01.05	R	New document unit	Yes
AMM 63-23-60-991	Inspection criteria - Rotor brake POST 0763C86	N	2021.12.20	R	New document unit	Yes
AMM 63-23-61-061	Removal / Installation - Brake disc POST 0763C86	N	2021.12.15	R	New document unit	Yes
AMM 63-23-62-061	Removal / Installation - Brake pads - POST 0763C86	N	2021.11.25	R	New document unit	Yes
AMM 63-24-01-061	Removal / Installation - Tail Drive Shaft Flange	R	2022.01.05	C	Discrepancy corrected	No
AMM 63-24-01-062	Removal / Installation - Tail Drive Shaft Flange Seal	R	2021.12.15	I	Information added	No
AMM 63-24-02-061	Removal / Installation - Fan Power Takeoff Seals	R	2021.11.29	I	Information added	Yes
AMM 63-24-61-061	Removal / Installation - Tail Drive Line Flange - MGB POST 0763C88	N	2021.11.29	R	New document unit	Yes
AMM 63-24-61-062	Removal / Installation - Seal holder and dynamic seal of the tail drive line power take-off - MGB POST 0763C88	N	2021.12.10	R	New document unit	Yes
AMM 63-24-61-211	Visual inspection of the tail drive line flange - MGB POST 0763C88	N	2021.10.21	R	New document unit	Yes
AMM 63-24-61-721	Check of the tightening torque of the tail drive line flange - MGB POST 0763C88	N	2022.01.05	R	New document unit	Yes
AMM 63-24-61-991	Inspection criteria of the tail drive line flange - MGB POST 0763C88	N	2021.11.08	R	New document unit	Yes

THE DOCUMENT REFERENCE IS AVAILABLE ONLINE. PLEASE CHECK IF THE ONLINE DOCUMENTATION CORRESPONDS TO THE PRINTED VERSION

Documentary Unit	Title	NRD	Publication Date	Type of change	Reason for update	Maintenance Work Affected
AMM 63-24-62-061	Removal / Installation - Dynamic seal of the fan power take-off - MGB POST 0763C88	N	2021.11.30	R	New document unit	Yes
AMM 63-24-62-721	Check of the tightening torque - MGB POST 0763C88	N	2021.12.23	R	New document unit	Yes
AMM 63-24-65-061	Removal / Installation - Dynamic seal of the tachometer generator power take-off - MGB POST 0763C88	N	2021.11.16	R	New document unit	Yes
AMM 63-25-60-061	Removal / Installation - Seal holder and dynamic seal of the power take-off of the accessory gearbox hydraulic pump - MGB POST 0763C95	N	2021.11.19	R	New document unit	Yes
AMM 63-25-60-062	Removal / Installation - Seal holder and dynamic seal of the AGB lower power take-off - MGB POST 0763C95	N	2021.11.30	R	New document unit	Yes
AMM 63-25-60-063	Removal / Installation - Lubrication line and unions of the accessory gear box - MGB POST 0763C95	N	2022.01.03	R	New document unit	Yes
AMM 63-25-60-211	Visual inspection of the MGB accessory gear box POST 0763C95 - Search for seepage	N	2022.01.10	R	New document unit	Yes
AMM 63-25-60-721	Check of the tightening torques of the accessory gear box POST 0763C95	N	2022.01.05	R	New document unit	Yes
AMM 63-25-60-991	Criteria for the visual inspections of the accessory gear box - POST 0763C95	N	2022.01.05	R	New document unit	Yes
AMM 63-25-60-992	Criteria for visual inspections of accessory gear box links - POST 0763C95	N	2022.01.03	R	New document unit	Yes

THE DOCUMENT REFERENCE IS AVAILABLE ONLINE. PLEASE CHECK IF THE ONLINE DOCUMENTATION CORRESPONDS TO THE PRINTED VERSION

Documentary Unit	Title	NRD	Publication Date	Type of change	Reason for update	Maintenance Work Affected
AMM 63-40-03-721	Functional Tests - MGB Oil Thermostat Switch and Oil Temperature Warning System	R	2021.11.30	C	Discrepancy corrected	No
AMM 63-40-61-061	Removal / Installation - Tachometer Generator - MGB POST 0763C88	N	2021.12.08	R	New document unit	Yes
AMM 63-40-61-221	Inspection of the tachometer generator - MGB POST 0763C88	N	2021.12.14	R	New document unit	Yes
AMM 63-40-61-991	Inspection criteria for the tachometer generator - MGB POST 0763C88	N	2021.12.15	R	New document unit	Yes
AMM 63-40-62-061	Removal / Installation - Electrical Magnetic Plugs - MGB POST 0763C88	N	2022.01.03	R	New document unit	Yes
AMM 63-40-62-211	Inspection - MGB electrical magnetic plug POST 0763C88	N	2021.10.21	R	New document unit	Yes
AMM 63-40-62-711	Functional test - MGB electrical magnetic plug POST 0763C88	N	2021.10.15	R	New document unit	Yes
AMM 63-40-63-721	Functional tests - MGB oil thermal switch and oil temperature warning system - MGB POST 0763C88	N	2022.01.05	R	New document unit	Yes
AMM 63-40-64-061	Removal / Installation - MGB oil temperature probe POST 0763C88	N	2021.12.15	R	New document unit	Yes
AMM 63-40-65-061	Removal / Installation - MGB oil pressure transmitter POST 0763C88	N	2021.12.15	R	New document unit	Yes
AMM 64-10-00-221B	Inspection - Tail Rotor Blades with Removal POST 0761B27	R	2021.11.18	F	Form changed	No
AMM 64-20-00-061	Removal / Installation - Tail Rotor Head	R	2021.10.18	I	Information added	No
AMM 64-20-00-551	Packing / Unpacking - TRH in Safelog container	N	2021.10.19	R	New document unit	No

THE DOCUMENT REFERENCE IS AVAILABLE ONLINE. PLEASE CHECK IF THE ONLINE DOCUMENTATION CORRESPONDS TO THE PRINTED VERSION

Documentary Unit	Title	NRD	Publication Date	Type of change	Reason for update	Maintenance Work Affected
AMM 64-20-00-991	Inspection Criteria - Tail Rotor Head	R	2021.11.24	I	Information added	No
AMM 64-20-03-061	Removal/Installation of the torsion tie-bar	R	2021.03.09	C	Discrepancy corrected	No
AMM 65-10-00-211	DELETED	D	2018.01.29			
AMM 65-10-00-211A	Inspection - Tail drive line	N	2021.12.21	M	Aircraft build standard changed	No
AMM 65-10-00-211B	Inspection - Tail drive line - MGB POST 0763C88	N	2021.12.16	R	New document unit	Yes
AMM 65-10-00-221	DELETED	D	2015.01.14			
AMM 65-10-00-222A	Detailed inspection - Tail drive line	N	2021.12.16	M	Aircraft build standard changed	Yes
AMM 65-10-00-222B	Detailed inspection - Tail drive line - MGB POST 0763C88	N	2021.11.16	R	New document unit	Yes
AMM 65-10-00-224	Inspection - Tail Rotor Drive Shaft Alignment	R	2022.01.06	I	Information added	No
AMM 65-10-00-991	DELETED	D	2020.12.04			
AMM 65-10-00-991A	Inspection criteria - Tail drive line	N	2021.11.24	R	New document unit	No
AMM 65-10-00-991B	Inspection criteria - Tail drive line - MGB POST 0763C88	N	2021.11.26	R	New document unit	Yes
AMM 65-10-04-061	Removal / Installation - TGB Input Sliding Flange and Flexible Coupling	R	2021.10.11	C	Discrepancy corrected	Yes
AMM 65-20-01-061	Removal / Installation - Tail Gearbox	R	2021.09.17	I	Information added	No
AMM 65-20-01-221	Endoscopy inspection to check for obstruction of the TGB lubrication ducts	R	2021.07.09	R	New document unit	Yes
AMM 65-20-01-551	Preservation / Depreservation - Tail Gearbox	R	2022.01.03	C	Discrepancy corrected	Yes
AMM 65-20-01-552	Packing / Unpacking - TGB in Safelog container X652P6204101	N	2021.09.29	R	New document unit	No

THE DOCUMENT REFERENCE IS AVAILABLE ONLINE. PLEASE CHECK IF THE ONLINE DOCUMENTATION CORRESPONDS TO THE PRINTED VERSION

Documentary Unit	Title	NRD	Publication Date	Type of change	Reason for update	Maintenance Work Affected
AMM 67-10-00-991	Inspection of the cyclic and collective control rods	R	2021.10.05	I	Information added	No
AMM 67-11-01-061	Removal / Installation - Main rotor actuator	R	2021.10.01	I	Information added	No
AMM 67-11-02-821	Adjustment - Copilot's Cyclic Stick Balance Assembly	R	2021.07.19	I	Information added	Yes
AMM 67-20-00-991	Inspection of the yaw control rods	R	2021.10.05	I	Information added	No
AMM 67-20-01-221	Inspection - Pedal stops	R	2021.07.19	I	Information added	Yes
AMM 67-20-02-063	Removal/Installation - Tail rotor series actuator	R	2021.10.04	I	Information added	No
AMM 67-20-02-821	Adjustment - Tail Rotor Control Friction-Lock	R	2021.07.19	I	Information added	Yes
AMM 71-00-00-062C	Disassembly / Assembly Engine - MGB POST 0763C88	N	2021.12.23	R	New document unit	Yes
AMM 71-61-01-063	Removal / Installation - Optional sand filter	N	2021.11.24	R	New document unit	Yes
AMM 79-00-00-611A	Draining / Filling - Engine Oil System	R	2021.07.19	I	Information added	Yes
AMM 79-00-00-611B	Draining / Filling - Engine Oil System	R	2021.07.19	I	Information added	Yes
AMM 79-20-00-061C	Removal / Installation - Equipped radiator - MGB POST 0763C88	N	2021.12.20	R	New document unit	Yes

© Copyright - Airbus

THE DOCUMENT REFERENCE IS AVAILABLE ONLINE. PLEASE CHECK IF THE ONLINE DOCUMENTATION CORRESPONDS TO THE PRINTED VERSION