

DESCRIPTION	TASK No. / SPARES CATALOG ITEM
Deletion of the (maintenance method) "expandable/repairable" labels for the equipment and accessory TBOs.	05-15-00-201-801
Changes in the reference to task for this task: "Oil system - Draining".	05-20-10-201-835
Update of HYLOMAR sealing compound references for sealing faces.	70-04-00-940-803
Creation of the troubleshooting task "Oil tank level slowly decreases after engine shutdown".	71-00-08-816-833
Creation of the task "Powerplant - Removal of the engine/module from storage in a box or container".	71-02-12-280-802
Creation of the task "Treatment of an engine/module after an incorrect attachment in the transport packaging".	71-02-12-280-803
Update of the "Containers and blanks" task.	71-05-01-280-802
Changes in the inspection procedure for the sleeve. Changes in the installation procedure for the sleeve of the bleed valve mounting boss.	72-00-32-900-802
Creation of the task "Module 02 Compressor - Jet - Removal/Installation" TU222.	72-32-10-900-801
Update of the inspection and check task for the Module 03 - Gas generator.	72-43-00-200-805
Changes in the "Actions" column of table 3.B. Changes in the actions to be done when signs of wear are found on the rear spline sides of the power shaft.	72-61-00-200-801
Update of the removal/installation task for the seal of the breather cover.	72-61-00-900-811
Update of the removal/installation task for the seal of the Dynastart adapter.	72-61-00-900-812
Update of the replacement task for the magnetic seal of the drive shaft.	72-61-20-950-801
Update of the EECU task for installation of the poly-box unit and interface software starting.	73-21-00-280-801
Creation of a task for bleed valve electrical tests (9550002500, 9550002800).	75-31-00-750-801

Task Code	Modification description
00-00-00-APP-801-A01	-
05-15-00-201-801-A01	Removal of maintenance method.
72-00-32-200-803-A01	Revision without technical impact
71-00-06-812-803-A01	DELETED
71-00-06-814-804-A01	DELETED
71-00-06-815-803-A01	DELETED
71-00-06-816-809-A01	DELETION
71-00-06-RPU-801-A01	Update: deletion of the lines Task Nos. 710006-812-803 (table B), 710006-814-804 (table C), 710006-815-803 (table D).