

CONTINUING AIRWORTHINESS MANAGEMENT OFFICE MEMO

TO: GAM AMO Dept, GAM CAMO Dept.	FROM: Technical Publication
CC: GAM AM, GAM QAM	DATE: 19.07.2021
REFERENCE NO.: CAMO/MEMO/2021/49	

Dear all,

Please be informed that the following publication/s has/have been issued and uploaded to GAM server. Kindly refer all publication below for your acknowledgement and to take action.

NO.	VENDOR	REV. NO.	ISSUE/REV DATE	EFFECTIVITY	SUBJECT	LINK TO GAM SERVER
1.	CAAM	AI 7/2021 REV.2	16.07.2021	ALL OPERATORS IN MALAYSIA	CAAM OPERATIONS DURING THE MOVEMENT CONTROL ORDER	1
2.	AIRBUS	SIN NO. 3704-S-25 REV. 0	16.07.2021	EC120B EC155B	EQUIPMENT AND FURNISHING - HELICOPTER HOIST OPERATOR (HHO) HARNES	2
3.	LEONARDO	TMI NO. 139-544 NEW ISSUE	12.07.2021	AW139	MAIN ROTOR BLADE - LAP PLATE DAMAGE - REPAIR PROCEDURE	3
4.	LEONARDO	TMI NO. 139-545 NEW ISSUE	15.07.2021	AW139	UPPER LH/RH LONGERON ASSY P/N 3G5350A00335/3G350A00535 REPLACEMENT PROCEDURE	4
5.	LEONARDO	TMI NO. 109-532 NEW ISSUE	15.07.2021	A109E	MAIN ROTOR BLADE - IDENTIFICATION PLATE DEBONDINGS - REPAIR PROCEDURE	5

Please be advised, all engineering and CAMO staff shall update their working computer (control computer) effected immediately.

Thank you and stay safe!



**NUR NABILLA MOHD HASNAN
TECHNICAL PUBLICATION,
CAMO DEPARTMENT,
GALAXY AEROSPACE (M) SDN. BHD.**