

CONTINUING AIRWORTHINESS MANAGEMENT ORGANISATION MEMO

TO: GAM AMO Dept, GAM CAMO Dept.	FROM: Technical Publication
CC: GAM AM, GAM QAM	DATE: 05.08.2022
REFERENCE NO.: CAMO/MEMO/2022/57	

Dear all,

Please be informed that the following publication/s has/have been issued and uploaded to GAM server. Kindly refer all publication below for your acknowledgement and to take action.

NO.	VENDOR	REV. NO.	ISSUE/REV DATE	EFFECTIVITY	SUBJECT	LINK TO GAM SERVER
1.	GENERAL ELECTRIC	IC 70-80-04-015 SPM REVISION 111	29.07.2022	CT7-2E1	INCREMENTAL CHANGES - CONSUMABLE PRODUCTS - CLEANING COMPOUNDAS AND SOLVENTS	1
2.	LEONARDO	MANUAL NO. GB967-090-300 NEW ISSUE	12.04.2022	AW189	TOOL KIT, FUEL SYSTEM TEST STAND	2
3.	AIRBUS	IN NO. 3826-I-00 NEW ISSUE	29.07.2022	EC120B	TECH DATA: UPCOMING VERSION OF THE H120/EC120 PUBLICATIONS	3
4.	AIRBUS	IN NO. 3629-I-25 NEW ISSUE	29.07.2022	EC120B EC155B	EQUIPMENT AND FURNISHINGS - MAINTENANCE OF THE EMERGENCY FLOATATION SYSTEMS	4
5.	MECAER AVIATION	REVISION CU	05.07.2022	AW139 (9M-JPM, 9M-SAAS)	INSTRUCTIONS FOR CONTINUED AIRWORTHINESS IFEEL ENTERTAINMENT SYSTEM INSTALLATION P/N 6AB1AD016-001	5
6.	GENERAL ELECTRIC	IC 70-21-29-06 SPM REVISION 111	03.08.2022	CT7-2E1	INCREMENTAL CHANGES - CLEANING METHOD NO.29 - DRY ICE BLAST (CRYOBLAST) CLEANING	6
7.	LEONARDO	T-109E-22-003 NEW ISSUE	03.08.2022	A109E	RDR-2000 WEATHER RADAR RECOMMENDED OPERATOR ACTIONS FOR GREEN BLOCK LIKE EXTERNAL RADAR INTERFERENCE	7

8.	LEONARDO	T-139-22-007 NEW ISSUE	05.08.2022	AW139	TAIL ROTOR SLIDING CONTROL ASSY INSTALL AND REMOVE PROCEDURES	8
9.	LEONARDO	T-139-22-008 NEW ISSUE	05.08.2022	AW139	TAIL ROTOR DUPLEX BEARING REPLACEMENT PROCEDURE	9

Please be advised, all engineering and CAMO staff shall update their working computer (control computer) effected immediately.

Thank you and stay safe!



DEANNA IZZATY BINTI AHMAD SHOUFIK
TECHNICAL PUBLICATION,
CAMO DEPARTMENT,
GALAXY AEROSPACE (M) SDN. BHD