

## CONTINUING AIRWORTHINESS MANAGEMENT ORGANISATION MEMO

|   |                                    |
|---|------------------------------------|
| <b>TO:</b> GAM AMO Dept, GAM CAMO Dept. | <b>FROM:</b> Technical Publication |
| <b>CC:</b> GAM AM, GAM QAM              | <b>DATE:</b> 09.11.2022            |
| <b>REFERENCE NO.:</b> CAMO/MEMO/2022/80 |                                    |

Dear all,

Please be informed that the following publication/s has/have been issued and uploaded to GAM server. Kindly refer all publication below for your acknowledgement and to take action.

| NO. | VENDOR   | REV. NO.   | ISSUE/REV DATE | EFFECTIVITY             | SUBJECT  | LINK TO GAM SERVER   |
|-----|----------|--|----------------|-------------------------|--|--|
| 1.  | LEONARDO | ISSUE 23<br>UPDATE 001                                     | 24.10.2022     | AW189                   | AW189 IETP   | <a href="#">1</a>  |
| 2.  | LEONARDO | S-109E-22-003<br>S-189-22-005<br>S-139-22-006<br>NEW ISSUE | 07.11.2022     | A109E<br>AW189<br>AW139 | MANAGEMENT OF MASTER<br>MINIMUM EQUIPMENT LIST<br>(MMEL) APPROVED BY FAA | <a href="#">2A</a><br><a href="#">2B</a><br><a href="#">2C</a> |
| 3.  | SAFRAN   | DOC. REF.:<br>X 319 L6 301 2<br>UPDATE NO. 47              | 15.10.2022     | ARRIUS 2F               | ARRIUS 2F ENGINE<br>MAINTENANCE MANUAL                                   | <a href="#">3</a>  |
| 4.  | SAFRAN   | DOC. REF.:<br>X 319 L6 700 2<br>UPDATE NO. 44              | 15.10.2022     | ARRIUS 2F               | ARRIUS 2F SPARE PARTS<br>CATALOGUE                                       | <a href="#">4</a>  |
| 5.  | SAFRAN   | DOC. REF.:<br>X 319 L6 800 2<br>UPDATE NO. 32              | 15.10.2022     | ARRIUS 2F               | ARRIUS 2F MAINTENANCE<br>TOOLS CATALOGUE                                 | <a href="#">5</a>  |
| 6.  | SAFRAN   | DOC. REF.:<br>X 319 L6 301 2<br>UPDATE NO. 47              | 15.10.2022     | ARRIUS 2F               | ARRIUS 2F TROUBLESHOOTING  | <a href="#">6</a>  |
| 7.  | LEONARDO | TMI NO. 139-562<br>NEW ISSUE                               | 07.11.2022     | AW139                   | SLIDER BUSHING - INSTALL<br>PROCEDURE                                    | <a href="#">7</a>  |

| NO. | VENDOR | REV. NO.                | ISSUE/REV. DATE | EFFECTIVITY                     | SUBJECT                                | LINK TO GAM SERVER |
|-----|--------|-------------------------|-----------------|---------------------------------|--|--------------------|
| 8.  | CAAM   | AI 20/2022<br>NEW ISSUE | 08.11.2022      | ALL<br>OPERATORS<br>IN MALAYSIA | TRAINING OF CAMO<br>PERSONNEL          | <a href="#">8</a>  |
| 9.  | CAAM   | AI 21/2022<br>NEW ISSUE | 08.11.2022      | ALL<br>OPERATORS<br>IN MALAYSIA | RELOCATION OF CAAM<br>CORPORATE OFFICE | <a href="#">9</a>  |

Please be advised, all engineering and CAMO staff shall update their working computer (control computer) effected immediately.

*Thank you and stay safe!*

*Harlina*

NUR HARLINA BINTI ABDULLAH  
TECHNICAL PUBLICATION,  
CAMO DEPARTMENT,  
GALAXY AEROSPACE (M) SDN. BHD