

## CONTINUING AIRWORTHINESS MANAGEMENT ORGANISATION MEMO

<b>TO:</b> GAM AMO Dept, GAM CAMO Dept.	<b>FROM:</b> Technical Publication
<b>CC:</b> GAM AM, GAM QAM	<b>DATE:</b> 14.10.2022
<b>REFERENCE NO.:</b> CAMO/MEMO/2022/73	

Dear all,

Please be informed that the following publication/s has/have been issued and uploaded to GAM server. Kindly refer all publication below for your acknowledgement and to take action.

NO.	VENDOR	REV. NO.	ISSUE/REV DATE	EFFECTIVITY	SUBJECT	LINK TO GAM SERVER
1.	ROLLS-ROYCE	NTO NO. RR300-058 ISSUE 1	06.10.2022	RR300	STARTER/GENERATOR BRUSH REPLACEMENT AT OVERHAUL	<a href="#">1</a>
2.	LEONARDO	S-139-22-005 NEW ISSUE	07.10.2022	AW139	AW139 FULL FLIGHT SIMULATOR UPGRADE TO NEW PRIMUS EPIC AVIONICS PHASE	<a href="#">2</a>
3.	AIRBUS	IN NO. 3841-I-33 REVISION 0	06.10.2022	EC155	LIGHTS- OBSOLESCENCE INFORMATION NOTICE	<a href="#">3</a>
4.	LEONARDO	T-AW139-22-010 REV. A	12.10.2022	AW139	FORWARD CABIN ROOF CEILING HARNESS INSPECTION (STA 3120-3900) - RELEASE OF ALERT SB139-731	<a href="#">4</a>
5.	LEONARDO	SN NO. 139-22-002 REVISION 0	01.10.2022	AW139	SAFETY BRIEFING CARD CONTENTS	<a href="#">5</a>

Please be advised, all engineering and CAMO staff shall update their working computer (control computer) effected immediately.

*Thank you and stay safe!*



**DEANNA IZZATY BINTI AHMAD SHOUIK**  
**TECHNICAL PUBLICATION,**  
**CAMO DEPARTMENT,**  
**GALAXY AEROSPACE (M) SDN. BHD**