

CONTINUING AIRWORTHINESS MANAGEMENT ORGANISATION MEMO

TO: GAM AMO Dept, GAM CAMO Dept.	FROM: Technical Publication
CC: GAM AM, GAM QAM	DATE: 03.03.2022
REFERENCE NO.: CAMO/MEMO/2022/18	

Dear all,

Please be informed that the following publication/s has/have been issued and uploaded to GAM server. Kindly refer all publication below for your acknowledgement and to take action.

NO.	VENDOR	REV. NO.	ISSUE/REV DATE	EFFECTIVITY	SUBJECT	LINK TO GAM SERVER
1.	LEONARDO	TMI NO. 139-550 NEW ISSUE	17.02.2022	AW139	FRAME STA 3120 - SPECIFIC REPAIR PROCEDURE	1
2.	AIRBUS	IN NO. 2302-I-00 REV. 2	23.02.2022	ALL AIRBUS PRODUCTS	GENERAL - PROTECTION AND USE OF THE HELICOPTERS IN COLD WEATHER AND IN DAMP CONDITIONS	2
3.	AIRBUS	IN NO. 3751-I-00 REV. 0	23.02.2022	EC155	GENERAL - TECH DATA: UPCOMING REVISION OF THE H155/EC155 PUBLICATIONS	3
4.	LEONARDO	ISSUE 2 REV. 27 TEMPORARY REVISION 5-3	15.02.2022	AW139	ROTORCRAFT FLIGHT MANUALS SECTION 5 - OPERATIONAL EQUIPMENT SUPPLEMENTS DOC REF. NO.: 139G0290X002	4
5.	LEONARDO	TMI NO. 139-552 NEW ISSUE	22.02.2022	AW139	ROOT END BUSHINGS (MAIN ROTOR BLADE) - REPLACEMENT (REMOVE AND INSTALL A NEW ITEM)	5


6.	LEONARDO	TMI NO. 139-384 REV. A	22.02.2022	AW139	LEFT BRACKET ASSY - REPLACEMENT PROCEDURE (REMOVE AND INSTALL A NEW ITEM)	6
7.	AIRBUS	IN NO. 3686-I-00 REV. 1	21.02.2022	ALL AIRBUS PRODUCTS	GENERAL – PUBLISHING OF COMPLEMENTARY INSTRUCTIONS FOR CONTINUED AIRWORTHINESS THROUGH DELIVERY NOTES	7
8.	LEONARDO	T-AW189- 22-002 NEW ISSUE	25.02.2022	AW189	AMMC FAULT ISOLATION PROCEDURE IMPROVEMENT	8
9.	TEXTRON AVIATION	REVISION B2	15.02.2022	B300	STANDARD PRACTICES MANUAL PART NO. 130-590031-487	9
10.	LEONARDO	CHAPTER 00 - ISSUE 009 CHAPTER 04 - ISSUE 023 CHAPTER 05 - ISSUE 029	26.04.2021 09.09.2021 21.12.2021	AW189	AIR VEHICLE MAINTENANCE PLANNING INFORMATION	10
11.	LEONARDO	ISSUE 22 UPDATE 002	18.02.2022	AW189	AW189 IETP	11
12.	GENERAL ELECTRIC	IC 70-00-99-030- 748 SPM REVISION 110	25.02.2022	CT7-2E1	INCREMENTAL CHANGES – ACID STRIPPING SOLUTION FOR NI-CR-AL-Y PLASMA COATINGS	12
13.	MYSAFT	CMM NO. 24-32-10, 4017CH-3 REV 01	01.03.2022	BATTERY 4017CH-3	NICKEL CADMINUM AIRCRAFT BATTERIES 4017CH-3	13
14.	MYSAFT	CMM NO. 24-30-31, A2746CH1 REV 01	08.12.2021	BATTERY A2746CH1	NICKEL CADMINUM AIRCRAFT BATTERIES A2746CH1	14

15.	MYSAFT	CMM NO. 24-36-06, 443CH1 REV 01	27.07.2021	BATTERY 443CH1	NICKEL CADMINUM AIRCRAFT BATTERIES 443CH1	15
16.	LEONARDO	T-109E-22-001 NEW ISSUE	01.03.2022	A109E	TGB OIL DRAIN PROCEDURE	16
17.	GENERAL ELECTRIC	IC 79-00-00-01 IPC REV. 5	30.06.2021	CT7-2E1	INCREMENTAL CHANGES – OIL SYSTEM	17
18.	GENERAL ELECTRIC	IC 72-37-00-02 IPC REV. 5	30.06.2021	CT7-2E1	INCREMENTAL CHANGES – STAGE 1 AND STAGE 2 ACTUATING RINGS	18
19.	GENERAL ELECTRIC	IC 72-35-00-01 IPC REV. 5	30.06.2021	CT7-2E1	INCREMENTAL CHANGES - ACTUATING SYSTEM LINKAGE ASSEMBLY	19
20.	GENERAL ELECTRIC	IC 72-31-00-01 IPC REV. 5	30.06.2021	CT7-2E1	INCREMENTAL CHANGES – A-SUMP OUTPUT SHAFT ASSEMBLY	20

For item no. 11, this IETP is just an update not an issue. You may click (download) the application type as usual, and it will automatically update your IETP.

Please be advised, all engineering and CAMO staff shall update their working computer (control computer) effected immediately.

Thank you and stay safe!



NUR NABILLA MOHD HASNAN
TECHNICAL PUBLICATION,
CAMO DEPARTMENT,
GALAXY AEROSPACE (M) SDN. BHD.