


<b>EASA</b>	<b>AIRWORTHINESS DIRECTIVE CANCELLATION NOTICE</b>	
	<p><b>AD No.: 2009-0183-CN</b></p> <p><b>Date: 11 February 2010</b></p> <p>Note: This Airworthiness Directive Cancellation Notice is issued by EASA, acting in accordance with Regulation (EC) No 216/2008 on behalf of the European Community, its Member States and of the European third countries that participate in the activities of EASA under Article 66 of that Regulation.</p>	
<b>Type Approval Holder's Name:</b>		<b>Type/Model designation(s):</b>
<p>Agusta S.p.A, Eurocopter,</p> <p>Eurocopter Deutschland GmbH, Sikorsky Aircraft Corporation</p>		<p>A109 series and AB139/AW139, AS332, AS350 and AS355 series, EC225, SA365, AS365 and EC155 series, EC135 and MBB-BK 117, S-61, S76 series and S92 helicopters</p>
TCDS Number:	EASA R.001, R.002, R.005, R.006, R.008, R.009, R.010 and R.146, DGAC France No. 159, FAA U.S.A. 1H15 and H1NE.	
Foreign AD:	FAA AD 2010-03-02	
Cancellation:	<b> Cancels EASA AD 2009-0183-E dated 14 August 2009</b>	
<b>ATA 25</b>	<b>Equipment / Furnishings – D-Lok Hook of the Rescue Hoist – Inspection / Removal from Service / Replacement</b>	
Manufacturer(s):	Agusta S.p.A., Agusta Aerospace Corporation, American Eurocopter LLC, Eurocopter (formerly Eurocopter France), Eurocopter Deutschland GmbH, Eurocopter ESPANA S.A., Sikorsky Aircraft Corporation.	
Applicability:	<p>Agusta S.p.A model A109 series and AB139/AW139 helicopters ,</p> <p><u>and</u></p> <p>Eurocopter model AS332, AS350, AS355, SA365, AS365 and EC155 series and EC225 LP helicopters,</p> <p><u>and</u></p> <p>Eurocopter Deutschland GmbH model EC135 and MBB-BK 117 helicopters,</p> <p><u>and</u></p> <p>Sikorsky Aircraft Corporation S-61N, S76 series and S92A helicopters,</p> <p>all serial numbers, if equipped with Lifesaving Systems D-Lok Hooks with part numbers (P/N) 410-A or 410-F and identified as part of lot number</p>	

	<p>208 or 1108.</p> <p>Note: the rescue hoist P/N provided in the service information of the rescue hoist system manufacturers (Goodrich or Breeze-Eastern) is for information only. Refer to Lifesaving Systems D-Lok Hooks P/N to determine AD applicability.</p>
Reason:	<p>The Federal Aviation Administration, which is the State of Design Authority for the Lifesavings Systems Corp. D-Lok Hooks installed on certain Goodrich and Breeze-Eastern rescue hoist assemblies, has issued AD 2010-03-02, which becomes effective on 11 February 2010.</p> <p>EASA has decided to adopt this FAA AD, whose applicability is broader than EASA AD 2009-0183-E, as it affects all rotorcraft where the D-Lok Hook might be installed.</p> <p>For the reasons described above, EASA AD 2009-0183-E is cancelled.</p>
Effective Date:	11 February 2010
Compliance	Not applicable
Ref. Publications:	FAA Airworthiness Directive 2010-03-02 - Lifesaving Systems Corp.
Remarks:	<ol style="list-style-type: none"> <li>Enquiries regarding this AD Cancellation Notice should be referred to the AD Focal Point - Airworthiness Directives, Safety Management &amp; Research Section, Certification Directorate, EASA. E-mail: <a href="mailto:ADs@easa.europa.eu">ADs@easa.europa.eu</a></li> <li>For any questions concerning the technical content of this AD Cancellation Notice, please contact: <p>Goodrich Corporation , Sensors and Integrated Systems 1550 S. Valley Vista Drive, Diamond Bar, California United States of America Tel: +1 909 569-0210 ; Fax: +1 909 569-0387.</p> <p>Goodrich Corporation , Sensors and Integrated Systems Saint-Ouen l'Aumône 13 Avenue de l'Eguillette BP 7186 Cergy-Pontoise, Val d'Oise 95056 - France Tel: +33 (0) 1 3432 6781 ; Fax: +33 (0) 1 3432 6323.</p> <p>Breeze-Eastern Corporation 700 Liberty Avenue Union, New Jersey 07083-8198 USA Ph.: +1 (908) 686-4000, Ext. 3897, or 3890. 1-800-929-1919 (Toll-Free US and Canada only) Fax: +1 (908) 688-6495 E-Mail: <a href="mailto:customerservice@breeze-eastern.com">customerservice@breeze-eastern.com</a> .</p> </li> </ol>