

BUREAU VERITAS

AIRWORTHINESS DIRECTIVE

released by Direction Générale de l'Aviation Civile

Inspections and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive.

Translation of "Consigne de Navigabilité"

Réf. :

86-30-43(B)
In case of any difficulty, reference should be made to the French original issue.

AEROSPATIALE HELICOPTERS AS 350 ALL MODELS (ASTAR AND ECUREUIL)

Interference of emergency floatation gear with rear steps on raised skid-type landing gear

The present Airworthiness Directive is applicable to AEROSPATIALE AS 350 series helicopters, all models, which are equipped with both the optional raised skid-type landing gear and emergency floatation gear installations and which are not modified in accordance with AEROSPATIALE modification AMS 350 A 07-1755.

A possibility of interference between the steps fitted to the raised skid-type landing gear rear cross-beam, and the RH and LH floatation bags in the inflated configuration, has been evidenced.

In consequence, the following measures have been made mandatory to preclude the risk of floatation bag puncture, unless already complied with.

Within the next 10 hours of flight following the effective date of the present Airworthiness Directive, remove the rear RH and LH steps P/N 350 A 41-0172-00 and -01 or -06 and -07, in accordance with AEROSPATIALE Telex Service AS 350 number 32-06A.

The same removal operation is to be carried out prior to installation of the optional emergency floatation gear on an helicopter fitted with the optional raised skid-type landing gear installation.

Ref. : AEROSPATIALE AS 350 Telex Service 32-06 A

EFFECTIVE DATE : 26 FEBRUARY 1986

Dated : Feb. 19, 86

**AEROSPATIALE HELICOPTERS AS 350
ALL MODELS (ASTAR AND ECUREUIL)**

Ref. : 86-30-43(B)