

AIRWORTHINESS DIRECTIVE

released by DIRECTION GENERALE DE L'AVIATION CIVILE

Inspection and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive.

**Translation of 'Consigne de Navigabilité' ref. : 92-142-045(B)
In case of any difficulty, reference should be made to the French original issue.**

EUROCOPTER FRANCE

AS 355 helicopters

"JOLLIET" Emergency Locator Transmitter Antenna

This Airworthiness Directive applies to AS 355 helicopters, versions E, F, F1, and F2, fitted with the "JOLLIET" emergency locator transmitter system, not modified par AMS 350A.07.2492.

In order to improve the antenna resistance to vibrations and prevent any risk of loss in flight, the following measures are rendered mandatory :

- Within the next 400 flying hours without exceeding April 1, 1993, apply EUROCOPTER AS 355 Service Bulletin N° 25.33 (if this has not already been done).

REF. : EUROCOPTER AS 355 Service Bulletin N° 25.33

EFFECTIVE DATE : JULY 18, 1992

e/W

July 08, 1992

EUROCOPTER FRANCE
AS 355 helicopters

92-142-045(B)