

AIRWORTHINESS DIRECTIVE

released by DIRECTION GENERALE DE L'AVIATION CIVILE

Inspection and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive.

Translation of 'Consigne de Navigabilité' ref. : 92-145-062(B)
In case of any difficulty, reference should be made to the French original issue.

EUROCOPTER FRANCE

AS 350 helicopters

Hydraulic system

This Airworthiness Directive applies to AS 350 helicopters, versions B, BA, B1, B2 and D, fitted with the hydraulic reservoir P/N 350A75-1030-00.

In order to decontaminate the hydraulic system and eliminate the possibility of water penetrating the hydraulic reservoir the following measures are rendered mandatory :

Apply paragraph 2B1 or 2B2 of the EUROCOPTER Service Bulletin N° 01.36 (if this has not already been done) :

- 1) Within 100 hours following the effectivity date of the present Airworthiness Directive without exceeding October 1, 1992, for aircraft operating in temperatures equal to or less than -10°C.
- 2) Within 400 hours following the effectivity date of the present Airworthiness Directive for all other aircraft.

REF. : EUROCOPTER AS 350 Service Bulletin N° 01.36

EFFECTIVE DATE : JULY 18, 1992

e/W

July 08, 1992

EUROCOPTER FRANCE
AS 350 helicopters

92-145-062(B)