

AIRWORTHINESS DIRECTIVE

released by DIRECTION GENERALE DE L'AVIATION CIVILE

Inspection and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive.

**Translation of 'Consigne de Navigabilité' ref. : 93-137-049(B)
In case of any difficulty, reference should be made to the French original issue.**

EUROCOPTER FRANCE

AS 355 helicopters

Engines fire detection

The present Airworthiness Directive applies to AS 355 helicopters versions E, F, F1, F2 and N.

It has been found a non conformity which affects the functioning of the engines fire detection. The following measures are rendered mandatory :

- After the last flight of the day and, at the latest within the next 25 flying hours, following the effective date of the present Airworthiness Directive, perform the actions described in paragraphs BB and CC of EUROCOPTER FRANCE Telex Service N° 26-03 (versions E, F, F1 and F2 with ALLISON engines) or 26-04 (version N with ARRIUS engines).

REF.: EUROCOPTER FRANCE Telex Service N° 26-03 and 26-04.

EFFECTIVE DATE : UPON RECEIPT

n/W

August 18, 1993

EUROCOPTER FRANCE
AS 355 helicopters

93-137-049(B)