

# AIRWORTHINESS DIRECTIVE

released by DIRECTION GENERALE DE L'AVIATION CIVILE

*Inspection and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive.*

Translation of 'Consigne de Navigabilité' ref. : 2003-323(A)  
In case of any difficulty, reference should be made to the French original issue.

## EUROCOPTER

### EC 155 helicopters

Indicating and recording systems -  
Landing gear PCBs 10 and 11 Alpha (ATA 31)

#### 1. EFFECTIVITY

EC 155 helicopters, versions B and B1, equipped with ASU board 10 Alpha 2 (PN SE 07451):

- After embodiment of drawing 365 PCS 76023 or compliance with EUROCOPTER EC 155 Telex Alert No. 31A005,
- Before embodiment of MOD 07 39C22.

#### 2. REASON

This Airworthiness Directive (AD) is issued following a case of the landing gear not extending in "NORMAL" and "EMERGENCY" modes.

#### 3. MANDATORY ACTIONS AND COMPLIANCE TIME

The following actions are rendered mandatory from the effective date of this AD:

- Before June 30, 2004, modify the wiring and finalize the harnesses in compliance with the instructions described in paragraph 2 of referenced EUROCOPTER EC 155 Alert Service Bulletin (ASB) No. 31A008.

\_\_\_\_\_  
REF.: EUROCOPTER EC 155 Alert Service Bulletin No. 31A008.  
(or any further approved revision).  
\_\_\_\_\_

**EFFECTIVE DATE : SEPTEMBER 13, 2003**