K	AIRWORTHINESS DIRECTIVE No F-2004-174			Distribution:	Issue date: November 10, 2004	Page : <b>1/2</b>
Direction générale de l'aviation	This Airworthiness Directive is published by the DGAC EASA, Airworthiness Authority of the State of Design for product, part or appliance.				Translation of « Consigne de Navigabilité » of same number. In case of difficulty, reference should be made to the French issue.	
civile France GSAC publication	No person may operate an aircraft to which an Airworthiness Directive applies, except in accordance with the requirements of that Airworthiness Directive, unless otherwise agreed with the Authority of the State of Registry.					
Corresponding	Corresponding foreign Airworthiness Directive(s):			Airworthiness Directive(s) replaced:		
Not applicable			None	None		
Person in charge of airworthiness: <b>EUROCOPTER</b>			٠, ،	Type(s): AS 350 helicopters		
Type certificat	Type certificate(s) No. 84					
TCDS No 157						
ATA chapter:		Subject:	•			
29	Hydraulic power - Hydraulic power loss					

#### 1. **EFFECTIVITY**:

AS 350 helicopter versions B, BA, B1, B2, B3, BB and D.

Note: The information contained in this Airworthiness Directive (AD) is intended for crews.

#### 2. REASON:

This AD is issued after having noted that some crews do not understand how to comply with the emergency procedures in the event of a hydraulic power system failure or during emergency procedure training (hydraulic failure training procedures). The Flight Manuals have been revised to prevent misunderstanding.

#### 3. MANDATORY ACTIONS AND COMPLIANCE TIMES:

The following measures are rendered mandatory as from the effective date of this AD:

- No later than within one month, incorporate the Revisions listed below into the Flight Manuals of the helicopters concerned and comply with the instructions covered by these Revisions:

AS 350 AIRCRAFT VERSIONS	RUSH REVISIONS	FLIGHT MANUAL SUPPLEMENTS	NORMAL REVISIONS
В	RR 13 Q	SUPPLEMENT 19	NORMAL REVISION RN 1
BA	RR 2I	SUPPLEMENT 7	NORMAL REVISION RN 1
BB	RR 1F	SUPPLEMENT 7	NORMAL REVISION RN 1
B1	RR 5Q	SUPPLEMENT 11.7	NORMAL REVISION RN 1
B2	RR 3A	SUPPLEMENT 7	NORMAL REVISION RN 1
B3	RR 2K	SUPPLEMENT 7	NORMAL REVISION RN 1
D	RR 5M	SUPPLEMENT 19	NORMAL REVISION RN 1



# AIRWORTHINESS DIRECTIVE No F-2004-174

Distribution:

Α

Issue date:

Page:

November 10, 2004

2/2

## 4. REFERENCE PUBLICATIONS:

Helicopter Flight Manuals (Any subsequent approved revision to these documents is acceptable).

## 5. **EFFECTIVE DATE**:

November 20, 2004.

## 6. REMARK:

For any questions concerning the technical content of the requirements in this AD, please contact:

EUROCOPTER (STXI) - Aéroport de Marseille Provence, 13725 Marignane Cedex - France

Phone: +33 (0)4 42 85 97 97 - Fax: +33 (0)4 42 85 99 66 E-mail: Directive.technical-support@eurocopter.com

## 7. APPROVAL:

This AD is approved under EASA reference No 2004-10840 dated November 03, 2004.