







FAA AD NO: 2017-18-14  TURBINE SECTION	*	-	-	-	-	WORK SHOP VISIT 
FAA AD NO: 2017-18-14  TURBINE SECTION	Engine1 Hours*	50.0 Hours	0.00	2025.00 	1500.48 	TO BE COMPLIED 

Edit Limitation FAA AD NO: 2017-18-14 -TURBINE SECTION

Based On:	<input type="text" value="Engine1 Hours"/> ▼
Warning:	<input type="text" value="50"/>
Warning Unit:	<input type="text" value="Hours"/> ▼
Completed:	<input type="text" value="0.00"/>
Due At:	<input type="text" value="2025.00"/>
Status:	<input type="text" value="TO BE COMPLIED"/> ▼
Limitation Notes:	<p>REFER TIC-R66-21-0004 DATED 10 MAY 2021.</p> <p>REFER ROLLS-ROYCE LOGBOOK RR300 AD NOTE COMPLIANCE AND SB MODIFICATION RECORD.</p> <p>COMPLIANCE: WITHIN 2,025 HSLI, OR AT THE NEXT ENGINE SHOP VISIT, WHICHEVER OCCURS LATER, REMOVE 4TH-STAGE TURBINE WHEELS, P/N RR30000240, FROM SERVICE.</p>