

International AIRWORTHINESS DIRECTIVES (since October 1st, 2003)

Date: 20/04/2010

helicopter total time: **NEW**


 sign: **Andrea Taldo** 

Helicopter Type: **AW139**

S/N **31289**

marks: **//**

Page **2** of **6**

| Acronyms: | | | N.A. (Not applicable) | N.C.W. (Not Complied With) | C.W. (Complied With) | | | |
|-----------|-----------|--------------------------------|------------------------|--|----------------------|------------------------------|---------------|---|
| COUNTRY | AUTHORITY | CHECK CARRIED OUT THRU A.D. n. | APPLICABLE A. D.s | TITLE | LINKED E.N.A.C. P.A. | APPLICABILITY | STATUS | NOTES |
| | | | 2008-0148 | FUSELAGE – WIRE STRIKE PROTECTION SYSTEM (WSPS) TOP CABLE CUTTER – REWORK / REPLACEMENT | 2008-295 | SEE AGUSTA BT 139-126 | N.A. | WIRE STRIKE PROTECTION SYSTEM NOT INSTALLED |
| | | | 2008-0157 <i>x</i> | FUSELAGE – TAIL BOOM ASSEMBLY – INSPECTION / REPAIR / REPLACEMENT | 2008-306 | SEE AGUSTA BT 139-134 | N.A. | SUPERSEDED BY AD 2009-198-E |
| | | | 2009-0042 | ELECTRICAL POWER – GENERATOR CONTROL UNIT (GCU) - REPLACEMENT | // | SEE AGUSTA BT 139-133 | C.W. | INSTALLED GENERATOR CONTROL UNIT (GCU) P/N 1152550-4. |
| | | | 2009-0124 | EQUIPMENT / FURNISHINGS – LIFESAVING SYSTEMS' D-LOK HOOK OF THE RESCUE HOIST – INSPECTION / REPLACEMENT | 2009-205 | // | N.A. | SUPERSEDED BY AD 2009-0148-E |
| | | | 2009-0148-E | EQUIPMENT / FURNISHINGS – D-LOK HOOK OF THE RESCUE HOIST – INSPECTION / REMOVAL FROM SERVICE / REPLACEMENT | 2009-227 | // | N.A. | SUPERSEDED BY AD 2009-0179-E |
| | | | 2009-0179-E | EQUIPMENT / FURNISHINGS – D-LOK HOOK OF THE RESCUE HOIST – INSPECTION / REMOVAL FROM SERVICE / REPLACEMENT | 2009-276 | // | N.A. | SUPERSEDED BY AD 2009-0183-E |
| | | | 2009-0183-E | EQUIPMENT / FURNISHINGS – D-LOK HOOK OF THE RESCUE HOIST – INSPECTION / REMOVAL FROM SERVICE / REPLACEMENT | 2009-280 | // | N.A. | CANCELLED BY AD 2009-0183-CN |
| | | | 2009-0198-E | FUSELAGE – TAIL BOOM – INSPECTION | // | // | N.A. | SUPERSEDED BY AD 2009-0234-E |
| | | | 2009-0234-ER1 <i>x</i> | FUSELAGE – TAIL BOOM – INSPECTION | 2009-351 | SEE AGUSTA BT 139-195 REV. A | N.C.W. | WITHIN 50 FH AND THEREAFTER AT INTERVALS NOT TO EXCEED 50 FH. |
| | | | 2009-0251-E | FIRE PROTECTION – PORTABLE FIRE EXTINGUISHERS – IDENTIFICATION / REPLACEMENT | 2009-382 | // | C.W. | |
| | | | 2009-0262 | FIRE PROTECTION – HALON 1211 FIRE EXTINGUISHERS – IDENTIFICATION / REPLACEMENT | 2009-411 | // | N.A. | SUPERSEDED BY AD 2009-0262R1 |