

GAM PUBLICATION - GOOGLE DRIVE LINK

GD Link No.	: GDLINK/CAMO/22/034
Subject	: SAFRAN HELICOPTER ENGINES - ARRIUS 2F ENGINE MAINTENANCE MANUAL
Revision No.	: DOC. REF. X 319 L6 301 2, UPDATE NO. 47
Revision Date	: 15 OCTOBER 2022

You may click Google Drive link below to view and download the attachment.

1. [ARRIUS 2F MAINTENANCE MANUAL, UPDATE NO. 47](#)

SAFRAN HELICOPTER ENGINES
ARRIUS 2 F MAINTENANCE MANUAL

HIGHLIGHTS

These HIGHLIGHTS list the main changes introduced through the update of this document. This list does not replace the transmittal letter but serves as an additional document to make it easier to identify the main effects of the update on your document.

Please continue to help us improve the quality of our documents by letting us know what you think about the content of this update via the "Managing my Maintenance Document Revision Requests" field on the "EngineLife® Customer Portal".

DESCRIPTION / PURPOSE	TASK No.
Creation of this general task related to plastic clamps.	70-11-00-940-805-AD1
Addition of an inspection on the connector.	70-43-00-940-801-AD1
Deletion of this task that duplicates the other tasks in Chapter "Particles in the oil system".	71-02-07-280-802-AD1
Full revision of this task.	71-02-15-280-801-AD1
Update of tools and procedure.	72-00-11-900-801-AD1
Update of tools and procedure.	72-00-42-900-801-AD1
Update of tools and procedure.	72-00-42-900-801-B01
Addition of information that follows the power turbine wheel when it is sent back (Engine variant, Engine/M02 PN/SGN, Engine/M02 TGN, Engine/M02 GSN, removed PT disc PN/SGN...).	72-42-20-900-805-AD1
Update of the procedure of this task.	71-00-06-811-812-AD1
Deletion of the reference to task 71-02-07-280-802.	71-00-06-812-805-AD1
Deletion of this task.	71-00-06-812-813-AD1
Update of the procedure of this task.	71-00-06-813-804-AD1
Full revision of the procedure of this task.	71-00-06-813-805-AD1
Update of the procedure of this task.	71-00-06-813-806-AD1
Deletion of the reference to task 71-02-07-280-802.	71-00-06-814-802-AD1
Update of the procedure.	71-00-06-814-814-AD1
Deletion of the reference to task 71-02-07-280-802.	71-00-06-814-823-AD1
Creation of this task if the P3 air transmitter test is unsatisfactory.	71-00-06-816-827-AD1

Please find below the list of tasks that have been subject to modification but without revision mark:

Task Code	Modification description
71-02-07-280-802-AD1	DELETED
71-00-06-812-813-AD1	DELETED

Note: Do not hesitate to contact Technical Publication from CAMO department for any further inquiry.