



**GO BEYOND**

P&WC 11524 (2020-11) MRO Information Management (9290)

S.I.L. NO.  
**GEN-168**

# SERVICE INFORMATION LETTER

## WARNING - PROPRIETARY RIGHTS NOTICE

This document is the property of Pratt & Whitney Canada Corp. ("P&WC"). You may not possess, use, copy or disclose this document or any information in it, for any purpose, including without limitation to design, manufacture, or repair parts, or obtain FAA or other government approval to do so, without P&WC's express written permission. Neither receipt nor possession of this document alone, from any source, constitutes such permission. Possession, use, copying or disclosure by anyone without P&WC's express written permission is not authorized and may result in criminal or civil liability.

Subject: **Reminder Regarding Scheduled Maintenance Tasks at Engine Shop Visits**

Applicability: **All P&WC products except PW900 and APS-Model APU**

---

Except for engine models installed on aircraft for which MRB programs were developed, P&WC typically provides scheduled maintenance recommendations in section 05-20 Scheduled Maintenance Checks or 72-00-00 Inspection of the applicable engine maintenance manual. Even in the case of MRB programs, those sections can sometimes contain additional scheduled maintenance recommendations as well as the recommendation to replace certain components which would coincide with an engine shop visit or that can only be carried out at an engine overhaul facility.

An engine overhaul facility's scope of work is mainly contained in the applicable engine overhaul and shop manuals. While many engine overhaul facilities will recommend those part replacements during an engine shop visit based on your engine's maintenance records, operators should not assume that overhaul facilities will automatically refer to section 05-20 or 72-00-00 of the applicable engine maintenance manual and complete those tasks.

P&WC, therefore, recommends that operators review the recommended scheduled maintenance tasks for their engines to confirm compliance and coordinate with their overhaul facility accordingly.

P&WC intends to add a recommendation in engine overhaul and shop manuals to review section 05-20 or 72-00-00 of the applicable engine maintenance manual at engine induction and compare with the engine's maintenance records.

---

This Service Information Letter is valid until superseded or cancelled by revision.

ISSUED: 23-Sep-2022

Page 1 of 2

**PRATT & WHITNEY CANADA CORP.**

MARIE-VICTORIN, LONGUEUIL  
QUEBEC, CANADA J4G 1A1  
PRINTED IN CANADA

Pratt & Whitney Canada Corp.  
SERVICE INFORMATION LETTER

S.I.L. NO.  
**GEN-168**

---

Please contact your local Field Service Manager or P&WC Customer First (CFirst) center (1-800-268-8000, CFirst@pwc.ca) should you require assistance or clarification on P&WC engine scheduled maintenance recommendations.

Sincerely,



Tammy Stupalo  
Deputy Chief Engineer  
Customer Service  
PRATT & WHITNEY CANADA CORP

---

This Service Information Letter is valid until superseded or cancelled by revision.

ISSUED: 23-Sep-2022

Page 2 of 2

P&WC Proprietary Information. Subject to restriction on first page.

**PRATT & WHITNEY CANADA CORP.**

MARIE-VICTORIN, LONGUEUIL  
QUEBEC, CANADA J4G 1A1  
PRINTED IN CANADA