

HC-SB-61-392 REV 2 - PROPELLER NO. 1-108298 CYLINDER BUSHIN... [X] Cancel [S] Save

Based On:

Warning:

Warning Unit:

Completed:

Due At:

Status:

Limitation Notes:

NOT APPLICABLE DUE TO AIRCRAFT FITTED WITH HC-B4MP-3C PROPELLERS WHICH ARE NOT AFFECTED BY THIS SB. REFER TIC-B300-22-0006 DATED 24/02/2022.

HC-SB-61-392 REV 2 - PROPELLER NO. 2-108298 CYLINDER BUSHIN... [X] Cancel [S] Save

Based On:

Warning:

Warning Unit:

Completed:

Due At:

Status:

Limitation Notes:

NOT APPLICABLE DUE TO AIRCRAFT FITTED WITH HC-B4MP-3C PROPELLERS WHICH ARE NOT AFFECTED BY THIS SB. REFER TIC-B300-22-0006 DATED 24/02/2022.

@	Aircraft	Based On	Period	Warning Unit	Warning	Last Done	Next Due	Status	
	9M-PTA	Not Applicable	-		0	-	-	NOT APPLICABLE	
	9M-PTB	Not Applicable	-		0	-	-	NOT APPLICABLE	
	9M-PTC	Not Applicable	-		0	-	-	NOT APPLICABLE	
	9M-PTD	Not Applicable	-		0	-	-	NOT APPLICABLE	
	9M-PTE	Not Applicable	-		0	-	-	NOT APPLICABLE	