

HC-SL-61-371, NEW ISSUE – PROPELLER NO. 1

Aeronet Galaxy Aerospace > Modifications > Update - Mozilla Firefox

https://galaxy.aeronet.nz/index.html

AD/SB ID: 9424 Close Update Save & Close

General | Config List | Aircraft List | Task List | Linked To | BOM

Type: SBS Repetitive

Reference/Number: INTRODUCTION OF ALTERNATE O-RING (P/N C-3317-AR-157)

Title/Subject: HC-SL-61-371, NEW ISSUE - PROPELLER NO. 1

Version No:

Reason For Raising:

URL:

Date: 05 / 08 / 2021

Tolerance: 0 % (Whole numbers only)

Creep Type: Creep on Completion Unit

Document	Title	Filename
	HC-SL-61-371, NEW ISSUE	9424-2422.pdf

AD/SB ID: 9424 Close Update Save & Close

General | Config List | Aircraft List | Task List | Linked To | BOM

@	Aircraft	Based On	Period	Warning Unit	Warning	Last Done	Next Due	Status	
	9M-PTA		-		0	-	-	NOT APPLICABLE	
	9M-PTB		-		0	-	-	NOT APPLICABLE	
	9M-PTC		-		0	-	-	NOT APPLICABLE	
	9M-PTD		-		0	-	-	NOT APPLICABLE	
	9M-PTE		-		0	-	-	NOT APPLICABLE	

HC-SL-61-371, NEW ISSUE – PROPELLER NO. 2

Aeronet Galaxy Aerospace > Modifications > Update - Mozilla Firefox

https://galaxy.aerospace.aeronet.nz/index.html

AD/SB ID: 9447 Close Update Save & Close

General **Config List** Aircraft List Task List Linked To BOM

Type: SBS Repetitive

Reference/Number: INTRODUCTION OF ALTERNATE O-RING (P/N C-3317-AR-157)

Title/Subject: HC-SL-61-371, NEW ISSUE - PROPELLER NO. 2

Version No:

Reason For Raising:

URL:

Date: 05 08 2021

Tolerance: 0% (Whole numbers only)

Creep Type: Creep on Completion Unit

Document	Title	Filename
	HC-SL-61-371, NEW ISSUE	9447-2424.pdf

AD/SB ID: 9447 Close Update Save & Close

General **Config List** Aircraft List Task List Linked To BOM

@	Aircraft	Based On	Period	Warning Unit	Warning	Last Done	Next Due	Status	
	9M-PTA		-		0	-	-	NOT APPLICABLE	
	9M-PTB		-		0	-	-	NOT APPLICABLE	
	9M-PTC		-		0	-	-	NOT APPLICABLE	
	9M-PTD		-		0	-	-	NOT APPLICABLE	
	9M-PTE		-		0	-	-	NOT APPLICABLE	