



HELISTAR RESOURCES SDN. BHD.

Job/Task/Maintenance payable by: **HRSB**
Remark/Justification:

A) CAMO MAINTENANCE INSTRUCTION DATA No: 1187

1.	Aircraft Registration / Component	9M-SBK			
2.	Effectivity	Aircraft Type		Engine Type	
		EC 120 B		ARRIUS 2F	
3.		AD	SB	MISC	MAINT. PROGRAM
			✓		
		INSPECTION			
		377	1.	ADSB - ASB EC120-05A019 R1 - MRH INSPECTION OF ROTATING AND NON-ROTATING SCISSORS BOLTS	
378	2.	12M KANNAD AF-H INTEGRA - ICA 1230222 SECT.B			
4.	Maintenance Data Originator	• ASB EC120-05A019 R1 DATED 05/10/2020			
5.	Date Requested	14 TH OCTOBER 2020			

B) MAINTENANCE CONTRACTOR ACTION

Acceptance of Instruction:-

Name: Affiq Signature: Affiq Date: 15.10.2020.

	Action	Remarks
1.	Inspections Commence Date	
2.	Inspections Completion Date	
3.	Worksheet No.	YES / NO HRSB/2020/JC 0377-0378
4.	Spare Order No.	YES / NO

C) CAMO SUPPORT

	Action	Remarks
1.	Log Book Entry / Mod Record Book	YES / NO LBE SBK 2020 010
2.	Document Filed	YES / NO
3.	Defer Defect	YES / NO

Completion of compliance signatory:-

Name: Nik Umi Signature: Nik Umi Date: 30/10/2020

3PG
IDR x 1




HELISTAR RESOURCES SDN. BHD. (845650-K)
 c/o Mycopter Aviation Services Sdn. Bhd.
 Helicopter Centre,
 Malaysia International Aerospace Centre (MIAC)
 Sultan Abdul Aziz Shah Airport, 47200 SUBANG
 Selangor, Malaysia

JOB CARD

AIRCRAFT TYPE:		SERIAL NO	HOURS	LDG/CYCLES	NG/N1 CYCLES	NF/N2 CYCLES	JOB CARD NO
EC 120 B	AIRCRAFT:	1089	3480.60	4373			HRSB/2020/0377
REGISTRATION:	ENGINE #1:	34077	4601.70		3650.05	3709.10	PAGE NO
9M-SBK	ENGINE #2:						1 of 1
	APU:	N/A	N/A	N/A			

REASON FOR RAISING: TO PERFORM ONCE-OFF 50H COMPLIANCE FOR AD 2019-0139 R0//ASB EC120-05A019 REV.1 MRH INSPECTION OF ROTATING AND NON-ROTATING SCISSORS BOLTS

RAISED BY AND DATE:
GABRIEL. 14.10.2020

ITEM	TASK/DEFECT DESCRIPTION	TASK/RECTIFICATION CARRIED OUT	TECHNICIAN	INSP. CRS*	DATE
1.	PROTECTIVE MEASURE TIME LIMITS - MAINTENANCE CHECKS - Main Rotor Hub. Inspection of rotating and non-rotating scissors bolts. Application of the red line on the nut side. ATA: 62 I.A.W. ASB EC120-05A019 R1, PARA 3.B.2.b	CARRIED OUT: TASK CARRIED OUT AS PER EC120B ASB NO. EC120 - 05A019, R1, PARA 3.B.2-b. FOUND SATISFACTORY.	<i>[Signature]</i>	 <i>[Signature]</i>	15/10/2020

*The work recorded above has been carried out in accordance with the requirements of the Malaysian Civil Aviation Regulations for the time being in force and in that respect the aircraft / equipment is considered fit for Release to Service.

HRSB/CAMO/WO
 DATE : 07-JAN-19



HELISTAR RESOURCES SDN. BHD. (845650-K)
 c/o Mycopter Aviation Services Sdn. Bhd.
 Helicopter Centre,
 Malaysia International Aerospace Centre (MIAC)
 Sultan Abdul Aziz Shah Airport, 47200 SUBANG
 Selangor, Malaysia

JOB CARD

AIRCRAFT TYPE:	AIRCRAFT:	SERIAL NO	HOURS	LDG/CYCLES	NG/N1 CYCLES	NF/N2 CYCLES	JOB CARD NO
EC 120 B	1089	3480.60	4373				HRSB/2020/0378
REGISTRATION:	ENGINE #1:	ENGINE #2:					PAGE NO
9M-SBK	34077	4601.70	1646.30	1549.55			1 of 1
	APU:	N/A	N/A	N/A			

To Carry Out All Due Inspection I.A.W Aircraft Maintenance Program REF HRSB/ AMP/ EC 120 B ISSUE NO.01, REV NO.03/
 DATED 11TH MARCH 2019- 12M ANNUAL INSPECTION(AF-H INTEGRA)

RAISED BY AND DATE:
 GABRIEL PILLAI. 15.10.2020

ITEM	TASK/DEFECT DESCRIPTION	TASK/RECTIFICATION CARRIED OUT	TECHNICIAN	INSP. CRS*	DATE
1.	ELT- 12M KANNAD AF-H INTEGRA INSPECTION I.A.W MYCAS ICA 1230222 R0 Dated 09/10/2017,SECTION B	Satisfactory / Unsatisfactory. (Rectification Ref.....)		 	15/10/20

*The work recorded above has been carried out in accordance with the requirements of the Malaysian Civil Aviation Regulations for the time being in force and in that respect the aircraft / equipment is considered fit for Release to Service.

HRSB/CAMO/WO
 DATE : 07-JAN-19