



SERVICES BULLETINS IMPERATIFS ET RECOMMANDES  
*MANDATORY AND RECOMMENDED SERVICES BULLETINS*

APPAREIL TYPE  
*AIRCRAFT TYPE*

**EC 120 B**

NUMERO DE SERIE  
*SERIAL NUMBER*

**1089**

**SERVICES BULLETINS IMPERATIFS ET RECOMMANDES**  
*MANDATORY AND RECOMMENDED SERVICE BULLETINS*

No SB	Code I/R/T	Modification	Consignes de nav. <i>Airworthiness directives</i>	Objet <i>Object</i>	Application
01.002				LIMIT.VOL TROMPETTE GTM/BTP & FERRURE SUPPORT GTM FLIGHT RESTRIC. ARM ASSY ENG/MGB & SUPP. FITTING	NON CONCERNE NO CONCERNED
01-001	I		1999-151-001 (A)	BOITE DE TRANSSION ARRIERE TAIL GEAR BOX	NON CONCERNE NOT CONCERNED
05-001	T		1999-349-002(A) R2	TROMPETTE DE LIASON BTP/GTM COUPLING FLARED ASSY MGB/ENGINE	REFERENCE NON CONCERNE. CHECEP ATER NOT CONCERNED.
05-002	R			POLLUTION DU CIRCUIT CARBURANT FUEL SYSTEM CONTAMINATION	NON CONCERNE APPRES APPAREIL 1048. NO CONCERNED AFTER A-C NUMBER 1048.
65.002	R			PATTES DE FIXATION DU CARTER B.T.A. ATTACH TAB OF T.G.B. HOUSING.	S/O APRES N. DE SERIE M135. NOT CONCERNED AFTER S/N M135.
65-001	R			BTA AVANT BAGUES EN "TORLON". TAIL GEAR BOX WITH "TORLON" SPLIT.	APPLIQUE. APPLIED.

I = IMPERATIF / MANDATORY  
 R = RECOMMANDE / RECOMMENDED  
 T = TELEX SERVICE

Visa des Services Qualité

Quality Department's signature



EUROCOPTER	REGISTRE INDIVIDUEL DE CONTROLE INDIVIDUAL INSPECTION LOG BOOK	APPAREIL AIRCRAFT EC 120 B	N ° SERIE SERIAL Nr 1089	PAGE 3
------------	---	----------------------------------	--------------------------------	-----------

- SB 32-002 c/w 30/7/02.	- SB 05-004	- SB 28-004	- SB 67-005
- SB 21-006	- SB 52-004R1	- SB 67A008	- SB 32-002
- SB 71-003	- SB 63-003	- SB 62-007	- SB 67A009
- SB 52-007 c/w 08/10/13	- SB 67-017 c/w 05.05.2017	- SB 56-004 <i>lu</i>	SB 26-001 <i>lu</i> JC# HRSB/2020/0319



FIN  
END