






JOB CARD NO: 1409

PAGE NO: 1

AIRCRAFT TYPE:	EC120 B	ENGINE 1:	ENGINE 2	APU:
REGISTRATION:	9M-SBK	SERIAL NO:	34077	SERIAL NO:
SERIAL NO:	1089	HOURS:	3946.50	HOURS:
AIRFRAME		CYCLES Nf/N1:	6511.40	CYCLES Nf/N1:
HOURS:	2824.40	CYCLES Nf/N2:	7236.95	CYCLES Nf/N2:
LDG/CYC:	3478	PROP 1 (HRS):	PROP 2 (HRS):	AMP REF:
				LOCATION: MYCAS HAR SBG

Reason for raising: TO REVIEW EASA BI-WEEKLY 17-2016 UNTIL 20-2016

Raised by and date:
Airworthiness Engineer
27/09/2016

Task ID	Defects or work required	Work / Rectification carried out	Tech.	Insp. CRS*	Date
20886	EASA bi-weekly 17-2016 until 20-2016 reviewed and found not applicable to Airbus Helicopter EC120 and Arrius 2F except for the following: a) 2016-0180; Equipment & Furnishings - Emergency Floatation Gear Lighting and Ancillary Control Unit (LACU) Pushbutton - In-Flight Check/Replacement	AD 2016-0180 reviewed and found not applicable due to part not fitted		 	27/9/16

*The work recorded above has been carried out in accordance with the requirements of the Malaysian Civil Aviation Regulation./

_____ for the time being in force and in that respect the aircraft/ equipment is considered fit for release to service.



Publ. number	Issue Date	TC Holder	Type	Subject
2016-0165	2016-08-12	CZECH SPORT AIRCRAFT	PS-28 Cruiser	Engine Fuel & Control - Carburettor Float - Inspection / Replacement
US-2016-16-12	2016-08-12	CONTINENTAL MOTORS, INC	GIO-550, GTSIO-520, IO-470, IO-520, IO-550, IOF-550, LTSIO-520, O-470, TSIO-470, TSIO-520, TSIO-550, TSIOF-550, TSIOL-550	Reciprocating Engine - Cylinder Assemblies - Removal
2016-0166-E	2016-08-12	LEONARDO S.p.A. HELICOPTERS	AB204/AB205, AB212/AB412	Main Rotor Drive - Spiral Bevel Gear - Inspection
US-2016-14-04	2016-08-10	BOEING	787	Fuselage - Potable Water System Coupling or Main Cabin Water Source - Replacement / Sealing
US-2016-13-13	2016-08-10	BEECHCRAFT CORPORATION	BAe/BH/DH/HS.125, Hawker	Engine Exhaust - Thrust Reverser - Installation
2016-0164	2016-08-10	ZODIAC SEATS FRANCE	Cabin Attendant Seats	Equipment / Furnishings - Cabin Attendant Seats - Inspection
2016-0163	2016-08-10	ZODIAC SEATS FRANCE	Cabin Attendant Seats	Equipment / Furnishings - Cabin Attendant Seat - Modification / Replacement
2016-0162	2016-08-09	EVEKTOR, SPOL. S R.O.	SportStar RTC	Engine Fuel and Control - Float - Inspection / Replacement
2016-0161	2016-08-08	LEONARDO S.p.A. HELICOPTERS	AW189	Stabilizers - Tail plane Lower Fitting - Inspection / Replacement
2016-0159	2016-08-05	AIRBUS	A318, A319, A320, A321	Airborne Auxiliary Power - Auxiliary Power Unit Starter Motor and Air Intake System - Inspection / Cleaning
2014-0164R1	2016-08-04	AIRBUS	A300, A300-600, A310	[Correction] Fuselage - Tail Cone / Trimmable Horizontal Stabilizer Support Struts at Frame 91 - Inspection / Modification
RU-2016-27-01	2016-08-02	SUKHOI CIVIL AIRCRAFT, JSC	RRJ-95	Stabilizers - Hinge Fitting Elevator - Inspection
2016-0155	2016-08-02	328 SUPPORT SERVICES	Dornier 328	Fuselage - Removal of Teledyne Telelink System - Specific Maintenance Requirements
2016-0156	2016-08-02	DIAMOND AIRCRAFT INDUSTRIES	DA 42 / 62	Engine Exhaust - Exhaust Pipes - Replacement
2011-0135R2	2016-08-02	BLANIK Ltd	L-13 (Blanik)	Prohibition of all flights / Restoration of Airworthiness Wings - Wing Main Spar - Inspection / Operational Limitation / Operational Records Check
US-2016-15-04	2016-08-01	BOEING	757	Fuselage - Skin Lap Splice / Inner Skin Fasteners - Inspection



N/A

Publ. number	Issue Date	TC Holder	Type	Subject
2016-0173-E	2016-08-24	LEONARDO S.p.A. HELICOPTERS	A109/A119	Tail Rotor Drive - Blade Retention Bolts - Inspection / Replacement [Retirement Life Reduction]
2016-0172	2016-08-23	AIRBUS	A300-600, A300-600ST (Beluga), A310	Electrical Power - Wing Electrical Installation - Modification
2016-0171	2016-08-22	SAAB AB, AERONAUTICS	2000	Nacelles/Pylons - Engine Mounting Upper Longeron and Upper Fitting Fasteners - Inspection
CF-2016-24	2016-08-22	BOMBARDIER	BD-100	Landing Gear - Uncommanded Nose Wheel Steering
2016-0170	2016-08-19	AIRBUS	A310	Wings - Bottom Skin at Main Landing Gear Reinforcing Plate - Modification
2016-0168	2016-08-17	DASSAULT AVIATION	Falcon 2000	Ice and Rain Protection - Air Inlet Anti-Ice System - Inspection / Repair
2016-0167	2016-08-17	ZODIAC SEATS FRANCE	Cabin Attendant Seats	Equipment / Furnishings - Rear Cabin Attendant Seat - Inspection / Repair
2016-0169	2016-08-17	328 SUPPORT SERVICES	Dornier 328	Fuel - Fuel Line Clamps - Inspection / Replacement
2010-0136R1	2016-08-16	TECHNIFY MOTORS	TAE125	Engine - Timing Chain - Replacement
US-2016-16-13	2016-08-15	BOEING	737	Fuselage - Fuselage Skin at Crown Stringers S-1 and S-2R - Inspections / Repair

N/A



Publ. number	Issue Date	TC Holder	Type	Subject
2016-0177	2016-09-08	LEONARDO S.p.A. HELICOPTERS	AW189	Structures - Tail Gearbox Fitting - Inspection / Replacement
US-2016-18-04	2016-09-07	BOEING	747	Powerplant - Forward Engine Mount Barrel Nuts and Bolts - Inspection / Installation
US-2016-16-10	2016-09-07	BOEING	747	Fuselage - Station 320 Crown Frame, Window Post No.3 and Upper Sill - Inspection / Rework
CF-2016-26	2016-09-07	BOMBARDIER	BD-100	Equipment / Furnishings - Equipment Racks - Modification of the Left and the Right Equipment Racks
US-2016-18-02	2016-09-07	BOEING	777	Oxygen - Low-Pressure Oxygen Flex Hoses - Replacement
US-2016-18-10	2016-09-05	INTERNATIONAL AERO ENGINES AG	V2500-()5	Engine - High-Pressure Turbine Stage 1 & Stage 2 Hubs - Inspection
US-2016-17-11	2016-09-05	BOEING	787	Wings - Engine Pylon Wiring Bracket - Inspection / Re-identification / Replacement
2016-0176	2016-09-01	AIRBUS	A318, A319, A320, A321	[Correction] Airborne Auxiliary Power - Auxiliary Power Unit Starter Motor and Air Intake System - Inspection / Cleaning
US-2016-17-06	2016-09-01	BOEING	767	Fuselage - Aft Pressure Bulkhead Web - Inspection
2016-0175	2016-08-31	AIRBUS	A380	Pneumatic - Duct Assembly Material - Replacement
2015-0173R1	2016-08-31	AIRBUS	A300	Fuselage, Wings - Multiple Cracks Development Structural Parts / Joints - Inspection / Modification
2015-0124R2	2016-08-31	AIRBUS	A330, A340	Flight Controls - Flight Control Primary Computers - Modification / Replacement
CF-2016-25	2016-08-31	BOMBARDIER	DHC-8	Fire Protection - Inadvertent Discharge of Multiple Fire Extinguishing Bottles
2016-0174	2016-08-30	AIRBUS	A300-600	Wings - Outer Wing Stringer Run-Outs at Rib 14 - Modification
US-2016-17-08	2016-08-29	TEXTRON AVIATION INC.	310, 320 (Skyknight), 335, 340, 401, 402, 411, 414, 421	Flight Controls - Elevator Trim Push-pull Rod - Replacement / Inspection



Publ. number	Issue Date	TC Holder	Type	Subject
US-2016-17-10	2016-09-23	BOEING	777	Landing Gear - Main Landing Gear Aft Trunnion Pin - Identification / Replacement
US-2016-19-05	2016-09-23	INTERNATIONAL AERO ENGINES AG	V2500-A1	Engine - High-Pressure Turbine Seal - Removal / Inspection
2016-0188	2016-09-22	AIRBUS	A330, A340	[Correction] Doors - Forward and Aft Cargo Doors - Inspection / Reinforcement
CF-2014-45R1	2016-09-22	BOMBARDIER	DHC-8	Nacelle - A-Frame Structure - Insufficient Fillet Radius and Fouling with Main Landing Gear Stabilizer Brace and the Electrical Wiring Harnesses
2015-0120R1	2016-09-21	AIRBUS	A330, A340	Wings - Main Landing Gear Rib 6 Aft Bearing Lugs - Inspection / Replacement
US-2016-18-11	2016-09-21	GULFSTREAM AEROSPACE CORPORATION	G-1159, GIV, GV	Landing Gear - Main Landing Gear Door Actuator End Cap Fitting - Replacement / Revision of the Maintenance / Inspection Program
US-2016-18-01	2016-09-21	BOEING	737	Landing Gear - Main Landing Gear Forward and Aft Trunnion Pin Assemblies - Lubrication / Inspection
US-2016-18-15	2016-09-19	BOEING	737	Fuselage - Aft Pressure Bulkhead Web - Inspection
2016-0187	2016-09-19	AIRBUS	A319, A320, A321	Door - Forward and Aft Cargo Door Frame Forks - Inspection
CF-2016-27	2016-09-16	BOMBARDIER	DHC-8	Equipment and Furnishings - Instrument Panel - Pilot and Co-pilot Wiring Shroud Inspection and Modification
2016-0018R1	2016-09-14	AIRBUS	A318, A319, A320, A321	Landing Gear - Main Landing Gear Side Stay Assemblies - Replacement / Modification
2016-0184	2016-09-13	AIRBUS	A318, A319, A320, A321	Flight Controls - Trimmable Horizontal Stabilizer Actuator - Inspection / Replacement (Life Limitation)
2016-0181	2016-09-13	AIRBUS	A320	Wings - Centre Section / Pressurized Floor Fittings at Frame 36 Junction - Inspection / Modification
2016-0180	2016-09-13	AIRBUS HELICOPTERS	EC 120 B	Equipment & Furnishings - Emergency Floatation Gear Lighting and Ancillary Control Unit (LACU) Pushbutton - In-Flight Check / Replacement
2016-0183	2016-09-13	PILATUS AIRCRAFT LTD	PC-6	Wings - Aileron Mass-Balance Counterweight Attachment - Inspection
2016-0182	2016-09-13	AIRBUS	A319, A320, A321	Doors - Main Landing Gear Door Actuator Fittings - Inspection / Replacement
2016-0178	2016-09-12	AIRBUS	A300-600, A310	Fuselage - Forward Cargo Door Structure - Modification
2016-0179	2016-09-12	AIRBUS	A300-600	Wings - Fuselage Frame 40 Lower Outboard Radius - Inspection
US-2016-18-06	2016-09-12	BOEING	767	Equipment / Furnishings - Escape Slide Regulator Valves - Modification