

SECTION 1.0 AIRWORTHINESS DIRECTIVES (AIRFRAME) COMPLIANCE SUMMARY

Aircraft Type: **AS365N3**
 Aircraft S/N: **6835**
 Registration: **9M-TSV**

Last Reviewed: **10-Jun-24**

No.	Authority	AD Reference	Effective Date	Description	Applicability	Corresponding SB	Status	Compliance
26		F-2002-474-058 R2	5/11/2005	Check main landing gear wheel and brake hose.	No	32.00.09 R1	Closed	N/A. Floatation gear not installed.Refer Individual Inspection Log Book
27		F-2003-028 R1	18/08/2004	Check interference between Fuel air vent hoses and screw at 9 degree frame	Yes	28.00.31	Closed	C/W by manufacturer. Refer Individual Inspection Log Book; AD Section Page 9 of 10.
28		F-2003-036	15/02/2003	Check Transponder MST 67 A Mode S.	No	Honeywell S/B MST 67A SW2	Closed	N/A. P/N 066-01143-2101 installed Refer Individual Inspection Log Book
29		F-2003-277-IMP	21/08/2003	VHF Communication transceiver AR4201 (Becker)	No	S/B Becker AR 4201-01-03	Closed	N/A. Equipment not installed. Refer Individual Inspection Log Book; AD Section Page 9 of 10.
30		F-2003-278-IMP	16/08/2003	Ground proximity warning TAWS8000	No	Goodrich Memo SL # 134	Closed	N/A. Honeywell System P/N 700-170-020 installed. Refer Individual Inspection Log Book
31		F-2003-321	13/09/2003	Landing gears: end ball corrosion inspection.	Yes	32.00.10	Closed	Complied on 09 January 2013 at A/F TT 511.9FH. W/O2012501001. Task incorporated into MSM
32		F-2003-322 R1	5/6/2004	To ensure Double safetying on flight control stop screw before MOD 0776B58	No	67.00.09 R1	Closed	N/A Mod 0767B58 C/W by manufacturer. Refer Individual Inspection Log Book
33		F-2004-053	14/04/2004	Replacement of computer System TCAS II / ACAS II equipment P/N 457-400 EA-0311	No	S/B Thales 457400-34-082-1 0085	Closed	N/A. AFCS computer system P/N 418-00491-350 installed. Refer Individual Inspection Log Book
34		F-2004-116	21/07/2004	Tail rotor blade monitoring and limitations of the fatigue failure of the tie bar of the blade.	No	05.00.17 R1	Superseded	AD Cancelled and superseded by EASA AD 2012-0067
35		F-2004-154	11/9/2004	MGB oil LP warning. P/N 365A32-6002-XX and P/N 365A32-6004-XX.	No	63.00.12	Closed	N/A. MGB P/N 365A32-6001-05 installed.
36		F-2004-154R1	30/06/2010	MGB oil LP warning. P/N 365A32-6002-XX and P/N 365A32-6004-XX.	No	NIL	Superseded	AD Cancelled and superseded by EU 2010-0116-E.
37		F-2004-179	20/11/2004	Check and replacement of Engine fire extinguishers, before MOD 0726B22	No	05.00.46	Closed	N/A. Mod 0726B22 embodied at production. Refer Individual Inspection Log Book
38		F-2004-188	8/12/2004	Inspection of Cargo hold upholstery modification	Yes	25.00.62	Closed	C/W by manufacturer. Refer Individual Inspection Log Book
39		F-2005-127 R1	11-Feb-06	Check: collective pitch lever restraining tab Inadvertent locking / unlocking of collective pitch lever during the various flight / ground phases.	No	67.00.10	Superseded	N/A. Mod 767B65 embodied at production. Refer Individual Inspection Log Book SUPERSEDED BY EASA AD 2011-0154
40		F-2005-170 R1	12-Oct-05	Check cracks on Main rotor rotating star	No	05.00.50	Cancelled	AD Cancelled.
41		F-2005-182 R0	9-Nov-05	Check of the MGB planet gear carrier	No	05.00.48 R0	Superseded	Superseded by AD EU-2007-0288.
42		F-2006-042 R0	10-Feb-06	Hydraulic Power - Flexible Hydraulic Pipes & Attachment Clamps - Check	No	29.00.08	Closed	N/A. Mod 0729B67 embodied at production. Refer Individual Inspection Log Book
43	EASA	2006-0078 R0	12-Apr-06	Tail Rotor - Blade Tuning Weights	No	64.00.23 R1	Closed	N/A. Mod 0764B48 embodied at production. Refer Individual Inspection Log Book
44	EASA	2006-0080 R0	12-Apr-06	Equipment/Furnishings - Life Raft Installation	No	25.00.70	Closed	N/A. Life raft not installed. Refer RIC.
45	EASA	2006-0084-E R0	11-Apr-06	Main Rotor - Hub-to-Mast Bolted Attachment - Check	No	62.00.22	Closed	N/A. Aircraft delivered after 03/2006.(D,O,M Dec 2008)
46	EASA	2006-0098 R0	5-May-06	[Corrected] Equipment / Furnishings - Hoist Hooks	No	E ASB 01.00.57	Closed	N/A. Hoist not installed. Refer Individual Inspection Log Book
47	EASA	2006-0099 R0	5-May-06	Tail Rotor- Tail Rotor Blade Check	No	05.00.49	Closed	N/A. Tail rotor blade PN 365A12-0070-01 installed. Refer Individual Inspection Log Book
48	EASA	2006-0101 R0	5-May-06	Rotor Drive(s) - Check of Main Gearbox (MGB) Base Plate	No	05.00.45 R1	Closed	N/A Mod 0763C45 embodied at production. Refer Individual Inspection Log Book
49	EASA	2006-0126-E R0	18-May-06	CPT 609 crash position transmitter beacon to prevent loss of antenna	No	05.00.53	Superseded	A/D superseded by A/D 2007-0224.
50	EASA	2006-0213 R0	28-Jul-06	Landing gear – optional ski installation Info's for flight crew	No	Nil	Closed	N/A. SKI not installed. Refer Individual Inspection Log Book.