


General Accounts Production Time Allocations Documents ATA List History

Task Number :



Task ID : 27091

Job : #0 -  SearchParent :  SearchStart Date : 

Created By : Continuing Airworthiness Manager

Due Date : 

Modified By : Continuing Airworthiness Manager

Defects/Title : MSM 28-20 FUEL DISTRIBUTION  Priority : Low Status : WIP Reference/IAW : Category :

Details/Rectification : 28/20/00/211/000/010

TRANSFER PUMP

CHECK THE BRUSHES AND THE ARMATURE.

REF: CMM 28.19.03

28-19-03-220-007-A01

28-19-03-220-008-A01

REMARKS:

Notes :

General Accounts Production Time Allocations Documents ATA List History

Task Number : 0

Task ID : 26927

Job : 0 #0 - Search

Parent : 0 Search

Start Date : 28 06 2019

Created By : Continuing Airworthiness Manager

Due Date : 30 06 2019

Modified By : Continuing Airworthiness Manager

Defects/Title : MSM 45-11 OPT - CVFDR

Priority : Low

Status : WIP

Reference/AW :

Category :

Details/Rectification : 45/11/01/723/000/000

IMMERSION PROBE









HONEYWELL AR204C. / AR602C

FUNCTIONAL TEST.

REF: AMM 45.11.01.723GRT 05

REMARKS:

General Accounts Production Time Allocations Documents ATA List History

Task Number :	<input type="text" value="0"/>	Task ID :	107815
Job :	<input type="text" value="0"/> #0 -  Search	Parent :	<input type="text" value="0"/>  Search
Start Date :	<input type="text" value="17"/> <input type="text" value="03"/> <input type="text" value="2021"/> 	Created By :	CAMO JBPM
Due Date :	<input type="text" value="19"/> <input type="text" value="03"/> <input type="text" value="2021"/> 	Modified By :	CAMO JBPM
Defects/Title :	<input type="text" value="52-30 CARGO DOOR"/>  	Priority :	<input type="text" value="Low"/> 
Reference/IAW :	<input type="text"/>	Status :	<input type="text" value="WIP"/> 
Remarks/Rectification :	<input type="text" value="52/30/00/520/221/000"/> COMPARTMENT AND BATTERY DOOR LOCKS POST MOD 0752C68 CHECK. REF: AMM 52.00.00.221, GRT 06 REMARKS:		
Notes :	<input type="text"/>		

General Accounts Production Time Allocations Documents ATA List History

Task Number :	<input type="text" value="0"/>	Task ID :	107817
Job :	<input type="text" value="0"/> #0 - <input type="text" value="Search"/>	Parent :	<input type="text" value="0"/> <input type="text" value="Search"/>
Start Date :	<input type="text" value="17"/> <input type="text" value="03"/> <input type="text" value="2021"/> <input type="text" value="Calendar"/>	Created By :	<input type="text" value="CAMO JBPM"/>
Due Date :	<input type="text" value="19"/> <input type="text" value="03"/> <input type="text" value="2021"/> <input type="text" value="Calendar"/>	Modified By :	CAMO JBPM
Defects/Title :	<input type="text" value="64-10 ROTOR BLADES"/> <input type="text" value="Download"/> <input type="text" value="Upload"/>	Priority :	<input type="text" value="Low"/>
Reference/AW :	<input type="text"/>	Status :	<input type="text" value="WIP"/>
		Category :	<input type="text"/>

Details/Rectification :

64/10/00/221/001/042
TAIL ROTOR BLADE

365A12-0070-00 (/)
365A12-0070-01 (-)

VISUAL INSPECTION.
WITH BLADE REMOVAL.
WITH TRH FAIRING REMOVAL.

NOTE 1: IF THERE IS SEPARATION OF BLADE SHIELDING IN ZONE A2 AND A5: INSPECTION EVERY 100 FH OR 1 Y, AS LONG AS THE REPLACEMENT CRITERIA ARE NOT MET (WITHOUT BLADE REMOVAL) .

NOTE 2: IF THERE IS SEPARATION OF BLADE SHIELDING IN ZONE C AND E: INSPECTION EVERY 50 FH, 100 FH, 150 FH AND 300 FH (WITHOUT BLADE REMOVAL) . IF NO CHANGE IS NOTICED, RESUME THE REGULAR INSPECTION CYCLE.

REF: AMM 64.10.00.221B; 64.10.00.221.003; 64.10.00.221.004

REMARKS: