

Aircraft Registration: 9M-PTA Date of Values: 25/11/2022 | Airframe: 6298-15

General Log Book Inspections Components Airframe Engine 1 Engine 2 Modifications ADs SBs Flight History Documents SORs Jobs History Notes Rates Users

With Selected

Repetitive SBs [View All]

SB Number/Subject	Based On	Period	Warning	Last SB	Next SB	Remaining	Status
SB 27-3459 REV. 2 ATA 27 - FLIGHT CONTROLS - FLIGHT CONTROL GUST LOCK INSPECTION/ REPLACEMENT (RECURRING INSP)	Date (Months)	12.0	3.0 Months	04/07/2022	03/07/2023	217 days	Complete

Standard SBs [View All]

SB Number/Subject	Based On	Warning	Completed	Due At	Remaining	Status
MTL-53-02 REV. 1 FUSELAGE - FORWARD FUSELAGE FASTENER INSPECTION		-	-	-	-	CANCELLED

Aircraft Registration: 9M-PTB Date of Values: 25/11/2022 | Airframe: 5797-11

General Log Book Inspections Components Airframe Engine 1 Engine 2 Modifications ADs SBs Flight History Documents SORs Jobs History Notes Rates Users

With Selected

Repetitive SBs [View All]

SB Number/Subject	Based On	Period	Warning	Last SB	Next SB	Remaining	Status
SB 27-3459 REV. 2 ATA 27 - FLIGHT CONTROLS - FLIGHT CONTROL GUST LOCK INSPECTION/ REPLACEMENT (RECURRING INSP)	Date (Months)	12.0	3.0 Months	25/06/2022	24/06/2023	208 days	Complete

Standard SBs [View All]

SB Number/Subject	Based On	Warning	Completed	Due At	Remaining	Status
MTL-53-02 REV. 1 FUSELAGE - FORWARD FUSELAGE FASTENER INSPECTION		-	-	-	-	CANCELLED

Aircraft Registration: 9M-PTC Date of Values: 24/11/2022 | Airframe: 4160-02

General Log Book Inspections Components Airframe Engine 1 Engine 2 Modifications ADs SBs Flight History Documents SORs Jobs History Notes Rates Users

With Selected

Repetitive SBs [View All]

SB Number/Subject	Based On	Period	Warning	Last SB	Next SB	Remaining	Status
SB 27-3459 REV. 2 ATA 27 - FLIGHT CONTROLS - FLIGHT CONTROL GUST LOCK INSPECTION/ REPLACEMENT (RECURRING INSP)	Date (Months)	12.0	3.0 Months	26/09/2022	25/09/2023	301 days	Complete

Standard SBs [View All]

SB Number/Subject	Based On	Warning	Completed	Due At	Remaining	Status
MTL-53-02 REV. 1 FUSELAGE - FORWARD FUSELAGE FASTENER INSPECTION		-	-	-	-	CANCELLED

Aircraft Registration: 9M-PTD Date of Values: 30/05/2022 | Airframe: 1275-20

General Log Book Inspections Components Airframe Engine 1 Engine 2 Modifications ADs SBs Flight History Documents SORs Jobs History Notes Rates Users

With Selected

Repetitive SBs [View All]

SB Number/Subject	Based On	Period	Warning	Last SB	Next SB	Remaining	Status
SB 27-3459 REV. 2 ATA 27 - FLIGHT CONTROLS - FLIGHT CONTROL GUST LOCK INSPECTION/ REPLACEMENT (RECURRING INSP)	Date (Months)	12.0	3.0 Months	02/09/2022	01/09/2023	277 days	Complete

Standard SBs [View All]

SB Number/Subject	Based On	Warning	Completed	Due At	Remaining	Status
MTL-53-02 REV. 1 FUSELAGE - FORWARD FUSELAGE FASTENER INSPECTION		-	-	-	-	CANCELLED

Aircraft Registration: 9M-PTE Date of Values: 24/11/2022 | Airframe: 2292-49

General Log Book Inspections Components Airframe Engine 1 Engine 2 Modifications ADs SBs Flight History Documents SORs Jobs History Notes Rates Users

With Selected

Repetitive SBs [View All]

SB Number/Subject	Based On	Period	Warning	Last SB	Next SB	Remaining	Status
SB 27-3459 REV. 2 ATA 27 - FLIGHT CONTROLS - FLIGHT CONTROL GUST LOCK INSPECTION/ REPLACEMENT (RECURRING INSP)	Date (Months)	12.0	3.0 Months	01/08/2022	31/07/2023	245 days	Complete

Standard SBs [View All]

SB Number/Subject	Based On	Warning	Completed	Due At	Remaining	Status
MTL-53-02 REV. 1 FUSELAGE - FORWARD FUSELAGE FASTENER INSPECTION		-	-	-	-	CANCELLED