



MYCOPTER AVIATION SERVICES SDN.BHD.
 LOT 10, HELICOPTER CENTRE,
 MALAYSIA INTERNATIONAL AEROSPACE CENTRE,
 SULTAN ABDUL AZIZ SHAH AIRPORT,
 47200 SUBANG, SELANGOR, MALAYSIA










WORKSHEET

WORKSHEET NUMBER: WS-026
 ISSUE DATE: 14.10.2021

AIRCRAFT TYPE: AW139	AIRCRAFT	#1 ENGINE	#2 ENGINE
AIRCRAFT REGISTRATION: N917YB	HOURS	300:40	300:40
AIRCRAFT SERIAL NUMBER: 31763	LDG CYCLE	838	
#1 ENGINE SERIAL NUMBER: PCE-KB1931	HOIST	414	
#2 ENGINE SERIAL NUMBER: PCE-KB1885	HEC	-	
REASON FOR RAISING	ENGINE START CYCLE	261	261
AIRCRAFT SERVICE BULLETIN AND FAA AIRWORTHINESS DIRECTIVE NEED TO BE CARRIED OUT			
I.A.W. CHAPTER 4 AND CHAPTER 5 - AMPI (FAA) - IETP 39th ISSUE 07 JUN 2021 (UPDATED: 20 JUL 2021)			

AIRCRAFT SERVICE BULLETIN AND FAA AIRWORTHINESS DIRECTIVE

ITEM	TASK/DESCRIPTION	REFERENCE	TECHNICIAN	INSPECTOR	DATE
01	PERFORM LEONARDO SB 139-467, PART 1 : TAIL ROTOR DRIVE LINE (TRDL) BEARING SUPPORT BRACKET. DUE: 297:51 FH (RECURRENT EVERY 25 FH) REMARKS:	SB 139-467		 	12/11/21
02	PERFORM LEONARDO SB 139-452, REVISION B, PART 1 : MAIN ROTOR DAMPER INSPECTION AND REPLACEMENT. DUE: AFTER LAST FLIGHT (ALF) (RECURRENT EVERY ALF) REMARKS:	SB 139-452, REVISION B		 	16/11/21

ITEM	TASK/DESCRIPTION	REFERENCE	TECHNICIAN	INSPECTOR	DATE
03	<p>PERFORM LEONARDO SB 139-450, REVISION D, PART 1, 3, 4, 5 AND 6 : MAIN ROTOR DAMPER INSPECTIONS</p> <p>PART 1: APPLICABLE TO ALL MR DAMPER. PART 3: APPLICABLE TO ALL MR DAMPER. PART 4: APPLICABLE TO ALL MR DAMPER. PART 5: APPLICABLE TO MR DAMPER COLOR BLACK. PART 6: APPLICABLE TO ALL MR DAMPER.</p> <p>DUE: PART 1: 300:00 FH (ONE OFF) PART 3: BFF/ALF (RECURRENT) PART 4: BFF/ALF (RECURRENT) PART 5: 300:40 FH (RECURRENT) PART 6: 300:40 FH (RECURRENT)</p> <p>REMARKS:</p>	SB 139-450, REVISION D		 	8/11/21
04	<p>PERFORM LEONARDO SB 139-594, PART 1 : INSPECTION OF MAIN LANDING GEAR ACTUATOR BOLTS.</p> <p>DUE: 289:14 FH (ONE OFF)</p> <p>REMARKS:</p>	SB 139-594		 	17/11/21
05	<p>PERFORM LEONARDO SB 139-642, PART 1 : TAIL ROTOR HEAD INSPECTION AND MODIFICATION.</p> <p>DUE: 16.10.2020 / 291:19 FH (ONE OFF)</p> <p>REMARKS:</p>	SB 139-642		 	22/11/21