

## Annex 1 - AIRWORTHINESS DIRECTIVES (SINCE OCTOBER 1<sup>ST</sup>, 2003)

Helicopter type: **AW139**

S.N.: **31726**

Marks:

**9M-PMB**

Date: **17/06/2016**

Helicopter total time: **NEW**

Marcello Palmini

Acronyms:

N.A. = Not Applicable;

C.W. = Complied With;

N.C.W. = Not Complied With

AUTHORITY	APPLICABLE A. D.s	ISSUE DATE	TITLE	RELATED INFORMATION	STATUS	NOTES
TCCA Last checked: CF-2016-20	CF-2012-24	02/08/2012	SECOND STAGE POWER TURBINE DISK DAMAGE	PRATT AND WHITNEY CANADA MODEL PT6C-67C ENGINES WITH PRE-SERVICE BULLETIN 41056 CONFIGURATION	N.A.	ENGINE POST SB41056
EASA Last checked: 2016-0116	2006-0242-E	11/08/2006	EXHAUST - TAILPIPE ASSY LH P/N 3G7800L00131 AND TAILPIPE ASSY RH P/N 3G7800L00231 - INSPECTION	//	N.A.	SUPERSEDED BY EASA AD 2006-0360-E
	2006-0265-CN	17/04/2013	CANCELLED: NAVIGATION SYSTEMS - MODE C AND S TRANSPONDERS - CHECK	//	N.A.	NOT APPLICABLE: CANCELLATION NOTICE
	2006-0357R2	19/05/2015	FUSELAGE - FRAME 5700 MIDDLE SECTION - INSPECTION	SEE AGUSTA BT 139-018 REV. B SEE AGUSTA BT 139-089	N.A.	NOT APPLICABLE: P/N NOT AFFECTED.
	2006-0358R1	28/09/2011	STABILIZERS - FIN ASSEMBLY - INSPECTION/REPLACEMENT	SEE AGUSTA BT 139-020 REV. B	N.A.	SUPERSEDED BY EASA AD 2011-0205
	2006-0360-E	29/11/2006	EXHAUST - TAILPIPE ASSEMBLY - INSPECTION/REPAIR/REPLACEMENT	SEE AGUSTA BT 139-069 REV. B	N.A.	NOT APPLICABLE: INSTALLED DIFFERENT P/N (REF. HELICOPTER LOGBOOK)
	2007-0142	18/05/2007	WINDOWS - COCKPIT DOORS WINDOWS SEALING - INSPECTION/REPAIR/REPLACEMENT	//	N.A.	SUPERSEDED BY EASA AD 2008-0011
	2007-0156	14/06/2007	COMMUNICATION - COMM UNITS & TRANSPONDERS - MODIFICATION/REPLACEMENT	SEE AGUSTA BT 139-080 REV. A	N.A.	NOT APPLICABLE: MODE S TRANSPONDER NEW P/N INSTALLED (REF. HELICOPTER LOGBOOK)
	2007-0256	19/09/2007	EQUIPMENT AND FURNISHING - SEAT RESTRAINT SYSTEM PLASTIC ROTARY BUCKLE HANDLE - INSPECTION/REPLACEMENT	//	N.A.	NOT APPLICABLE: DIFFERENT EQUIPMENT INSTALLED.
	2008-0011	05/06/2008	WINDOWS - COCKPIT DOORS WINDOWS AND SEALING - INSPECTION/REPAIR/REPLACEMENT/MODIFICATION	//	N.A.	SUPERSEDED BY EASA AD 2008-0108
	2008-0108	05/06/2008	WINDOWS - COCKPIT DOORS WINDOWS REPLACEMENT	SEE AGUSTA BT 139-129 REV. A	N.A.	NOT APPLICABLE PER HELICOPTER S/N: INSTALLED DIFFERENT WINDOW P/N (REF. HELICOPTER LOGBOOK)
	2008-0148	05/08/2008	FUSELAGE - WIRE STRIKE PROTECTION SYSTEM (WSPS) TOP CABLE CUTTER - REWORK/REPLACEMENT	SEE AGUSTA BT 139-126	N.A.	KIT NOT INSTALLED.
	2008-0157	13/08/2008	FUSELAGE - TAIL BOOM ASSEMBLY - INSPECTION / REPAIR / REPLACEMENT	//	N.A.	SUPERSEDED BY EASA AD 2009-0198-E
	2009-0042	25/02/2009	ELECTRICAL POWER - GENERATOR CONTROL UNIT (GCU) - REPLACEMENT	SEE AGUSTA BT 139-133 REV. A	N.A.	NOT APPLICABLE: INSTALLED GCU P/N 1152550-4.

