TOOL SERVICE BULLETIN

NO: PT-910R1

Service Tool: PWC32092 Rev. B

Description: Crimper - Cup Washer

Effectivity: PT6A-45A, PT6A-45B, PT6A-45R, PT6A-50, PT6A-60A, PT6A-60AG,

PT6A-61, PT6A-62, PT6A-64, PT6A-65AG, PT6A-65AR, PT6A-65B, PT6A-65R, PT6A-66A, PT6A-66D, PT6A-66, PT6A-66B, PT6A-67B, PT6A-67D, PT6A-67P, PT6A-67F, PT6A-67, PT6A-67A, PT6A-67AF, PT6A-67AG, PT6A-67R, PT6A-67T, PT6A-68, PT6B-67A, PT6C-67C,

PT6C-67D

Subject: Tool obsolete

Reason:

Problem: Tool may damage engine hardware.

Cause: Improper use.

Solution: Obsolete, replaced by PWC50565.

WARNING - PROPRIETARY RIGHTS & EXPORT CONTROLS NOTICE

This bulletin contains proprietary information of Pratt & Whitney Canada Corp. ("P&WC"), which P&WC provides in confidence and solely for the purposes of supporting engine certification and providing applicable information regarding the proper use, maintenance, inspection, repair, servicing and parts application of P&WC products and services, as directed therein. Neither this bulletin nor any information in it may be disclosed to others, or used for any other purpose, including, without limitation, to design, create, develop, reproduce, manufacture or derive any design, part, product, material, process, modification, configuration change or repair, or obtain FAA or other government approval to do so. Possession and use of this bulletin is also subject to the restrictions set out in P&WC's Technical Data Agreement (a copy of which may be obtained by contacting P&WC Technical Publications). The contents of this bulletin may be subject to export control laws. Unauthorized export or re-export of the bulletin, or parts thereof, is prohibited. By accepting and possessing this bulletin, you agree to be bound by the foregoing terms.

If a Government agency or department intends to disclose any information, written notice should be given to: VP - Legal Services, Pratt & Whitney Canada Corp., 1000 Marie-Victorin (01BE5), Longueuil, Quebec J4G 1A1.

Issued: May 08/2017
Revised: Jul 16/2022
Page 1 of 3

TOOL SERVICE BULLETIN

NO: PT-910R1

Instruction: Tool PWC32092 is obsoleted, replaced by PWC50565.

Compliance: Required

Tool Usage: Overhaul

Tool Disposition: Discard PWC32092, do not use for any application.

P&WC Proprietary Information. Subject to the restrictions on the first page.

Issued: May 08/2017 Revised: Jul 16/2022

PWC32092 Page 2 of 3

TOOL SERVICE BULLETIN

NO: PT-910R1

TSB Revision Notes			
TSB	DATE	Tool Rev No.	CHANGES
PT-910	07/2022	1	Effectivity Revised to Include PT6A-62, PT6A-68

ICN-00198-G000124091-001-01

Figure 1

P&WC Proprietary Information. Subject to the restrictions on the first page.

Issued: May 08/2017 Revised: Jul 16/2022 **PWC32092** Page 3 of 3